



**RESERVE STUDY** 

Full Study

# **Cameron Park Community Services District**

Final Published - May 09, 2014 Prepared for the 2014/2015 Fiscal Year

## **Browning Reserve Group**

P. O. Box 60125 / Sacramento, CA 95860 Office (916) 393-0600 Fax (916) 393-0610 Bob@BrowningRG.com / www.BrowningRG.com



# **Cameron Park Community Services District**

Final

# **Table of Contents**

Section	Report		Page
Section I:	Summary of District Reserves		1
Section II:	30 Year Expense Forecast	Detailed	5
Section III:	30 Year Reserve Funding Plan	Cash Flow Method {c}	55
Section III-a:	30 Year Reserve Funding Plan	Cash Flow Method - Ending Balances Chart	56
Section IV:	30 Year Reserve Funding Plan	Fully Funded Balance and % Funded	57
Section IV-a:	30 Year Reserve Funding Plan	Cash Flow Method - Percent Funded Chart	58
Section V:	Reserve Fund Balance Forecast	Component Method	59
Section VI:	Component Listing	Included Components	95
Section VII:	Tabular Component Listing	Included Components	323
Section VII-a:	Expenditures by Year	- Next 3 Years	342
Section X:	Auditor Notes		350
Section X-a:	Supplementary Information for Auditor	Component Method	352
Section XI:	Glossary	Reserve Study Terms	371



Full Study



Cameron Park Community

Services District
Final
Published - May 09, 2014
Prepared for the 2014/2015 Fiscal Year

# **Reserve Study Summary**

A Reserve Study was conducted of Cameron Park Community Services District (the "**District**"). A **Full Study** includes an on-site review upon where the following tasks are performed:

- development of a reserve component inventory;
- condition assessment based upon on-site visual observation;
- life and valuation estimates;
- fund status;
- and a funding plan.

# **Physical Inspection**

Browning Reserve Group ("**BRG**") conducted a physical inspection of the District. The inspection encompassed those major components that the District is required to maintain. For this study components are determined to be major components if:

- 1. As of the date of the study, they have a remaining useful life of less than 30 years, and a value greater than \$1,000.
- 2. Such additional components, if any, determined by the Project Manager.

During the inspection, BRG utilized the services of our own construction cost estimator. In addition, independent contractors were retained to render opinions on selected components as indicated in *Section VI*, *Included Component Listing*.

Supplemental information to the physical inspection may have been obtained from the following sources:

- 1. Project plans where available.
- 2. Maintenance records of the reserve components where available.
- 3. District board members, management and staff.

## **Summary of Reserves**

For the first year of the Reserve Study, the reserve contribution is based upon the existing budget unless otherwise noted in "Section III, Reserve Funding Plan." In addition BRG relied on the District to provide an accurate Beginning Reserve Balance.

The status of the District's reserves, as reflected in the following Reserve Study, is as follows:

- 1. The Expenditure Forecast of the following Reserve Study identifies the major components which the District is obligated to repair, replace, restore or maintain, as determined in accordance with the criteria specified above, and specifies for each such component:
  - Its current estimated replacement cost;
  - b. Its estimated useful life; and
  - c. Its estimated remaining useful life.
- 2. It is estimated that the total cash reserves necessary to repair, replace, restore or maintain such major components (in the aggregate) during and at the end of their first remaining useful life is \$3,970,543.
  - [For purposes of this calculation, "necessary" is defined as the Fully Funded Balance (FFB) (Component Current Cost X Effective Age / Useful Life, including a provision for interest and inflation in future years.)]
- 3. The current amount of accumulated cash reserves actually set aside to repair, replace, restore, or maintain such major components as of the fiscal year ending June 30, 2015 is estimated to be \$2,989,309, constituting 75.3% of the total expenditures anticipated for all such major components through their first end of useful life replacement.
- 4. Based upon the schedule of annual reserve contributions necessary to defray the cost of repairing, replacing, restoring or maintaining such major components in the years such expenditures are estimated to be required, it is estimated that annual reserve contributions in the initial amount of \$448,000 [\$37,333.33 per Unit per month (average)] for the fiscal year ending June 30, 2015 (the first full fiscal year following first distribution of this report) will be necessary in order to meet all such reserve expenditures when they are projected to come due.

## **Funding Assessment**

Based on the 30 year cash flow projection, the District's reserves appear adequately funded as the reserve fund ending balances remain positive throughout the replacement of all major components during the next 30 years.

California statute imposes no reserve funding level requirements nor does it address funding level adequacy, and although one or more of the reserve fund percentages expressed in this report may be less than one hundred percent, those percentages do not necessarily indicate that the District's reserves are inadequately funded.

## **Percent Funded Status**

Based on paragraphs 1 - 3 above, the District is 75.3% funded. The following scale can be used as a measure to determine the District's financial picture whereas the lower the percentage, the higher the likelihood of the District requiring a special assessment, or other large increases to the reserve contribution in the future.



# **Methodology**

The above recommended reserve contribution for the next fiscal year (and future fiscal years as outlined in <u>Section III, Reserve Fund Balance Forecast</u>) was developed using the cash flow method. This is a method of developing a reserve funding plan where the contributions to the reserve fund are designed to offset the variable annual expenditures from the reserve fund. Different reserve funding plans are tested against the anticipated schedule of reserve expenses until the desired funding goal is achieved.

## **Funding Goals**

The funding goal employed for Cameron Park Community Services District is

**<u>Threshold Funding</u>**: Establishing a Reserve funding goal of keeping the Reserve

balance above a specified dollar or Percent Funded amount.

Depending on the threshold, this may be more or less

conservative than "Fully Funding."

### Limitations

The intention of the Reserve Study is to forecast the District's ability to repair or replace major components as they wear out in future years. The Reserve Study is not an engineering report, and no destructive testing was performed. The costs outlined in the study are for budgetary and planning purposes only, and actual bid costs would depend upon the defined scope of work at the time repairs are made. Also, any latent defects are excluded from this report.

## Compliance

The Reserve Study was conducted pursuant with standards set forth by the Community Associations Institute (CAI) and the Association of Professional Reserve Analysts (APRA).

# **Supplemental Disclosures**

### **General:**

BRG has no other involvement(s) with the District which could result in actual or perceived conflicts of interest.

## **Personnel Credentials:**

BRG is a licensed general building contractor in California, #768851, and the owner, Robert W. Browning, holds the Reserve Specialist designation, #46 from the Community Associations Institute.

## **Completeness:**

BRG has found no material issues which, if not disclosed, would cause a distortion of the District's situation.

### **Reliance on Client Data:**

Information provided by the official representative of the District regarding financial, physical, quantity, or historical issues will be deemed reliable by BRG.

# Scope:

This Reserve Study is a reflection of information provided to BRG and assembled for the District's use, not for the purpose of performing an audit, quality/forensic analysis, health and safety inspection, or background checks of historical records.

## **Reserve Balance:**

The actual beginning reserve fund balance in this Reserve Study is based upon information provided and was not audited.

# **Reserve Projects:**

Information provided about reserve projects will be considered reliable. Any on-site inspection should not be considered a project audit, quality inspection, or health and safety review.

CAI-RS Z All C Sesignation Seserve Specialis

Browning Reserve Group



Final



Cameron Park Community Services District

30 Year Expense Forecast - Detailed

Prepared for the 2014/2015 Fiscal Year

Life Current Replacement Useful /

Reserve Component	Cost	Rem	aining	2013/14 201	14/15 2015	5/16 2016	5/17 2017/1	8 2018/1	9 2019/2	0 2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	2027/2
00010 - Community Center																	
01000 - Paving																	
124 - Asphalt: Sealing 59,100 Sq. Ft. Parking Lot	7,269	5	2		7,6	37				8,641					9,776		
224 - Asphalt: Ongoing Repairs 59,100 Sq. Ft. Parking Lot (3%)	4,922	5	2		5,1	71				5,851					6,619		
424 - Asphalt: Major Repairs 59,100 Sq. Ft. Parking Lot	302,887	25	20														
808 - Striping Parking Lot	3,587	5	2		3,7	69				4,264					4,825		
Total 01000 - Paving	318,666				16,5	78				18,756					21,221		
02000 - Concrete																	
904 - Miscellaneous 38,500 Sq. Ft. Community Center Concrete (2%)	12,628	5	2		13,2	67				15,011					16,983		
Total 02000 - Concrete	12,628				13,2	67				15,011					16,983		
03000 - Painting: Exterior																	
108 - Surface Restoration 27,500 Sq. Ft. Community Center Buildings	28,187	10	5					31,892									
400 - Wrought Iron 600 Lin. Ft. Pool Fence	5,535	4	4				6,110				6,744				7,444		
500 - Light Poles 14 Common Area Light Poles	2,655	4	1	2,	,721			3,004				3,315				3,660	
Total 03000 - Painting: Exterior	36,377			2,	,721		6,110	34,895			6,744	3,315			7,444	3,660	
03500 - Painting: Interior																	
100 - Building 46,447 Sq. Ft. Community Center Interiors	47,608	10	5					53,864									
Total 03500 - Painting: Interior	47,608							53,864									
04000 - Structural Repairs																	
356 - Garbage Enclosure Community Center Enclosure	1,537	5	2		1,6	15				1,828					2,068		
540 - Bridge Maintenance Community Center Bridge	5,125	10	5					5,798									
914 - Doors 45 Community Center Interior Doors (11%)	3,075	2	0	3,075	3,2	31	3,394		3,566		3,747		3,936		4,136		4,345
Total 04000 - Structural Repairs	9,737			3,075	4,8	46	3,394	5,798	3,566	1,828	3,747		3,936		6,203		4,345
05000 - Roofing																	
330 - Low Slope: Vinyl 178 Squares- Community Center Buildings	91,225	30	25														

2279 05/09/2014 06fsv4.5.74-543:jf.jf

Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

Current Life

Replacement Useful / Prepared for the 2014/2015 Fiscal Year Cost Remaining 2013/14 2014/15 2015/16 2016/17 2017/18 2018/19 2019/20 2020/21 2021/22 2022/23 2023/24 2024/25 2025/26 2026/27 2027/28 Reserve Component 688 - Pitched: Metal 48,687 30 25 95 Squares- Community Center Buildings 700 - Gutters / Downspouts 2,060 30 25 335 Lin. Ft. Community Center Buildings Total 05000 - Roofing 141,973 08000 - Rehab 100 - General 3.075 15 10 3,936 2 C02 & Chlorine 104 - General 28,700 20 15 8 Offices 3,075 20 15 108 - General 2 First Aid & Lifeguard 116 - General 7,687 10 5 8,698 Stage Room 5,125 10 5 124 - General 5,798 2 Classroom & Preschool 10,250 20 15 222 - Bathrooms 2 Pool Area- Shower/Locker/Restrooms 238 - Restrooms 6,150 10 5 6,958 2 Community Center Restrooms 242 - Restrooms 3,075 10 5 3,479 2 Community Center Single Restrooms 258 - Kitchen 3,075 20 15 Pool Concession Room 266 - Kitchen 10,250 20 15 Kitchen 380 - Tile 1,025 10 5 1,160 2 Outdoor Showers 590 - Operable Wall/Partition 36,900 20 15 720 Sq. Ft. Stage Room Total 08000 - Rehab 118,387 26,093 3,936 12000 - Pool 110 - Resurface 30,750 12 7 36,552 375 Lin. Ft. Pool 200 - Edge: Tile, Coping, Mastic 17,297 24 19 375 Lin. Ft. Pool 210 - Tile: Lanes 22,570 12 7 26,829 734 Lin. Ft. Pool 320 - Hand Rail / Ladder 7,380 24 19 6 Pool 400 - ADA Chair Lift 4,510 10 5 5,103 Pool Equipment Room 700 - Equipment: Replacement 1,537 10 5 1,740 Pool Eqpt Rm- Ultra Max 704 - Equipment: Replacement 1,025 10 5 1,160 Pool Eqpt Rm- Aquavac 5,125 10 5 5,798 708 - Equipment: Replacement 2 Pool Equipment Room- Filters 720 - Heater 15,375 10 5 17,395 Pool Equipment Room 740 - Pumps 2,050 8 2,208 2,690 3

Pool Equipment Room- Pool Pump

Current Life Replacement Useful /

Prepared for the 2014/2015 Fiscal Year Cost Remaining 2013/14 2014/15 2015/16 2016/17 2017/18 2018/19 2019/20 2020/21 2021/22 2022/23 2023/24 2024/25 2025/26 2026/27 2027/28 Reserve Component 744 - Pumps 2,050 8 3 2,208 2,690 Pool Equipment Room- Slide Pump 748 - Pumps 2,050 8 3 2,208 2,690 Pool Equipment Room- Feature Pump 7,611 5 1 7,801 8,826 9,986 752 - Cover 7,425 Sq. Ft. Pool 780 - Water Feature 30,750 15 10 39,363 Pool Area Slide Structure 800 - Solar System 15,375 12 7 18,276 30 Roof- Pool Solar System Panels 950 - Furniture: Lifeguard Chair 8.200 10 5 9,278 4 Pool Area 960 - Furniture: Misc 10,250 10 5 11,597 Pool Furniture (Stored) 990 - Miscellaneous 2,562 10 5 2,899 Floating Racing Lanes Total 12000 - Pool 186,468 7,801 6,623 54,969 8,826 81,657 39,363 18,055 17500 - Basketball / Sport Court 300 - Basketball Standard 13,837 15 10 17.713 6 Basketball Hoops 680 - Scoreboard 4,407 20 15 Gym Total 17500 - Basketball / Sport 18,245 17,713 Court 19000 - Fencing 230 - Wrought Iron: 6' 22,140 30 25 600 Lin. Ft. Pool Fence Total 19000 - Fencing 22,140 20000 - Lighting 300 - Common Area 26,137 20 15 17 Common Area Light Standards 400 - Interior 12,300 20 15 24 Gym- Lighting 900 - Miscellaneous 25,625 20 15 RF Access Rm- Lighting Controller Total 20000 - Lighting 64,062 22000 - Office Equipment 100 - Computers, Misc. 1,537 10 5 1,740 Offices- Main Room- PC 104 - Computers, Misc. 1,025 10 5 1,160 Roof Access Room- PC 1,740 108 - Computers, Misc. 1,537 10 5 Offices- Receptionist- PC 112 - Computers, Misc. 5,125 10 5 5,798 Gym Building Electrical Room- Server 1,537 10 5 1,740 116 - Computers, Misc. Offices- Main Room- PC 120 - Computers, Misc. 1,537 10 5 1,740 Offices- Receptionist- PC 124 - Computers, Misc. 5,125 10 5 5,798 Gym Building Electrical Room- Server

ancu

Current Life Replacement Useful /

	Replacement															14/2015 F	
Reserve Component	Cost	Rem	aining 20	3/14 2014/1	5 2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	2027/28
128 - Computers, Misc. Gym Building Electrical Room- PC	1,537	7 10	5					1,740									
132 - Computers, Misc. Offices- Mary- PC	1,537	7 10	5					1,740									
136 - Computers, Misc. Offices- Kitchen/Workroom- Printer	769	9 10	5					870									
140 - Computers, Misc. Offices- Main Room- Shredder	1,537	7 10	5					1,740									
144 - Computers, Misc. Offices- Mary- Printer	769	9 10	5					870									
148 - Computers, Misc. Offices- Robert- PC	1,537	7 10	5					1,740									
152 - Computers, Misc. Offices- Robert- Printer	769	9 10	5					870									
156 - Computers, Misc. Offices- Office 1- PC	1,537	7 10	5					1,740									
160 - Computers, Misc. Offices- Office 1- Printer	769	9 10	5					870									
164 - Computers, Misc. Electrical Room- Server	30,750	10	5					34,791									
308 - Copier Offices- Kitchen/Workroom- Copier	3,587	7 10	5					4,059									
312 - Copier Offices- Main Room	3,587	7 10	5					4,059									
Total 22000 - Office Equipment	66,112	2						74,800									
23000 - Mechanical Equipment																	
240 - HVAC Roof- Trane: AC 1	10,250	) 15	10										13,121				
244 - HVAC Roof- Trane: AC 2, 3	20,500	) 15	10										26,242				
248 - HVAC Roof- Trane: AC 4, 5	20,500	) 15	10										26,242				
252 - HVAC Roof- Trane AC 6	10,250	) 15	10										13,121				
256 - HVAC Roof- Trane AC 7	10,250	) 15	10										13,121				
260 - HVAC Roof- Trane AC 8	10,250	) 15	10										13,121				
264 - HVAC Roof- Trane: AC 9	10,250	) 15	10										13,121				
268 - HVAC Roof- Trane: AC 10	10,250	) 15	10										13,121				
272 - HVAC Roof- AC-11	30,750	) 15	10										39,363				
276 - HVAC Roof- AC-12	30,750	) 15	10										39,363				
280 - HVAC Roof- Reznor Preeva Air Handler	10,250	) 15	10										13,121				
284 - HVAC Roof- Reznor Preeva Air Handler	10,250	) 15	10										13,121				
288 - HVAC Roof- Reznor Preeva Air Handler	10,250	) 15	10										13,121				
292 - HVAC Roof Carrier: HP-1	7,687	7 15	10									-	9,841				

Current Life Replacement Useful /

	Replacement	Use	ful /											Prepare	d for the	2014/2	2015 Fis	scal Year
Reserve Component	Cost	: Rem	aining	2013/14 2014/15	2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23	2023/24	2024/25	2025/	26 202	26/27	2027/28
296 - HVAC Roof Carrier: HP-2	7,687	7 15	10										9,841					
300 - HVAC Roof- Fujitsu	5,125	5 15	10										6,560					
612 - Water Heater Pool Storage/Water Heater Rm	5,637	7 12	7							6,701								
616 - Water Heater Kitchen Storage- Rheem	5,637	7 12	7							6,701								
620 - Water Heater Janitorial Room- Rheem	820	12	7							975								
Total 23000 - Mechanical Equipment	227,345	;								14,377			275,538					
24000 - Furnishings																		
104 - Miscellaneous Social Room Furnishings	5,125	5 10	5					5,798										
192 - Chairs 93 Community Center Folding Chairs	4,766	5 15	10										6,101					
196 - Chairs 270 Community Center Stackable Cha		20	15															
204 - Chairs 9 Office Task Chairs	4,612	2 10	5					5,219										
334 - Tables 47 Community Center Folding Tables	9,635	5 20	15															
644 - Modular Office Desk 8 Office Desks	19,680	20	15															
Total 24000 - Furnishings	61,807	t						11,017					6,101					
24500 - Audio / Visual																		
112 - Television, Large Screen Social Room	3,075	5 10	5					3,479										
300 - PA System Roof Access Room- QSC Mixer	2,562	2 10	5					2,899										
304 - PA System 3 Roof Access Room- Speakers & Stan		5 10	5					2,609										
Total 24500 - Audio / Visual	7,944	+						8,988										
24600 - Safety / Access																		
900 - Miscellaneous Stage Room- Handicap Lift	10,250	15	10										13,121					
Total 24600 - Safety / Access	10,250	1											13,121					
25000 - Flooring																		
200 - Carpeting 189 Sq. Yds. Community Center Office		9 10	5					7,014										
400 - Tile 9,333 Sq. Ft. Restrooms, Concession, Kitchen	57,398	3 20	15															
600 - Vinyl 1,106 Sq. Yds. Community Center Vin Tile	29,475 yl	20	15															
700 - Hardwood Floors 7,257 Sq. Ft. Yoga Room & Gym	44,631	l 15	10										57,131					
920 - Coatings 1,063 Sq. Ft. Community Center Concrete Floors	6,537	7 12	7							7,771								

Current Life Replacement Useful /

Cost Remaining 2013/14 2014/15 2015/16 2016/17 2017/18 2018/19 2019/20 2020/21 2021/22 2022/23 2023/24 2024/25 2025/26 2026/27 2027/28 Reserve Component Total 25000 - Flooring 144,240 7,014 7,771 57,131 25500 - Wallcoverings 300 - FRP 11,999 20 15 1,951 Sq. Ft. Community Center Total 25500 - Wallcoverings 11,999 26000 - Outdoor Equipment 050 - Flag Pole 4.100 20 15 Community Center 300 - Picnic Table: Wood 820 15 10 1,050 2 Pool Area 332 - Benches 1,230 20 15 2 Common Area 336 - Picnic Table: Metal 6.970 20 15 8 Pool Area 380 - Garbage Receptacles 2,870 20 15 14 Common Area & Pool 10,762 20 15 430 - Bleachers 3 Gym- Wood & Metal Bleachers 844 - Shade Structure 6,765 10 5 7,654 12 Portable Shade Structures Total 26000 - Outdoor Equipment 33,517 7,654 1,050 27000 - Appliances 200 - Refrigerator 512 7 2 538 640 Pool Maintenance Room 1.025 10 5 1.160 204 - Refrigerator Offices- Kitchen/Workroom 224 - Refrigerator: Commercial: Large 4,100 20 15 Kitchen- Fridge 240 - Freezer: Large 4,100 20 15 Kitchen- Fridge/Freezer Combo 270 - Stove / Oven: Commercial grade 6-4,612 20 15 burner Kitchen 278 - Oven: Wall 3,587 20 15 Kitchen- Double Oven 282 - Microwave Oven 410 10 4 453 579 Offices- Kitchen/Workroom 290 - Microwave Oven 871 10 5 986 Kitchen- Panasonic 298 - Stove: Exhaust Hood w/ Fan 3,075 20 15 Kitchen- Greencheck Hood 4,305 10 5 4,871 320 - Dishwasher, Commercial Kitchen- Hobart 940 - Drinking Fountain 2,562 20 15 Community Center Entry 950 - Point of Sale Computer 2,050 6 1 2,101 2,437 2,826 Pool Maintenance Room 2,101 2,437 2,826 954 - Point of Sale Computer 2,050 6 1 Pool Concession Room 992 - Garbage Disposal 1,537 10 5 1,740 Kitchen- Savajor 579 Total 27000 - Appliances 34,799 4,202 538 453 8,756 4,874 640 5,652

Version 4/8/2014 11:17:33 AM

Current Life Replacement Useful /

Reserve Component	Cost	Rema	aining	2013/14	2014/15	2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	2027/28
30000 - Miscellaneous																		
806 - Maintenance Equipment Riding Mower	11,651	20	19															
810 - Maintenance Equipment Kitchen Changing Room- Grout Cleaner	1,230													1,575				
818 - Maintenance Equipment Roof Access Room- Floor Scrubber	5,637	5	0	5,637					6,378					7,216				
822 - Maintenance Equipment Pool Eqpt Rm- Pressure Washer	1,025	10	5						1,160									
830 - Maintenance Equipment Roof Access Room- Floor Buffer	1,537	5	0	1,537					1,740					1,968				
Total 30000 - Miscellaneous	21,081			7,175					9,278					10,759				
Total [Community Center] Expenditures In	ıflated @ 2.5	50%		10,250	14,725	35,229	6,623	9,956	303,126	12,392	144,273	10,490	3,955	428,648	18,055	51,851	9,311	4,924
00030 - Cameron Park Lake																		
01000 - Paving																		
108 - Asphalt: Sealing 5,911 Sq. Ft. Drives & Parking	727	5	2			764					864					978		
208 - Asphalt: Ongoing Repairs 56,911 Sq. Ft. Drives & Parking (2%)	3,792	5	2			3,984					4,507					5,099		
408 - Asphalt: Major Repairs 56,911 Sq. Ft. Drives & Parking (50%)	145,834	20	9										182,127					
800 - Striping 98 Parking Stalls	1,507	5	2			1,583					1,791					2,026		
Total 01000 - Paving	151,860					6,331					7,162		182,127			8,104		
02000 - Concrete																		
208 - Walkways 12,350 Sq. Ft. Walkways, Pads, & Slabs (2%)	4,051	5	2			4,256					4,815					5,448		
Total 02000 - Concrete	4,051					4,256					4,815					5,448		
03000 - Painting: Exterior																		
104 - Surface Restoration 1,140 Sq. Ft. Guard Shack & [3] Wood Sheds	1,168	5	1		1,198					1,355					1,533			
<ul><li>112 - Surface Restoration</li><li>3,680 Sq. Ft. Corporate Yard House</li></ul>	3,772	5	0	3,772					4,268					4,828				
116 - Surface Restoration 1,036 Sq. Ft. Concession Building	1,062	5	3				1,144					1,294					1,464	
120 - Surface Restoration 1,950 Sq. Ft. Gazebo Painting	1,999	5	3				2,152					2,435					2,755	
408 - Railings 186 Lin. Ft. Concrete Footbridge Railings	1,525	4	2			1,602				1,769				1,952				2,155
412 - Railings 80 Lin. Ft. Lake Observation Deck	656	4	0	656				724				799				882		
420 - Wrought Iron Gates 2 Park Entrance Gates	1,025	4	0	1,025				1,131				1,249				1,379		
504 - Light Poles 32 Park Light Poles	6,068	4	1		6,220				6,865				7,578				8,365	
Total 03000 - Painting: Exterior	17,275			5,453	7,417	1,602	3,296	1,856	11,133	3,124		5,777	7,578	6,781	1,533	2,261	12,584	2,155
03500 - Painting: Interior 400 - Restrooms 1,904 Sq. Ft. Concession Building	1,952	10	4					2,154										2,758

Current Life Replacement Useful /

Total 03500 - Painting: Interior  04000 - Structural Repairs  200 - Wood: Siding & Trim  3,680 Sq. Ft. Corporate Yard House	1,952 7,544	10					2,154									2,758
200 - Wood: Siding & Trim 3,680 Sq. Ft. Corporate Yard House	7,544	10														_,. 50
3,680 Sq. Ft. Corporate Yard House	7,544	10														
(10%)			0	7,544								9,657				
550 - Bridge Maintenance 1,313 Sq. Ft. [3] Pedestrian Bridges (10%)	6,729	5	3			7,247				8,199					9,276	
658 - Decking 800 Sq. Ft. Lake Observation Deck	20,500	20	9								25,602					
828 - Dock Floatation [2] Docks & [10] Barges	5,125	10	4				5,657									7,241
Total 04000 - Structural Repairs	39,898			7,544		7,247	5,657			8,199	25,602	9,657			9,276	7,241
05000 - Roofing																
448 - Pitched: Dimensional Composition 36 Squares- Corporate Yard House	14,760	25	9								18,433					
452 - Pitched: Dimensional Composition 44 Squares- Concession, Gazebo, [3] Small Bldgs	18,040	25	11										23,670			
704 - Gutters / Downspouts 184 Lin. Ft. Concession Building Gutters	1,132	25	11										1,485			
708 - Gutters / Downspouts 400 Lin. Ft. Corporate Yard House	2,460	25	9								3,072					
Total 05000 - Roofing	36,392										21,505		25,155			
08000 - Rehab																
234 - Restrooms 2 Concession Building	6,150	20	9								7,681					
254 - Kitchen Concession Building	3,075	20	9								3,840					
Total 08000 - Rehab	9,225										11,521					
11000 - Gate Equipment 910 - Vehicle Gate Replacement 2 Park Entrance Gates	3,075	20	9								3,840					
Total 11000 - Gate Equipment	3,075										3,840					
17000 - Tennis Court																
100 - Reseal 28,600 Sq. Ft. [4] Tennis Courts	14,657	7	3			15,785						18,763				
500 - Resurface 28,600 [4] Tennis Courts	43,972	21	16													
Total 17000 - Tennis Court	58,630					15,785						18,763				
18000 - Landscaping																
112 - Irrigation: Controllers Shed	1,025	10	4				1,131									1,448
344 - Irrigation: Pumps 25 GPM Well	5,125	5	2		5,384				6,092					6,893		
478 - Pathways & Trails 59,910 Sq. Ft. Lake Perimeter- DG Path (10%)	30,704	10	4				33,891									43,384
Total 18000 - Landscaping	36,854				5,384		35,023		6,092					6,893		44,832
18500 - Lakes / Ponds					 											

Current Life Replacement Useful /

	Replacemen	t Use	eful /	_											Prepared	for the 2	014/2015 I	Fiscal Year
Reserve Component	Cos	t Rem	aining	g 2013/14	2014/15	2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	2027/28
300 - Pumps / Mechanical 10 GPM Well	10,25	0 10	4					11,314										14,483
320 - Filter 5 Filters- Lake & Lagoon	12,81	2 10	4					14,143										18,104
990 - Miscellaneous 300 Lin. Ft. Dam/Spillway (5%)	7,68	7 5	3				8,279					9,366					10,597	
Total 18500 - Lakes / Ponds	30,75	0					8,279	25,457				9,366					10,597	32,587
19000 - Fencing																		
104 - Chain Link: 4' 1,644 Lin. Ft. Lake Perimeter Fencing	18,53	6 30	19															
128 - Chain Link: 6' 21 Lin. Ft. Boat Rental Shack	25	8 30	19															
132 - Chain Link: 6' 6,877 Lin. Ft. Park Perimeter Fencing (20%)	16,91	7 6	2			17,774						20,612						23,904
352 - Wood: 6' 80 Lin. Ft. Enclosure	2,05	0 18	14															2,897
356 - Wood: 6' 555 Lin. Ft. Corporate Yard Perimeter	14,22	2 18	8									17,328						
522 - Post & Cable 902 Lin. Ft. Park Post & Chain Fencing		1 25	14															26,127
Total 19000 - Fencing	70,47	5				17,774						37,940						52,928
19500 - Retaining Wall																		
120 - Wood: 1' 125 Lin. Ft. Park Entrance	4,48	4 20	9										5,600					
124 - Wood: 2' 80 Lin. Ft. Enclosure	4,92	0 18	14															6,952
Total 19500 - Retaining Wall	9,40	4											5,600					6,952
20000 - Lighting																		
216 - Pole Lights 32 Park & Lagoon (9%)	3,69	0 5	2			3,877					4,386					4,963		
Total 20000 - Lighting	3,69	0				3,877					4,386					4,963		
21000 - Signage																		
778 - Wood Monument Park Entrance		7 5	3				1,656					1,873					2,119	
Total 21000 - Signage	1,53	7					1,656					1,873					2,119	
23000 - Mechanical Equipment 232 - HVAC		5 15	7								6,092							
Concession Roof Total 23000 - Mechanical Equipment	5,12	5									6,092							
26000 - Outdoor Equipment																		
104 - Tot Lot: Play Equipment Play Area- 4-Swing Set	7,68	7 20	9										9,601					
108 - Tot Lot: Play Equipment Play Area- Large Structure	35,87	5 20	9										44,803					
124 - Tot Lot: Play Equipment Play Area- 2-Swing Set	5,12	5 20	9										6,400					
144 - Tot Lot: Safety Surface 10,000 Sq. Ft. Play Area	2,56	2 3	1		2,627			2,829			3,046			3,280			3,532	

Final

Current Life

	Replacement	Use	ful /	=											Prepared	for the 20	)14/2015 F	iscal Year
Reserve Component	Cost	Rema	aining	2013/14	2014/15	2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	2027/28
200 - Pedestal Grill BBQ 11 Park Barbecues	3,382	20	9										4,224					
280 - Picnic Tables 50 Park Picnic Tables	30,750	20	9										38,403					
328 - Benches 25 Park Benches	15,375	20	9										19,201					
392 - Garbage Receptacles 40 Park Trash Cans	8,200	20	9										10,241					
492 - Drinking Fountain Park Tennis Courts	2,460	20	9										3,072					
Total 26000 - Outdoor Equipment	111,417				2,627			2,829			3,046		135,945	3,280			3,532	
30000 - Miscellaneous																		
700 - Tools Compressor	2,562	10	6							2,972								
704 - Tools Grinder/Sander	1,537	10	4					1,697										2,172
708 - Tools Bench Grinder	1,025	10	4					1,131										1,448
712 - Tools Bench Grinder	1,025	10	4					1,131										1,448
716 - Tools Drill Press	1,537	10	4					1,697										2,172
814 - Maintenance Equipment Woods RM500	3,587	20	4					3,960										
826 - Maintenance Equipment Vermeer 1230 Chipper	51,250	20	14															72,415
834 - Tractor Massey Ferguson 1525	20,500	20	14															28,966
838 - Vehicle Dodge 2500 V8- Lic 1101411	21,525	10	0	21,525										27,554				
846 - Vehicle Ford Expedition- Lic 1011647	51,250	10	4					56,570										72,415
850 - Vehicle 2008 Ford F150 XL- Lic 1273235	25,625	10	5						28,992									
854 - Vehicle Dodge Pick Up P-01- Lic 1088018	15,375	10	4					16,971										21,724
866 - Vehicle Ford Bronco- Lic E041782	21,525	10	1		22,063										28,243			
894 - Trailer PacWest 20'- Lic. E946571	5,125	15	9										6,400					
898 - Trailer Carson 20'- Lic. 1108445	4,100	15	8									4,995						
902 - Trailer 11' Trailer- Lic. E323108	2,562	15	7								3,046							
906 - Trailer 15' Trailer	3,075	15	6							3,566								
910 - Trailer 12' Trailer- Lic. 4LF5474	7,175	15	9										8,961					
914 - Trailer 2003 Vintage Trailer- Lic 1152569	7,687	15	5						8,698									
918 - Trailer BBQ Trailer	4,100	15	7								4,874							
Total 30000 - Miscellaneous	252,150			21,525	22,063			83,159	37,690	6,538	7,920	4,995	15,361	27,554	28,243			202,762

Current Life Replacement Useful /

	Replacement	US	егиі /	_											Prepared	for the 20	)14/2015 I	iscal Year
Reserve Component	Cost	Rem	nainin	2013/14	2014/15	2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	2027/28
Total [Cameron Park Lake] Expenditu	res Inflated @ 2	2.50%		34,522	32,107	39,224	36,261	156,133	48,823	9,662	39,513	68,151	409,080	66,035	54,931	27,667	38,109	352,214
00040 - Rasmussen Park																		
01000 - Paving																		
112 - Asphalt: Sealing 27,200 Sq. Ft. Parking Lot	3,346	5	2			3,515					3,977					4,499		
212 - Asphalt: Ongoing Repairs 27,200 Sq. Ft. Parking Lot (2%)	1,812	2 5	2			1,904					2,154					2,437		
412 - Asphalt: Major Repairs 27,200 Sq. Ft. Parking Lot	139,400	25	14															196,969
804 - Striping Parking Lot	1,537	' 5	2			1,615					1,828					2,068		
Total 01000 - Paving	146,095	5				7,034					7,959					9,004		196,969
02000 - Concrete																		
212 - Walkways 5,610 Sq. Ft. Park Walkways (2%)	1,840	5	2			1,933					2,187					2,475		
Total 02000 - Concrete	1,840	)				1,933					2,187					2,475		
03000 - Painting: Exterior																		
350 - Touch-Up 3 Park Buildings	1,537	' 5	1		1,576					1,783					2,017			
Total 03000 - Painting: Exterior	1,537	,			1,576					1,783					2,017			
03500 - Painting: Interior																		
408 - Restrooms 1,104 Sq. Ft. Concession Building Restrooms	1,132	10	4					1,249										1,599
Total 03500 - Painting: Interior	1,132	2						1,249										1,599
04000 - Structural Repairs																		
554 - Bridge Maintenance Park Pedestrian Bridge	2,562	2 20	9										3,200					
Total 04000 - Structural Repairs	2,562	2											3,200					
05000 - Roofing																		
160 - Pitched: Dimensional Composition 3 Squares- Maint. Bldg & Wood Shed		25	14															1,738
684 - Pitched: Metal 6 Squares- Concession Building	3,075	30	19															
864 - Skylights 2 Concession Building Restrooms	820	20	9										1,024					
Total 05000 - Roofing	5,125	5											1,024					1,738
08000 - Rehab																		
246 - Restrooms 2 Concession Stand Restrooms	3,075	20	9										3,840					
250 - Kitchen Concession Stand Interior	3,075	20	9										3,840					
Total 08000 - Rehab	6,150	)											7,681					
18000 - Landscaping																		
104 - Irrigation: Misc. Park Irrigation	1,025	5 3	1		1,051			1,131			1,218			1,312			1,413	
340 - Irrigation: Pumps Park- Irrigation Pump	1,230	) 5	2			1,292					1,462					1,654		

Current Life

Proposed for the 2014/2015 Fiscal Vear

Re	placement	Use	eful /												Prepared	for the 20	14/2015 F	iscal Year
Reserve Component	Cost	Rem	aining	2013/14	2014/15	2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	2027/28
420 - General Repairs/Upgrades Park	1,025	5 3	1		1,051			1,131			1,218			1,312			1,413	
474 - Pathways & Trails 15,570 Sq. Ft. Park- Walking Path (10%)	7,980	) 5	2			8,384					9,485					10,732		
498 - Bedding Header 252 Lin. Ft. South Play Area	775	5 20	9										968					
Total 18000 - Landscaping	12,035	5			2,101	9,676		2,263			13,384		968	2,624		12,386	2,826	
19000 - Fencing																		
100 - Chain Link 36 Lin. Ft. Tee Ball Field 5' Chain Link	406	30	28															
116 - Chain Link 1,850 Lin. Ft. Ball Fields- 5' Chain Link	20,859	30	14															29,473
124 - Chain Link: 6' 170 Lin. Ft. Tee Ball Field	2,091	. 30	28															
140 - Chain Link: 6' 332 Lin. Ft. North Play Area Perimeter	4,084	30	14															5,770
144 - Chain Link: 8' 65 Lin. Ft. Tee Ball Field	933	30	28															
148 - Chain Link: 8' 400 Lin. Ft. Ball Fields	5,740	30	14															8,110
152 - Chain Link 150 Lin. Ft. Ball Field Back Stops	3,844	30	14															5,431
344 - Wood: 6' 885 Lin. Ft. East & West Perimeter	22,678	18	8									27,631						
514 - Post & Cable 730 Lin. Ft. Parking Perimeter	14,965	25	14															21,145
540 - Metal 980 Lin. Ft. South Perimeter- Post & Wire	10,045	25	14															14,193
Total 19000 - Fencing	85,644	1										27,631						84,123
19500 - Retaining Wall																		
364 - Masonry Wall 332 Lin. Ft. North Play Area	13,612	30	19															
Total 19500 - Retaining Wall	13,612	2																
21000 - Signage																		
794 - Wood Monument Park Sign	2,562	2 10	4					2,829										3,621
Total 21000 - Signage	2,562	2						2,829										3,621
25000 - Flooring																		
404 - Tile 224 Sq. Ft. Concession Building Restrooms	1,378	3 20	9										1,720					
Total 25000 - Flooring	1,378	3											1,720					
26000 - Outdoor Equipment																		
100 - Tot Lot: Play Equipment North Play Area	25,625	20	14															36,207
120 - Tot Lot: Play Equipment South Play Area	10,250	20	14															14,483
- Tot Lot: Safety Surface 10,410 Sq. Ft. North & South Play Areas	2,668	3	1		2,734			2,944			3,171			3,415			3,677	

Current Life Replacement Useful / Prepared for the 2014/2015 Fiscal Year Cost Remaining 2013/14 2014/15 2015/16 2016/17 2017/18 2018/19 2019/20 2020/21 2021/22 2022/23 2023/24 2024/25 2025/26 2026/27 2027/28 Reserve Component 294 - Picnic Table: Cement 1,025 20 9 1,280 2 Park Picnic Tables 304 - Picnic Table: Wood 820 15 7 975 2 Park Picnic Tables 312 - Benches 3,690 20 4,608 6 Park- Metal Benches 320 - Benches 3,690 12 5 4,175 6 Park- Wood Benches 380 - Pet Stations 1,066 15 7 1,267 4 Park 384 - Garbage Receptacles 1.230 20 9 1,536 6 Park- Trash Cans 440 - Bleachers: Aluminum 12,300 20 9 15,361 4 Ball Field Bleachers 484 - Drinking Fountain 2,460 20 9 3,072 Park- Drinking Fountain 840 - Shade Structure 6.355 20 11 8,338 1,240 Sq. Ft. North Play Area Total 26000 - Outdoor Equipment 2,734 5,413 25,858 3,677 71,179 2,944 4,175 3,415 8,338 50,690 Total [Rasmussen Park] Expenditures Inflated @ 2.50% 6,411 18,643 9,285 4,175 1,783 28,943 27,631 40,451 10,356 23,865 6,503 338,740 6,039 00050 - Christa McAuliffe Park 01000 - Paving 116 - Asphalt: Sealing 2,283 5 1 2,340 2,648 2,996 18,563 Sq. Ft. Parking Lot 216 - Asphalt: Ongoing Repairs 1,237 5 1 1,268 1.434 1,623 18,563 Sq. Ft. Parking Lot (2%) 416 - Asphalt: Major Repairs 95,135 25 14 134,424 18,563 Sq. Ft. Parking Lot Total 01000 - Paving 98,655 3,608 4,082 4,619 134,424 02000 - Concrete 216 - Walkways 1,338 5 2 1,406 1.591 1,800 2,720 Sq. Ft. Park Walkways (3%) 900 - Miscellaneous 32,800 10 36,205 46,346 4 16,000 Sq. Ft. Skate Park Concrete (10%)Total 02000 - Concrete 1,406 36,205 1,591 1,800 46,346 34,138 03000 - Painting: Exterior 6,231 404 - Wrought Iron 4,520 4 1 4,633 5,114 5,645 490 Lin. Ft. Play Area Perimeter Total 03000 - Painting: Exterior 4,520 4,633 5,114 5,645 6.231 03500 - Painting: Interior 404 - Restrooms 1,246 10 4 1,376 1,761 1,216 Sq. Ft. Restroom Building Total 03500 - Painting: Interior 1,376 1,246 1,761 04000 - Structural Repairs 994 - Miscellaneous 8,690 6,150 20 14 300 Sq. Ft. Decorative Wall Resurfacing Total 04000 - Structural Repairs 6,150 8,690 05000 - Roofing

2279 05/09/2014 06fsv4.5.74-543:jf.jf

2013/14 to 2027/28

Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

Current Life

Replacement Useful / Prepared for the 2014/2015 Fiscal Year Cost Remaining 2013/14 2014/15 2015/16 2016/17 2017/18 2018/19 2019/20 2020/21 2021/22 2022/23 2023/24 2024/25 2025/26 2026/27 2027/28 Reserve Component 440 - Pitched: Dimensional Composition 2,050 25 14 2,897 5 Squares- Restroom Building 456 - Pitched: Dimensional Composition 25 4 410 453 Skate Park Building Total 05000 - Roofing 453 2,897 2,460 08000 - Rehab 1,537 10 1 2.017 112 - General 1.576 Skate Park Building 2,050 10 1 2,101 2,690 230 - Restrooms Restroom Building Total 08000 - Rehab 3,587 3,677 4,707 19000 - Fencing 108 - Chain Link: 4' 9,640 30 19 855 Lin. Ft. North Perimeter 120 - Chain Link: 6' 14,637 30 19 1,190 Lin. Ft. South & East Perimeter 136 - Chain Link: 6' 3,198 30 19 260 Lin. Ft. Skate Park Perimeter 220 - Wrought Iron: 4' 15,067 30 19 490 Lin. Ft. Play Area Perimeter 10,122 18 8 12,333 360 - Wood: 6' 395 Lin. Ft. West Perimeter Fence 518 - Post & Cable 10,762 25 13,441 525 Lin. Ft. Parking Lot Perimeter (No Cable) Total 19000 - Fencing 63,427 12,333 13,441 19500 - Retaining Wall 360 - Masonry Wall 20,090 30 19 490 Lin. Ft. Play Area Perimeter Total 19500 - Retaining Wall 20,090 21000 - Signage 790 - Wood Monument 3,621 2,562 10 4 2,829 Park Monument Sign Total 21000 - Signage 2,562 2,829 3,621 26000 - Outdoor Equipment 112 - Tot Lot: Play Equipment 30,750 20 13 42,389 Park Large Play Structure 116 - Tot Lot: Play Equipment 15,375 20 13 21,195 2 Park- Smaller Structures 284 - Picnic Tables 3,075 20 3,840 9 5 Park Picnic Tables 324 - Benches 7,175 20 14 10,138 10 Park Metal Benches 2,050 20 9 396 - Garbage Receptacles 2,560 10 Park Trash Cans 488 - Drinking Fountain 7,380 20 9 9,217 3 Park Drinking Fountains Total 26000 - Outdoor Equipment 65,805 15,617 63,584 10,138 Total [Christa McAuliffe Park] Expenditures Inflated @ 2.50% 11,918 1,406 40,862 5,114 4,082 1,591 12,333 34,703 9,326 1,800 69,815 207,876

Final

	Replacement <u>Useful /</u>									Prepared 1		14/2015 F		
Reserve Component	Cost Remaining 2013/14	2014/15 2015/16	2016/17 2017/1	8 2018/19	2019/20	2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	2027/28	

Reserve Component	Cost	Rema	aining 20	13/14 2	2014/15	2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	2027/28
00060 - Chardi Corner																		
18000 - Landscaping																		
116 - Irrigation: Controllers Chardi Corner- Irrigation Controller	1,025	10	4					1,131										1,448
300 - Irrigation: Backflow Preventors Chardi Corner- Backflow Prevention Device	615	20	9										768					
424 - General Repairs/Upgrades Chardi Corner	1,025	3	1		1,051			1,131			1,218			1,312			1,413	
Total 18000 - Landscaping	2,665				1,051			2,263			1,218		768	1,312			1,413	1,448
19000 - Fencing																		
348 - Wood: 6' 300 Lin. Ft. Chardi Corner- Perimeter Fencing	7,687	18	8									9,366						
Total 19000 - Fencing	7,687											9,366						
19500 - Retaining Wall																		
368 - Masonry Wall 380 Lin. Ft. Chardi Corner- Perimeter Wall	15,580	30	19															
Total 19500 - Retaining Wall	15,580																	
20000 - Lighting																		
220 - Landscape 3 Chardi Corner- Sign Lights	1,230	12	5						1,392									
Total 20000 - Lighting	1,230								1,392									
21000 - Signage																		
782 - Monument 35 Lin. Ft. Chardi Corner- Monument Sign (25%)	2,242	5	3				2,415					2,732					3,091	
Total 21000 - Signage	2,242						2,415					2,732					3,091	
26000 - Outdoor Equipment																		
064 - Flag Pole Chardi Corner- Flag Pole	4,100	20	9										5,120					
Total 26000 - Outdoor Equipment	4,100												5,120					
Total [Chardi Corner] Expenditures Inflated	i @ 2.50%				1,051		2,415	2,263	1,392		1,218	12,098	5,888	1,312			4,504	1,448
00070 - Hacienda Park																		
01000 - Paving																		
120 - Asphalt: Sealing 4,500 Sq. Ft. Hacienda- Parking Lot	553	5	2			582					658					744		
220 - Asphalt: Ongoing Repairs 4,500 Sq. Ft. Hacienda Parking Lot (3%)	450	5	2			472					535					605		
420 - Asphalt: Major Repairs 4,500 Sq. Ft. Hacienda- Parking Lot	23,062	25	14															32,587
Total 01000 - Paving	24,066					1,054					1,193					1,349		32,587
02000 - Concrete																		
380 - Pad 462 Sq. Ft. [5] Concrete Slabs (10%)	947	10	2			995										1,274		
Total 02000 - Concrete	947					995										1,274		

Current

Life

Current	Life
Danlacament	Heaful /

Prepared for the 2014/2015 Fiscal Year Replacement Useful / Cost Remaining 2013/14 2014/15 2015/16 2016/17 2017/18 2018/19 2019/20 2020/21 2021/22 2022/23 2023/24 2024/25 2025/26 2026/27 2027/28 Reserve Component 04000 - Structural Repairs 706 998 - Miscellaneous 512 5 3 552 624 Park- Shed- Upkeep Total 04000 - Structural Repairs 512 552 624 706 18000 - Landscaping 100 - Irrigation: Misc. 1,025 3 0 1,025 1,104 1,189 1,280 1,379 Park 450 - Drainage System Maint. 2,050 3 1 2,101 2,263 2,437 2,624 2,826 Deer Creek Tributary 470 - Pathways & Trails 30,202 10 4 33,337 42,674 29,465 Sq. Ft. Park- DG Paths (20%) 494 - Bedding Header 1.291 20 14 1.825 420 Lin. Ft. Turf Perimeter 500 - Tree Maintenance 5,125 5 2 5,384 6,092 6,893 Park- Scrub & Heritage Oaks Total 18000 - Landscaping 39,693 1,025 2,101 5,384 1,104 35,600 1,189 8,529 1,280 2,624 8,271 2,826 44,499 19000 - Fencing 112 - Chain Link: 4' 1,127 20 9 1,408 100 Lin. Ft. Creek Perimeter 364 - Wood: Split Rail 16,619 11,762 20 14 765 Lin. Ft. Park Perimeter 1,471 1,883 510 - Post & Cable 1,332 10 4 26 Parking Lot Posts (50%) Total 19000 - Fencing 1.471 1,408 18,502 14,222 21000 - Signage 798 - Wood Monument 1.025 10 6 1.189 Park Sign Total 21000 - Signage 1,025 1,189 26000 - Outdoor Equipment 290 - Picnic Table: Cement 2,306 20 14 3,259 3 Park- Picnic Tables 316 - Benches 615 20 14 869 Park Bench 333 376 - Pet Stations 266 15 9 Park- Pet Station 388 - Garbage Receptacles 410 20 14 579 2 Park- Trash Cans 480 - Drinking Fountain 2,460 20 14 3,476 Park- Drinking Fountain 333 8,183 Total 26000 - Outdoor Equipment 6,058 Total [Hacienda Park] Expenditures Inflated @ 2.50% 1,025 2,101 7,434 1,656 37,071 2,377 9,721 624 3,021 2,624 10,894 3,532 103,771 00188 - Station 88 01000 - Paving 972 5 4 1,073 100 - Asphalt: Sealing 1,214 1,373 3,950 Sq. Ft. Parking Lot- Seal & Stripe 200 - Asphalt: Ongoing Repairs 658 10 4 726 930 3,950 Sq. Ft. Parking Lot (5%) 400 - Asphalt: Major Repairs 8,097 25 17

3,950 Sq. Ft. Parking Lot (50%)

Current Life Replacement Useful /

	eplacement													-		014/2015 I	
Reserve Component			aining 2	013/14 2014/15	2015/16	2016/17		2018/19	2019/20	2020/21	2021/22		2023/24	2024/25	2025/26	5 2026/27	
Total 01000 - Paving	9,727	·					1,799					1,214					2,30
02000 - Concrete																	
200 - Sidewalks, Curbs & Gutters 2,400 Sq. Ft. Exterior Concrete (3%)	1,181	L 5	2		1,241					1,404					1,588		
710 - Sealing 1,225 Sq. Ft. Vehicle Bays- Concrete Floors	2,700	) 5	2		2,836					3,209					3,631		
Total 02000 - Concrete	3,880	1			4,077					4,613					5,219		
03000 - Painting: Exterior																	
100 - Surface Restoration 360 Sq. Ft. Patio Shed- Paint & Repair	1,107	7 5	2		1,163					1,316					1,489		
310 - Trim 825 Sq. Ft. Station 88- Wood Trim	846	, 5	2		888					1,005					1,137		
Total 03000 - Painting: Exterior	1,953	j			2,051					2,321					2,626		
03500 - Painting: Interior																	
110 - Building 7,122 Sq. Ft. Station 88- Interior Spaces		10	4				8,058										10,315
Total 03500 - Painting: Interior	7,300	1					8,058										10,315
04000 - Structural Repairs																	
364 - Garbage Enclosure Parking Area	1,537	7 10	4				1,697										2,172
910 - Doors 11 Station 88- Interior & Exterior Doors	6,765	5 20	9									8,449					
Total 04000 - Structural Repairs	8,302	1					1,697					8,449					2,172
05000 - Roofing																	
444 - Pitched: Dimensional Composition 36 Squares- Station 88	14,760	25	15														
712 - Gutters / Downspouts 110 Lin. Ft. Station 88	676	5 25	15														
860 - Skylights 2 Lobby & Lounge	820	) 25	15														
Total 05000 - Roofing	16,256	1															
08000 - Rehab																	
120 - General 2 Quarters	2,050	10	4				2,263										2,897
210 - Bathrooms 2 Bathroom & Restroom	3,075	5 10	1	3,152										4,035			
214 - Kitchen Kitchen	2,050	20	1	2,101													
Total 08000 - Rehab	7,175	i		5,253			2,263							4,035			2,897
14000 - Recreation																	
200 - Exercise: Treadmill Vehicle Bays	2,050	10	4				2,263										2,897
204 - Exercise: Miscellaneous Equip. Vehicle Bays: Weights & Rack	3,075	5 15	7							3,655							
Total 14000 - Recreation	5,125	,					2,263			3,655							2,897

Final

Current Life

	Replacement	Us	eful	_											Prepared for	the 201	4/2015 Fis	scal Year
Reserve Component	Cost	Rer	naini	ng 2013/1	4 2014/15	2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23	2023/24	2024/25 20	025/26	2026/27	2027/2
104 - Exterior: Misc. Fixtures 8 Building & Landscape Lights	2,050	) 15	5 9	ı									2,560					
540 - Parking Lot Parking Lot Light	2,255	5 25	14															3,186
Total 20000 - Lighting	4,305	5											2,560					3,186
21000 - Signage																		
786 - Wood Monument Station 88 Entrance	1,025	5 10	0	1,025										1,312				
Total 21000 - Signage	1,025	5		1,025										1,312				
22000 - Office Equipment																		
200 - Computers, Misc. Lobby	2,050	) (	5 3				2,208						2,560					
204 - Computers, Misc. Mulit-Quarters Laptop	1,537	7 6	5 2			1,615						1,873						2,172
208 - Computers, Misc. Mulit-Quarters PC Workstation	1,537	7 (	5 2			1,615						1,873						2,172
300 - Copier Lobby	1,537	7 (	5 2			1,615						1,873						2,172
Total 22000 - Office Equipment	6,662	2				4,846	2,208					5,620	2,560					6,517
23000 - Mechanical Equipmen	t																	
200 - HVAC Patio Area HVAC	5,125	5 15	5 4					5,657										
600 - Water Heater Water Heater Closet	820	) 12	. 5						928									
Total 23000 - Mechanical Equipment	5,945	5						5,657	928									
24000 - Furnishings																		
100 - Miscellaneous Lobby Additional Furnishings	5,125	5 20	) 9										6,400					
200 - Bar Stools 2 Lounge Barstools	512	2 15	5 9										640					
212 - Chairs 4 Station 88 Task Chairs	1,025	5 10	) 5						1,160									
228 - Chairs 3 Lounge Recliners	1,537	7 20	) 6	1						1,783								
640 - Modular Office Desk 3 Station 88 Office Desks	3,075	5 20	) 9	l									3,840					
910 - Window Coverings 8 Station 88- Window Blinds	4,100	) 15	5 9	ı									5,120					
Total 24000 - Furnishings	15,375	5							1,160	1,783			16,001					
24600 - Safety / Access																		
340 - Defibrillators Lobby	2,562	2 5	5 2			2,692					3,046					3,446		
Total 24600 - Safety / Access	2,562	2				2,692					3,046					3,446		
25000 - Flooring																		
210 - Carpeting 87 Sq. Yds. Station 88- Carpeting	2,854	1 10	) 3				3,073										3,934	
410 - Tile 362 Sq. Ft. Bathroom, Restroom, & Lobby	2,226	5 20	1		2,282													

Current Life Replacement <u>Useful /</u>

Reserve Component	Cost	Rema	aining	2013/14	2014/15	2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	2027/2
610 - Vinyl 15 Sq. Yds. Kitchen- Linoleum	400	20	1		410													
Total 25000 - Flooring	5,480				2,692		3,073										3,934	
26000 - Outdoor Equipment																		
060 - Flag Pole Station 88 Entrance	4,100	20	14															5,793
210 - Barbecue Patio Barbecue	615	8	4					679								827		
350 - Furniture 8 Patio Furniture Items	2,050	10	4					2,263										2,897
Total 26000 - Outdoor Equipment	6,765							2,942								827		8,690
27000 - Appliances																		
208 - Refrigerator Kitchen	1,025	7	3				1,104							1,312				
248 - Ice Machine Vehicle Bays- Hoshizaki	2,050	10	5						2,319									
266 - 4-Burner Stove & Oven Kitchen	1,845	7	1		1,891							2,248						
302 - Stove: Exhaust Hood w/ Fan Kitchen	2,665	20	9										3,328					
306 - Dishwasher Kitchen	1,025	10	4					1,131										1,448
410 - Washer Vehicle Bay	1,537	10	5						1,740									
414 - Dryer Vehicle Bay	1,845	10	5						2,087									
Total 27000 - Appliances	11,992				1,891		1,104	1,131	6,146			2,248	3,328	1,312				1,448
30000 - Miscellaneous																		
270 - Garage Door: Metal 2 Vehicle Bay Doors	10,250	20	9										12,801					
842 - Vehicle E 88 Lic 1206288	597,017	15	5						675,470									
858 - Vehicle E 288 Lic 1375275	479,216	15	12													644,492		
898 - Vehicle U 88 Lic 127543	35,321	15	11												46,345			
Total 30000 - Miscellaneous	1,121,805								675,470				12,801		46,345	644,492		
Total [Station 88] Expenditures Inflated	@ 2.50%			1,025	9,836	13,667	6,384	25,810	683,704	1,783	13,635	7,868	46,913	2,624	50,380	656,611	3,934	40,425
00189 - Station 89																		
01000 - Paving																		
104 - Asphalt: Sealing 20,899 Sq. Ft. Parking Lot- Seal & Stripe	3,280	5	4					3,621					4,096					4,635
204 - Asphalt: Ongoing Repairs 20,899 Sq. Ft. Parking Lot (10%)	6,962							7,685										9,837
404 - Asphalt: Major Repairs 20,899 Sq. Ft. Parking Lot (50%)	53,554	25	15															
Total 01000 - Paving	63,796							11,305					4,096					14,472
02000 - Concrete 204 - Sidewalks, Curbs & Gutters 8,840 Sq. Ft. Exterior Concrete (3%)	4,349	5	2			4,569					5,170					5,849		

Current Life Replacement <u>Useful /</u> Prepared for the 2014/2015 Fiscal Year

Reserve Component	Cost			2013/14	2014/15	2015/16	2016/17 2017/18	2018/19	2019/20	2020/21 2021/22	2022/23	2023/24	2024/25 202		-	
714 - Sealing 5,016 Sq. Ft. Vehicle Bays- Concrete Floors	11,054	5	0	11,054				12,507				14,150				
Total 02000 - Concrete	15,403			11,054		4,569		12,507		5,170		14,150	5,8	849		
03000 - Painting: Exterior																
124 - Surface Restoration 8,500 Lin. Ft. Station 89	8,712	10	4				9,617									12,311
416 - Railings 90 Lin. Ft. Balcony & Stairs	738	4	1		756			835			922				1,017	
920 - Miscellaneous Sheds, Wrought Iron, & Touch-Up	3,587	5	0	3,587				4,059				4,592				
Total 03000 - Painting: Exterior	13,038			3,587	756		9,617	4,894			922	4,592			1,017	12,311
03500 - Painting: Interior																
120 - Building 24,962 Sq. Ft. Station 89 Interior Painting	25,586	10	4				28,242									36,152
Total 03500 - Painting: Interior	25,586						28,242									36,152
04000 - Structural Repairs 360 - Garbage Enclosure	2,562	10	4				2,829									3,621
Station 89- Enclosure  920 - Doors 31 Station 89 Interior & Exterior Doors	19,065	15	5					21,570								
990 - Miscellaneous 4 Wood Sheds	2,050	10	5					2,319								
Total 04000 - Structural Repairs	23,677						2,829	23,890								3,621
04500 - Decking/Balconies																
110 - Concrete 375 Sq. Ft. South Side Building (25%)	1,441	10	4				1,591									2,037
500 - Railing: Wrought Iron 90 Lin. Ft. Balcony & Stair Railings	3,136	20	10									4,015				
Total 04500 - Decking/Balconies	4,578						1,591					4,015				2,037
05000 - Roofing 334 - Low Slope: Vinyl 48 Squares- Station 89 Flat Roofing	24,600	20	10									31,490				
680 - Pitched: Metal 31 Squares- Station 89 Metal Roof	15,887	30	20													
720 - Gutters / Downspouts 210 Lin. Ft. Station 89	1,291	30	20													
Total 05000 - Roofing	41,779											31,490				
08000 - Rehab																
128 - General 4 Dormitory Rooms	8,200	20	10									10,497				
132 - General Work Room	2,562	20	10									3,280				
136 - General 3 Offices	6,150	20	10									7,873				
140 - General Reception	2,562	20	10									3,280				
218 - Bathrooms 2 Upstairs Bathrooms	6,150	20	2			6,461										

Final

Current Life

	Replacement	Use	ful /												Prepared	for the 201	14/2015 Fi	iscal Year
Reserve Component	Cost	Rem	aining	2013/14	2014/15	2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	2027/28
226 - Bathrooms 2 Downstairs Restrooms	4,100	20	10											5,248				
262 - Kitchen Coffee Room	1,537	20	10											1,968				
270 - Kitchen Kitchen	3,075	20	19															
274 - Laundry Room Upstairs Laundry	1,537	20	19															
Total 08000 - Rehab	35,875					6,461								32,146				
14000 - Recreation																		
220 - Exercise: Treadmill Weight Room	2,050	10	4					2,263										2,897
224 - Exercise: Cardio Equipment Weight Room Elliptical	1,845	10	4					2,037										2,607
228 - Exercise: Weight Machine Weight Room	3,587	20	10											4,592				
232 - Exercise: Miscellaneous Equip. Weight Room Tuff Stuff Rack	1,537	20	10											1,968				
236 - Exercise: Miscellaneous Equip. Weight Room Dumbbells & Rack	3,075	15	9										3,840					
Total 14000 - Recreation	12,095							4,299					3,840	6,560				5,504
18000 - Landscaping																		
108 - Irrigation: Misc. Backflows, Controllers, Valves	1,025	5	1		1,051					1,189					1,345			
482 - Pathways & Trails 520 Sq. Ft. DG Walking Path	2,665	5	1		2,732					3,091					3,497			
Total 18000 - Landscaping	3,690				3,782					4,279					4,842			
19000 - Fencing																		
310 - Wood: 3' 50 Lin. Ft. Northeast Perimeter	769				788													
340 - Wood: 6' 895 Lin. Ft. Perimeter Fencing	22,934	18	3				24,698											
Total 19000 - Fencing	23,703				788		24,698											
19500 - Retaining Wall 372 - Masonry Wall Maintenance 225 Lin. Ft. Keystone Retaining Wall (25%)	1,441	10	4					1,591										2,037
Total 19500 - Retaining Wall	1,441							1,591										2,037
20000 - Lighting																		
100 - Exterior: Misc. Fixtures 21 Station 89- Exterior Building Light	5,381	20	10											6,888				
420 - Interior 72 Station 89 Interior Lighting (50%	7,380	20	10											9,447				
424 - Interior 6 Station 89 Ceiling Fans	1,230	15	8									1,499						
Total 20000 - Lighting	13,991											1,499		16,335				
21000 - Signage 774 - Wood Monument 2 Station 89 Signs	3,075	15	0	3,075														

Current Life Replacement Useful /

Reserve Component	Cost	Rema	aining	2013/14	2014/15	2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	2027/28
Total 21000 - Signage	3,075			3,075														
22000 - Office Equipment																		
212 - Computers, Misc. Reception Dell PC Workstation #3101	1,025	6	1		1,051						1,218						1,413	
216 - Computers, Misc. Reception Dell PC Workstation #3102	1,025	6	1		1,051						1,218						1,413	
220 - Computers, Misc. Reception Gateway PC Workstation #3092	1,025	6	0	1,025						1,189						1,379		
224 - Computers, Misc. Reception Brother Printer	1,025	6	0	1,025						1,189						1,379		
228 - Computers, Misc. Station Captains Office	1,025	6	4					1,131						1,312				
232 - Computers, Misc. Station Captain's Office- Shredder	1,230	10	4					1,358										1,738
236 - Computers, Misc. Station Captain's Office- Printer	512	6	2			538						624						724
240 - Computers, Misc. Work Room- Fax	1,332	10	4					1,471										1,883
244 - Computers, Misc. Work Room- Shredder	1,127	10	4					1,245										1,593
248 - Computers, Misc. Equipment Room- UPS 1500	1,537	6	2			1,615						1,873						2,172
252 - Computers, Misc. Equipment Room- Power Connect 2724	5,125	6	2			5,384						6,244						7,241
256 - Computers, Misc. Equipment Room- Surge Protector	1,025	6	2			1,077						1,249						1,448
260 - Computers, Misc. Equipment Room- Poweredge 2900	5,125	6	2			5,384						6,244						7,241
264 - Computers, Misc. Fire Prevention Office	1,025	6	0	1,025						1,189						1,379		
268 - Computers, Misc. Fire Prevention Office- Shredder	1,230	6	2			1,292						1,499						1,738
272 - Computers, Misc. Battalion Chief's Office	1,025	6	4					1,131						1,312				
304 - Copier Work Room- Copier	3,587	10	4					3,960										5,069
360 - Telephone Equipment Equipment Room- Phone System	4,612	6	2			4,846						5,620						6,517
364 - Telephone Equipment Equipment Room- Integration Hub	4,612	6	2			4,846						5,620						6,517
368 - Telephone Equipment Equipment Room- Phone System	4,612	6	2			4,846						5,620						6,517
Total 22000 - Office Equipment	42,845			3,075	2,101	29,830		10,296		3,566	2,437	34,594		2,624		4,136	2,826	50,401
23000 - Mechanical Equipment																		
204 - HVAC Roof- AC-1	10,250	15	7								12,184							
208 - HVAC Roof- AC-2	10,250	15	7								12,184							
212 - Fan Roof- Ventilation Fan	4,612	20	10											5,904				
216 - Fan Roof- Captive Aire Systems, Supply	4,100	20	10											5,248				

Current Life Penlacement | | | | | |

	Replacemen	t <u>Us</u>	eful /	=										Prepared	for the 20	14/2015 F	iscal Year
Reserve Component	Cos	t Ren	naining	2013/14	2014/15	2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23 2023/24	2024/25	2025/26	2026/27	2027/28
220 - Fan Roof- Captive Aire Systems, Exhaust		0 20	10										5,248				
224 - Swamp Cooler Roof- Evaporative Air Cooler	5,12	5 20	10										6,560				
228 - Swamp Cooler Roof- Evaporative Air Cooler	5,12	5 20	10										6,560				
330 - Fuel Tank 2 Parking Area Fueling Tanks	15,37	5 30	20														
580 - Cooling Tower Roof- REF-1	3,58	7 20	10										4,592				
604 - Water Heater Upstairs Closet	82	0 12	7								975						
608 - Water Heater Mechanic's Bay	82	0 12	. 0	820											1,103		
Total 23000 - Mechanical Equipment	64,16	5		820							25,343		34,114		1,103		
24000 - Furnishings																	
208 - Chairs 9 Station 89 Task Chairs	2,30	6 10	2			2,423									3,102		
216 - Chairs 10 Station 89 Wood/Cloth Chairs	76	9 15	8									937					
220 - Chairs 15 Station 89 Stackable Chairs	1,15	3 20	3				1,242										
224 - Chairs 46 Station 89 Folding Chairs	3,53	6 20	10										4,527				
232 - Chairs 6 Lounge- Recliners	3,07	5 10	4					3,394									4,345
310 - Tables: Dining: Large Lounge & Kitchen	1,02	5 20	10										1,312				
330 - Tables 17 Station 89 Folding Tables	1,74	2 20	10										2,231				
650 - Modular Office Desk 5 Station 89 Office Desks	5,12	5 20	10										6,560				
880 - Security Deposit Boxes Station Captain's Office Lockbox	51	2 12	5						580								
884 - Security Deposit Boxes Station Captain's Office Safe	2,56	2 20	10										3,280				
920 - Window Coverings 19 Station 89 Window Blinds	9,73	7 15	5						11,017								
Total 24000 - Furnishings	31,54	4				2,423	1,242	3,394	11,597			937	17,910		3,102		4,345
24500 - Audio / Visual																	
100 - Television Weight Room	1,53	7 10	4					1,697									2,172
200 - DVD Player Storage (Conference)- Sony DVD	51	2 6	2			538						624					724
204 - DVD Player Storage (Conference)- Toshiba DVD	51	2 6	2			538						624					724
308 - PA System Equipment Room- Amplifier	76	9 10	4					849									1,086
312 - PA System Conference Room- Podium	2,56	2 10	4					2,829									3,621
316 - PA System Conference Room- Projector	3,58	7 6	2			3,769						4,371					5,069

Current Life Replacement Useful /

Total 24500 - Audio / Visual  24600 - Safety / Access	9,481	Rema	aining	2013/14	2014/15	2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	2027/28
24600 - Safety / Access	9,481																	- , -
						4,846		5,374				5,620						13,397
120 - Fire Control Misc Building Alarm & Extinguishers	5,125	10	4					5,657										7,241
350 - Defibrillators Lobby	2,562	5	2			2,692					3,046					3,446		
Total 24600 - Safety / Access	7,687					2,692		5,657			3,046					3,446		7,241
25000 - Flooring																		
220 - Carpeting 262 Sq. Yds. Station 89 Interior Carpeting	8,594	10	4					9,486										12,143
420 - Tile 2,543 Sq. Ft. Station 89 Floor & Wall T	15,639 ïle	20	10											20,020				
620 - Vinyl 50 Sq. Yds. Bathroom Vinyl Tile	1,332	20	10											1,706				
624 - Vinyl 166 Sq. Yds. Station 89 Wood Laminat Flooring	5,104 e	20	10											6,534				
990 - Miscellaneous 27 Sq. Yds. Weight Room Rubber Flooring	830	15	9										1,037					
Total 25000 - Flooring	31,500							9,486					1,037	28,260				12,143
26000 - Outdoor Equipment																		
068 - Flag Pole Station 89- Flag Pole	5,637	30	20															
220 - Barbecue Balcony	512	8	3				552								672			
308 - Picnic Table: Wood Patio	410	15	8									500						
Total 26000 - Outdoor Equipment	6,560						552					500			672			
27000 - Appliances																		
220 - Refrigerator: Commercial: Large Kitchen	2,050	10	6							2,377								
244 - Freezer: Large Kitchen	820	10	6							951								
252 - Ice Machine Upstairs Closet- Ice-O-Matic	2,050	10	4					2,263										2,897
256 - Ice Machine Mechanic's Bay- Manitowac	2,050	10	4					2,263										2,897
260 - Stove Kitchen	3,587	12	8									4,371						
274 - Oven: Wall Kitchen	2,562	10	4					2,829										3,621
286 - Microwave Oven Kitchen	615	10	4					679										869
294 - Stove: Fire Suppression Kitchen	5,637	10	4					6,223										7,966
310 - Dishwasher, Residential Type Kitchen	1,025	5	0	1,025					1,160					1,312				
418 - Washer: Large Mechanic's Bay- Washer/Extractor	12,300	10	4					13,577										17,380

Replacement Useful / Prepared for the 2014/2015 Fiscal Year

Reserve Component	Cost	Rema	ainina	2013/14	2014/15	2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	7 2027/2
422 - Dryer Mechanic's Bay- Kenmore	1,025				<u> </u>	<u> </u>	<u> </u>	1,131	<u> </u>	<u> </u>	<u> </u>			<u> </u>	<u> </u>	<u> </u>	· ·	1,448
426 - Washer Upstairs Laundry	717	10	6							832								
430 - Dryer Upstairs Laundry	1,025	10	6							1,189								
684 - Miscellaneous Coffee Room- Coffee Maker	512	10	4					566										724
984 - Miscellaneous Kitchen- Coffee Maker	512	10	4					566										724
988 - Miscellaneous Kitchen- Coffee Grinder	256	10	4					283										362
Total 27000 - Appliances	36,746			1,025				30,378	1,160	5,349		4,371		1,312				38,887
30000 - Miscellaneous																		
266 - Garage Door: Metal 3 Station 89 Garage Bay Doors	15,375	20	19															
274 - Garage Door: Metal 4 Station 89 Garage Bay Doors- Rear	20,500	20	3				22,076											
870 - Vehicle B2715- Lic 1275433	39,737	10	6							46,083								
874 - Vehicle B2716 Lic 1275432	39,737	10	6							46,083								
878 - Vehicle E-89- Lic 1206287	597,017	15	1		611,943													
882 - Vehicle E-289- Lic E1109085	490,842	15	2			515,691												
886 - Vehicle E-389 Lic E000391	555,238	10	7								660,004							
890 - Vehicle U-89 Lic 1088016	45,491	15	3				48,988											
894 - Vehicle U-289 Lic 041782	39,563	15	2			41,566												
922 - Generator Building East Side- Generac Series	30,750	30	20															
Total 30000 - Miscellaneous	1,874,250				611,943	557,256	71,065			92,166	660,004							
Total [Station 89] Expenditures Inflated @	2.50%			22,637	619,371	608,078	97,556	124,060	54,047	105,360	695,999	47,519	9,895	193,510	5,514	17,636	3,843	202,545
Total Expenditures Inflated @ 2.50%				69,459	697,520	723,681	150,895	405,439	1,100,381	137,440	934,894	186,715	553,906	700,792	148,561	790,324	139,552	1,251,943

Total Current Replacement Cost

6,840,814

Current

Life

Reserve Component	2028/29	2029/30	2030/31	2031/32	2032/33	2033/34	2034/35	2035/36 2036/3	7 2037/38	2038/39	2039/40	2040/41	2041/42	2042/4
00010 - Community Center														
01000 - Paving														
124 - Asphalt: Sealing 59,100 Sq. Ft. Parking Lot			11,061					12,515				14,159		
224 - Asphalt: Ongoing Repairs 59,100 Sq. Ft. Parking Lot (3%)			7,489					8,473				9,587		
424 - Asphalt: Major Repairs 59,100 Sq. Ft. Parking Lot						496,316								
808 - Striping Parking Lot			5,459					6,176				6,988		
Total 01000 - Paving			24,009			496,316		27,164				30,734		
02000 - Concrete														
904 - Miscellaneous 38,500 Sq. Ft. Community Center Concrete (2%)			19,215					21,740				24,597		
Total 02000 - Concrete			19,215					21,740				24,597		
03000 - Painting: Exterior  108 - Surface Restoration 27,500 Sq. Ft. Community Center	40,824									52,258				
Buildings 400 - Wrought Iron		8,217				9,070			10,011				11,051	
600 Lin. Ft. Pool Fence		-,												
500 - Light Poles 14 Common Area Light Poles			4,040				4,459			4,922				5,433
Total 03000 - Painting: Exterior	40,824	8,217	4,040			9,070	4,459		10,011	57,180			11,051	5,433
03500 - Painting: Interior														
100 - Building 46,447 Sq. Ft. Community Center Interiors	68,951									88,263				
Total 03500 - Painting: Interior	68,951									88,263				
04000 - Structural Repairs														
356 - Garbage Enclosure Community Center Enclosure			2,339					2,647				2,995		
540 - Bridge Maintenance Community Center Bridge	7,423									9,501				
914 - Doors 45 Community Center Interior Doors (11%)		4,565		4,796		5,039		5,294	5,562		5,843		6,139	
Total 04000 - Structural Repairs	7,423	4,565	2,339	4,796		5,039		7,941	5,562	9,501	5,843	2,995	6,139	
05000 - Roofing														
330 - Low Slope: Vinyl 178 Squares- Community Center Buildings										169,126				
688 - Pitched: Metal 95 Squares- Community Center Buildings										90,264				
700 - Gutters / Downspouts 335 Lin. Ft. Community Center Buildings										3,820				
Total 05000 - Roofing										263,210				

2279 05/09/2014 06fsv4.5.74-543:jf.jf

© Browning Reserve Group 2014 Version 4/8/2014 11:17:33 AM

Prepared for the 2014/2015 Fiscal Year 2028/29 2029/30 2030/31 2031/32 2032/33 2033/34 2034/35 2035/36 2036/37 2037/38 2038/39 2039/40 2040/41 2041/42 2042/43

Reserve Component	2028/29 2029/30	2030/31 2031/32	2032/33 20	33/34 2034/35	2035/36 203	36/37 2037/38	2038/39	2039/40 20		
100 - General 2 C02 & Chlorine							5,701			
104 - General 8 Offices	41,566									
108 - General 2 First Aid & Lifeguard	4,454									
116 - General Stage Room	11,134						14,252			
124 - General 2 Classroom & Preschool	7,423						9,501			
222 - Bathrooms 2 Pool Area- Shower/Locker/Restrooms	14,845									
238 - Restrooms 2 Community Center Restrooms	8,907						11,402			
242 - Restrooms 2 Community Center Single Restrooms	4,454						5,701			
258 - Kitchen Pool Concession Room	4,454									
266 - Kitchen Kitchen	14,845									
380 - Tile 2 Outdoor Showers	1,485						1,900			
590 - Operable Wall/Partition 720 Sq. Ft. Stage Room	53,442									
Total 08000 - Rehab	167,007						48,457			
12000 - Pool										
110 - Resurface 375 Lin. Ft. Pool			49,158							
200 - Edge: Tile, Coping, Mastic 375 Lin. Ft. Pool			27,652							
210 - Tile: Lanes 734 Lin. Ft. Pool			36,082							
320 - Hand Rail / Ladder 6 Pool			11,798							
400 - ADA Chair Lift Pool Equipment Room	6,532						8,361			
700 - Equipment: Replacement Pool Eqpt Rm- Ultra Max	2,227						2,850			
704 - Equipment: Replacement Pool Eqpt Rm- Aquavac	1,485						1,900			
708 - Equipment: Replacement 2 Pool Equipment Room- Filters	7,423						9,501			
720 - Heater Pool Equipment Room	22,268						28,504			
740 - Pumps Pool Equipment Room- Pool Pump			3,277						3,993	
744 - Pumps Pool Equipment Room- Slide Pump			3,277						3,993	
748 - Pumps Pool Equipment Room- Feature Pump			3,277						3,993	
752 - Cover 7,425 Sq. Ft. Pool	11,298			12,783				14,462		
780 - Water Feature Pool Area Slide Structure							57,009			

2279 05/09/2014 06fsv4.5.74-543:jf.jf

Version 4/8/2014 11:17:33 AM

2028/29 to 2042/43 **31** © Browning Reserve Group 2014

Reserve Component	2028/29	2029/30	2030/31 2031/32	2032/33 2	033/34	2034/35 2035/36	2036/37 203	7/38 2038/39	-	2040/41	
800 - Solar System 30 Roof- Pool Solar System Panels				24,579							
950 - Furniture: Lifeguard Chair 4 Pool Area	11,876							15,202			
960 - Furniture: Misc Pool Furniture (Stored)	14,845							19,003			
990 - Miscellaneous Floating Racing Lanes	3,711							4,751			
Total 12000 - Pool	70,366	11,298		159,101		12,783		147,083	14,462	11,979	
17500 - Basketball / Sport Court 300 - Basketball Standard 6 Basketball Hoops								25,654			
680 - Scoreboard Gym	6,383										
Total 17500 - Basketball / Sport Court	6,383							25,654			
19000 - Fencing											
230 - Wrought Iron: 6' 600 Lin. Ft. Pool Fence								41,046			
Total 19000 - Fencing								41,046			
20000 - Lighting											
300 - Common Area 17 Common Area Light Standards	37,855										
400 - Interior 24 Gym- Lighting	17,814										
900 - Miscellaneous RF Access Rm- Lighting Controller	37,113										
Total 20000 - Lighting	92,782										
22000 - Office Equipment											
100 - Computers, Misc. Offices- Main Room- PC	2,227							2,850			
104 - Computers, Misc. Roof Access Room- PC	1,485							1,900			
108 - Computers, Misc. Offices- Receptionist- PC	2,227							2,850			
112 - Computers, Misc. Gym Building Electrical Room- Server	7,423							9,501			
116 - Computers, Misc. Offices- Main Room- PC	2,227							2,850			
120 - Computers, Misc. Offices- Receptionist- PC	2,227							2,850			
124 - Computers, Misc. Gym Building Electrical Room- Server	7,423							9,501			
128 - Computers, Misc. Gym Building Electrical Room- PC	2,227							2,850			
132 - Computers, Misc. Offices- Mary- PC	2,227							2,850			
136 - Computers, Misc. Offices- Kitchen/Workroom- Printer	1,113							1,425			
140 - Computers, Misc. Offices- Main Room- Shredder	2,227							2,850			

Reserve Component	2028/20	2029/30 20	130/31	2031/32	2032/33	2033/34	2034/35	2035/36	2036/37	2037/38				2014/2015 11 2041/43	
144 - Computers, Misc.	1,113	2029/30 20	750/51	2031/32	2032/33	2033/34	2034/33	2033/30	2030/37	2037/30	1,425	2033/	70 2040/4	<del>7</del> 1 2041/42	2 2042/43
Offices- Mary- Printer															
148 - Computers, Misc. Offices- Robert- PC	2,227										2,850				
152 - Computers, Misc. Offices- Robert- Printer	1,113										1,425				
156 - Computers, Misc. Offices- Office 1- PC	2,227										2,850				
160 - Computers, Misc. Offices- Office 1- Printer	1,113										1,425				
164 - Computers, Misc. Electrical Room- Server	44,535										57,009				
308 - Copier Offices- Kitchen/Workroom- Copier	5,196										6,651				
312 - Copier Offices- Main Room	5,196										6,651				
Total 22000 - Office Equipment	95,751									:	122,569				
23000 - Mechanical Equipment															
240 - HVAC Roof- Trane: AC 1											19,003				
244 - HVAC Roof- Trane: AC 2, 3											38,006				
248 - HVAC Roof- Trane: AC 4, 5											38,006				
252 - HVAC Roof- Trane AC 6											19,003				
256 - HVAC Roof- Trane AC 7											19,003				
260 - HVAC Roof- Trane AC 8											19,003				
264 - HVAC Roof- Trane: AC 9											19,003				
268 - HVAC Roof- Trane: AC 10											19,003				
272 - HVAC Roof- AC-11											57,009				
276 - HVAC Roof- AC-12											57,009				
280 - HVAC Roof- Reznor Preeva Air Handler											19,003				
284 - HVAC Roof- Reznor Preeva Air Handler											19,003				
288 - HVAC Roof- Reznor Preeva Air Handler											19,003				
292 - HVAC Roof Carrier: HP-1											14,252				
296 - HVAC Roof Carrier: HP-2											14,252				
300 - HVAC Roof- Fujitsu											9,501				
612 - Water Heater Pool Storage/Water Heater Rm					9,012										
616 - Water Heater Kitchen Storage- Rheem					9,012										

# Cameron Park Community Services District 30 Year Expense Forecast - Detailed

canca

Reserve Component	2028/29 2029/30 20	030/31 2031/32 2032/33 2033/34 2034/35 .	2035/36	/41 2041/42 2042/43
620 - Water Heater Janitorial Room- Rheem		1,311		
Total 23000 - Mechanical Equipment		19,336	399,061	
24000 - Furnishings				
104 - Miscellaneous Social Room Furnishings	7,423		9,501	
192 - Chairs 93 Community Center Folding Chairs			8,836	
196 - Chairs 270 Community Center Stackable Chairs	26,053			
204 - Chairs 9 Office Task Chairs	6,680		8,551	
334 - Tables 47 Community Center Folding Tables	13,954			
644 - Modular Office Desk 8 Office Desks	28,503			
Total 24000 - Furnishings	82,613		26,889	
24500 - Audio / Visual				
112 - Television, Large Screen Social Room	4,454		5,701	
300 - PA System Roof Access Room- QSC Mixer	3,711		4,751	
304 - PA System 3 Roof Access Room- Speakers & Stands	3,340		4,276	
Total 24500 - Audio / Visual	11,505		14,727	
24600 - Safety / Access				
900 - Miscellaneous Stage Room- Handicap Lift			19,003	
Total 24600 - Safety / Access			19,003	
25000 - Flooring				
200 - Carpeting 189 Sq. Yds. Community Center Offices	8,978		11,493	
400 - Tile 9,333 Sq. Ft. Restrooms, Concession, Kitchen	83,129			
600 - Vinyl 1,106 Sq. Yds. Community Center Vinyl Tile	42,688			
700 - Hardwood Floors 7,257 Sq. Ft. Yoga Room & Gym			82,743	
920 - Coatings 1,063 Sq. Ft. Community Center Concrete Floors		10,451		
Total 25000 - Flooring	134,796	10,451	94,236	
25500 - Wallcoverings				
300 - FRP 1,951 Sq. Ft. Community Center	17,378			
Total 25500 - Wallcoverings	17,378			

Final

Reserve Component	2028/29	2029/30 2030/	/31 2031/32	2032/33 2	2033/34	2034/35	2035/36	2036/37	2037/38	2038/39		14/2015 Fi 2041/42	
050 - Flag Pole Community Center	5,938												
300 - Picnic Table: Wood 2 Pool Area										1,520			
332 - Benches 2 Common Area	1,781												
336 - Picnic Table: Metal 8 Pool Area	10,095												
380 - Garbage Receptacles 14 Common Area & Pool	4,157												
430 - Bleachers 3 Gym- Wood & Metal Bleachers	15,587												
844 - Shade Structure 12 Portable Shade Structures	9,798									12,542			
Total 26000 - Outdoor Equipment	47,356									14,062			
27000 - Appliances 200 - Refrigerator Pool Maintenance Room		761						904					
204 - Refrigerator Offices- Kitchen/Workroom	1,485									1,900			
224 - Refrigerator: Commercial: Large Kitchen- Fridge	5,938												
240 - Freezer: Large Kitchen- Fridge/Freezer Combo	5,938												
270 - Stove / Oven: Commercial grade 6- burner Kitchen	6,680												
278 - Oven: Wall Kitchen- Double Oven	5,196												
282 - Microwave Oven Offices- Kitchen/Workroom									742				
290 - Microwave Oven Kitchen- Panasonic	1,262									1,615			
298 - Stove: Exhaust Hood w/ Fan Kitchen- Greencheck Hood	4,454												
320 - Dishwasher, Commercial Kitchen- Hobart	6,235									7,981			
940 - Drinking Fountain Community Center Entry	3,711												
950 - Point of Sale Computer Pool Maintenance Room				3,277						3,801			
954 - Point of Sale Computer Pool Concession Room				3,277						3,801			
992 - Garbage Disposal Kitchen- Savajor	2,227									2,850			
Total 27000 - Appliances	43,125	761		6,554				904	742	21,948			
30000 - Miscellaneous 806 - Maintenance Equipment				18,626									
Riding Mower  810 - Maintenance Equipment Kitchen Changing Room- Grout Cleaner										2,280			
818 - Maintenance Equipment Roof Access Room- Floor Scrubber	8,165				9,238					10,452			

erve Component	2028/29 2029/	30 2030/31	2031/32	2032/33	2033/34	2034/35	2035/36	2036/37	2037/38	2038/39	2039/40	2040/41	2041/42	2042/43	
----------------	---------------	------------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	--

Reserve Component	2028/29	2029/30	2030/31	2031/32	2032/33	2033/34	2034/35	2035/36	2036/37	2037/38	2038/39	2039/40	2040/41	2041/42	2042/4
822 - Maintenance Equipment Pool Eqpt Rm- Pressure Washer	1,485										1,900				
830 - Maintenance Equipment Roof Access Room- Floor Buffer	2,227					2,519					2,850				
Total 30000 - Miscellaneous	11,876				18,626	11,757					17,483				
Total [Community Center] Expenditures Inflated @ 2.50%	898,133	24,840	49,603	4,796	214,069	522,182	17,242	56,845	904	16,315	1,410,373	20,306	70,304	17,190	5,433
00030 - Cameron Park Lake															
01000 - Paving															
108 - Asphalt: Sealing 5,911 Sq. Ft. Drives & Parking			1,106					1,252					1,416		
208 - Asphalt: Ongoing Repairs 56,911 Sq. Ft. Drives & Parking (2%)			5,770					6,528					7,385		
408 - Asphalt: Major Repairs 56,911 Sq. Ft. Drives & Parking (50%)															298,437
800 - Striping 98 Parking Stalls			2,293					2,594					2,935		
Total 01000 - Paving			9,169					10,373					11,736		298,437
02000 - Concrete															
208 - Walkways 12,350 Sq. Ft. Walkways, Pads, & Slabs (2%)			6,164					6,974					7,890		
Total 02000 - Concrete			6,164					6,974					7,890		
03000 - Painting: Exterior															
104 - Surface Restoration 1,140 Sq. Ft. Guard Shack & [3] Wood Sheds		1,735					1,963					2,220			
- Surface Restoration 3,680 Sq. Ft. Corporate Yard House	5,463					6,181					6,993				
116 - Surface Restoration 1,036 Sq. Ft. Concession Building				1,656					1,874					2,120	
120 - Surface Restoration 1,950 Sq. Ft. Gazebo Painting				3,117					3,527					3,990	
408 - Railings 186 Lin. Ft. Concrete Footbridge Railings				2,379				2,626				2,898			
412 - Railings 80 Lin. Ft. Lake Observation Deck		974				1,075				1,187				1,310	
420 - Wrought Iron Gates 2 Park Entrance Gates		1,522				1,680				1,854				2,046	
504 - Light Poles 32 Park Light Poles			9,233				10,192				11,250				12,418
Total 03000 - Painting: Exterior	5,463	4,230	9,233	7,152		8,935	12,154	2,626	5,401	3,040	18,243	5,119		9,467	12,418
03500 - Painting: Interior															
400 - Restrooms 1,904 Sq. Ft. Concession Building										3,530					
Total 03500 - Painting: Interior										3,530					
04000 - Structural Repairs															
200 - Wood: Siding & Trim 3,680 Sq. Ft. Corporate Yard House (10%)						12,362									

Reserve Component	2028/29 2029/30	2030/31	2031/32	2032/33	2033/34	2034/35	2035/36	2036/37	2037/38	2038/39	2039/40	2040/41	2041/42	2042/43
550 - Bridge Maintenance 1,313 Sq. Ft. [3] Pedestrian Bridges (10%)			10,495					11,874					13,435	
658 - Decking 800 Sq. Ft. Lake Observation Deck														41,951
828 - Dock Floatation [2] Docks & [10] Barges									9,270					
Total 04000 - Structural Repairs			10,495		12,362			11,874	9,270				13,435	41,951
05000 - Roofing														
448 - Pitched: Dimensional Composition 36 Squares- Corporate Yard House														
452 - Pitched: Dimensional Composition 44 Squares- Concession, Gazebo, [3] Small Bldgs														
704 - Gutters / Downspouts 184 Lin. Ft. Concession Building Gutters														
708 - Gutters / Downspouts 400 Lin. Ft. Corporate Yard House														
Total 05000 - Roofing														
<b>08000 - Rehab</b> 234 - Restrooms														12 505
2 Concession Building														12,585
254 - Kitchen Concession Building														6,293
Total 08000 - Rehab														18,878
11000 - Gate Equipment														
910 - Vehicle Gate Replacement 2 Park Entrance Gates														6,293
Total 11000 - Gate Equipment														6,293
17000 - Tennis Court														
100 - Reseal 28,600 Sq. Ft. [4] Tennis Courts		22,303							26,511					
500 - Resurface 28,600 [4] Tennis Courts	65,277													
Total 17000 - Tennis Court	65,277	22,303							26,511					
18000 - Landscaping														
112 - Irrigation: Controllers Shed									1,854					
344 - Irrigation: Pumps 25 GPM Well		7,798					8,823					9,982		
478 - Pathways & Trails 59,910 Sq. Ft. Lake Perimeter- DG Path (10%)									55,535					
Total 18000 - Landscaping		7,798					8,823		57,389			9,982		
18500 - Lakes / Ponds									10.530					
300 - Pumps / Mechanical 10 GPM Well									18,539					
320 - Filter 5 Filters- Lake & Lagoon									23,174					

Prepared for the 2014/2015 Fiscal Year

Reserve Component	2028/29 2029/30 203	30/31 2031/32	2032/33	2033/34	2034/35	2035/36	2036/37	2037/38 203	88/39 2039/	40 2040/43	2041/42	2042/43
990 - Miscellaneous 300 Lin. Ft. Dam/Spillway (5%)		11,990					13,565				15,348	
Total 18500 - Lakes / Ponds		11,990					13,565	41,714			15,348	
19000 - Fencing												
104 - Chain Link: 4' 1,644 Lin. Ft. Lake Perimeter Fencing			29,633									
128 - Chain Link: 6' 21 Lin. Ft. Boat Rental Shack			413									
132 - Chain Link: 6' 6,877 Lin. Ft. Park Perimeter Fencing (20%)				27,721					32,14	3		
352 - Wood: 6' 80 Lin. Ft. Enclosure												
356 - Wood: 6' 555 Lin. Ft. Corporate Yard Perimeter									27,02	5		
522 - Post & Cable 902 Lin. Ft. Park Post & Chain Fencing												
Total 19000 - Fencing			30,046	27,721					59,17	1		
19500 - Retaining Wall 120 - Wood: 1' 125 Lin. Ft. Park Entrance												9,177
124 - Wood: 2' 80 Lin. Ft. Enclosure												
Total 19500 - Retaining Wall												9,177
20000 - Lighting												
216 - Pole Lights 32 Park & Lagoon (9%)	5	,615				6,353				7,187		
Total 20000 - Lighting	5	,615				6,353				7,187		
21000 - Signage												
778 - Wood Monument Park Entrance		2,398					2,713				3,070	
Total 21000 - Signage		2,398					2,713				3,070	
23000 - Mechanical Equipment 232 - HVAC						8,823						
Concession Roof						0,023						
Total 23000 - Mechanical Equipment						8,823						
26000 - Outdoor Equipment												
104 - Tot Lot: Play Equipment Play Area- 4-Swing Set												15,732
108 - Tot Lot: Play Equipment Play Area- Large Structure												73,415
124 - Tot Lot: Play Equipment Play Area- 2-Swing Set												10,488
144 - Tot Lot: Safety Surface 10,000 Sq. Ft. Play Area	3,804		4,097			4,412		4	,751		5,116	
200 - Pedestal Grill BBQ 11 Park Barbecues												6,922
280 - Picnic Tables 50 Park Picnic Tables												62,927

2279 05/09/2014 06fsv4.5.74-543:jf.jf

38

Prepared for the 2014/2015 Fiscal Year

Reserve Component	2028/29	2029/30	2030/31	2031/32	2032/33	2033/34	2034/35	2035/36	2036/37	2037/38	2038/39	2039/40	2040/41	2041/42	2042/43
328 - Benches 25 Park Benches															31,464
392 - Garbage Receptacles 40 Park Trash Cans															16,781
492 - Drinking Fountain Park Tennis Courts															5,034
Total 26000 - Outdoor Equipment		3,804			4,097			4,412			4,751			5,116	222,762
30000 - Miscellaneous															
700 - Tools Compressor		3,804										4,869			
704 - Tools Grinder/Sander										2,781					
708 - Tools Bench Grinder										1,854					
712 - Tools Bench Grinder										1,854					
716 - Tools Drill Press										2,781					
814 - Maintenance Equipment Woods RM500										6,489					
826 - Maintenance Equipment Vermeer 1230 Chipper															
834 - Tractor Massey Ferguson 1525															
838 - Vehicle Dodge 2500 V8- Lic 1101411						35,271									
846 - Vehicle Ford Expedition- Lic 1011647										92,697					
850 - Vehicle 2008 Ford F150 XL- Lic 1273235	37,113										47,507				
854 - Vehicle Dodge Pick Up P-01- Lic 1088018										27,809					
866 - Vehicle Ford Bronco- Lic E041782							36,153								
894 - Trailer PacWest 20'- Lic. E946571										9,270					
898 - Trailer Carson 20'- Lic. 1108445									7,235						
902 - Trailer 11' Trailer- Lic. E323108								4,412							
906 - Trailer 15' Trailer							5,165								
910 - Trailer 12' Trailer 12' Trailer- Lic. 4LF5474										12,978					
914 - Trailer 2003 Vintage Trailer- Lic 1152569						12,597									
918 - Trailer BBQ Trailer								7,058							
Total 30000 - Miscellaneous	37,113	3,804				47,868	41,318	11,470	7,235	158,512	47,507	4,869			
Total [Cameron Park Lake] Expenditures Inflated @ 2.50%	42,576	77,116	60,282	32,035	34,142	96,886	53,472	59,853	40,789	299,966	70,501	69,162	36,796	46,435	609,915

00040 - Rasmussen Park

01000 - Paving

Propaged for the 2014/2015 Fiscal Vear

							Prepared for the	2014/2015	Fiscal Year
Reserve Component	2028/29 2029/30 2030	/31 2031/32	2032/33 2033/34	2034/35	2035/36 2036/37	2037/38 2038/39	2039/40 2040/4	11 2041/42	2 2042/43
112 - Asphalt: Sealing 27,200 Sq. Ft. Parking Lot	5,0	91			5,760		6,517	7	
212 - Asphalt: Ongoing Repairs 27,200 Sq. Ft. Parking Lot (2%)	2,7	57			3,120		3,530	)	
412 - Asphalt: Major Repairs 27,200 Sq. Ft. Parking Lot									
804 - Striping Parking Lot	2,3	39			2,647		2,995	5	
Total 01000 - Paving	10,:	88			11,526		13,041		
02000 - Concrete									
212 - Walkways 5,610 Sq. Ft. Park Walkways (2%)	2,8	00			3,168		3,584	ŀ	
Total 02000 - Concrete	2,8	00			3,168		3,584	ļ	
03000 - Painting: Exterior									
350 - Touch-Up 3 Park Buildings	2,282			2,582			2,922		
Total 03000 - Painting: Exterior	2,282			2,582			2,922		
03500 - Painting: Interior									
408 - Restrooms 1,104 Sq. Ft. Concession Building Restrooms						2,047			
Total 03500 - Painting: Interior						2,047			
04000 - Structural Repairs									
554 - Bridge Maintenance Park Pedestrian Bridge									5,244
Total 04000 - Structural Repairs									5,244
05000 - Roofing									
460 - Pitched: Dimensional Composition 3 Squares- Maint. Bldg & Wood Shed									
684 - Pitched: Metal 6 Squares- Concession Building			4,916						
864 - Skylights 2 Concession Building Restrooms									1,678
Total 05000 - Roofing			4,916						1,678
08000 - Rehab									
246 - Restrooms 2 Concession Stand Restrooms									6,293
250 - Kitchen Concession Stand Interior									6,293
Total 08000 - Rehab									12,585
18000 - Landscaping									
104 - Irrigation: Misc. Park Irrigation	1,522		1,639		1,765	1,900		2,046	
340 - Irrigation: Pumps Park- Irrigation Pump	1,8	72			2,118		2,396	5	
420 - General Repairs/Upgrades Park	1,522		1,639		1,765	1,900		2,046	
474 - Pathways & Trails 15,570 Sq. Ft. Park- Walking Path (10%)	12,:	42			13,737		15,543	3	

Version 4/8/2014 11:17:33 AM

Reserve Component	2028/29 2029/30	2030/31	2031/32 203	2/33 2033/34	2034/35	2035/36	2036/37	2037/38	2038/39	2039/40	2040/41	2041/42	2042/43
498 - Bedding Header 252 Lin. Ft. South Play Area													1,586
Total 18000 - Landscaping	3,043	14,014	3,	277		19,384			3,801		17,939	4,093	1,586
19000 - Fencing													
100 - Chain Link 36 Lin. Ft. Tee Ball Field 5' Chain Link												810	
116 - Chain Link 1,850 Lin. Ft. Ball Fields- 5' Chain Link													
124 - Chain Link: 6' 170 Lin. Ft. Tee Ball Field												4,175	
140 - Chain Link: 6' 332 Lin. Ft. North Play Area Perimeter													
144 - Chain Link: 8' 65 Lin. Ft. Tee Ball Field												1,862	
148 - Chain Link: 8' 400 Lin. Ft. Ball Fields													
152 - Chain Link 150 Lin. Ft. Ball Field Back Stops													
344 - Wood: 6' 885 Lin. Ft. East & West Perimeter										43,095			
514 - Post & Cable 730 Lin. Ft. Parking Perimeter													
540 - Metal 980 Lin. Ft. South Perimeter- Post & Wire													
Total 19000 - Fencing										43,095		6,847	
19500 - Retaining Wall													
364 - Masonry Wall 332 Lin. Ft. North Play Area			21,	761									
Total 19500 - Retaining Wall			21,	761									
21000 - Signage													
794 - Wood Monument Park Sign								4,635					
Total 21000 - Signage								4,635					
25000 - Flooring													
404 - Tile 224 Sq. Ft. Concession Building Restrooms													2,819
Total 25000 - Flooring													2,819
26000 - Outdoor Equipment  100 - Tot Lot: Play Equipment North Play Area													
120 - Tot Lot: Play Equipment South Play Area													
140 - Tot Lot: Safety Surface 10,410 Sq. Ft. North & South Play Areas	3,960		4,	264		4,592			4,946			5,326	
294 - Picnic Table: Cement 2 Park Picnic Tables													2,098
304 - Picnic Table: Wood 2 Park Picnic Tables						1,412							

Prepared for the 2014/2015 Fiscal Year

2028/29 2029/30	2030/31	2031/32	2032/33	2033/34	2034/35	2035/36	2036/37	2037/38	2038/39	2039/40	2040/41	2041/42	2042/43
													7,551
	5,615												7,551
						1,835							
													2,517
													25,171
													5,034
3,960	5,615		4,264			7,839			4,946			5,326	49,922
9,286	32,616		34,218		2,582	41,918		6,682	8,746	46,017	34,564	16,266	73,834
3,389					3,835					4,339			
1,836					2,077					2,350			
5,225					5,912					6,689			
	2,036					2,304					2,607		
								59,326					
	2,036					2,304		59,326			2,607		
	6,878				7,592				8,380				9,250
	6,878				7,592				8,380				9,250
								2,254					
								2,254					
													839
	3,960 9,286 3,389 1,836	5,615  3,960 5,615  9,286 32,616  3,389  1,836  5,225  2,036  2,036  6,878	5,615  3,960 5,615  9,286 32,616  3,389  1,836  5,225  2,036  2,036  6,878	5,615  3,960 5,615 4,264  9,286 32,616 34,218  3,389  1,836  5,225  2,036  6,878	5,615  3,960 5,615 4,264  9,286 32,616 34,218  3,389  1,836  5,225  2,036  2,036  6,878	5,615  3,960 5,615 4,264  9,286 32,616 34,218 2,582  3,389 3,835  1,836 2,077  5,225 5,912  2,036  2,036  6,878 7,592	5,615       3,960     5,615     4,264     7,839       9,286     32,616     34,218     2,582     41,918       3,389     3,835       1,836     2,077       5,225     5,912       2,036     2,304       6,878     7,592	5,615  1,835  3,960 5,615 4,264 7,839  9,286 32,616 34,218 2,582 41,918  3,389 3,835  1,836 2,077  5,225 5,912  2,036 2,304  6,878 7,592	5,615  1,835  3,960 5,615 4,264 7,839  9,286 32,616 34,218 2,582 41,918 6,682  3,389 3,835 1,836 2,077  5,225 5,912  2,036 2,304  59,326  6,878 7,592  6,878 7,592	5,615       3,960     5,615     4,264     7,839     4,946       9,286     32,616     34,218     2,582     41,918     6,682     8,746       3,389     3,835       1,836     2,077       5,225     5,912       2,036     2,304     59,326       2,036     2,304     59,326       6,878     7,592     8,380       6,878     7,592     8,380       2,254	5,615  1,835  1,835  3,960 5,615 4,264 7,839 4,946  9,286 32,616 34,218 2,582 41,918 6,682 8,746 46,017  3,389 3,835 4,339  1,836 2,077 2,350  5,225 5,912 6,689  2,036 2,304  59,326  2,036 2,304 59,326  6,878 7,592 8,380  6,878 7,592 8,380	5,615  1,835  1,835  3,960 5,615 4,264 7,839 4,946  9,286 32,616 34,218 2,582 41,918 6,682 8,746 46,017 34,564  3,389 3,835 4,339  1,836 2,077 2,350  5,225 5,912 6,689  2,036 2,304 59,326  2,036 2,304 59,326  5,936 2,304 59,326  2,036 7,592 8,380  6,878 7,592 8,380  2,254	1,835  3,960 5,615 4,264 7,839 4,946 5,326  9,286 32,616 34,218 2,582 41,918 6,682 8,746 46,017 34,564 16,266  3,389 3,835 4,339 2,350  5,225 5,912 6,689  2,036 2,304 59,326 2,607  59,326  2,036 2,304 59,326 2,607  6,878 7,592 8,380  2,254

2279 05/09/2014 06fsv4.5.74-543:jf.jf

Prepared for the 2014/2015 Fiscal Year

Reserve (	Component
-----------	-----------

2028/29 2029/30 2030/31 2031/32 2032/33 2033/34 2034/35 2035/36 2036/37 2037/38 2038/39 2039/40 2040/41 2041/42 2042/43

reserve compenent	2020,25 2025,00	2000,01 200	1,02 2002,00 200	0,0. 200.,00	2000,00 200	0,0, 200,,00	2000,00	_000, .0	20 .0, .1 20 .	-, ,
Total 05000 - Roofing										839
08000 - Rehab										
112 - General Skate Park Building				2,582						
230 - Restrooms Restroom Building				3,443						
Total 08000 - Rehab				6,025						
19000 - Fencing										
108 - Chain Link: 4' 855 Lin. Ft. North Perimeter			15,411							
L20 - Chain Link: 6' 1,190 Lin. Ft. South & East Perimeter			23,399							
- Chain Link: 6' 260 Lin. Ft. Skate Park Perimeter			5,112							
- Wrought Iron: 4' 490 Lin. Ft. Play Area Perimeter			24,088							
360 - Wood: 6' 395 Lin. Ft. West Perimeter Fence								19,235		
518 - Post & Cable 525 Lin. Ft. Parking Lot Perimeter (No Cable)										
Total 19000 - Fencing			68,011					19,235		
19500 - Retaining Wall										
360 - Masonry Wall 490 Lin. Ft. Play Area Perimeter			32,117							
Total 19500 - Retaining Wall			32,117							
21000 - Signage										
790 - Wood Monument Park Monument Sign						4,635				
Total 21000 - Signage						4,635				
26000 - Outdoor Equipment										
112 - Tot Lot: Play Equipment Park Large Play Structure										
116 - Tot Lot: Play Equipment 2 Park- Smaller Structures										
- Picnic Tables 5 Park Picnic Tables										6,293
- Benches 10 Park Metal Benches										
- Garbage Receptacles 10 Park Trash Cans										4,195
488 - Drinking Fountain 3 Park Drinking Fountains										15,102
Total 26000 - Outdoor Equipment										25,590
Total [Christa McAuliffe Park] Expenditures Inflated @ 2.50%	5,225	8,914	100,128	19,530	2,304	66,215	8,380	25,924	2,607	35,680
00060 - Chardi Corner										
18000 - Landscaping										
116 - Irrigation: Controllers Chardi Corner- Irrigation Controller						1,854				

Chardi Corner- Irrigation Controller 2279 05/09/2014 06fsv4.5.74-543:jf.jf

2028/29 to 2042/43 **43** Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

Einal

Prepared for the 2014/2015 Fiscal Year

Reserve Component	2028/29 2	2029/30	2030/31	2031/32	2032/33	2033/34	2034/35	2035/36	2036/37	2037/38	2038/39	-	for the 20 <i>2040/41</i>		
300 - Irrigation: Backflow Preventors Chardi Corner- Backflow Prevention Device		· ·					<u> </u>		<u> </u>		<u>·</u>				1,259
424 - General Repairs/Upgrades Chardi Corner		1,522			1,639			1,765			1,900			2,046	
Total 18000 - Landscaping		1,522			1,639			1,765		1,854	1,900			2,046	1,259
19000 - Fencing															
348 - Wood: 6' 300 Lin. Ft. Chardi Corner- Perimeter Fencing												14,608			
Total 19000 - Fencing												14,608			
19500 - Retaining Wall															
368 - Masonry Wall 380 Lin. Ft. Chardi Corner- Perimeter Wall					24,907										
Total 19500 - Retaining Wall					24,907										
20000 - Lighting															
220 - Landscape 3 Chardi Corner- Sign Lights			1,872												2,517
Total 20000 - Lighting			1,872												2,517
21000 - Signage															
782 - Monument 35 Lin. Ft. Chardi Corner- Monument Sign (25%)				3,497					3,957					4,477	
Total 21000 - Signage				3,497					3,957					4,477	
26000 - Outdoor Equipment															
064 - Flag Pole Chardi Corner- Flag Pole															8,390
Total 26000 - Outdoor Equipment															8,390
Total [Chardi Corner] Expenditures Inflated @ 2.50%		1,522	1,872	3,497	26,546			1,765	3,957	1,854	1,900	14,608		6,523	12,166
00070 - Hacienda Park															
01000 - Paving															
120 - Asphalt: Sealing 4,500 Sq. Ft. Hacienda- Parking Lot			842					953					1,078		
220 - Asphalt: Ongoing Repairs 4,500 Sq. Ft. Hacienda Parking Lot (3%)			684					774					876		
420 - Asphalt: Major Repairs 4,500 Sq. Ft. Hacienda- Parking Lot															
Total 01000 - Paving			1,527					1,727					1,954		
02000 - Concrete															
380 - Pad 462 Sq. Ft. [5] Concrete Slabs (10%)								1,631							
Total 02000 - Concrete								1,631							
04000 - Structural Repairs															
998 - Miscellaneous Park- Shed- Upkeep				799					904					1,023	
Total 04000 - Structural Repairs				799					904					1,023	

2279 05/09/2014 06fsv4.5.74-543:jf.jf

2028/29 to 2042/43 **44** 

Prepared for the 2014/2015 Fiscal Year

Reserve Component	2028/29	2029/30	2030/31	2031/32	2032/33	2033/34	2034/35	2035/36	2036/37	2037/38	2038/39	•	for the 20 2040/41		
18000 - Landscaping															
100 - Irrigation: Misc. Park	1,485			1,599			1,722			1,854			1,996		
450 - Drainage System Maint. Deer Creek Tributary		3,043			3,277			3,529			3,801			4,093	
470 - Pathways & Trails 29,465 Sq. Ft. Park- DG Paths (20%)										54,626					
494 - Bedding Header 420 Lin. Ft. Turf Perimeter															
500 - Tree Maintenance Park- Scrub & Heritage Oaks			7,798					8,823					9,982		
Total 18000 - Landscaping	1,485	3,043	7,798	1,599	3,277		1,722	12,352		56,480	3,801		11,979	4,093	
19000 - Fencing 112 - Chain Link: 4' 100 Lin. Ft. Creek Perimeter															2,307
364 - Wood: Split Rail 765 Lin. Ft. Park Perimeter															
510 - Post & Cable 26 Parking Lot Posts (50%)										2,410					
Total 19000 - Fencing										2,410					2,307
21000 - Signage															
798 - Wood Monument Park Sign		1,522										1,948			
Total 21000 - Signage		1,522										1,948			
26000 - Outdoor Equipment															
290 - Picnic Table: Cement 3 Park- Picnic Tables															
316 - Benches Park Bench															
376 - Pet Stations Park- Pet Station										482					
388 - Garbage Receptacles 2 Park- Trash Cans															
480 - Drinking Fountain Park- Drinking Fountain															
Total 26000 - Outdoor Equipment										482					
Total [Hacienda Park] Expenditures Inflated @ 2.50%	1,485	4,565	9,325	2,398	3,277		1,722	15,710	904	59,373	3,801	1,948	13,933	5,116	2,307
00188 - Station 88															
01000 - Paving															
100 - Asphalt: Sealing 3,950 Sq. Ft. Parking Lot- Seal & Stripe					1,553					1,758					1,988
200 - Asphalt: Ongoing Repairs 3,950 Sq. Ft. Parking Lot (5%)										1,190					
400 - Asphalt: Major Repairs 3,950 Sq. Ft. Parking Lot (50%)			12,321												
Total 01000 - Paving			12,321		1,553					2,948					1,988
02000 - Concrete															
200 - Sidewalks, Curbs & Gutters 2,400 Sq. Ft. Exterior Concrete (3%)			1,797					2,033					2,300		

Version 4/8/2014 11:17:33 AM

Prepared for the 2014/2015 Fiscal Year

								Prepared for the 20	014/2015 F	iscal Year
Reserve Component	2028/29 2029/3	0 2030/31 2	2031/32 2032/33	2033/34 20	34/35 2035/36	2036/37 203	7/38 2038/39	2039/40 2040/41	2041/42	2042/43
710 - Sealing 1,225 Sq. Ft. Vehicle Bays- Concrete Floors		4,108			4,648			5,258		
Total 02000 - Concrete		5,904			6,680			7,558		
03000 - Painting: Exterior										
100 - Surface Restoration 360 Sq. Ft. Patio Shed- Paint & Repair		1,684			1,906			2,156		
310 - Trim 825 Sq. Ft. Station 88- Wood Trim		1,287			1,456			1,647		
Total 03000 - Painting: Exterior		2,971			3,362			3,803		
03500 - Painting: Interior										
110 - Building 7,122 Sq. Ft. Station 88- Interior Spaces						13,	204			
Total 03500 - Painting: Interior						13,	204			
04000 - Structural Repairs										
364 - Garbage Enclosure Parking Area						2,	781			
910 - Doors 11 Station 88- Interior & Exterior Doors										13,844
Total 04000 - Structural Repairs						2,	781			13,844
05000 - Roofing										
444 - Pitched: Dimensional Composition 36 Squares- Station 88	21,377									
712 - Gutters / Downspouts 110 Lin. Ft. Station 88	980									
860 - Skylights 2 Lobby & Lounge	1,188									
Total 05000 - Roofing	23,544									
08000 - Rehab										
120 - General 2 Quarters						3,	708			
210 - Bathrooms 2 Bathroom & Restroom				!	5,165					
214 - Kitchen Kitchen				:	3,443					
Total 08000 - Rehab					8,608	3,	708			
14000 - Recreation										
200 - Exercise: Treadmill Vehicle Bays						3,	708			
204 - Exercise: Miscellaneous Equip. Vehicle Bays: Weights & Rack					5,294					
Total 14000 - Recreation					5,294	3,	708			
20000 - Lighting										
104 - Exterior: Misc. Fixtures 8 Building & Landscape Lights						3,	708			
540 - Parking Lot Parking Lot Light										
Total 20000 - Lighting						3,	708			

2279 05/09/2014 06fsv4.5.74-543:jf.jf

Reserve Component	2028/29	2029/30	2030/31	2031/32	2032/33	2033/34	2034/35	2035/36	2036/37	2037/38	2038/39	2039/40	2040/41	2041/42	2042/43
21000 - Signage															
786 - Wood Monument Station 88 Entrance						1,680									
Total 21000 - Signage						1,680									
22000 - Office Equipment															
200 - Computers, Misc. Lobby	2,969						3,443						3,993		
204 - Computers, Misc. Mulit-Quarters Laptop						2,519						2,922			
208 - Computers, Misc. Mulit-Quarters PC Workstation						2,519						2,922			
300 - Copier Lobby						2,519						2,922			
Total 22000 - Office Equipment	2,969					7,558	3,443					8,765	3,993		
23000 - Mechanical Equipment															
200 - HVAC Patio Area HVAC					8,193										
600 - Water Heater Water Heater Closet			1,248												1,678
Total 23000 - Mechanical Equipment			1,248		8,193										1,678
24000 - Furnishings															
100 - Miscellaneous Lobby Additional Furnishings															10,488
200 - Bar Stools 2 Lounge Barstools										927					
212 - Chairs 4 Station 88 Task Chairs	1,485										1,900				
228 - Chairs 3 Lounge Recliners												2,922			
640 - Modular Office Desk 3 Station 88 Office Desks															6,293
910 - Window Coverings 8 Station 88- Window Blinds										7,416					
Total 24000 - Furnishings	1,485									8,343	1,900	2,922			16,781
24600 - Safety / Access															
340 - Defibrillators Lobby			3,899					4,412					4,991		
Total 24600 - Safety / Access			3,899					4,412					4,991		
25000 - Flooring															
210 - Carpeting 87 Sq. Yds. Station 88- Carpeting									5,035						
- Tile 362 Sq. Ft. Bathroom, Restroom, &							3,739								
Lobby 610 - Vinyl							671								<del></del>
15 Sq. Yds. Kitchen- Linoleum  Total 25000 - Flooring							4,411		5,035						
26000 - Outdoor Equipment															

Reserve Component	2028/29 2029/30	2030/31 2	031/32 203	32/33 2033/3	34 2034/35	2035/36	2036/37	2037/38	2038/39	2039/40	2040/41	2041/42	2042/43
060 - Flag Pole Station 88 Entrance													
210 - Barbecue Patio Barbecue				1,008	1							1,228	
350 - Furniture 8 Patio Furniture Items								3,708					
Total 26000 - Outdoor Equipment				1,008	l			3,708				1,228	
27000 - Appliances													
208 - Refrigerator Kitchen		1,560						1,854					
248 - Ice Machine Vehicle Bays- Hoshizaki	2,969								3,801				
266 - 4-Burner Stove & Oven Kitchen	2,672					3,176							3,776
302 - Stove: Exhaust Hood w/ Fan Kitchen													5,454
306 - Dishwasher Kitchen								1,854					
410 - Washer Vehicle Bay	2,227								2,850				
414 - Dryer Vehicle Bay	2,672								3,421				
Total 27000 - Appliances	10,540	1,560				3,176		3,708	10,072				9,229
30000 - Miscellaneous													
270 - Garage Door: Metal 2 Vehicle Bay Doors													20,976
842 - Vehicle E 88 Lic 1206288				978,283									
858 - Vehicle E 288 Lic 1375275											933,417		
898 - Vehicle U 88 Lic 127543										67,121			
Total 30000 - Miscellaneous				978,283						67,121	933,417		20,976
Total [Station 88] Expenditures Inflated @ 2.50%	38,538	27,903	9,	,746 988,528	16,462	22,924	5,035	45,814	11,972	78,808	953,763	1,228	64,496
00189 - Station 89													
01000 - Paving			_										
104 - Asphalt: Sealing 20,899 Sq. Ft. Parking Lot- Seal & Stripe			5,	,244				5,933					6,712
204 - Asphalt: Ongoing Repairs 20,899 Sq. Ft. Parking Lot (10%)								12,592					
404 - Asphalt: Major Repairs 20,899 Sq. Ft. Parking Lot (50%)	77,562												
Total 01000 - Paving	77,562		5,	,244				18,525					6,712
02000 - Concrete													
204 - Sidewalks, Curbs & Gutters 8,840 Sq. Ft. Exterior Concrete (3%)		6,618				7,488					8,472		
714 - Sealing 5,016 Sq. Ft. Vehicle Bays- Concrete Floors	16,010			18,113					20,494				
Total 02000 - Concrete	16,010	6,618		18,113		7,488			20,494		8,472		

2279 05/09/2014 06fsv4.5.74-543:jf.jf

2028/29 to 2042/43 **48** 

Prepared for the 2014/2015 Fiscal Year

Reserve Component	2028/29 20	029/30	2030/31	2031/32	2032/33 203	3/34	2034/35 2035/3	36 2036/37 2037/38	2038/39	=	40/41 2041/42	
03000 - Painting: Exterior 124 - Surface Restoration 8,500 Lin. Ft. Station 89								15,759				
416 - Railings 90 Lin. Ft. Balcony & Stairs			1,123				1,240		1,368			1,510
920 - Miscellaneous Sheds, Wrought Iron, & Touch-Up	5,196				5,	879			6,651			
Total 03000 - Painting: Exterior	5,196		1,123		5,	879	1,240	15,759	8,019			1,510
03500 - Painting: Interior												
120 - Building 24,962 Sq. Ft. Station 89 Interior Painting								46,278				
Total 03500 - Painting: Interior								46,278				
04000 - Structural Repairs												
360 - Garbage Enclosure Station 89- Enclosure								4,635				
920 - Doors 31 Station 89 Interior & Exterior Doors					31,	240						
990 - Miscellaneous 4 Wood Sheds	2,969								3,801			
Total 04000 - Structural Repairs	2,969				31,	240		4,635	3,801			
04500 - Decking/Balconies												
110 - Concrete 375 Sq. Ft. South Side Building (25%)								2,607				
500 - Railing: Wrought Iron 90 Lin. Ft. Balcony & Stair Railings												
Total 04500 - Decking/Balconies								2,607				
05000 - Roofing												
334 - Low Slope: Vinyl 48 Squares- Station 89 Flat Roofing												
680 - Pitched: Metal 31 Squares- Station 89 Metal Roof					26,	034						
720 - Gutters / Downspouts 210 Lin. Ft. Station 89					2,	116						
Total 05000 - Roofing					28,	150						
08000 - Rehab												
128 - General 4 Dormitory Rooms												
132 - General Work Room												
136 - General 3 Offices												
140 - General Reception												
218 - Bathrooms 2 Upstairs Bathrooms							10,588	3				
226 - Bathrooms 2 Downstairs Restrooms												
262 - Kitchen Coffee Room												

2279 05/09/2014 06fsv4.5.74-543:jf.jf

2028/29 to 2042/43

49

Prepared for the 2014/2015 Fiscal Year

270   Lindrich Kitchen   1,916   1,926   1,928   1,9	Reserve Component	2028/29 2029/30 2030/3	1 2031/32 2032/33 2033	/34 2034/35 2035/36	2036/37 2037/38 2038/	Prepared for the 2014/2015 Fiscal Ye /39 2039/40 2040/41 2041/42 2042/4
Total   1900   Rereation   1,000   Rereation			4,916			
14000 - Recreation			2,458			
220   Exercise: Treadmill   Weight Room	Total 08000 - Rehab		7,374	10,588		
Weight Room   Sand	14000 - Recreation					
Melight Room Eliptocia'   Weight Room Sequip.   Sequip					3,708	
New					3,337	
Megin Room Tuff Stuff Rack						
National Landor Recreation   1,522   1,948	232 - Exercise: Miscellaneous Equip. Weight Room Tuff Stuff Rack					
1800 - Landscaping   1,522   1,722   1,948					5,562	
1,522 1,726 1,948	Total 14000 - Recreation				12,607	
Age	18000 - Landscaping					
S20 Sq. ft. DG Walking Path   Total 18000 - Landscaping	Backflows, Controllers, Valves					1,948
19000 - Fencing 310 - Wood: 3' 1,229 340 - Wood: 6' 38,520 38,520 350 Lin. Ft. Northeast Perinter Fencing 372 - Masonry Wall Maintenance 2,25 Lin. Ft. Keystone Retaining Wall (25%) 372 - Masonry Wall Maintenance 2,25 Lin. Ft. Keystone Retaining Wall (25%) 373 - Masonry Wall Maintenance 2,5007 374 - Masonry Wall Maintenance 2,5007 375 - Masonry Wall Maintenance 2,5007 376 - Lighting Wall (25%) 377 - Masonry Wall Maintenance 2,5007 378 - Keystone Retaining Wall (25%) 379 - Lighting Wall (25%) 38,520 38,	482 - Pathways & Trails 520 Sq. Ft. DG Walking Path	3,956		4,476		5,064
1,229   1,22	Total 18000 - Landscaping	5,478		6,198		7,012
Sol Lin. Ft. Northeast Perimeter   Sol Lin. Ft. Perimeter Fencing   Sol Lin. Ft. Perimeter Fencin	_					
Note   1900 - Fencing   1,229   38,520   19500 - Retaining Wall   372 - Masonry Wall Maintenance   2,607   2,607   225 Lin. Ft. Keystone Retaining Wall   1900 - Retaining Wall   2,607   20000 - Lighting   1900 - Exterior: Misc. Fixtures   21 Station 89 - Exterior Building Lights   1900 - Retaining Wall   1900 - Ret			1,229			
1,229   38,520   38				38,520		
372 - Masonry Wall Maintenance 225 Lin. Ft. Keystone Retaining Wall (225 Lin. Ft. Keystone Retaining Wall (25%)			1,229	38,520		
372 - Masonry Wall Maintenance 225 Lin. Ft. Keystone Retaining Wall (225 Lin. Ft. Keystone Retaining Wall (25%)	19500 - Retaining Wall					
Total   19500 - Retaining Wall   2,607	372 - Masonry Wall Maintenance 225 Lin. Ft. Keystone Retaining Wall				2,607	
100 - Exterior: Misc. Fixtures 21 Station 89- Exterior Building Lights  420 - Interior 72 Station 89 Interior Lighting (50%)  424 - Interior 6 Station 89 Ceiling Fans  Total 20000 - Lighting  2,170  2,170  2,170  2,170					2,607	
21 Station 89- Exterior Building Lights  420 - Interior 72 Station 89 Interior Lighting (50%)  424 - Interior 6 Station 89 Ceiling Fans  Total 20000 - Lighting 2,170  21000 - Signage	20000 - Lighting					
72 Station 89 Interior Lighting (50%) 424 - Interior 6 Station 89 Ceiling Fans  Total 20000 - Lighting  2,170  21000 - Signage						
6 Station 89 Ceiling Fans  Total 20000 - Lighting 2,170  21000 - Signage						
21000 - Signage					2,170	
	Total 20000 - Lighting				2,170	
774 - Wood Monument 4 454						
2 Station 89 Signs	774 - Wood Monument 2 Station 89 Signs	4,454				
Total 21000 - Signage 4,454	Total 21000 - Signage	4,454				
22000 - Office Equipment	The state of the s					
212 - Computers, Misc. 1,639 1,900 Reception Dell PC Workstation #3101			1,639		1,90	00

2279 05/09/2014 06fsv4.5.74-543:jf.jf

© Browning Reserve Group 2014

Prepared for the 2014/2015 Fiscal Year

eserve Component	2028/29 2029/30	2030/31 2	2031/32	2032/33	2033/34	2034/35	2035/36 20	036/37 2037/38	2038/39	2039/40 2	2040/41 2041/42 204
16 - Computers, Misc. Reception Dell PC Workstation #3102				1,639					1,900		
20 - Computers, Misc. Reception Gateway PC Workstation 3092			1,599					1,854			
24 - Computers, Misc. Reception Brother Printer			1,599					1,854			
28 - Computers, Misc. Station Captains Office	1,522						1,765				2,046
2 - Computers, Misc. Station Captain's Office- Shredder								2,225			
36 - Computers, Misc. Station Captain's Office- Printer					840					974	
0 - Computers, Misc. Work Room- Fax								2,410			
4 - Computers, Misc. Work Room- Shredder								2,039			
48 - Computers, Misc. Equipment Room- UPS 1500					2,519					2,922	
52 - Computers, Misc. Equipment Room- Power Connect 2724					8,398					9,739	
66 - Computers, Misc. Equipment Room- Surge Protector					1,680					1,948	
0 - Computers, Misc. Equipment Room- Poweredge 2900					8,398					9,739	
4 - Computers, Misc. Fire Prevention Office			1,599					1,854			
8 - Computers, Misc. Fire Prevention Office- Shredder					2,015					2,337	
2 - Computers, Misc. Battalion Chief's Office	1,522						1,765				2,046
4 - Copier Work Room- Copier								6,489			
0 - Telephone Equipment Equipment Room- Phone System					7,558					8,765	
4 - Telephone Equipment Equipment Room- Integration Hub					7,558					8,765	
8 - Telephone Equipment Equipment Room- Phone System					7,558					8,765	
Total 22000 - Office Equipment	3,043		4,796	3,277	46,524		3,529	18,725	3,801	53,954	4,093
23000 - Mechanical Equipment 14 - HVAC							17,646				
Roof- AC-1 8 - HVAC							17,646				
Roof- AC-2 2 - Fan											
Roof- Ventilation Fan  6 - Fan Roof- Captive Aire Systems, Supply											
70 - Fan Roof- Captive Aire Systems, Exhaust											
24 - Swamp Cooler Roof- Evaporative Air Cooler											
8 - Swamp Cooler Roof- Evaporative Air Cooler											

2279 05/09/2014 06fsv4.5.74-543:jf.jf

2028/29 to 2042/43 Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

Final

Prepared for the 2014/2015 Fiscal Year

Reserve Component	2028/29 2029/30	2030/31	2031/32	2032/33	2033/34	2034/35	2035/36	2036/37	2037/38	2038/39	2039/40	2040/41	2041/42	2042/43
330 - Fuel Tank 2 Parking Area Fueling Tanks					25,194									
580 - Cooling Tower Roof- REF-1														
604 - Water Heater Upstairs Closet				1,311										
608 - Water Heater Mechanic's Bay									1,483					
Total 23000 - Mechanical Equipment				1,311	25,194		35,292		1,483					
24000 - Furnishings														
208 - Chairs 9 Station 89 Task Chairs							3,970							
216 - Chairs 10 Station 89 Wood/Cloth Chairs								1,357						
220 - Chairs 15 Station 89 Stackable Chairs								2,035						
224 - Chairs 46 Station 89 Folding Chairs														
232 - Chairs 6 Lounge- Recliners									5,562					
310 - Tables: Dining: Large Lounge & Kitchen														
330 - Tables 17 Station 89 Folding Tables														
650 - Modular Office Desk 5 Station 89 Office Desks														
880 - Security Deposit Boxes Station Captain's Office Lockbox		780												1,049
884 - Security Deposit Boxes Station Captain's Office Safe														
920 - Window Coverings 19 Station 89 Window Blinds					15,956									
Total 24000 - Furnishings		780			15,956		3,970	3,391	5,562					1,049
24500 - Audio / Visual 100 - Television Weight Room									2,781					
200 - DVD Player Storage (Conference)- Sony DVD					840						974			
204 - DVD Player Storage (Conference)- Toshiba DVD					840						974			
308 - PA System Equipment Room- Amplifier									1,390					
312 - PA System Conference Room- Podium									4,635					
316 - PA System Conference Room- Projector					5,879						6,817			
Total 24500 - Audio / Visual					7,558				8,806		8,765			
24600 - Safety / Access 120 - Fire Control Misc									9,270					
Building Alarm & Extinguishers									5,270					
350 - Defibrillators Lobby		3,899					4,412					4,991		

2279 05/09/2014 06fsv4.5.74-543:jf.jf

2028/29 to 2042/43 **52** 

Reserve Component	2028/29 2029/30	2030/31	2031/32	2032/33	2033/34	2034/35	2035/36	2036/37	2037/38	2038/39	2039/40	2040/41	2041/42	2042/43
Total 24600 - Safety / Access		3,899					4,412		9,270			4,991		
25000 - Flooring 220 - Carpeting 262 Sq. Yds. Station 89 Interior Carpeting									15,543					
420 - Tile 2,543 Sq. Ft. Station 89 Floor & Wall Tile														
620 - Vinyl 50 Sq. Yds. Bathroom Vinyl Tile														
624 - Vinyl 166 Sq. Yds. Station 89 Wood Laminate Flooring														
990 - Miscellaneous 27 Sq. Yds. Weight Room Rubber Flooring									1,502					
Total 25000 - Flooring									17,045					
26000 - Outdoor Equipment 068 - Flag Pole Station 89- Flag Pole					9,238									
220 - Barbecue Balcony				819								998		
308 - Picnic Table: Wood Patio								723						
Total 26000 - Outdoor Equipment				819	9,238			723				998		
27000 - Appliances														
220 - Refrigerator: Commercial: Large Kitchen	3,043										3,896			
244 - Freezer: Large Kitchen	1,217										1,558			
252 - Ice Machine Upstairs Closet- Ice-O-Matic									3,708					
256 - Ice Machine Mechanic's Bay- Manitowac									3,708					
260 - Stove Kitchen					5,879									
274 - Oven: Wall Kitchen									4,635					
286 - Microwave Oven Kitchen									1,112					
294 - Stove: Fire Suppression Kitchen									10,197					
310 - Dishwasher, Residential Type Kitchen	1,485				1,680					1,900				
418 - Washer: Large Mechanic's Bay- Washer/Extractor									22,247					
422 - Dryer Mechanic's Bay- Kenmore									1,854					
426 - Washer Upstairs Laundry	1,065										1,363			
430 - Dryer Upstairs Laundry	1,522										1,948			
684 - Miscellaneous Coffee Room- Coffee Maker									927					

## 30 Year Expense Forecast - Detailed

Reserve Component	2028/29 2	029/30	2030/31	2031/32	2032/33	2033/34	2034/35	2035/36	2036/37	2037/38	2038/39	2039/40	2040/41	2041/42	2042/43
984 - Miscellaneous Kitchen- Coffee Maker										927					
988 - Miscellaneous Kitchen- Coffee Grinder										463					
Total 27000 - Appliances	1,485	6,847				7,558				49,778	1,900	8,765			
30000 - Miscellaneous															
266 - Garage Door: Metal 3 Station 89 Garage Bay Doors					24,579										
274 - Garage Door: Metal 4 Station 89 Garage Bay Doors- Rear									36,175						
870 - Vehicle B2715- Lic 1275433		58,990										75,512			
874 - Vehicle B2716 Lic 1275432	Ę	58,990										75,512			
878 - Vehicle E-89- Lic 1206287	88	86,276													
882 - Vehicle E-289- Lic E1109085			746,874												
886 - Vehicle E-389 Lic E000391			844,861									1	.,081,493		
890 - Vehicle U-89 Lic 1088016				70,950											
894 - Vehicle U-289 Lic 041782			60,200												
922 - Generator Building East Side- Generac Series						50,387									
Total 30000 - Miscellaneous	1,00	04,256 1,	651,934	70,950	24,579	50,387			36,175			151,025	,081,493		
Total [Station 89] Expenditures Inflated @ 2.50%	107,674 1,01	19,624 1,	664,354	75,746	43,833	245,797	45,957	65,279	42,460	213,687	38,014	229,521	,095,954	4,093	9,271
Total Expenditures Inflated @ 2.50%	1,088,405 1,14	42,178 1,	854,869	118,472	465,959	1,853,394	156,966	266,596	94,049	709,906 1	,553,687	486,294	2,207,922	96,850	813,102





## 30 Year Reserve Funding Plan Cash Flow Method

Final

Prepared for the 2014/2015 Fiscal Year

	2013/14	2014/15	2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23
Beginning Balance	3,154,345	3,162,877	2,989,309	2,798,523	3,196,929	3,362,005	2,842,449	3,300,199	2,977,745	3,421,010
Inflated Expenditures @ 2.5%	69,459	697,520	723,681	150,895	405,439	1,100,381	137,440	934,894	186,715	553,906
Reserve Contribution	0	448,000	461,440	475,283	489,541	504,227	519,354	534,935	550,983	567,512
Unit/month @ 1	0.00	37,333.33	38,453.33	39,606.92	40,795.08	42,018.92	43,279.50	44,577.92	45,915.25	47,292.67
Percentage Increase		0.0%	3.0%	3.0%	3.0%	3.0%	3.0%	3.0%	3.0%	3.0%
Special Assessments / Other	0	0	0	0	0	0	0	0	0	0
Interest Pre Tax @ 2.50%	77,990	75,953	71,455	74,018	80,975	76,598	75,835	77,505	78,997	85,695
Ending Balance	3,162,877	2,989,309	2,798,523	3,196,929	3,362,005	2,842,449	3,300,199	2,977,745	3,421,010	3,520,311
	2023/24	2024/25	2025/26	2026/27	2027/28	2028/29	2029/30	2030/31	2031/32	2032/33
Beginning Balance	3,520,311	3,490,611	4,037,057	3,965,667	4,570,236	4,083,024	3,769,198	3,413,665	2,348,843	3,037,341
Inflated Expenditures @ 2.5%	700,792	148,561	790,324	139,552	1,251,943	1,088,405	1,142,178	1,854,869	118,472	465,959
Reserve Contribution	584,537	602,073	620,135	638,739	657,901	677,638	697,967	718,906	740,473	762,687
Unit/month @ 1	48.711.42	50,172.75	51,677.92	53,228.25	54,825.08	56,469.83	58,163.92	59,908.83	61,706.08	63,557.25
Percentage Increase	3.0%	3.0%	3.0%	3.0%	3.0%	3.0%	3.0%	3.0%	3.0%	3.0%
Special Assessments / Other	0	0	0	0	0	0	0	0	0	0
Interest Pre Tax @ 2.50%	86,555	92,934	98,799	105,382	106,830	96,941	88,677	71,142	66,496	79,643
Ending Balance	3,490,611	4,037,057	3,965,667	4,570,236	4,083,024	3,769,198	3,413,665	2,348,843	3,037,341	3,413,711
9	37.307022	.,007,007	3/303/00/	.,5, 0,250	.,,,,,,,,	37, 337233	37.137003	2/3 .0/0 .3	3,007,011	37.137.11
	2033/34	2034/35	2035/36	2036/37	2037/38	2038/39	2039/40	2040/41	2041/42	2042/43
Beginning Balance	3,413,711	2,417,880	3,138,648	3,791,012	4,659,704	4,952,631	4,425,411	4,993,408	3,860,949	4,866,984
Inflated Expenditures @ 2.5%	1,853,394	156,966	266,596	94,049	709,906	1,553,687	486,294	2,207,922	96,850	813,102
Reserve Contribution	785,568	809,135	833,409	858,411	884,163	910,688	938,009	966,149	995,133	1,024,987
Unit/month @ 1	65,464.00	67,427.92	69,450.75	71,534.25	73,680.25	75,890.67	78,167.42	80,512.42	82,927.75	85,415.58
Percentage Increase	3.0%	3.0%	3.0%	3.0%	3.0%	3.0%	3.0%	3.0%	3.0%	3.0%
Special Assessments / Other	0	0	0	0	0	0	0	0	0	0
Interest Pre Tax @ 2.50%	71,995	68,599	85,551	104,330	118,671	115,778	116,282	109,313	107,752	124,323
	. =,555	00,000	00,001	20.,000	,	,	,	200,020	-0.,.02	,5-5

4,659,704

4,952,631

4,425,411

4,993,408

3,860,949

4,866,984

2279 05/09/2014 06fsv4.5.74-543:jf.jf Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

Ending Balance 2,417,880

3,138,648

3,791,012

5,203,192






30 Year Reserve Funding Plan Cash Flow Method - Ending Balances

Final

Prepared for the 2014/2015 Fiscal Year



2279 05/09/2014 06fsv4.5.74-543:jf.jf Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014





## 30 Year Reserve Funding Plan Including Fully Funded Balance and % Funded

Final

Prepared for the 2014/2015 Fiscal Year

Cameron Park Community Services District

Year	Beginning Balance	Fully Funded Balance	Percent Funded	Inflated Expenditures @ 2.50%	Reserve Contribution	Special Assessments & Other Contributions	Interest	Ending Balance
2013/14	3,154,345	3,457,409	91.5%	69,459	0	0	77,990	3,162,877
2014/15	3,162,877	3,970,543	75.3%	697,520	448,000	0	75,953	2,989,309
2015/16	2,989,309	3,866,353	72.4%	723,681	461,440	0	71,455	2,798,523
2016/17	2,798,523	3,745,531	85.4%	150,895	475,283	0	74,018	3,196,929
2017/18	3,196,929	4,221,901	79.6%	405,439	489,541	0	80,975	3,362,005
2018/19	3,362,005	4,462,708	63.7%	1,100,381	504,227	0	76,598	2,842,449
2019/20	2,842,449	4,010,990	82.3%	137,440	519,354	0	75,835	3,300,199
2020/21	3,300,199	4,549,110	65.5%	934,894	534,935	0	77,505	2,977,745
2021/22	2,977,745	4,297,759	79.6%	186,715	550,983	0	78,997	3,421,010
2022/23	3,421,010	4,821,838	73.0%	553,906	567,512	0	85,695	3,520,311
2023/24	3,520,311	4,997,849	69.8%	700,792	584,537	0	86,555	3,490,611
2024/25	3,490,611	5,043,282	80.0%	148,561	602,073	0	92,934	4,037,057
2025/26	4,037,057	5,671,858	69.9%	790,324	620,135	0	98,799	3,965,667
2026/27	3,965,667	5,674,711	80.5%	139,552	638,739	0	105,382	4,570,236
2027/28	4,570,236	6,361,455	64.2%	1,251,943	657,901	0	106,830	4,083,024
2028/29	4,083,024	5,942,364	63.4%	1,088,405	677,638	0	96,941	3,769,198
2029/30	3,769,198	5,698,050	59.9%	1,142,178	697,967	0	88,677	3,413,665
2030/31	3,413,665	5,410,580	43.4%	1,854,869	718,906	0	71,142	2,348,843
2031/32	2,348,843	4,403,935	69.0%	118,472	740,473	0	66,496	3,037,341
2032/33	3,037,341	5,170,914	66.0%	465,959	762,687	0	79,643	3,413,711
2033/34	3,413,711	5,620,351	43.0%	1,853,394	785,568	0	71,995	2,417,880
2034/35	2,417,880	4,678,848	67.1%	156,966	809,135	0	68,599	3,138,648
2035/36	3,138,648	5,473,089	69.3%	266,596	833,409	0	85,551	3,791,012
2036/37	3,791,012	6,195,768	75.2%	94,049	858,411	0	104,330	4,659,704
2037/38	4,659,704	7,134,854	69.4%	709,906	884,163	0	118,671	4,952,631
2038/39	4,952,631	7,488,178	59.1%	1,553,687	910,688	0	115,778	4,425,411
2039/40	4,425,411	7,008,024	71.3%	486,294	938,009	0	116,282	4,993,408
2040/41	4,993,408	7,633,075	50.6%	2,207,922	966,149	0	109,313	3,860,949
2041/42	3,860,949	6,532,790	74.5%	96,850	995,133	0	107,752	4,866,984
2042/43	4,866,984	7,593,147	68.5%	813,102	1,024,987	0	124,323	5,203,192

**57** 






30 Year Reserve Funding Plan Cash Flow Method - Percent Funded

Final

Prepared for the 2014/2015 Fiscal Year



Years





## Reserve Fund Balance Forecast Component Method

Final

Prepared for the 2014/2015 Fiscal Year

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	<i>Per Year</i>	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00010 - Community Center									
01000 - Paving									
124 - Asphalt: Sealing 59,100 Sq. Ft. Parking Lot	7,269	5	2	7,637	1,527	4,362	5,961	0.26%	1,174
224 - Asphalt: Ongoing Repairs 59,100 Sq. Ft. Parking Lot (3%)	4,922	5	2	5,171	1,034	2,953	4,036	0.18%	795
424 - Asphalt: Major Repairs 59,100 Sq. Ft. Parking Lot	302,887	25	20	496,316	19,853	60,578	74,510	3.41%	15,255
808 - Striping Parking Lot	3,587	5	2	3,769	754	2,153	2,942	0.13%	579
Sub-total [01000 - Paving]	318,666			512,894	23,168	70,045	87,449	3.97%	17,802
02000 - Concrete									
904 - Miscellaneous 38,500 Sq. Ft. Community Center Concrete (2%)	12,628	5	2	13,267	2,653	7,577	10,355	0.46%	2,039
03000 - Painting: Exterior									
108 - Surface Restoration 27,500 Sq. Ft. Community Center Buildings	28,187	10	5	31,892	3,189	14,094	17,335	0.55%	2,451
400 - Wrought Iron 600 Lin. Ft. Pool Fence	5,535	4	4	6,110	1,222	1,107	1,418	0.21%	939
500 - Light Poles 14 Common Area Light Poles	2,655	4	1	2,721	680	1,991	2,721	0.12%	523
Sub-total [03000 - Painting: Exterior]	36,377			40,722	5,091	17,192	21,475	0.87%	3,912
03500 - Painting: Interior									
100 - Building 46,447 Sq. Ft. Community Center Interiors	47,608	10	5	53,864	5,386	23,804	29,279	0.92%	4,139
04000 - Structural Repairs									
356 - Garbage Enclosure Community Center Enclosure	1,538	5	2	1,615	323	923	1,261	0.06%	248
540 - Bridge Maintenance Community Center Bridge	5,125	10	5	5,798	580	2,563	3,152	0.10%	446
914 - Doors 45 Community Center Interior Doors (11%)	3,075	2	0	3,075	1,538	3,075	1,576	0.26%	1,181
Sub-total [04000 - Structural Repairs]	9,737			10,489	2,440	6,560	5,989	0.42%	1,875

2279 05/09/2014 06fsv4.5.74-543:jf.jf

**59** © Browning Reserve Group 2014 Version 4/8/2014 11:17:33 AM

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00010 - Community Center									
05000 - Roofing									
330 - Low Slope: Vinyl 178 Squares- Community Center Buildings	91,225	30	25	169,126	5,638	15,204	18,701	0.97%	4,332
688 - Pitched: Metal 95 Squares- Community Center Buildings	48,687	30	25	90,264	3,009	8,115	9,981	0.52%	2,312
700 - Gutters / Downspouts 335 Lin. Ft. Community Center Buildings	2,060	30	25	3,820	127	343	422	0.02%	98
Sub-total [05000 - Roofing]	141,973			263,210	8,774	23,662	29,104	1.50%	6,742
08000 - Rehab									
100 - General 2 C02 & Chlorine	3,075	15	10	3,936	262	1,025	1,261	0.05%	202
104 - General 8 Offices	28,700	20	15	41,566	2,078	7,175	8,825	0.36%	1,597
108 - General 2 First Aid & Lifeguard	3,075	20	15	4,454	223	769	946	0.04%	171
116 - General Stage Room	7,687	10	5	8,698	870	3,844	4,728	0.15%	668
124 - General 2 Classroom & Preschool	5,125	10	5	5,798	580	2,563	3,152	0.10%	446
222 - Bathrooms 2 Pool Area- Shower/Locker/Restrooms	10,250	20	15	14,845	742	2,563	3,152	0.13%	570
238 - Restrooms 2 Community Center Restrooms	6,150	10	5	6,958	696	3,075	3,782	0.12%	535
242 - Restrooms 2 Community Center Single Restrooms	3,075	10	5	3,479	348	1,538	1,891	0.06%	267
258 - Kitchen Pool Concession Room	3,075	20	15	4,454	223	769	946	0.04%	171
266 - Kitchen Kitchen	10,250	20	15	14,845	742	2,563	3,152	0.13%	570
380 - Tile 2 Outdoor Showers	1,025	10	5	1,160	116	513	630	0.02%	89
590 - Operable Wall/Partition 720 Sq. Ft. Stage Room	36,900	20	15	53,442	2,672	9,225	11,347	0.46%	2,053
Sub-total [08000 - Rehab]	118,387			163,635	9,552	35,619	43,811	1.64%	7,340

2279 05/09/2014 06fsv4.5.74-543:jf.jf
Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00010 - Community Center									
12000 - Pool									
110 - Resurface 375 Lin. Ft. Pool	30,750	12	7	36,552	3,046	12,813	15,759	0.52%	2,341
200 - Edge: Tile, Coping, Mastic 375 Lin. Ft. Pool	17,297	24	19	27,652	1,152	3,604	4,432	0.20%	885
210 - Tile: Lanes 734 Lin. Ft. Pool	22,570	12	7	26,829	2,236	9,404	11,567	0.38%	1,718
320 - Hand Rail / Ladder 6 Pool	7,380	24	19	11,798	492	1,538	1,891	0.08%	378
400 - ADA Chair Lift Pool Equipment Room	4,510	10	5	5,103	510	2,255	2,774	0.09%	392
700 - Equipment: Replacement Pool Eqpt Rm- Ultra Max	1,538	10	5	1,740	174	769	946	0.03%	134
704 - Equipment: Replacement Pool Eqpt Rm- Aquavac	1,025	10	5	1,160	116	513	630	0.02%	89
708 - Equipment: Replacement 2 Pool Equipment Room- Filters	5,125	10	5	5,798	580	2,563	3,152	0.10%	446
720 - Heater Pool Equipment Room	15,375	10	5	17,395	1,740	7,688	9,456	0.30%	1,337
740 - Pumps Pool Equipment Room- Pool Pump	2,050	8	3	2,208	276	1,281	1,576	0.05%	212
744 - Pumps Pool Equipment Room- Slide Pump	2,050	8	3	2,208	276	1,281	1,576	0.05%	212
748 - Pumps Pool Equipment Room- Feature Pump	2,050	8	3	2,208	276	1,281	1,576	0.05%	212
752 - Cover 7,425 Sq. Ft. Pool	7,611	5	1	7,801	1,560	6,089	7,801	0.27%	1,199
780 - Water Feature Pool Area Slide Structure	30,750	15	10	39,363	2,624	10,250	12,608	0.45%	2,016
800 - Solar System 30 Roof- Pool Solar System Panels	15,375	12	7	18,276	1,523	6,406	7,880	0.26%	1,170
950 - Furniture: Lifeguard Chair 4 Pool Area	8,200	10	5	9,278	928	4,100	5,043	0.16%	713
960 - Furniture: Misc Pool Furniture (Stored)	10,250	10	5	11,597	1,160	5,125	6,304	0.20%	891
990 - Miscellaneous Floating Racing Lanes	2,562	10	5	2,899	290	1,281	1,576	0.05%	223
Sub-total [12000 - Pool]	186,468			229,863	18,958	78,239	96,546	3.25%	14,567

Prepared for the 201	4/2015 Fiscal Year

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00010 - Community Center									
17500 - Basketball / Sport Court									
300 - Basketball Standard 6 Basketball Hoops	13,837	15	10	17,713	1,181	4,613	5,673	0.20%	907
680 - Scoreboard Gym	4,407	20	15	6,383	319	1,102	1,355	0.05%	245
Sub-total [17500 - Basketball / Sport Court]	18,245			24,097	1,500	5,714	7,029	0.26%	1,153
19000 - Fencing									
230 - Wrought Iron: 6' 600 Lin. Ft. Pool Fence	22,140	30	25	41,046	1,368	3,690	4,539	0.23%	1,051
20000 - Lighting									
300 - Common Area 17 Common Area Light Standards	26,137	20	15	37,855	1,893	6,534	8,037	0.32%	1,454
400 - Interior 24 Gym- Lighting	12,300	20	15	17,814	891	3,075	3,782	0.15%	684
900 - Miscellaneous RF Access Rm- Lighting Controller	25,625	20	15	37,113	1,856	6,406	7,880	0.32%	1,426
Sub-total [20000 - Lighting]	64,062			92,782	4,639	16,016	19,699	0.80%	3,565

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00010 - Community Center									
22000 - Office Equipment									
100 - Computers, Misc. Offices- Main Room- PC	1,538	10	5	1,740	174	769	946	0.03%	134
104 - Computers, Misc. Roof Access Room- PC	1,025	10	5	1,160	116	513	630	0.02%	89
108 - Computers, Misc. Offices- Receptionist- PC	1,538	10	5	1,740	174	769	946	0.03%	134
112 - Computers, Misc. Gym Building Electrical Room- Server	5,125	10	5	5,798	580	2,563	3,152	0.10%	446
116 - Computers, Misc. Offices- Main Room- PC	1,538	10	5	1,740	174	769	946	0.03%	134
120 - Computers, Misc. Offices- Receptionist- PC	1,538	10	5	1,740	174	769	946	0.03%	134
124 - Computers, Misc. Gym Building Electrical Room- Server	5,125	10	5	5,798	580	2,563	3,152	0.10%	446
128 - Computers, Misc. Gym Building Electrical Room- PC	1,538	10	5	1,740	174	769	946	0.03%	134
132 - Computers, Misc. Offices- Mary- PC	1,538	10	5	1,740	174	769	946	0.03%	134
136 - Computers, Misc. Offices- Kitchen/Workroom- Printer	769	10	5	870	87	384	473	0.01%	67
140 - Computers, Misc. Offices- Main Room- Shredder	1,538	10	5	1,740	174	769	946	0.03%	134
144 - Computers, Misc. Offices- Mary- Printer	769	10	5	870	87	384	473	0.01%	67
148 - Computers, Misc. Offices- Robert- PC	1,538	10	5	1,740	174	769	946	0.03%	134
152 - Computers, Misc. Offices- Robert- Printer	769	10	5	870	87	384	473	0.01%	67
156 - Computers, Misc. Offices- Office 1- PC	1,538	10	5	1,740	174	769	946	0.03%	134
160 - Computers, Misc. Offices- Office 1- Printer	769	10	5	870	87	384	473	0.01%	67
164 - Computers, Misc. Electrical Room- Server	30,750	10	5	34,791	3,479	15,375	18,911	0.60%	2,673
308 - Copier Offices- Kitchen/Workroom- Copier	3,587	10	5	4,059	406	1,794	2,206	0.07%	312
312 - Copier Offices- Main Room	3,587	10	5	4,059	406	1,794	2,206	0.07%	312
Sub-total [22000 - Office Equipment]	66,112			74,800	7,480	33,056	40,659	1.28%	5,748

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00010 - Community Center									
23000 - Mechanical Equipment									
240 - HVAC Roof- Trane: AC 1	10,250	15	10	13,121	875	3,417	4,203	0.15%	672
244 - HVAC Roof- Trane: AC 2, 3	20,500	15	10	26,242	1,749	6,833	8,405	0.30%	1,344
248 - HVAC Roof- Trane: AC 4, 5	20,500	15	10	26,242	1,749	6,833	8,405	0.30%	1,344
252 - HVAC Roof- Trane AC 6	10,250	15	10	13,121	875	3,417	4,203	0.15%	672
256 - HVAC Roof- Trane AC 7	10,250	15	10	13,121	875	3,417	4,203	0.15%	672
260 - HVAC Roof- Trane AC 8	10,250	15	10	13,121	875	3,417	4,203	0.15%	672
264 - HVAC Roof- Trane: AC 9	10,250	15	10	13,121	875	3,417	4,203	0.15%	672
268 - HVAC Roof- Trane: AC 10	10,250	15	10	13,121	875	3,417	4,203	0.15%	672
272 - HVAC Roof- AC-11	30,750	15	10	39,363	2,624	10,250	12,608	0.45%	2,016
276 - HVAC Roof- AC-12	30,750	15	10	39,363	2,624	10,250	12,608	0.45%	2,016
280 - HVAC Roof- Reznor Preeva Air Handler	10,250	15	10	13,121	875	3,417	4,203	0.15%	672
284 - HVAC Roof- Reznor Preeva Air Handler	10,250	15	10	13,121	875	3,417	4,203	0.15%	672
288 - HVAC Roof- Reznor Preeva Air Handler	10,250	15	10	13,121	875	3,417	4,203	0.15%	672
292 - HVAC Roof Carrier: HP-1	7,687	15	10	9,841	656	2,563	3,152	0.11%	504
296 - HVAC Roof Carrier: HP-2	7,687	15	10	9,841	656	2,563	3,152	0.11%	504
300 - HVAC Roof- Fujitsu	5,125	15	10	6,560	437	1,708	2,101	0.08%	336
612 - Water Heater Pool Storage/Water Heater Rm	5,637	12	7	6,701	558	2,349	2,889	0.10%	429
616 - Water Heater Kitchen Storage- Rheem	5,637	12	7	6,701	558	2,349	2,889	0.10%	429
620 - Water Heater Janitorial Room- Rheem	820	12	7	975	81	342	420	0.01%	62
Sub-total [23000 - Mechanical Equipment]	227,345			289,915	19,567	76,790	94,451	3.36%	15,035

Prepared to	or the 2014	1/2015 I	Fiscal Year
-------------	-------------	----------	-------------

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00010 - Community Center									
24000 - Furnishings									
104 - Miscellaneous Social Room Furnishings	5,125	10	5	5,798	580	2,563	3,152	0.10%	446
192 - Chairs 93 Community Center Folding Chairs	4,766	15	10	6,101	407	1,589	1,954	0.07%	313
196 - Chairs 270 Community Center Stackable Chairs	17,989	20	15	26,053	1,303	4,497	5,532	0.22%	1,001
204 - Chairs 9 Office Task Chairs	4,612	10	5	5,219	522	2,306	2,837	0.09%	401
334 - Tables 47 Community Center Folding Tables	9,635	20	15	13,954	698	2,409	2,963	0.12%	536
644 - Modular Office Desk 8 Office Desks	19,680	20	15	28,503	1,425	4,920	6,052	0.24%	1,095
Sub-total [24000 - Furnishings]	61,807			85,628	4,934	18,283	22,489	0.85%	3,791
24500 - Audio / Visual									
112 - Television, Large Screen Social Room	3,075	10	5	3,479	348	1,538	1,891	0.06%	267
300 - PA System Roof Access Room- QSC Mixer	2,562	10	5	2,899	290	1,281	1,576	0.05%	223
304 - PA System 3 Roof Access Room- Speakers & Stands	2,306	10	5	2,609	261	1,153	1,418	0.04%	200
Sub-total [24500 - Audio / Visual]	7,944			8,988	899	3,972	4,885	0.15%	691
24600 - Safety / Access									
900 - Miscellaneous Stage Room- Handicap Lift	10,250	15	10	13,121	875	3,417	4,203	0.15%	672
25000 - Flooring									
200 - Carpeting 189 Sq. Yds. Community Center Offices	6,199	10	5	7,014	701	3,100	3,813	0.12%	539
400 - Tile 9,333 Sq. Ft. Restrooms, Concession, Kitchen	57,398	20	15	83,129	4,156	14,349	17,650	0.71%	3,194
600 - Vinyl 1,106 Sq. Yds. Community Center Vinyl Tile	29,475	20	15	42,688	2,134	7,369	9,064	0.37%	1,640
700 - Hardwood Floors 7,257 Sq. Ft. Yoga Room & Gym	44,631	15	10	57,131	3,809	14,877	18,299	0.65%	2,927
920 - Coatings 1,063 Sq. Ft. Community Center Concrete Floors	6,537	12	7	7,771	648	2,724	3,350	0.11%	498
Sub-total [25000 - Flooring]	144,240			197,733	11,449	42,419	52,175	1.96%	8,797

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00010 - Community Center									
25500 - Wallcoverings									
300 - FRP 1,951 Sq. Ft. Community Center	11,999	20	15	17,378	869	3,000	3,690	0.15%	668
26000 - Outdoor Equipment									
050 - Flag Pole Community Center	4,100	20	15	5,938	297	1,025	1,261	0.05%	228
300 - Picnic Table: Wood 2 Pool Area	820	15	10	1,050	70	273	336	0.01%	54
332 - Benches 2 Common Area	1,230	20	15	1,781	89	308	378	0.02%	68
336 - Picnic Table: Metal 8 Pool Area	6,970	20	15	10,095	505	1,743	2,143	0.09%	388
380 - Garbage Receptacles 14 Common Area & Pool	2,870	20	15	4,157	208	718	883	0.04%	160
430 - Bleachers 3 Gym- Wood & Metal Bleachers	10,762	20	15	15,587	779	2,691	3,309	0.13%	599
844 - Shade Structure 12 Portable Shade Structures	6,765	10	5	7,654	765	3,383	4,160	0.13%	588
Sub-total [26000 - Outdoor Equipment]	33,517			46,262	2,713	10,139	12,471	0.47%	2,085

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00010 - Community Center									
27000 - Appliances									
200 - Refrigerator Pool Maintenance Room	513	7	2	538	77	366	450	0.01%	59
204 - Refrigerator Offices- Kitchen/Workroom	1,025	10	5	1,160	116	513	630	0.02%	89
224 - Refrigerator: Commercial: Large Kitchen- Fridge	4,100	20	15	5,938	297	1,025	1,261	0.05%	228
240 - Freezer: Large Kitchen- Fridge/Freezer Combo	4,100	20	15	5,938	297	1,025	1,261	0.05%	228
270 - Stove / Oven: Commercial grade 6-burner Kitchen	4,612	20	15	6,680	334	1,153	1,418	0.06%	257
278 - Oven: Wall Kitchen- Double Oven	3,587	20	15	5,196	260	897	1,103	0.04%	200
282 - Microwave Oven Offices- Kitchen/Workroom	410	10	4	453	45	246	294	0.01%	35
290 - Microwave Oven Kitchen- Panasonic	871	10	5	986	99	436	536	0.02%	76
298 - Stove: Exhaust Hood w/ Fan Kitchen- Greencheck Hood	3,075	20	15	4,454	223	769	946	0.04%	171
320 - Dishwasher, Commercial Kitchen- Hobart	4,305	10	5	4,871	487	2,153	2,648	0.08%	374
940 - Drinking Fountain Community Center Entry	2,562	20	15	3,711	186	641	788	0.03%	143
950 - Point of Sale Computer Pool Maintenance Room	2,050	6	1	2,101	350	1,708	2,101	0.06%	269
954 - Point of Sale Computer Pool Concession Room	2,050	6	1	2,101	350	1,708	2,101	0.06%	269
992 - Garbage Disposal Kitchen- Savajor	1,538	10	5	1,740	174	769	946	0.03%	134
Sub-total [27000 - Appliances]	34,799			45,866	3,294	13,407	16,483	0.56%	2,531

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00010 - Community Center									
30000 - Miscellaneous									
806 - Maintenance Equipment Riding Mower	11,651	20	19	18,626	931	583	1,194	0.16%	716
810 - Maintenance Equipment Kitchen Changing Room- Grout Cleaner	1,230	15	10	1,575	105	410	504	0.02%	81
818 - Maintenance Equipment Roof Access Room- Floor Scrubber	5,637	5	0	5,637	1,128	5,638	1,156	0.19%	866
822 - Maintenance Equipment Pool Eqpt Rm- Pressure Washer	1,025	10	5	1,160	116	513	630	0.02%	89
830 - Maintenance Equipment Roof Access Room- Floor Buffer	1,538	5	0	1,538	308	1,538	315	0.05%	236
Sub-total [30000 - Miscellaneous]	21,081			28,535	2,587	8,680	3,800	0.44%	1,988
Sub-total Community Center	1,595,388			2,254,095	138,197	501,280	610,579	23.70%	106,190
00030 - Cameron Park Lake									
01000 - Paving									
108 - Asphalt: Sealing 5,911 Sq. Ft. Drives & Parking	727	5	2	764	153	436	596	0.03%	117
208 - Asphalt: Ongoing Repairs 56,911 Sq. Ft. Drives & Parking (2%)	3,792	5	2	3,984	797	2,275	3,109	0.14%	612
408 - Asphalt: Major Repairs 56,911 Sq. Ft. Drives & Parking (50%)	145,834	20	9	182,127	9,106	80,209	89,688	1.56%	6,997
800 - Striping 98 Parking Stalls	1,507	5	2	1,583	317	904	1,236	0.05%	243
Sub-total [01000 - Paving]	151,860			188,458	10,372	83,824	94,629	1.78%	7,970
02000 - Concrete									
208 - Walkways 12,350 Sq. Ft. Walkways, Pads, & Slabs (2%)	4,051	5	2	4,256	851	2,430	3,322	0.15%	654

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00030 - Cameron Park Lake									
03000 - Painting: Exterior									
104 - Surface Restoration 1,140 Sq. Ft. Guard Shack & [3] Wood Sheds	1,169	5	1	1,198	240	935	1,198	0.04%	184
112 - Surface Restoration 3,680 Sq. Ft. Corporate Yard House	3,772	5	0	3,772	754	3,772	773	0.13%	580
116 - Surface Restoration 1,036 Sq. Ft. Concession Building	1,062	5	3	1,144	229	425	653	0.04%	176
120 - Surface Restoration 1,950 Sq. Ft. Gazebo Painting	1,999	5	3	2,152	430	800	1,229	0.07%	331
408 - Railings 186 Lin. Ft. Concrete Footbridge Railings	1,525	4	2	1,602	401	763	1,172	0.07%	308
412 - Railings 80 Lin. Ft. Lake Observation Deck	656	4	0	656	164	656	168	0.03%	126
420 - Wrought Iron Gates 2 Park Entrance Gates	1,025	4	0	1,025	256	1,025	263	0.04%	197
504 - Light Poles 32 Park Light Poles	6,068	4	1	6,220	1,555	4,551	6,220	0.27%	1,195
Sub-total [03000 - Painting: Exterior]	17,275			17,769	4,029	12,926	11,676	0.69%	3,096
03500 - Painting: Interior									
400 - Restrooms 1,904 Sq. Ft. Concession Building	1,952	10	4	2,154	215	1,171	1,400	0.04%	166
04000 - Structural Repairs									
200 - Wood: Siding & Trim 3,680 Sq. Ft. Corporate Yard House (10%)	7,544	10	0	7,544	754	7,544	773	0.13%	580
550 - Bridge Maintenance 1,313 Sq. Ft. [3] Pedestrian Bridges (10%)	6,729	5	3	7,247	1,449	2,692	4,138	0.25%	1,114
658 - Decking 800 Sq. Ft. Lake Observation Deck	20,500	20	9	25,602	1,280	11,275	12,608	0.22%	984
828 - Dock Floatation [2] Docks & [10] Barges	5,125	10	4	5,657	566	3,075	3,677	0.10%	435
Sub-total [04000 - Structural Repairs]	39,898			46,049	4,049	24,586	21,196	0.69%	3,112

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00030 - Cameron Park Lake									
05000 - Roofing									
448 - Pitched: Dimensional Composition 36 Squares- Corporate Yard House	14,760	25	9	18,433	737	9,446	10,288	0.13%	567
452 - Pitched: Dimensional Composition 44 Squares- Concession, Gazebo, [3] Small Bldgs	18,040	25	11	23,670	947	10,102	11,095	0.16%	728
704 - Gutters / Downspouts 184 Lin. Ft. Concession Building Gutters	1,132	25	11	1,485	59	634	696	0.01%	46
708 - Gutters / Downspouts 400 Lin. Ft. Corporate Yard House	2,460	25	9	3,072	123	1,574	1,715	0.02%	94
Sub-total [05000 - Roofing]	36,392			46,660	1,866	21,757	23,793	0.32%	1,434
08000 - Rehab									
234 - Restrooms 2 Concession Building	6,150	20	9	7,681	384	3,383	3,782	0.07%	295
254 - Kitchen Concession Building	3,075	20	9	3,840	192	1,691	1,891	0.03%	148
Sub-total [08000 - Rehab]	9,225			11,521	576	5,074	5,673	0.10%	443
11000 - Gate Equipment									
910 - Vehicle Gate Replacement 2 Park Entrance Gates	3,075	20	9	3,840	192	1,691	1,891	0.03%	148
17000 - Tennis Court									
100 - Reseal 28,600 Sq. Ft. [4] Tennis Courts	14,657	7	3	15,785	2,255	8,376	10,731	0.39%	1,733
500 - Resurface 28,600 [4] Tennis Courts	43,972	21	16	65,277	3,108	10,470	12,878	0.53%	2,389
Sub-total [17000 - Tennis Court]	58,630			81,062	5,363	18,845	23,609	0.92%	4,121
18000 - Landscaping									
112 - Irrigation: Controllers Shed	1,025	10	4	1,131	113	615	735	0.02%	87
344 - Irrigation: Pumps 25 GPM Well	5,125	5	2	5,384	1,077	3,075	4,203	0.18%	827
478 - Pathways & Trails 59,910 Sq. Ft. Lake Perimeter- DG Path (10%)	30,704	10	4	33,891	3,389	18,422	22,030	0.58%	2,604
Sub-total [18000 - Landscaping]	36,854			40,407	4,579	22,112	26,968	0.79%	3,519

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00030 - Cameron Park Lake									
18500 - Lakes / Ponds									
300 - Pumps / Mechanical 10 GPM Well	10,250	10	4	11,314	1,131	6,150	7,354	0.19%	869
320 - Filter 5 Filters- Lake & Lagoon	12,812	10	4	14,143	1,414	7,688	9,193	0.24%	1,087
990 - Miscellaneous 300 Lin. Ft. Dam/Spillway (5%)	7,687	5	3	8,279	1,656	3,075	4,728	0.28%	1,272
Sub-total [18500 - Lakes / Ponds]	30,750			33,735	4,201	16,913	21,275	0.72%	3,228
19000 - Fencing									
104 - Chain Link: 4 1,644 Lin. Ft. Lake Perimeter Fencing	18,536	30	19	29,633	988	6,797	7,600	0.17%	759
128 - Chain Link: 6' 21 Lin. Ft. Boat Rental Shack	258	30	19	413	14	95	106	0.00%	11
132 - Chain Link: 6' 6,877 Lin. Ft. Park Perimeter Fencing (20%)	16,917	6	2	17,774	2,962	11,278	14,450	0.51%	2,276
352 - Wood: 6' 80 Lin. Ft. Enclosure	2,050	18	14	2,897	161	456	584	0.03%	124
356 - Wood: 6' 555 Lin. Ft. Corporate Yard Perimeter	14,222	18	8	17,328	963	7,901	8,908	0.17%	740
522 - Post & Cable 902 Lin. Ft. Park Post & Chain Fencing	18,491	25	14	26,127	1,045	8,136	9,098	0.18%	803
Sub-total [19000 - Fencing]	70,475			94,171	6,133	34,662	40,746	1.05%	4,712
19500 - Retaining Wall									
120 - Wood: 1' 125 Lin. Ft. Park Entrance	4,484	20	9	5,600	280	2,466	2,758	0.05%	215
124 - Wood: 2' 80 Lin. Ft. Enclosure	4,920	18	14	6,952	386	1,093	1,401	0.07%	297
Sub-total [19500 - Retaining Wall]	9,404			12,552	666	3,560	4,159	0.11%	512
20000 - Lighting									
216 - Pole Lights 32 Park & Lagoon (9%)	3,690	5	2	3,877	775	2,214	3,026	0.13%	596
21000 - Signage									
778 - Wood Monument Park Entrance	1,538	5	3	1,656	331	615	946	0.06%	254
23000 - Mechanical Equipment	_		_						
232 - HVAC Concession Roof	5,125	15	7	6,092	406	2,733	3,152	0.07%	312

2279 05/09/2014 06fsv4.5.74-543:jf.jf Version 4/8/2014 11:17:33 AM © *Browning Reserve Group 2014* 

Prenared	for the	2014/2015	Fiscal Yea

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00030 - Cameron Park Lake									
26000 - Outdoor Equipment									
104 - Tot Lot: Play Equipment Play Area- 4-Swing Set	7,687	20	9	9,601	480	4,228	4,728	0.08%	369
108 - Tot Lot: Play Equipment Play Area- Large Structure	35,875	20	9	44,803	2,240	19,731	22,063	0.38%	1,721
124 - Tot Lot: Play Equipment Play Area- 2-Swing Set	5,125	20	9	6,400	320	2,819	3,152	0.05%	246
144 - Tot Lot: Safety Surface 10,000 Sq. Ft. Play Area	2,562	3	1	2,627	876	1,708	2,627	0.15%	673
200 - Pedestal Grill BBQ 11 Park Barbecues	3,382	20	9	4,224	211	1,860	2,080	0.04%	162
280 - Picnic Tables 50 Park Picnic Tables	30,750	20	9	38,403	1,920	16,913	18,911	0.33%	1,475
328 - Benches 25 Park Benches	15,375	20	9	19,201	960	8,456	9,456	0.16%	738
392 - Garbage Receptacles 40 Park Trash Cans	8,200	20	9	10,241	512	4,510	5,043	0.09%	393
492 - Drinking Fountain Park Tennis Courts	2,460	20	9	3,072	154	1,353	1,513	0.03%	118
Sub-total [26000 - Outdoor Equipment]	111,417			138,572	7,673	61,579	69,572	1.32%	5,896

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00030 - Cameron Park Lake									
30000 - Miscellaneous									
700 - Tools Compressor	2,562	10	6	2,972	297	1,025	1,313	0.05%	228
704 - Tools Grinder/Sander	1,538	10	4	1,697	170	923	1,103	0.03%	130
708 - Tools Bench Grinder	1,025	10	4	1,131	113	615	735	0.02%	87
712 - Tools Bench Grinder	1,025	10	4	1,131	113	615	735	0.02%	87
716 - Tools Drill Press	1,538	10	4	1,697	170	923	1,103	0.03%	130
814 - Maintenance Equipment Woods RM500	3,587	20	4	3,960	198	2,870	3,126	0.03%	152
826 - Maintenance Equipment Vermeer 1230 Chipper	51,250	20	14	72,415	3,621	15,375	18,386	0.62%	2,782
834 - Tractor Massey Ferguson 1525	20,500	20	14	28,966	1,448	6,150	7,354	0.25%	1,113
838 - Vehicle Dodge 2500 V8- Lic 1101411	21,525	10	0	21,525	2,153	21,525	2,206	0.37%	1,654
846 - Vehicle Ford Expedition- Lic 1011647	51,250	10	4	56,570	5,657	30,750	36,772	0.97%	4,347
850 - Vehicle 2008 Ford F150 XL- Lic 1273235	25,625	10	5	28,992	2,899	12,813	15,759	0.50%	2,228
854 - Vehicle Dodge Pick Up P-01- Lic 1088018	15,375	10	4	16,971	1,697	9,225	11,032	0.29%	1,304
866 - Vehicle Ford Bronco- Lic E041782	21,525	10	1	22,063	2,206	19,373	22,063	0.38%	1,695
894 - Trailer PacWest 20'- Lic. E946571	5,125	15	9	6,400	427	2,050	2,451	0.07%	328
898 - Trailer Carson 20'- Lic. 1108445	4,100	15	8	4,995	333	1,913	2,241	0.06%	256
902 - Trailer 11' Trailer- Lic. E323108	2,562	15	7	3,046	203	1,367	1,576	0.03%	156
906 - Trailer 15' Trailer	3,075	15	6	3,566	238	1,845	2,101	0.04%	183
910 - Trailer 12' Trailer- Lic. 4LF5474	7,175	15	9	8,961	597	2,870	3,432	0.10%	459
914 - Trailer 2003 Vintage Trailer- Lic 1152569	7,687	15	5	8,698	580	5,125	5,778	0.10%	446
918 - Trailer BBQ Trailer	4,100	15	7	4,874	325	2,187	2,522	0.06%	250
Sub-total [30000 - Miscellaneous]	252,150			300,631	23,445	139,537	141,791	4.02%	18,015

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00030 - Cameron Park Lake									
Sub-total Cameron Park Lake	843,760			1,033,463	75,725	456,229	498,824	12.99%	58,186
00040 - Rasmussen Park									
01000 - Paving									
112 - Asphalt: Sealing 27,200 Sq. Ft. Parking Lot	3,346	5	2	3,515	703	2,007	2,743	0.12%	540
212 - Asphalt: Ongoing Repairs 27,200 Sq. Ft. Parking Lot (2%)	1,812	5	2	1,904	381	1,087	1,486	0.07%	293
412 - Asphalt: Major Repairs 27,200 Sq. Ft. Parking Lot	139,400	25	14	196,969	7,879	61,336	68,585	1.35%	6,054
804 - Striping Parking Lot	1,538	5	2	1,615	323	923	1,261	0.06%	248
Sub-total [01000 - Paving]	146,095			204,003	9,286	65,353	74,075	1.59%	7,135
02000 - Concrete									
212 - Walkways 5,610 Sq. Ft. Park Walkways (2%)	1,840	5	2	1,933	387	1,104	1,509	0.07%	297
03000 - Painting: Exterior									
350 - Touch-Up 3 Park Buildings	1,538	5	1	1,576	315	1,230	1,576	0.05%	242
03500 - Painting: Interior									
408 - Restrooms 1,104 Sq. Ft. Concession Building Restrooms	1,132	10	4	1,249	125	679	812	0.02%	96
04000 - Structural Repairs									
554 - Bridge Maintenance Park Pedestrian Bridge	2,562	20	9	3,200	160	1,409	1,576	0.03%	123
05000 - Roofing									
460 - Pitched: Dimensional Composition 3 Squares- Maint. Bldg & Wood Shed	1,230	25	14	1,738	70	541	605	0.01%	53
684 - Pitched: Metal 6 Squares- Concession Building	3,075	30	19	4,916	164	1,128	1,261	0.03%	126
864 - Skylights 2 Concession Building Restrooms	820	20	9	1,024	51	451	504	0.01%	39
Sub-total [05000 - Roofing]	5,125			7,678	285	2,120	2,370	0.05%	219

D	C Ll	2014	/201F	F11	V
Prepared	for the	2014	/2015	Fiscai	rear

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00040 - Rasmussen Park									
08000 - Rehab									
246 - Restrooms 2 Concession Stand Restrooms	3,075	20	9	3,840	192	1,691	1,891	0.03%	148
250 - Kitchen Concession Stand Interior	3,075	20	9	3,840	192	1,691	1,891	0.03%	148
Sub-total [08000 - Rehab]	6,150			7,681	384	3,383	3,782	0.07%	295
18000 - Landscaping									
104 - Irrigation: Misc. Park Irrigation	1,025	3	1	1,051	350	683	1,051	0.06%	269
340 - Irrigation: Pumps Park- Irrigation Pump	1,230	5	2	1,292	258	738	1,009	0.04%	199
420 - General Repairs/Upgrades Park	1,025	3	1	1,051	350	683	1,051	0.06%	269
474 - Pathways & Trails 15,570 Sq. Ft. Park- Walking Path (10%)	7,980	5	2	8,384	1,677	4,788	6,543	0.29%	1,288
498 - Bedding Header 252 Lin. Ft. South Play Area	775	20	9	968	48	426	477	0.01%	37
Sub-total [18000 - Landscaping]	12,035			12,745	2,684	7,319	10,130	0.46%	2,062
19000 - Fencing									
100 - Chain Link 36 Lin. Ft. Tee Ball Field 5' Chain Link	406	30	28	810	27	27	42	0.00%	21
116 - Chain Link 1,850 Lin. Ft. Ball Fields- 5' Chain Link	20,859	30	14	29,473	982	11,125	12,115	0.17%	755
124 - Chain Link: 6' 170 Lin. Ft. Tee Ball Field	2,091	30	28	4,175	139	139	214	0.02%	107
140 - Chain Link: 6' 332 Lin. Ft. North Play Area Perimeter	4,084	30	14	5,770	192	2,178	2,372	0.03%	148
144 - Chain Link: 8' 65 Lin. Ft. Tee Ball Field	933	30	28	1,862	62	62	96	0.01%	48
148 - Chain Link: 8' 400 Lin. Ft. Ball Fields	5,740	30	14	8,110	270	3,061	3,334	0.05%	208
152 - Chain Link 150 Lin. Ft. Ball Field Back Stops	3,844	30	14	5,431	181	2,050	2,233	0.03%	139
344 - Wood: 6' 885 Lin. Ft. East & West Perimeter	22,678	18	8	27,631	1,535	12,599	14,205	0.26%	1,180
514 - Post & Cable 730 Lin. Ft. Parking Perimeter	14,965	25	14	21,145	846	6,585	7,363	0.15%	650
540 - Metal 980 Lin. Ft. South Perimeter- Post & Wire	10,045	25	14	14,193	568	4,420	4,942	0.10%	436
Sub-total [19000 - Fencing]	85,644			118,601	4,803	42,246	46,916	0.82%	3,691

2279 05/09/2014 06fsv4.5.74-543:jf.jf

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00040 - Rasmussen Park									
19500 - Retaining Wall									
364 - Masonry Wall 332 Lin. Ft. North Play Area	13,612	30	19	21,761	725	4,991	5,581	0.12%	557
21000 - Signage									
794 - Wood Monument Park Sign	2,562	10	4	2,829	283	1,538	1,839	0.05%	217
25000 - Flooring									
404 - Tile 224 Sq. Ft. Concession Building Restrooms	1,378	20	9	1,720	86	758	847	0.01%	66
26000 - Outdoor Equipment									
100 - Tot Lot: Play Equipment North Play Area	25,625	20	14	36,207	1,810	7,688	9,193	0.31%	1,391
120 - Tot Lot: Play Equipment South Play Area	10,250	20	14	14,483	724	3,075	3,677	0.12%	556
140 - Tot Lot: Safety Surface 10,410 Sq. Ft. North & South Play Areas	2,668	3	1	2,734	911	1,778	2,734	0.16%	700
294 - Picnic Table: Cement 2 Park Picnic Tables	1,025	20	9	1,280	64	564	630	0.01%	49
304 - Picnic Table: Wood 2 Park Picnic Tables	820	15	7	975	65	437	504	0.01%	50
312 - Benches 6 Park- Metal Benches	3,690	20	9	4,608	230	2,030	2,269	0.04%	177
320 - Benches 6 Park- Wood Benches	3,690	12	5	4,175	348	2,153	2,522	0.06%	267
380 - Pet Stations 4 Park	1,066	15	7	1,267	84	569	656	0.01%	65
384 - Garbage Receptacles 6 Park- Trash Cans	1,230	20	9	1,536	77	677	756	0.01%	59
440 - Bleachers: Aluminum 4 Ball Field Bleachers	12,300	20	9	15,361	768	6,765	7,565	0.13%	590
484 - Drinking Fountain Park- Drinking Fountain	2,460	20	9	3,072	154	1,353	1,513	0.03%	118
840 - Shade Structure 1,240 Sq. Ft. North Play Area	6,355	20	11	8,338	417	2,860	3,257	0.07%	320
Sub-total [26000 - Outdoor Equipment]	71,179			94,037	5,653	29,947	35,276	0.97%	4,344
Sub-total Rasmussen Park	350,851			479,013	25,175	162,075	186,289	4.32%	19,345

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00050 - Christa McAuliffe Park	·								
01000 - Paving									
116 - Asphalt: Sealing 18,563 Sq. Ft. Parking Lot	2,283	5	1	2,340	468	1,827	2,340	0.08%	360
216 - Asphalt: Ongoing Repairs 18,563 Sq. Ft. Parking Lot (2%)	1,237	5	1	1,268	254	989	1,268	0.04%	195
416 - Asphalt: Major Repairs 18,563 Sq. Ft. Parking Lot	95,135	25	14	134,424	5,377	41,860	46,807	0.92%	4,132
Sub-total [01000 - Paving]	98,655			138,032	6,099	44,676	50,415	1.05%	4,686
02000 - Concrete									
216 - Walkways 2,720 Sq. Ft. Park Walkways (3%)	1,338	5	2	1,406	281	803	1,097	0.05%	216
900 - Miscellaneous 16,000 Sq. Ft. Skate Park Concrete (10%)	32,800	10	4	36,205	3,621	19,680	23,534	0.62%	2,782
Sub-total [02000 - Concrete]	34,138			37,611	3,902	20,483	24,631	0.67%	2,998
03000 - Painting: Exterior									
404 - Wrought Iron 490 Lin. Ft. Play Area Perimeter	4,520	4	1	4,633	1,158	3,390	4,633	0.20%	890
03500 - Painting: Interior									
404 - Restrooms 1,216 Sq. Ft. Restroom Building	1,246	10	4	1,376	138	748	894	0.02%	106
04000 - Structural Repairs									
994 - Miscellaneous 300 Sq. Ft. Decorative Wall Resurfacing	6,150	20	14	8,690	434	1,845	2,206	0.07%	334
05000 - Roofing									
440 - Pitched: Dimensional Composition 5 Squares- Restroom Building	2,050	25	14	2,897	116	902	1,009	0.02%	89
456 - Pitched: Dimensional Composition Skate Park Building	410	25	4	453	18	344	370	0.00%	14
Sub-total [05000 - Roofing]	2,460			3,349	134	1,246	1,378	0.02%	103
08000 - Rehab									
112 - General Skate Park Building	1,538	10	1	1,576	158	1,384	1,576	0.03%	121
230 - Restrooms Restroom Building	2,050	10	1	2,101	210	1,845	2,101	0.04%	161
Sub-total [08000 - Rehab]	3,588			3,677	368	3,229	3,677	0.06%	283

Prepared for the	2014/2015 Fiscal Year

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00050 - Christa McAuliffe Park									
19000 - Fencing									
108 - Chain Link: 4' 855 Lin. Ft. North Perimeter	9,640	30	19	15,411	514	3,535	3,952	0.09%	395
120 - Chain Link: 6' 1,190 Lin. Ft. South & East Perimeter	14,637	30	19	23,399	780	5,367	6,001	0.13%	599
136 - Chain Link: 6' 260 Lin. Ft. Skate Park Perimeter	3,198	30	19	5,112	170	1,173	1,311	0.03%	131
220 - Wrought Iron: 4' 490 Lin. Ft. Play Area Perimeter	15,067	30	19	24,088	803	5,525	6,178	0.14%	617
360 - Wood: 6' 395 Lin. Ft. West Perimeter Fence	10,122	18	8	12,333	685	5,623	6,340	0.12%	526
518 - Post & Cable 525 Lin. Ft. Parking Lot Perimeter (No Cable)	10,762	25	9	13,441	538	6,888	7,501	0.09%	413
Sub-total [19000 - Fencing]	63,427			93,784	3,490	28,110	31,284	0.60%	2,682
19500 - Retaining Wall									
360 - Masonry Wall 490 Lin. Ft. Play Area Perimeter	20,090	30	19	32,117	1,071	7,366	8,237	0.18%	823
21000 - Signage									
790 - Wood Monument Park Monument Sign	2,562	10	4	2,829	283	1,538	1,839	0.05%	217
26000 - Outdoor Equipment									
112 - Tot Lot: Play Equipment Park Large Play Structure	30,750	20	13	42,389	2,119	10,763	12,608	0.36%	1,629
116 - Tot Lot: Play Equipment 2 Park- Smaller Structures	15,375	20	13	21,195	1,060	5,381	6,304	0.18%	814
284 - Picnic Tables 5 Park Picnic Tables	3,075	20	9	3,840	192	1,691	1,891	0.03%	148
324 - Benches 10 Park Metal Benches	7,175	20	14	10,138	507	2,153	2,574	0.09%	390
396 - Garbage Receptacles 10 Park Trash Cans	2,050	20	9	2,560	128	1,128	1,261	0.02%	98
488 - Drinking Fountain 3 Park Drinking Fountains	7,380	20	9	9,217	461	4,059	4,539	0.08%	354
Sub-total [26000 - Outdoor Equipment]	65,805			89,339	4,467	25,174	29,176	0.77%	3,432
Sub-total Christa McAuliffe Park	302,642			415,437	21,542	137,805	158,371	3.69%	16,553

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00060 - Chardi Corner									
18000 - Landscaping									
116 - Irrigation: Controllers Chardi Corner- Irrigation Controller	1,025	10	4	1,131	113	615	735	0.02%	87
300 - Irrigation: Backflow Preventors Chardi Corner- Backflow Prevention Device	615	20	9	768	38	338	378	0.01%	30
424 - General Repairs/Upgrades Chardi Corner	1,025	3	1	1,051	350	683	1,051	0.06%	269
Sub-total [18000 - Landscaping]	2,665			2,950	502	1,637	2,164	0.09%	386
19000 - Fencing									
348 - Wood: 6' 300 Lin. Ft. Chardi Corner- Perimeter Fencing  19500 - Retaining Wall	7,687	18	8	9,366	520	4,271	4,815	0.09%	400
368 - Masonry Wall 380 Lin. Ft. Chardi Corner- Perimeter Wall	15,580	30	19	24,907	830	5,713	6,388	0.14%	638
20000 - Lighting									
220 - Landscape 3 Chardi Corner- Sign Lights	1,230	12	5	1,392	116	718	841	0.02%	89
21000 - Signage									
782 - Monument 35 Lin. Ft. Chardi Corner- Monument Sign (25%)	2,242	5	3	2,415	483	897	1,379	0.08%	371
26000 - Outdoor Equipment									
064 - Flag Pole Chardi Corner- Flag Pole	4,100	20	9	5,120	256	2,255	2,522	0.04%	197
Sub-total Chardi Corner	33,505			46,150	2,707	15,489	18,108	0.46%	2,080
00070 - Hacienda Park									
01000 - Paving									
120 - Asphalt: Sealing 4,500 Sq. Ft. Hacienda- Parking Lot	554	5	2	582	116	332	454	0.02%	89
220 - Asphalt: Ongoing Repairs 4,500 Sq. Ft. Hacienda Parking Lot (3%)	450	5	2	472	94	270	369	0.02%	73
420 - Asphalt: Major Repairs 4,500 Sq. Ft. Hacienda- Parking Lot	23,062	25	14	32,587	1,303	10,148	11,347	0.22%	1,002
Sub-total [01000 - Paving]	24,066			33,641	1,514	10,749	12,169	0.26%	1,164
02000 - Concrete									
380 - Pad 462 Sq. Ft. [5] Concrete Slabs (10%)	947	10	2	995	100	758	874	0.02%	76

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00070 - Hacienda Park									
04000 - Structural Repairs									
998 - Miscellaneous Park- Shed- Upkeep	513	5	3	552	110	205	315	0.02%	85
18000 - Landscaping									
100 - Irrigation: Misc. Park	1,025	3	0	1,025	342	1,025	350	0.06%	263
450 - Drainage System Maint. Deer Creek Tributary	2,050	3	1	2,101	700	1,367	2,101	0.12%	538
470 - Pathways & Trails 29,465 Sq. Ft. Park- DG Paths (20%)	30,202	10	4	33,337	3,334	18,121	21,670	0.57%	2,562
494 - Bedding Header 420 Lin. Ft. Turf Perimeter	1,292	20	14	1,825	91	387	463	0.02%	70
500 - Tree Maintenance Park- Scrub & Heritage Oaks	5,125	5	2	5,384	1,077	3,075	4,203	0.18%	827
Sub-total [18000 - Landscaping]	39,693			43,673	5,544	23,975	28,787	0.95%	4,260
19000 - Fencing									
112 - Chain Link: 4' 100 Lin. Ft. Creek Perimeter	1,128	20	9	1,408	70	620	693	0.01%	54
364 - Wood: Split Rail 765 Lin. Ft. Park Perimeter	11,762	20	14	16,619	831	3,529	4,220	0.14%	639
510 - Post & Cable 26 Parking Lot Posts (50%)	1,333	10	4	1,471	147	800	956	0.03%	113
Sub-total [19000 - Fencing]	14,222			19,498	1,048	4,948	5,869	0.18%	806
21000 - Signage									
798 - Wood Monument Park Sign	1,025	10	6	1,189	119	410	525	0.02%	91
26000 - Outdoor Equipment									
290 - Picnic Table: Cement 3 Park- Picnic Tables	2,306	20	14	3,259	163	692	827	0.03%	125
316 - Benches Park Bench	615	20	14	869	43	185	221	0.01%	33
376 - Pet Stations Park- Pet Station	267	15	9	333	22	107	127	0.00%	17
388 - Garbage Receptacles 2 Park- Trash Cans	410	20	14	579	29	123	147	0.00%	22
480 - Drinking Fountain Park- Drinking Fountain	2,460	20	14	3,476	174	738	883	0.03%	134
Sub-total [26000 - Outdoor Equipment]	6,058			8,516	431	1,844	2,205	0.07%	331

2279 05/09/2014 06fsv4.5.74-543:jf.jf
Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00070 - Hacienda Park									
Sub-total Hacienda Park	86,523			108,063	8,867	42,889	50,745	1.52%	6,813
00188 - Station 88									
01000 - Paving									
100 - Asphalt: Sealing 3,950 Sq. Ft. Parking Lot- Seal & Stripe	972	5	4	1,073	215	194	398	0.04%	165
200 - Asphalt: Ongoing Repairs 3,950 Sq. Ft. Parking Lot (5%)	658	10	4	726	73	395	472	0.01%	56
400 - Asphalt: Major Repairs 3,950 Sq. Ft. Parking Lot (50%)	8,097	25	17	12,321	493	2,591	2,988	0.08%	379
Sub-total [01000 - Paving]	9,727			14,120	780	3,180	3,858	0.13%	599
02000 - Concrete									
200 - Sidewalks, Curbs & Gutters 2,400 Sq. Ft. Exterior Concrete (3%)	1,181	5	2	1,241	248	708	968	0.04%	191
710 - Sealing 1,225 Sq. Ft. Vehicle Bays- Concrete Floors	2,700	5	2	2,836	567	1,620	2,214	0.10%	436
Sub-total [02000 - Concrete]	3,880			4,077	815	2,328	3,182	0.14%	627
03000 - Painting: Exterior									
100 - Surface Restoration 360 Sq. Ft. Patio Shed- Paint & Repair	1,107	5	2	1,163	233	664	908	0.04%	179
310 - Trim 825 Sq. Ft. Station 88- Wood Trim	846	5	2	888	178	507	693	0.03%	137
Sub-total [03000 - Painting: Exterior]	1,953			2,051	410	1,172	1,601	0.07%	315
03500 - Painting: Interior									
110 - Building 7,122 Sq. Ft. Station 88- Interior Spaces	7,300	10	4	8,058	806	4,380	5,238	0.14%	619
04000 - Structural Repairs									
364 - Garbage Enclosure Parking Area	1,538	10	4	1,697	170	923	1,103	0.03%	130
910 - Doors 11 Station 88- Interior & Exterior Doors	6,765	20	9	8,449	422	3,721	4,160	0.07%	325
Sub-total [04000 - Structural Repairs]	8,302			10,146	592	4,643	5,264	0.10%	455

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00188 - Station 88									
05000 - Roofing									
444 - Pitched: Dimensional Composition 36 Squares- Station 88	14,760	25	15	21,377	855	5,904	6,657	0.15%	657
712 - Gutters / Downspouts 110 Lin. Ft. Station 88	677	25	15	980	39	271	305	0.01%	30
860 - Skylights 2 Lobby & Lounge	820	25	15	1,188	48	328	370	0.01%	37
Sub-total [05000 - Roofing]	16,256			23,544	942	6,503	7,332	0.16%	724
08000 - Rehab									
120 - General 2 Quarters	2,050	10	4	2,263	226	1,230	1,471	0.04%	174
210 - Bathrooms 2 Bathroom & Restroom	3,075	10	1	3,152	315	2,768	3,152	0.05%	242
214 - Kitchen Kitchen	2,050	20	1	2,101	105	1,948	2,101	0.02%	81
Sub-total [08000 - Rehab]	7,175			7,516	647	5,945	6,724	0.11%	497
14000 - Recreation									
200 - Exercise: Treadmill Vehicle Bays	2,050	10	4	2,263	226	1,230	1,471	0.04%	174
204 - Exercise: Miscellaneous Equip. Vehicle Bays: Weights & Rack	3,075	15	7	3,655	244	1,640	1,891	0.04%	187
Sub-total [14000 - Recreation]	5,125			5,918	470	2,870	3,362	0.08%	361
20000 - Lighting									
104 - Exterior: Misc. Fixtures 8 Building & Landscape Lights	2,050	15	9	2,560	171	820	981	0.03%	131
540 - Parking Lot Parking Lot Light	2,255	25	14	3,186	127	992	1,109	0.02%	98
Sub-total [20000 - Lighting]	4,305			5,746	298	1,812	2,090	0.05%	229
21000 - Signage									
786 - Wood Monument Station 88 Entrance	1,025	10	0	1,025	103	1,025	105	0.02%	79

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00188 - Station 88									
22000 - Office Equipment									
200 - Computers, Misc. Lobby	2,050	6	3	2,208	368	1,025	1,401	0.06%	283
204 - Computers, Misc. Mulit-Quarters Laptop	1,538	6	2	1,615	269	1,025	1,313	0.05%	207
208 - Computers, Misc. Mulit-Quarters PC Workstation	1,538	6	2	1,615	269	1,025	1,313	0.05%	207
300 - Copier Lobby	1,538	6	2	1,615	269	1,025	1,313	0.05%	207
Sub-total [22000 - Office Equipment]	6,663			7,054	1,176	4,100	5,341	0.20%	903
23000 - Mechanical Equipment									
200 - HVAC Patio Area HVAC	5,125	15	4	5,657	377	3,758	4,203	0.06%	290
600 - Water Heater Water Heater Closet	820	12	5	928	77	478	560	0.01%	59
Sub-total [23000 - Mechanical Equipment]	5,945			6,585	454	4,237	4,763	0.08%	349
24000 - Furnishings									
100 - Miscellaneous Lobby Additional Furnishings	5,125	20	9	6,400	320	2,819	3,152	0.05%	246
200 - Bar Stools 2 Lounge Barstools	513	15	9	640	43	205	245	0.01%	33
212 - Chairs 4 Station 88 Task Chairs	1,025	10	5	1,160	116	513	630	0.02%	89
228 - Chairs 3 Lounge Recliners	1,538	20	6	1,783	89	1,076	1,182	0.02%	69
640 - Modular Office Desk 3 Station 88 Office Desks	3,075	20	9	3,840	192	1,691	1,891	0.03%	148
910 - Window Coverings 8 Station 88- Window Blinds	4,100	15	9	5,120	341	1,640	1,961	0.06%	262
Sub-total [24000 - Furnishings]	15,375			18,944	1,101	7,944	9,062	0.19%	846
24600 - Safety / Access									
340 - Defibrillators Lobby	2,562	5	2	2,692	538	1,538	2,101	0.09%	414

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00188 - Station 88									
25000 - Flooring									
210 - Carpeting 87 Sq. Yds. Station 88- Carpeting	2,854	10	3	3,073	307	1,998	2,340	0.05%	236
410 - Tile 362 Sq. Ft. Bathroom, Restroom, & Lobby	2,226	20	1	2,282	114	2,115	2,282	0.02%	88
610 - Vinyl 15 Sq. Yds. Kitchen- Linoleum	400	20	1	410	20	380	410	0.00%	16
Sub-total [25000 - Flooring]	5,480			5,765	442	4,492	5,032	0.08%	340
26000 - Outdoor Equipment									
060 - Flag Pole Station 88 Entrance	4,100	20	14	5,793	290	1,230	1,471	0.05%	223
210 - Barbecue Patio Barbecue	615	8	4	679	85	308	394	0.01%	65
350 - Furniture 8 Patio Furniture Items	2,050	10	4	2,263	226	1,230	1,471	0.04%	174
Sub-total [26000 - Outdoor Equipment]	6,765			8,735	601	2,768	3,336	0.10%	462
27000 - Appliances									
208 - Refrigerator Kitchen	1,025	7	3	1,104	158	586	750	0.03%	121
248 - Ice Machine Vehicle Bays- Hoshizaki	2,050	10	5	2,319	232	1,025	1,261	0.04%	178
266 - 4-Burner Stove & Oven Kitchen	1,845	7	1	1,891	270	1,581	1,891	0.05%	208
302 - Stove: Exhaust Hood w/ Fan Kitchen	2,665	20	9	3,328	166	1,466	1,639	0.03%	128
306 - Dishwasher Kitchen	1,025	10	4	1,131	113	615	735	0.02%	87
410 - Washer Vehicle Bay	1,538	10	5	1,740	174	769	946	0.03%	134
414 - Dryer Vehicle Bay	1,845	10	5	2,087	209	923	1,135	0.04%	160
Sub-total [27000 - Appliances]	11,992			13,601	1,322	6,964	8,357	0.23%	1,016

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00188 - Station 88									
30000 - Miscellaneous									
270 - Garage Door: Metal 2 Vehicle Bay Doors	10,250	20	9	12,801	640	5,638	6,304	0.11%	492
842 - Vehicle E 88 Lic 1206288	597,017	15	5	675,470	45,031	398,012	448,758	7.72%	34,602
858 - Vehicle E 288 Lic 1375275	479,216	15	12	644,492	42,966	95,843	130,986	7.37%	33,015
898 - Vehicle U 88 Lic 127543	35,321	15	11	46,345	3,090	9,419	12,068	0.53%	2,374
Sub-total [30000 - Miscellaneous]	1,121,805			1,379,109	91,727	508,911	598,116	15.73%	70,483
Sub-total Station 88	1,241,636			1,524,685	103,224	574,811	674,862	17.70%	79,317
00189 - Station 89									
01000 - Paving									
104 - Asphalt: Sealing 20,899 Sq. Ft. Parking Lot- Seal & Stripe	3,280	5	4	3,621	724	656	1,345	0.12%	556
204 - Asphalt: Ongoing Repairs 20,899 Sq. Ft. Parking Lot (10%)	6,962	10	4	7,685	768	4,177	4,995	0.13%	590
404 - Asphalt: Major Repairs 20,899 Sq. Ft. Parking Lot (50%)	53,554	25	15	77,562	3,102	21,421	24,153	0.53%	2,384
Sub-total [01000 - Paving]	63,796			88,867	4,595	26,255	30,493	0.79%	3,531
02000 - Concrete									
204 - Sidewalks, Curbs & Gutters 8,840 Sq. Ft. Exterior Concrete (3%)	4,349	5	2	4,569	914	2,610	3,566	0.16%	702
714 - Sealing 5,016 Sq. Ft. Vehicle Bays- Concrete Floors	11,054	5	0	11,054	2,211	11,054	2,266	0.38%	1,699
Sub-total [02000 - Concrete]	15,403			15,623	3,125	13,664	5,832	0.54%	2,401
03000 - Painting: Exterior									
124 - Surface Restoration 8,500 Lin. Ft. Station 89	8,712	10	4	9,617	962	5,228	6,251	0.16%	739
416 - Railings 90 Lin. Ft. Balcony & Stairs	738	4	1	756	189	554	756	0.03%	145
920 - Miscellaneous Sheds, Wrought Iron, & Touch-Up	3,587	5	0	3,587	718	3,588	735	0.12%	551
Sub-total [03000 - Painting: Exterior]	13,038			13,961	1,868	9,369	7,743	0.32%	1,436
03500 - Painting: Interior									
120 - Building 24,962 Sq. Ft. Station 89 Interior Painting	25,586	10	4	28,242	2,824	15,352	18,358	0.48%	2,170

2279 05/09/2014 06fsv4.5.74-543:jf.jf

85 © Browning Reserve Group 2014 Version 4/8/2014 11:17:33 AM

Prepared	for the 2	014/2015	Fiscal Year
riepareu	OI LITE 2		1 13001 1 00

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00189 - Station 89									
04000 - Structural Repairs									
360 - Garbage Enclosure Station 89- Enclosure	2,562	10	4	2,829	283	1,538	1,839	0.05%	217
920 - Doors 31 Station 89 Interior & Exterior Doors	19,065	15	5	21,570	1,438	12,710	14,331	0.25%	1,105
990 - Miscellaneous 4 Wood Sheds	2,050	10	5	2,319	232	1,025	1,261	0.04%	178
Sub-total [04000 - Structural Repairs]	23,677			26,718	1,953	15,273	17,430	0.33%	1,501
04500 - Decking/Balconies									
110 - Concrete 375 Sq. Ft. South Side Building (25%)	1,441	10	4	1,591	159	865	1,034	0.03%	122
500 - Railing: Wrought Iron 90 Lin. Ft. Balcony & Stair Railings	3,136	20	10	4,015	201	1,568	1,768	0.03%	154
Sub-total [04500 - Decking/Balconies]	4,578			5,606	360	2,433	2,802	0.06%	277
05000 - Roofing									
334 - Low Slope: Vinyl 48 Squares- Station 89 Flat Roofing	24,600	20	10	31,490	1,575	12,300	13,868	0.27%	1,210
680 - Pitched: Metal 31 Squares- Station 89 Metal Roof	15,887	30	20	26,034	868	5,296	5,971	0.15%	667
720 - Gutters / Downspouts 210 Lin. Ft. Station 89	1,292	30	20	2,116	71	431	485	0.01%	54
Sub-total [05000 - Roofing]	41,779			59,640	2,513	18,026	20,325	0.43%	1,931

2279 05/09/2014 06fsv4.5.74-543:jf.jf
Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

Prepared for the 2014/2015 Fiscal Year
--

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00189 - Station 89									
08000 - Rehab									
128 - General 4 Dormitory Rooms	8,200	20	10	10,497	525	4,100	4,623	0.09%	403
132 - General Work Room	2,562	20	10	3,280	164	1,281	1,445	0.03%	126
136 - General 3 Offices	6,150	20	10	7,873	394	3,075	3,467	0.07%	302
140 - General Reception	2,562	20	10	3,280	164	1,281	1,445	0.03%	126
218 - Bathrooms 2 Upstairs Bathrooms	6,150	20	2	6,461	323	5,535	5,989	0.06%	248
226 - Bathrooms 2 Downstairs Restrooms	4,100	20	10	5,248	262	2,050	2,311	0.05%	202
262 - Kitchen Coffee Room	1,538	20	10	1,968	98	769	867	0.02%	76
270 - Kitchen Kitchen	3,075	20	19	4,916	246	154	315	0.04%	189
274 - Laundry Room Upstairs Laundry	1,538	20	19	2,458	123	77	158	0.02%	94
Sub-total [08000 - Rehab]	35,875			45,981	2,299	18,322	20,619	0.39%	1,767
14000 - Recreation									
220 - Exercise: Treadmill Weight Room	2,050	10	4	2,263	226	1,230	1,471	0.04%	174
224 - Exercise: Cardio Equipment Weight Room Elliptical	1,845	10	4	2,037	204	1,107	1,324	0.03%	156
228 - Exercise: Weight Machine Weight Room	3,587	20	10	4,592	230	1,794	2,022	0.04%	176
232 - Exercise: Miscellaneous Equip. Weight Room Tuff Stuff Rack	1,538	20	10	1,968	98	769	867	0.02%	76
236 - Exercise: Miscellaneous Equip. Weight Room Dumbbells & Rack	3,075	15	9	3,840	256	1,230	1,471	0.04%	197
Sub-total [14000 - Recreation]	12,095			14,700	1,014	6,130	7,155	0.17%	779
18000 - Landscaping									
108 - Irrigation: Misc. Backflows, Controllers, Valves	1,025	5	1	1,051	210	820	1,051	0.04%	161
482 - Pathways & Trails 520 Sq. Ft. DG Walking Path	2,665	5	1	2,732	546	2,132	2,732	0.09%	420
Sub-total [18000 - Landscaping]	3,690			3,782	756	2,952	3,782	0.13%	581

2279 05/09/2014 06fsv4.5.74-543:jf.jf
Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

Reserve Component	Current Repl. Cost	Useful Life	Remaining	Estimated Future Replacement	Per	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year	2014/2015 Line Item Contribution based on Cash Flow Method
Reserve Component	Repl. Cost	Lire	Life	Costs	Year	Dalatice	Dalatice	Straight Line	Cash Flow Method
00189 - Station 89									
19000 - Fencing									
310 - Wood: 3' 50 Lin. Ft. Northeast Perimeter	769	18	1	788	44	726	788	0.01%	34
340 - Wood: 6' 895 Lin. Ft. Perimeter Fencing	22,934	18	3	24,698	1,372	19,112	20,896	0.24%	1,054
Sub-total [19000 - Fencing]	23,703			25,486	1,416	19,838	21,684	0.24%	1,088
19500 - Retaining Wall									
372 - Masonry Wall Maintenance 225 Lin. Ft. Keystone Retaining Wall (25%)	1,441	10	4	1,591	159	865	1,034	0.03%	122
20000 - Lighting									
100 - Exterior: Misc. Fixtures 21 Station 89- Exterior Building Lights	5,381	20	10	6,888	344	2,691	3,034	0.06%	265
420 - Interior 72 Station 89 Interior Lighting (50%)	7,380	20	10	9,447	472	3,690	4,160	0.08%	363
424 - Interior 6 Station 89 Ceiling Fans	1,230	15	8	1,499	100	574	672	0.02%	77
Sub-total [20000 - Lighting]	13,991			17,834	917	6,955	7,867	0.16%	704
21000 - Signage									
774 - Wood Monument 2 Station 89 Signs	3,075	15	0	3,075	205	3,075	210	0.04%	158

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00189 - Station 89									
22000 - Office Equipment									
212 - Computers, Misc. Reception Dell PC Workstation #3101	1,025	6	1	1,051	175	854	1,051	0.03%	135
216 - Computers, Misc. Reception Dell PC Workstation #3102	1,025	6	1	1,051	175	854	1,051	0.03%	135
220 - Computers, Misc. Reception Gateway PC Workstation #3092	1,025	6	0	1,025	171	1,025	175	0.03%	131
224 - Computers, Misc. Reception Brother Printer	1,025	6	0	1,025	171	1,025	175	0.03%	131
228 - Computers, Misc. Station Captains Office	1,025	6	4	1,131	189	342	525	0.03%	145
232 - Computers, Misc. Station Captain's Office- Shredder	1,230	10	4	1,358	136	738	883	0.02%	104
236 - Computers, Misc. Station Captain's Office- Printer	513	6	2	538	90	342	438	0.02%	69
240 - Computers, Misc. Work Room- Fax	1,333	10	4	1,471	147	800	956	0.03%	113
244 - Computers, Misc. Work Room- Shredder	1,128	10	4	1,245	124	677	809	0.02%	96
248 - Computers, Misc. Equipment Room- UPS 1500	1,538	6	2	1,615	269	1,025	1,313	0.05%	207
252 - Computers, Misc. Equipment Room- Power Connect 2724	5,125	6	2	5,384	897	3,417	4,378	0.15%	690
256 - Computers, Misc. Equipment Room- Surge Protector	1,025	6	2	1,077	179	683	876	0.03%	138
260 - Computers, Misc. Equipment Room- Poweredge 2900	5,125	6	2	5,384	897	3,417	4,378	0.15%	690
264 - Computers, Misc. Fire Prevention Office	1,025	6	0	1,025	171	1,025	175	0.03%	131
268 - Computers, Misc. Fire Prevention Office- Shredder	1,230	6	2	1,292	215	820	1,051	0.04%	165
272 - Computers, Misc. Battalion Chief's Office	1,025	6	4	1,131	189	342	525	0.03%	145
304 - Copier Work Room- Copier	3,587	10	4	3,960	396	2,153	2,574	0.07%	304
360 - Telephone Equipment Equipment Room- Phone System	4,612	6	2	4,846	808	3,075	3,940	0.14%	621
364 - Telephone Equipment Equipment Room- Integration Hub	4,612	6	2	4,846	808	3,075	3,940	0.14%	621
368 - Telephone Equipment Equipment Room- Phone System	4,612	6	2	4,846	808	3,075	3,940	0.14%	621
Sub-total [22000 - Office Equipment]	42,845			45,302	7,015	28,762	33,151	1.20%	5,390

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00189 - Station 89									
23000 - Mechanical Equipment									
204 - HVAC Roof- AC-1	10,250	15	7	12,184	812	5,467	6,304	0.14%	624
208 - HVAC Roof- AC-2	10,250	15	7	12,184	812	5,467	6,304	0.14%	624
212 - Fan Roof- Ventilation Fan	4,612	20	10	5,904	295	2,306	2,600	0.05%	227
216 - Fan Roof- Captive Aire Systems, Supply	4,100	20	10	5,248	262	2,050	2,311	0.05%	202
220 - Fan Roof- Captive Aire Systems, Exhaust	4,100	20	10	5,248	262	2,050	2,311	0.05%	202
224 - Swamp Cooler Roof- Evaporative Air Cooler	5,125	20	10	6,560	328	2,563	2,889	0.06%	252
228 - Swamp Cooler Roof- Evaporative Air Cooler	5,125	20	10	6,560	328	2,563	2,889	0.06%	252
330 - Fuel Tank 2 Parking Area Fueling Tanks	15,375	30	20	25,194	840	5,125	5,778	0.14%	645
580 - Cooling Tower Roof- REF-1	3,587	20	10	4,592	230	1,794	2,022	0.04%	176
604 - Water Heater Upstairs Closet	820	12	7	975	81	342	420	0.01%	62
608 - Water Heater Mechanic's Bay	820	12	0	820	68	820	70	0.01%	53
Sub-total [23000 - Mechanical Equipment]	64,165			85,471	4,320	30,545	33,900	0.74%	3,319

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00189 - Station 89									
24000 - Furnishings									
208 - Chairs 9 Station 89 Task Chairs	2,306	10	2	2,423	242	1,845	2,128	0.04%	186
216 - Chairs 10 Station 89 Wood/Cloth Chairs	769	15	8	937	62	359	420	0.01%	48
220 - Chairs 15 Station 89 Stackable Chairs	1,153	20	3	1,242	62	980	1,064	0.01%	48
224 - Chairs 46 Station 89 Folding Chairs	3,536	20	10	4,527	226	1,768	1,994	0.04%	174
232 - Chairs 6 Lounge- Recliners	3,075	10	4	3,394	339	1,845	2,206	0.06%	261
310 - Tables: Dining: Large Lounge & Kitchen	1,025	20	10	1,312	66	513	578	0.01%	50
330 - Tables 17 Station 89 Folding Tables	1,743	20	10	2,231	112	871	982	0.02%	86
650 - Modular Office Desk 5 Station 89 Office Desks	5,125	20	10	6,560	328	2,563	2,889	0.06%	252
880 - Security Deposit Boxes Station Captain's Office Lockbox	513	12	5	580	48	299	350	0.01%	37
884 - Security Deposit Boxes Station Captain's Office Safe	2,562	20	10	3,280	164	1,281	1,445	0.03%	126
920 - Window Coverings 19 Station 89 Window Blinds	9,737	15	5	11,017	734	6,492	7,319	0.13%	564
Sub-total [24000 - Furnishings]	31,544			37,503	2,385	18,815	21,375	0.41%	1,832
24500 - Audio / Visual									
100 - Television Weight Room	1,538	10	4	1,697	170	923	1,103	0.03%	130
200 - DVD Player Storage (Conference)- Sony DVD	513	6	2	538	90	342	438	0.02%	69
204 - DVD Player Storage (Conference)- Toshiba DVD	513	6	2	538	90	342	438	0.02%	69
308 - PA System Equipment Room- Amplifier	769	10	4	849	85	461	552	0.01%	65
312 - PA System Conference Room- Podium	2,562	10	4	2,829	283	1,538	1,839	0.05%	217
316 - PA System Conference Room- Projector	3,587	6	2	3,769	628	2,392	3,064	0.11%	483
Sub-total [24500 - Audio / Visual]	9,481			10,220	1,345	5,996	7,433	0.23%	1,034

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00189 - Station 89									
24600 - Safety / Access									
120 - Fire Control Misc Building Alarm & Extinguishers	5,125	10	4	5,657	566	3,075	3,677	0.10%	435
350 - Defibrillators Lobby	2,562	5	2	2,692	538	1,538	2,101	0.09%	414
Sub-total [24600 - Safety / Access]	7,687			8,349	1,104	4,613	5,778	0.19%	848
25000 - Flooring									
220 - Carpeting 262 Sq. Yds. Station 89 Interior Carpeting	8,594	10	4	9,486	949	5,156	6,166	0.16%	729
420 - Tile 2,543 Sq. Ft. Station 89 Floor & Wall Tile	15,639	20	10	20,020	1,001	7,820	8,817	0.17%	769
620 - Vinyl 50 Sq. Yds. Bathroom Vinyl Tile	1,333	20	10	1,706	85	666	751	0.01%	66
624 - Vinyl 166 Sq. Yds. Station 89 Wood Laminate Flooring	5,104	20	10	6,534	327	2,552	2,878	0.06%	251
990 - Miscellaneous 27 Sq. Yds. Weight Room Rubber Flooring	830	15	9	1,037	69	332	397	0.01%	53
Sub-total [25000 - Flooring]	31,500			38,782	2,431	16,526	19,009	0.42%	1,868
26000 - Outdoor Equipment									
068 - Flag Pole Station 89- Flag Pole	5,637	30	20	9,238	308	1,879	2,119	0.05%	237
220 - Barbecue Balcony	513	8	3	552	69	320	394	0.01%	53
308 - Picnic Table: Wood Patio	410	15	8	500	33	191	224	0.01%	26
Sub-total [26000 - Outdoor Equipment]	6,560			10,289	410	2,391	2,737	0.07%	315

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00189 - Station 89									
27000 - Appliances									
220 - Refrigerator: Commercial: Large Kitchen	2,050	10	6	2,377	238	820	1,051	0.04%	183
244 - Freezer: Large Kitchen	820	10	6	951	95	328	420	0.02%	73
252 - Ice Machine Upstairs Closet- Ice-O-Matic	2,050	10	4	2,263	226	1,230	1,471	0.04%	174
256 - Ice Machine Mechanic's Bay- Manitowac	2,050	10	4	2,263	226	1,230	1,471	0.04%	174
260 - Stove Kitchen	3,587	12	8	4,371	364	1,196	1,532	0.06%	280
274 - Oven: Wall Kitchen	2,562	10	4	2,829	283	1,538	1,839	0.05%	217
286 - Microwave Oven Kitchen	615	10	4	679	68	369	441	0.01%	52
294 - Stove: Fire Suppression Kitchen	5,637	10	4	6,223	622	3,383	4,045	0.11%	478
310 - Dishwasher, Residential Type Kitchen	1,025	5	0	1,025	205	1,025	210	0.04%	158
418 - Washer: Large Mechanic's Bay- Washer/Extractor	12,300	10	4	13,577	1,358	7,380	8,825	0.23%	1,043
422 - Dryer Mechanic's Bay- Kenmore	1,025	10	4	1,131	113	615	735	0.02%	87
426 - Washer Upstairs Laundry	718	10	6	832	83	287	368	0.01%	64
430 - Dryer Upstairs Laundry	1,025	10	6	1,189	119	410	525	0.02%	91
684 - Miscellaneous Coffee Room- Coffee Maker	513	10	4	566	57	308	368	0.01%	43
984 - Miscellaneous Kitchen- Coffee Maker	513	10	4	566	57	308	368	0.01%	43
988 - Miscellaneous Kitchen- Coffee Grinder	256	10	4	283	28	154	184	0.00%	22
Sub-total [27000 - Appliances]	36,746			41,123	4,142	20,579	23,853	0.71%	3,183

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	Estimated Future Replacement Costs	Per Year	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	% Per Year Straight Line	2014/2015 Line Item Contribution based on Cash Flow Method
00189 - Station 89									
30000 - Miscellaneous									
266 - Garage Door: Metal 3 Station 89 Garage Bay Doors	15,375	20	19	24,579	1,229	769	1,576	0.21%	944
274 - Garage Door: Metal 4 Station 89 Garage Bay Doors- Rear	20,500	20	3	22,076	1,104	17,425	18,911	0.19%	848
870 - Vehicle B2715- Lic 1275433	39,737	10	6	46,083	4,608	15,895	20,365	0.79%	3,541
874 - Vehicle B2716 Lic 1275432	39,737	10	6	46,083	4,608	15,895	20,365	0.79%	3,541
878 - Vehicle E-89- Lic 1206287	597,017	15	1	611,943	40,796	557,216	611,943	7.00%	31,348
882 - Vehicle E-289- Lic E1109085	490,842	15	2	515,691	34,379	425,396	469,572	5.90%	26,417
886 - Vehicle E-389 Lic E000391	555,238	10	7	660,004	66,000	166,572	227,648	11.32%	50,714
890 - Vehicle U-89 Lic 1088016	45,491	15	3	48,988	3,266	36,392	40,411	0.56%	2,509
894 - Vehicle U-289 Lic 041782	39,563	15	2	41,566	2,771	34,288	37,849	0.48%	2,129
922 - Generator Building East Side- Generac Series	30,750	30	20	50,387	1,680	10,250	11,557	0.29%	1,291
Sub-total [30000 - Miscellaneous]	1,874,250			2,067,400	160,442	1,280,098	1,460,196	27.52%	123,282
Sub-total Station 89	2,386,508			2,695,547	207,597	1,566,830	1,772,765	35.61%	159,516
						[A]	[B]		
Totals	6,840,814			8,556,452	583,035	3,457,409	3,970,543	100.00%	448,000
						[EndBal]	[EndBal]		
						[A]	[B]		
Percent Funded						91.48%	75.29%		





Cameron Park Community Services District

# Component Listing Included Components

Fina

Prepared for the 2014/2015 Fiscal Year

00010 - Community Center

Summary

01000 - Paving

124 - Asphalt: Sealing Useful Life 5 Remaining Life 2

59,100 Sq. Ft. Parking Lot Quantity 59,100 Unit of Measure Square Feet

Cost /SqFt \$0.123

% Included 100.00% Total Cost/Study \$7,269

Replacement Year 2015/2016 Future Cost \$7,637

This is to prepare the surface and apply a single coat asphalt emulsion product. If a second coat is desired the cost is generally 10% to 20% higher. This component provides for the approximate 6,100 sq ft of pavement at

the Fire Station 89 recycling yard.



224 - Asphalt: Ongoing Repairs Useful Life 5 Remaining Life 2

59,100 Sq. Ft. Parking Lot (3%) Quantity 59,100 Unit of Measure Square Feet

Cost /SqFt \$3.33 Qty \* \$/SqFt \$196,877 % Included 2.50% Total Cost/Study \$4,922

Summary Replacement Year 2015/2016 Future Cost \$5,171

This is for miscellaneous repairs including crack fill, skin patching and minor dig out & fill. This component provides for the approximate 6,100 sq ft of pavement at the Fire Station 89 recycling yard.



01000 - Paving

424 - Asphalt: Major Repairs Useful Life 25 Remaining Life 20

59,100 Sq. Ft. Parking Lot Quantity 59,100 Unit of Measure Square Feet

Cost /SqFt \$5.12

% Included 100.00% Total Cost/Study \$302,887

Summary Replacement Year 2033/2034 Future Cost \$496,316

This is for major excavation, re-compaction and installation of new hot asphalt to selected areas. This component provides for the approximate 6,100 sq ft of pavement at the Fire Station 89 recycling yard.



808 - Striping Useful Life 5 Remaining Life 2

Parking Lot Quantity 1 Unit of Measure Lot

Cost /Lt \$3,587

% Included 100.00% Total Cost/Study \$3,587

Summary Replacement Year 2015/2016 Future Cost \$3,769

This is to re-stripe asphalt to match existing plan.



### 02000 - Concrete

904 - Miscellaneous Useful Life 5 Remaining Life 2

38,500 Sq. Ft. Community Center Quantity 38,500 Unit of Measure Square Feet Concrete (2%) Cost /SqFt \$16.40 Qty \* \$/SqFt \$631,400

% Included 2.00% Total Cost/Study \$12,628
Summary Replacement Year 2015/2016 Future Cost \$13,267

This is for miscellaneous concrete repair.



## 03000 - Painting: Exterior

108 - Surface Restoration Useful Life 10 Remaining Life 5

27,500 Sq. Ft. Community Center Buildings Quantity 27,500 Unit of Measure Square Feet

Cost /SqFt \$1.02

% Included 100.00% Total Cost/Study \$28,187

Summary Replacement Year 2018/2019 Future Cost \$31,892

This is to prepare, power wash, sand, scrape, caulk and paint with a 100% premium acrylic paint.



**00010 - Community Center 03000 - Painting: Exterior** 

400 - Wrought Iron Useful Life 4 Remaining Life 4

600 Lin. Ft. Pool Fence Quantity 600 Unit of Measure Linear Feet

Cost /l.f. \$9.22

% Included 100.00% Total Cost/Study \$5,535

Summary Replacement Year 2017/2018 Future Cost \$6,110

This is to prepare, power wash, sand, scrape, spot prime and paint the wrought iron.

2013/2014- work completed with volunteer labor. Cost of paint covered by operating.



500 - Light Poles Useful Life 4 Remaining Life 1

14 Common Area Light Poles Quantity 14 Unit of Measure Items

Cost /Itm \$190

% Included 100.00% Total Cost/Study \$2,655

Summary Replacement Year 2014/2015 Future Cost \$2,721

This is to prepare and paint the light poles.



## 03500 - Painting: Interior

100 - Building Useful Life 10 Remaining Life 5

46,447 Sq. Ft. Community Center Interiors Quantity 46,447 Unit of Measure Square Feet

Cost /SqFt \$1.02

% Included 100.00% Total Cost/Study \$47,608

Summary Replacement Year 2018/2019 Future Cost \$53,864

This is to prepare and paint all building interior spaces.



## 04000 - Structural Repairs

356 - Garbage Enclosure Useful Life 5 Remaining Life 2

Community Center Enclosure Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2015/2016 Future Cost \$1,615

This is for garbage enclosure repairs including walls, gates, hardware, concrete pad, paint, etc.



04000 - Structural Repairs

540 - Bridge Maintenance Useful Life 10 Remaining Life 5

Community Center Bridge Quantity 1 Unit of Measure Items

Cost /Itm \$5,125

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2018/2019 Future Cost \$5,798

This is to maintain the bridge.



914 - Doors Useful Life 2 Remaining Life 0

45 Community Center Interior Doors (11%) Quantity 45 Unit of Measure Items

Cost /Itm \$615 Qty \* \$/Itm \$27,675 % Included 11.11% Total Cost/Study \$3,075

Summary Replacement Year 2013/2014 Future Cost \$3,075

This is to repair, replace and maintain the doors.

2013/2014- per client, because of settling in the foundation increased replacement may soon be needed.

**05000 - Roofing** 

330 - Low Slope: Vinyl Useful Life 30 Remaining Life 25

178 Squares- Community Center Buildings Quantity 178 Unit of Measure Squares

Cost /Sqrs \$512

% Included 100.00% Total Cost/Study \$91,225

Summary Replacement Year 2038/2039 Future Cost \$169,126

This is to replace the low slope vinyl roofing with a similar type product.



05000 - Roofing

688 - Pitched: Metal Useful Life 30 Remaining Life 25

95 Squares- Community Center Buildings Quantity 95 Unit of Measure Squares

Cost /Sqrs \$512

% Included 100.00% Total Cost/Study \$48,687

Summary Replacement Year 2038/2039 Future Cost \$90,264

This is to replace the metal roofing system. With proper maintenance, this component's life may be extended.



700 - Gutters / Downspouts Useful Life 30 Remaining Life 25

335 Lin. Ft. Community Center Buildings Quantity 335 Unit of Measure Linear Feet

Cost /l.f. \$6.15

% Included 100.00% Total Cost/Study \$2,060

Summary Replacement Year 2038/2039 Future Cost \$3,820

This is to replace the gutters and downspouts.



08000 - Rehab

100 - General Useful Life 15 Remaining Life 10

2 CO2 & Chlorine Quantity 2 Unit of Measure Room

Cost /Rm \$1,537

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2023/2024 Future Cost \$3,936

This is for a general rehab of the pool chlorine and CO2 rooms. Includes basic provision for the 750 gallon CO2 tank, chlorine tank and associated pump.



104 - General Useful Life 20 Remaining Life 15

8 Offices Quantity 8 Unit of Measure Room

Cost /Rm \$3,587

% Included 100.00% Total Cost/Study \$28,700

Summary Replacement Year 2028/2029 Future Cost \$41,566

This is for a general rehab of the interior office spaces. Includes the storage office, receptionist, kitchen/workroom, the main central room, and four individual offices. Desks, task chairs, and PC workstations are

provided for in other components. District input will further define this component.



108 - General Useful Life 20 Remaining Life 15

2 First Aid & Lifeguard Quantity 2 Unit of Measure Room

Cost /Rm \$1,537

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2028/2029 Future Cost \$4,454

This is for a general rehab of the interiors. Includes 8 metal lockers, and 16 linear feet of counter. Painting and flooring are provided for in other components.

08000 - Rehab

116 - General Useful Life 10 Remaining Life 5

Stage Room Quantity 1 Unit of Measure Room

Cost /Rm \$7,687

% Included 100.00% Total Cost/Study \$7,687

Summary Replacement Year 2018/2019 Future Cost \$8,698

This is for a general rehab of the stage room interior. Items to include, curtains, stage, specialized lighting and

projectors.



124 - General Useful Life 10 Remaining Life 5

2 Classroom & Preschool Quantity 2 Unit of Measure Room

Cost /Rm \$2,562

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2018/2019 Future Cost \$5,798

This is for a general rehab of the interiors. Includes cabinets, countertops, lighting, windows, game tables, PC's,

and mini fridge.



08000 - Rehab

222 - Bathrooms Useful Life 20 Remaining Life 15

2 Pool Area- Shower/Locker/Restrooms Quantity 2 Unit of Measure Items

Cost /Itm \$5,125

% Included 100.00% Total Cost/Study \$10,250

Summary Replacement Year 2028/2029 Future Cost \$14,845

This is to rehab and redecorate the bathrooms. Includes items such as partitions, fixtures, lighting, ventilation, lockers, benches, drainage and decor. This item can be further defined with district input.



238 - Restrooms Useful Life 10 Remaining Life

2 Community Center Restrooms Quantity 2 Unit of Measure Items

Cost /Itm \$3,075

% Included 100.00% Total Cost/Study \$6,150

Summary Replacement Year 2018/2019 Future Cost \$6,958

This is to rehab and redecorate the restrooms. Includes items such as partitions, fixtures, lighting, ventilation and drainage. This item can be further defined with district input.



242 - Restrooms Useful Life 10 Remaining Life 5

2 Community Center Single Restrooms Quantity 2 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2018/2019 Future Cost \$3,479

This is to rehab and redecorate the restrooms. Includes items such as partitions, fixtures, lighting, ventilation and drainage. This item can be further defined with district input.

08000 - Rehab

258 - Kitchen Useful Life 20 Remaining Life 15

Pool Concession Room Quantity 1 Unit of Measure Room

Cost /Rm \$3,075

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2028/2029 Future Cost \$4,454

This is to rehab and redecorate the kitchen. Includes items such as cabinets, countertops, fixtures, lighting, etc. This item can be further defined with association input. Appliances, painting, and flooring are provided for within other components.

In 2012/2013, there is discussion of remodeling the concession room to facilitate access from the pool area. If major upgrade work is to take place, district input will further define this component.



266 - Kitchen Useful Life 20 Remaining Life 15

Kitchen Quantity 1 Unit of Measure Room

Cost /Rm \$10,250

% Included 100.00% Total Cost/Study \$10,250

Summary Replacement Year 2028/2029 Future Cost \$14,845

This is to rehab and redecorate the kitchen. Includes items such as cabinets, countertops, fixtures, lighting, etc. This item can be further defined with district input. Appliances, flooring and painting are provided for within other components.

52 linear feet stainless steel lower counter/shelf

30 linear feet stainless steel upper shelf

1- 5' x 4' roll up door



08000 - Rehab

380 - Tile Useful Life 10 Remaining Life 5

2 Outdoor Showers Quantity 2 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2018/2019 Future Cost \$1,160

This is for replacing the tile and fixtures per existing. Replacement costs will depend on the scope of work at replacement.

590 - Operable Wall/Partition Useful Life 20 Remaining Life 15

720 Sq. Ft. Stage Room Quantity 720 Unit of Measure Square Feet

Cost /SqFt \$51.25

% Included 100.00% Total Cost/Study \$36,900

Summary Replacement Year 2028/2029 Future Cost \$53,442

This is to replace the operable wall/partition.

### 12000 - Pool

110 - Resurface Useful Life 12 Remaining Life 7

375 Lin. Ft. Pool Quantity 375 Unit of Measure Linear Feet

Cost /l.f. \$82.00

% Included 100.00% Total Cost/Study \$30,750

Summary Replacement Year 2020/2021 Future Cost \$36,552

This is to resurface the pool including start-up costs.



12000 - Pool

200 - Edge: Tile, Coping, Mastic Useful Life 24 Remaining Life 19

375 Lin. Ft. Pool Quantity 375 Unit of Measure Linear Feet

Cost /l.f. \$46.12

% Included 100.00% Total Cost/Study \$17,297

Summary Replacement Year 2032/2033 Future Cost \$27,652

This is to replace the tile, coping and mastic in conjunction with every other resurfacing cycle.



210 - Tile: Lanes Useful Life 12 Remaining Life 7

734 Lin. Ft. Pool Quantity 734 Unit of Measure Linear Feet

Cost /l.f. \$30.75

% Included 100.00% Total Cost/Study \$22,570

Summary Replacement Year 2020/2021 Future Cost \$26,829

This is to remove and replace the existing 1' wide racing lanes in conjunction with the resurfacing project.



12000 - Pool

320 - Hand Rail / Ladder Useful Life 24 Remaining Life 19

6 Pool Quantity 6 Unit of Measure Items

Cost /Itm \$1,230

% Included 100.00% Total Cost/Study \$7,380

Summary Replacement Year 2032/2033 Future Cost \$11,798

This is to remove and replace the stainless steel pool handrail / ladder.



400 - ADA Chair Lift Useful Life 10 Remaining Life 5

Pool Equipment Room Quantity 1 Unit of Measure Items

Cost /Itm \$4,510

% Included 100.00% Total Cost/Study \$4,510

Summary Replacement Year 2018/2019 Future Cost \$5,103

This is to replace the pool's ADA compliant chair lift.

Linak
Item #: 343100+4L350020

Prod. Date: 2008/12/19 SO: 6032469

PO: 830934-0089



12000 - Pool

700 - Equipment: Replacement Useful Life 10 Remaining Life 5

Pool Egpt Rm- Ultra Max Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2018/2019 Future Cost \$1,740

This is to replace the Ultra-Max pool surface and tile cleaner.

Cameron Park CSD id #: 4112

PM#: A6010 A60106005308061090115036 DM#: A8523 A85232713121109011503



704 - Equipment: Replacement Useful Life 10 Remaining Life 5

Pool Egpt Rm- Aquavac Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2018/2019 Future Cost \$1,160

This is to replace the Hayward Aqua Vac Pro 30.



12000 - Pool

708 - Equipment: Replacement Useful Life 10 Remaining Life 5

2 Pool Equipment Room- Filters Quantity 2 Unit of Measure Items

Cost /Itm \$2,562

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2018/2019 Future Cost \$5,798

This is to replace the Paragon Aquatics pool filters by Pentair.



720 - Heater Useful Life 10 Remaining Life 5

Pool Equipment Room Quantity 1 Unit of Measure Items

Cost /Itm \$15,375

% Included 100.00% Total Cost/Study \$15,375

Summary Replacement Year 2018/2019 Future Cost \$17,395

This is to replace the pool water heater.

Pentair Water- Power Max Commercial Heater

Manufactured Date: Mar 04, 2009 Model Number: PM2000PACC2BXN Serial Number C 09 210558

National Board: 210558



12000 - Pool

740 - Pumps Useful Life 8 Remaining Life 3

Pool Equipment Room- Pool Pump Quantity 1 Unit of Measure Items

Cost /Itm \$2,050

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2016/2017 Future Cost \$2,208

This is to replace the pool pump.

Hostile Duty Premium Efficient 422683

Model #: S2930B Catalog #: H025P2BR



744 - Pumps Useful Life 8 Remaining Life 3

Pool Equipment Room- Slide Pump Quantity 1 Unit of Measure Items

Cost /Itm \$2,050

% Included 100.00% Total Cost/Study \$2,050

Replacement Year 2016/2017 Future Cost \$2,208

This is to replace the slide pump.

Sta-Rite Max-E-Pro pump model #: P6E6E-206L motor #: K48L2PA105C3 hp- 1

sq ft hp- 1.65

Summary



12000 - Pool

748 - Pumps Useful Life 8 Remaining Life 3

Pool Equipment Room- Feature Pump Quantity 1 Unit of Measure Items

Cost /Itm \$2,050

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2016/2017 Future Cost \$2,208

This is to replace the slide pump.

Sta-Rite Max-E-Pro pump model #: P6E6E-205L motor #: K48K2PA105C1 hp- .75 sq ft hp- 1.25



752 - Cover Useful Life 5 Remaining Life 1

7,425 Sq. Ft. Pool Quantity 7,425 Unit of Measure Square Feet

Cost /SqFt \$1.02

% Included 100.00% Total Cost/Study \$7,611

Summary Replacement Year 2014/2015 Future Cost \$7,801

This is to replace the pool cover. The cover should be properly cleaned and stored during non-use to ensure maximum life.



12000 - Pool

780 - Water Feature Useful Life 15 Remaining Life 10

Pool Area Slide Structure Quantity 1 Unit of Measure Items

Cost /Itm \$30,750

% Included 100.00% Total Cost/Study \$30,750

Summary Replacement Year 2023/2024 Future Cost \$39,363

This is to replace the pool area water slide structure.



800 - Solar System Useful Life 12 Remaining Life 7

30 Roof- Pool Solar System Panels Quantity 30 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$15,375

Summary Replacement Year 2020/2021 Future Cost \$18,276

This is to replace the solar panels and piping as needed.



12000 - Pool

950 - Furniture: Lifeguard Chair Useful Life 10 Remaining Life 5

4 Pool Area Quantity 4 Unit of Measure Items

Cost /Itm \$2,050

% Included 100.00% Total Cost/Study \$8,200

Summary Replacement Year 2018/2019 Future Cost \$9,278

This is to replace the lifeguard chair.



960 - Furniture: Misc Useful Life 10 Remaining Life 5

Pool Furniture (Stored) Quantity 1 Unit of Measure Lump Sum

Cost /LS \$10,250

% Included 100.00% Total Cost/Study \$10,250

Summary Replacement Year 2018/2019 Future Cost \$11,597

This is to replace miscellaneous pool furniture.



12000 - Pool

990 - Miscellaneous Useful Life 10 Remaining Life 5

Floating Racing Lanes Quantity 1 Unit of Measure Items

Cost /Itm \$2,562

% Included 100.00% Total Cost/Study \$2,562

Summary Replacement Year 2018/2019 Future Cost \$2,899

This is to replace the floating racing lanes and associated spool.



# 17500 - Basketball / Sport Court

300 - Basketball Standard Useful Life 15 Remaining Life 10

6 Basketball Hoops Quantity 6 Unit of Measure Items

Cost /Itm \$2,306

% Included 100.00% Total Cost/Study \$13,837

Summary Replacement Year 2023/2024 Future Cost \$17,713

This is to replace the basketball backboards and rims.



17500 - Basketball / Sport Court

680 - Scoreboard Useful Life 20 Remaining Life 15

Gym Quantity 1 Unit of Measure Items

Cost /Itm \$4,407

% Included 100.00% Total Cost/Study \$4,407

Summary Replacement Year 2028/2029 Future Cost \$6,383

This is to replace the electronic scoreboard.



19000 - Fencing

230 - Wrought Iron: 6' Useful Life 30 Remaining Life 25

600 Lin. Ft. Pool Fence Quantity 600 Unit of Measure Linear Feet

Cost /l.f. \$36.90

% Included 100.00% Total Cost/Study \$22,140

Summary Replacement Year 2038/2039 Future Cost \$41,046

This is to replace the 6' wrought iron fencing. With aggressive paint maintenance, this component's life may be extended. Painting is provided for within another component.



20000 - Lighting

300 - Common Area Useful Life 20 Remaining Life 15

17 Common Area Light Standards Quantity 17 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$26,137

Summary Replacement Year 2028/2029 Future Cost \$37,855

This is to replace common area lighting.

3- pool area

1- at pedestrian bridge

13- common and parking area



400 - Interior Useful Life 20 Remaining Life 15

24 Gym- Lighting Quantity 24 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$12,300

Summary Replacement Year 2028/2029 Future Cost \$17,814

This is to replace interior lighting.



### 20000 - Lighting

900 - Miscellaneous Useful Life 20 Remaining Life 15

RF Access Rm- Lighting Controller Quantity 1 Unit of Measure Items

Cost /Itm \$25,625

% Included 100.00% Total Cost/Study \$25,625

Summary Replacement Year 2028/2029 Future Cost \$37,113

This is to replace the Lehigh computerized lighting controller system. District input will further define this component.

serial #: 280640



# 22000 - Office Equipment

100 - Computers, Misc. Useful Life 10 Remaining Life 5

Offices- Main Room- PC Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2018/2019 Future Cost \$1,740

This is to replace the PC workstation in the main cubicle room of the offices.



22000 - Office Equipment

104 - Computers, Misc. Useful Life 10 Remaining Life 5

Roof Access Room- PC Quantity 1 Unit of Measure Lump Sum

Cost /LS \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2018/2019 Future Cost \$1,160

This is to replace the Dell Optiplex computer workstation.



108 - Computers, Misc. Useful Life 10 Remaining Life 5

Offices- Receptionist- PC Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2018/2019 Future Cost \$1,740

This is to replace the PC workstation in the receptionist area.

112 - Computers, Misc. Useful Life 10 Remaining Life 5

Gym Building Electrical Room- Server Quantity 1 Unit of Measure Items

Cost /Itm \$5,125

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2018/2019 Future Cost \$5,798

This is to replace the Dell Power Connect 2724.



22000 - Office Equipment

116 - Computers, Misc. Useful Life 10 Remaining Life 5

Offices- Main Room- PC Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2018/2019 Future Cost \$1,740

This is to replace the PC workstation in the main cubicle room of the offices.



120 - Computers, Misc. Useful Life 10 Remaining Life 5

Offices- Receptionist- PC Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2018/2019 Future Cost \$1,740

This is to replace the PC workstation in the receptionist area.



22000 - Office Equipment

124 - Computers, Misc. Useful Life 10 Remaining Life 5

Gym Building Electrical Room- Server Quantity 1 Unit of Measure Items

Cost /Itm \$5,125

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2018/2019 Future Cost \$5,798

This is to replace the Dell Power Connect 2824.



128 - Computers, Misc. Useful Life 10 Remaining Life 5

Gym Building Electrical Room- PC Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2018/2019 Future Cost \$1,740

This is to replace the Dell PC workstation.



22000 - Office Equipment

132 - Computers, Misc. Useful Life 10 Remaining Life 5

Offices- Mary- PC Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2018/2019 Future Cost \$1,740

This is to replace the PC workstation in Mary's office.



136 - Computers, Misc. Useful Life 10 Remaining Life 5

Offices- Kitchen/Workroom- Printer Quantity 1 Unit of Measure Items

Cost /Itm \$769

% Included 100.00% Total Cost/Study \$769

Summary Replacement Year 2018/2019 Future Cost \$870

This is to replace the Kyocera Mita KM-F650.



22000 - Office Equipment

140 - Computers, Misc. Useful Life 10 Remaining Life 5

Offices- Main Room- Shredder Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2018/2019 Future Cost \$1,740

This is to replace the shredder.



144 - Computers, Misc. Useful Life 10 Remaining Life 5

Offices- Mary- Printer Quantity 1 Unit of Measure Items

Cost /Itm \$769

% Included 100.00% Total Cost/Study \$769

Summary Replacement Year 2018/2019 Future Cost \$870

This is to replace the HP printer.



148 - Computers, Misc. Useful Life 10 Remaining Life 5

Offices- Robert- PC Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2018/2019 Future Cost \$1,740

This is to replace the PC workstation in Robert Dalton's office.

22000 - Office Equipment

152 - Computers, Misc. Useful Life 10 Remaining Life 5

Offices- Robert- Printer Quantity 1 Unit of Measure Items

Cost /Itm \$769

% Included 100.00% Total Cost/Study \$769

Summary Replacement Year 2018/2019 Future Cost \$870

This is to replace the Kyocera printer PS1010.

156 - Computers, Misc. Useful Life 10 Remaining Life 5

Offices - Office 1- PC Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2018/2019 Future Cost \$1,740

This is to replace the PC workstation in the office.

160 - Computers, Misc. Useful Life 10 Remaining Life 5

Offices - Office 1 - Printer Quantity 1 Unit of Measure Items

Cost /Itm \$769

% Included 100.00% Total Cost/Study \$769

Summary Replacement Year 2018/2019 Future Cost \$870

This is to replace the HP printer.

164 - Computers, Misc. Useful Life 10 Remaining Life 5

Electrical Room- Server Quantity 1 Unit of Measure Lump Sum

Cost /LS \$30,750

% Included 100.00% Total Cost/Study \$30,750

Summary Replacement Year 2018/2019 Future Cost \$34,791

This is to replace main server equipment. District input will further define this component.



22000 - Office Equipment

308 - Copier Useful Life 10 Remaining Life 5

Offices- Kitchen/Workroom- Copier Quantity 1 Unit of Measure Items

Cost /Itm \$3,587

% Included 100.00% Total Cost/Study \$3,587

Summary Replacement Year 2018/2019 Future Cost \$4,059

This is to replace the copy machine.

Xerox Phaser 6200



312 - Copier Useful Life 10 Remaining Life 5

Offices- Main Room Quantity 1 Unit of Measure Items

Cost /Itm \$3,587

% Included 100.00% Total Cost/Study \$3,587

Summary Replacement Year 2018/2019 Future Cost \$4,059

This is to replace the copy machine.

Royal 4530

Cameron Park CSD id#: 1012



23000 - Mechanical Equipment

240 - HVAC Useful Life 15 Remaining Life 10

Roof- Trane: AC 1 Quantity 1 Unit of Measure Items

Cost /Itm \$10,250

% Included 100.00% Total Cost/Study \$10,250

Summary Replacement Year 2023/2024 Future Cost \$13,121

This is to replace the Trane HVAC system. It is possible that sub-components of this system can be replaced or rebuilt to extend its life.

model #: YHC060E4EMA0C00A00000100

serial #: 827100100L date of mfg: 06/2008



244 - HVAC Useful Life 15 Remaining Life 10

Roof- Trane: AC 2, 3 Quantity 1 Unit of Measure Items

Cost /Itm \$20,500

% Included 100.00% Total Cost/Study \$20,500

Summary Replacement Year 2023/2024 Future Cost \$26,242

This is to replace the Trane HVAC system. It is possible that sub-components of this system can be replaced or rebuilt to extend its life.

model #: YSC092E4ELA0E00A000001B0

serial #: 827100298L date of mfg: 07/2008



23000 - Mechanical Equipment

248 - HVAC Useful Life 15 Remaining Life 10

Roof- Trane: AC 4, 5 Quantity 1 Unit of Measure Items

Cost /Itm \$20,500

% Included 100.00% Total Cost/Study \$20,500

Summary Replacement Year 2023/2024 Future Cost \$26,242

This is to replace the Trane HVAC system. It is possible that sub-components of this system can be replaced or rebuilt to extend its life.

model #: YSC072E4EMA0F000001B0

serial #: 827100128L date of mfg: 06/2008



252 - HVAC Useful Life 15 Remaining Life 10

Roof- Trane AC 6 Quantity 1 Unit of Measure Items

Cost /Itm \$10,250

% Included 100.00% Total Cost/Study \$10,250

Summary Replacement Year 2023/2024 Future Cost \$13,121

This is to replace the Trane HVAC system. It is possible that sub-components of this system can be replaced or rebuilt to extend its life.

model #: YSC072E4ELA0F00A00000100

serial #: 827100124L date of mfg: 06/2008



23000 - Mechanical Equipment

256 - HVAC Useful Life 15 Remaining Life 10

Roof- Trane AC 7 Quantity 1 Unit of Measure Items

Cost /Itm \$10,250

% Included 100.00% Total Cost/Study \$10,250

Summary Replacement Year 2023/2024 Future Cost \$13,121

This is to replace the Trane HVAC system. It is possible that sub-components of this system can be replaced or rebuilt to extend its life.

model #: YHC060E4EMA0C02A000001B0

serial #: 827100104L date of mfg: 06/2008



260 - HVAC Useful Life 15 Remaining Life 10

Roof- Trane AC 8 Quantity 1 Unit of Measure Items

Cost /Itm \$10,250

% Included 100.00% Total Cost/Study \$10,250

Summary Replacement Year 2023/2024 Future Cost \$13,121

This is to replace the Trane HVAC system. It is possible that sub-components of this system can be replaced or rebuilt to extend its life.

model #: YHC48E4ELA0C00A00000100

serial #: 827100084L date of mfg: 06/2008



23000 - Mechanical Equipment

264 - HVAC Useful Life 15 Remaining Life 10

Roof- Trane: AC 9 Quantity 1 Unit of Measure Items

Cost /Itm \$10,250

% Included 100.00% Total Cost/Study \$10,250

Summary Replacement Year 2023/2024 Future Cost \$13,121

This is to replace the Trane HVAC system. It is possible that sub-components of this system can be replaced or rebuilt to extend its life.

model #: YHC060E4EMA0C00A00000100

serial #: 827100096L date of mfg: 06/2008



268 - HVAC Useful Life 15 Remaining Life 10

Roof- Trane: AC 10 Quantity 1 Unit of Measure Items

Cost /Itm \$10,250

% Included 100.00% Total Cost/Study \$10,250

Summary Replacement Year 2023/2024 Future Cost \$13,121

This is to replace the Trane HVAC system. It is possible that sub-components of this system can be replaced or rebuilt to extend its life.

model #: YHC036E4ELA0DD0A00000100

serial #: 825100153L date of mfg: 06/2008



23000 - Mechanical Equipment

272 - HVAC Useful Life 15 Remaining Life 10

Roof- AC-11 Quantity 1 Unit of Measure Items

Cost /Itm \$30,750

% Included 100.00% Total Cost/Study \$30,750

Summary Replacement Year 2023/2024 Future Cost \$39,363

This is to replace the HVAC system. It is possible that sub-components of this system can be replaced or re-built to extend its life.

model #: J03ZJN07N4AZZ10003 C

serial #: N0E9841435



276 - HVAC Useful Life 15 Remaining Life 10

Roof- AC-12 Quantity 1 Unit of Measure Items

Cost /Itm \$30,750

% Included 100.00% Total Cost/Study \$30,750

Summary Replacement Year 2023/2024 Future Cost \$39,363

This is to replace the HVAC system. It is possible that sub-components of this system can be replaced or re-built to extend its life.

model #: J03ZJN07N4AZZ10003 C

serial #: N0E9841436



23000 - Mechanical Equipment

280 - HVAC Useful Life 15 Remaining Life 10

Roof- Reznor Preeva Air Handler Quantity 1 Unit of Measure Lump Sum

Cost /LS \$10,250

% Included 100.00% Total Cost/Study \$10,250

Summary Replacement Year 2023/2024 Future Cost \$13,121

This is to replace the Reznor Preeva pre engineered ventilation air handler.



284 - HVAC Useful Life 15 Remaining Life 10

Roof- Reznor Preeva Air Handler Quantity 1 Unit of Measure Items

Cost /Itm \$10,250

% Included 100.00% Total Cost/Study \$10,250

Summary Replacement Year 2023/2024 Future Cost \$13,121

This is to replace the Reznor Preeva pre engineered ventilation air handler.



23000 - Mechanical Equipment

288 - HVAC Useful Life 15 Remaining Life 10

Roof- Reznor Preeva Air Handler Quantity 1 Unit of Measure Items

Cost /Itm \$10,250

% Included 100.00% Total Cost/Study \$10,250

Summary Replacement Year 2023/2024 Future Cost \$13,121

This is to replace the Reznor Preeva pre engineered ventilation air handler.



292 - HVAC Useful Life 15 Remaining Life 10

Roof Carrier: HP-1 Quantity 1 Unit of Measure Items

Cost /Itm \$7,687

% Included 100.00% Total Cost/Study \$7,687

Summary Replacement Year 2023/2024 Future Cost \$9,841

This is to replace the Carrier HVAC system. It is possible that sub-components of this system can be replaced or re-built to extend its life.

serial #: 1507E36888

prod #: 25HCA318A0031010 model #: 25HCA318A310



23000 - Mechanical Equipment

296 - HVAC Useful Life 15 Remaining Life 10

Roof Carrier: HP-2 Quantity 1 Unit of Measure Items

Cost /Itm \$7,687

% Included 100.00% Total Cost/Study \$7,687

Summary Replacement Year 2023/2024 Future Cost \$9,841

This is to replace the Carrier HVAC system. It is possible that sub-components of this system can be replaced or re-built to extend its life.

serial #: 0208E03161

prod #: 25HCA318A0031010 model #: 25HCA318A310



300 - HVAC Useful Life 15 Remaining Life 10

Roof- Fujitsu Quantity 1 Unit of Measure Items

Cost /Itm \$5,125

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2023/2024 Future Cost \$6,560

This is to replace the Fujitsu Halcyon Inverter system. It is possible that sub-components of this system can be replaced or re-built to extend its life.

model #: A0U18CL serial #: DCN 015222



23000 - Mechanical Equipment

612 - Water Heater Useful Life 12 Remaining Life 7

Pool Storage/Water Heater Rm Quantity 1 Unit of Measure Items

Cost /Itm \$5,637

% Included 100.00% Total Cost/Study \$5,637

Summary Replacement Year 2020/2021 Future Cost \$6,701

This is to replace the 120 gallon gas water heater.

model #: HE119-199LP serial #: 1008T2660P mfg date: 10/7/2008



616 - Water Heater Useful Life 12 Remaining Life 7

Kitchen Storage- Rheem Quantity 1 Unit of Measure Items

Cost /Itm \$5,637

% Included 100.00% Total Cost/Study \$5,637

Summary Replacement Year 2020/2021 Future Cost \$6,701

This is to replace the Rheem 120 gallon gas water heater.

model #: HE119-199LP serial #: 0708T1869P mfg date: 07/16/2008



23000 - Mechanical Equipment

620 - Water Heater Useful Life 12 Remaining Life 7

Janitorial Room- Rheem Quantity 1 Unit of Measure Lump Sum

Cost /LS \$820

% Included 100.00% Total Cost/Study \$820

Summary Replacement Year 2020/2021 Future Cost \$975

This is to replace the Rheem 30 gallon gas water heater.

model #: 82V30-2 serial #: 0908R00965 mfg date: 09/2008



### 24000 - Furnishings

104 - Miscellaneous Useful Life 10 Remaining Life 5

Social Room Furnishings Quantity 1 Unit of Measure Room

Cost /Rm \$5,125

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2018/2019 Future Cost \$5,798

This is a provision for Social Room furniture and equipment.

- 1- bookshelf
- 2- couches
- 1- coffee table
- 4- window blinds
- 1- end table
- 1- lamp



24000 - Furnishings

192 - Chairs Useful Life 15 Remaining Life 10

93 Community Center Folding Chairs Quantity 93 Unit of Measure Items

Cost /Itm \$51.25

% Included 100.00% Total Cost/Study \$4,766

Summary Replacement Year 2023/2024 Future Cost \$6,101

This is to replace the chairs.



196 - Chairs Useful Life 20 Remaining Life 15

270 Community Center Stackable Chairs Quantity 270 Unit of Measure Items

Cost /Itm \$66.62

% Included 100.00% Total Cost/Study \$17,989

Summary Replacement Year 2028/2029 Future Cost \$26,053

This is to replace the chairs.



24000 - Furnishings

204 - Chairs Useful Life 10 Remaining Life 5

9 Office Task Chairs Quantity 9 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$4,612

Summary Replacement Year 2018/2019 Future Cost \$5,219

This is to replace the chairs.



334 - Tables Useful Life 20 Remaining Life 15

47 Community Center Folding Tables Quantity 47 Unit of Measure Items

Cost /Itm \$205

% Included 100.00% Total Cost/Study \$9,635

Summary Replacement Year 2028/2029 Future Cost \$13,954

This is to replace the folding tables.



24000 - Furnishings

644 - Modular Office Desk Useful Life 20 Remaining Life 15

8 Office Desks Quantity 8 Unit of Measure Items

Cost /Itm \$2,460

% Included 100.00% Total Cost/Study \$19,680

Summary Replacement Year 2028/2029 Future Cost \$28,503

This is for a modular desk system including a desk, hutches, partitions and other associated items.



24500 - Audio / Visual

112 - Television, Large Screen Useful Life 10 Remaining Life 5

Social Room Quantity 1 Unit of Measure Items

Cost /Itm \$3,075

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2018/2019 Future Cost \$3,479

This is to replace the large screen JVC television.



24500 - Audio / Visual

300 - PA System Useful Life 10 Remaining Life 5

Roof Access Room- QSC Mixer Quantity 1 Unit of Measure Items

Cost /Itm \$2,562

% Included 100.00% Total Cost/Study \$2,562

Summary Replacement Year 2018/2019 Future Cost \$2,899

This is to replace the QSC mixer.



304 - PA System Useful Life 10 Remaining Life 5

3 Roof Access Room- Speakers & Stands Quantity 3 Unit of Measure Items

Cost /Itm \$769

% Included 100.00% Total Cost/Study \$2,306

Summary Replacement Year 2018/2019 Future Cost \$2,609

This is to replace the public address system including the JBL speakers and stands.



24600 - Safety / Access

900 - Miscellaneous Useful Life 15 Remaining Life 10

Stage Room- Handicap Lift Quantity 1 Unit of Measure Lump Sum

Cost /LS \$10,250

% Included 100.00% Total Cost/Study \$10,250

Summary Replacement Year 2023/2024 Future Cost \$13,121

This is to replace the handicap lift.

model #: GVL-OP-42 serial #: 39498 elevator #: 152866

date for manufacture: June 13, 2008



25000 - Flooring

200 - Carpeting Useful Life 10 Remaining Life 5

189 Sq. Yds. Community Center Offices Quantity 189 Unit of Measure Square Yard

Cost /SqYd \$32.80

% Included 100.00% Total Cost/Study \$6,199

Summary Replacement Year 2018/2019 Future Cost \$7,014

This is to replace the carpeting.



25000 - Flooring

400 - Tile Useful Life 20 Remaining Life 15

9,333 Sq. Ft. Restrooms, Concession, Quantity 9,333 Unit of Measure Square Feet

chen Cost /SqFt \$6.15

% Included 100.00% Total Cost/Study \$57,398

Summary Replacement Year 2028/2029 Future Cost \$83,129

This is to replace the floor and wall tile.



600 - Vinyl Useful Life 20 Remaining Life 15

1,106 Sq. Yds. Community Center Vinyl Tile Quantity 1,106 Unit of Measure Square Yard

Cost /SqYd \$26.65

% Included 100.00% Total Cost/Study \$29,475

Summary Replacement Year 2028/2029 Future Cost \$42,688

This is to replace the vinyl flooring.



25000 - Flooring

700 - Hardwood Floors Useful Life 15 Remaining Life 10

7,257 Sq. Ft. Yoga Room & Gym Quantity 7,257 Unit of Measure Square Feet

Cost /SqFt \$6.15

% Included 100.00% Total Cost/Study \$44,631

Summary Replacement Year 2023/2024 Future Cost \$57,131

This is to resurface the hardwood flooring.



920 - Coatings Useful Life 12 Remaining Life 7

1,063 Sq. Ft. Community Center Concrete Quantity 1,063 Unit of Measure Square Feet

Floors Cost /SqFt \$6.15

% Included 100.00% Total Cost/Study \$6,537

Summary Replacement Year 2020/2021 Future Cost \$7,771

This is to coat the interior concrete floors.

# 25500 - Wallcoverings

300 - FRP Useful Life 20 Remaining Life 15

1,951 Sq. Ft. Community Center Quantity 1,951 Unit of Measure Square Feet

Cost /SqFt \$6.15

% Included 100.00% Total Cost/Study \$11,999

Summary Replacement Year 2028/2029 Future Cost \$17,378

This is to replace the wall fiberglass reinforced panels (FRP).



**00010 - Community Center 26000 - Outdoor Equipment** 

050 - Flag Pole Useful Life 20 Remaining Life 15

Community Center Quantity 1 Unit of Measure Items

Cost /Itm \$4,100

% Included 100.00% Total Cost/Study \$4,100

Summary Replacement Year 2028/2029 Future Cost \$5,938

This is to replace the large flag pole in the common area.



300 - Picnic Table: Wood Useful Life 15 Remaining Life 10

2 Pool Area Quantity 2 Unit of Measure Items

Cost /Itm \$410

% Included 100.00% Total Cost/Study \$820

Summary Replacement Year 2023/2024 Future Cost \$1,050

This is to replace the wood picnic tables.



26000 - Outdoor Equipment

332 - Benches Useful Life 20 Remaining Life 15

2 Common Area Quantity 2 Unit of Measure Items

Cost /Itm \$615

% Included 100.00% Total Cost/Study \$1,230

Summary Replacement Year 2028/2029 Future Cost \$1,781

This is to replace the expanded metal, plastic coated benches.



336 - Picnic Table: Metal Useful Life 20 Remaining Life 15

8 Pool Area Quantity 8 Unit of Measure Items

Cost /Itm \$871

% Included 100.00% Total Cost/Study \$6,970

Summary Replacement Year 2028/2029 Future Cost \$10,095

This is to replace the picnic tables with an expanded metal model coated with Plastisol.



380 - Garbage Receptacles Useful Life 20 Remaining Life 15

14 Common Area & Pool Quantity 14 Unit of Measure Items

Cost /Itm \$205

% Included 100.00% Total Cost/Study \$2,870

Summary Replacement Year 2028/2029 Future Cost \$4,157

This is to replace the garbage containers.

5- common area

9- pool area

26000 - Outdoor Equipment

430 - Bleachers Useful Life 20 Remaining Life 15

3 Gym- Wood & Metal Bleachers Quantity 3 Unit of Measure Items

Cost /Itm \$3,587

% Included 100.00% Total Cost/Study \$10,762

Summary Replacement Year 2028/2029 Future Cost \$15,587

This is to replace the bleachers.



844 - Shade Structure Useful Life 10 Remaining Life 5

12 Portable Shade Structures Quantity 12 Unit of Measure Items

Cost /Itm \$564

% Included 100.00% Total Cost/Study \$6,765

Summary Replacement Year 2018/2019 Future Cost \$7,654

This is to replace the portable shade structures.

27000 - Appliances

200 - Refrigerator Useful Life 7 Remaining Life 2

Pool Maintenance Room Quantity 1 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$512

Summary Replacement Year 2015/2016 Future Cost \$538

This is to replace the Sanyo mini refrigerator.



27000 - Appliances

204 - Refrigerator Useful Life 10 Remaining Life 5

Offices- Kitchen/Workroom Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2018/2019 Future Cost \$1,160

This is to replace the refrigerator.

General Electric

m/n: TBX14GADGRWW

s/n: SZ763646



224 - Refrigerator: Commercial: Large Useful Life 20 Remaining Life 15

Kitchen- Fridge Quantity 1 Unit of Measure Items

Cost /Itm \$4,100

% Included 100.00% Total Cost/Study \$4,100

Summary Replacement Year 2028/2029 Future Cost \$5,938

This is to replace the True large commercial type refrigerator.

Cameron Park CSD id #: 4119 refrig unit: TPA9421YXA cabinet s/n: 5032886



27000 - Appliances

Useful Life 20 Remaining Life 15 240 - Freezer: Large

Quantity 1 Unit of Measure Items Kitchen- Fridge/Freezer Combo

Cost /Itm \$4,100

% Included 100.00% Total Cost/Study \$4,100

Summary Replacement Year 2028/2029 Future Cost \$5,938

This is to replace the True large commercial type fridge/freezer.

Cameron Park CSD id #: 4118

refrig unit: T2168GK cabinet s/n: 5032886



270 - Stove / Oven: Commercial grade 6-burner

Useful Life 20 Remaining Life Kitchen

Unit of Measure Items Quantity 1

Cost /Itm \$4,612

% Included 100.00% Total Cost/Study \$4,612

Replacement Year 2028/2029 Future Cost \$6,680 Summary

This is to replace the 6-burner stove/oven & griddle with a similar model.

Cameron Park CSD id #: 4107



27000 - Appliances

278 - Oven: Wall Useful Life 20 Remaining Life 15

Kitchen- Double Oven Quantity 1 Unit of Measure Items

Cost /Itm \$3,587

% Included 100.00% Total Cost/Study \$3,587

Summary Replacement Year 2028/2029 Future Cost \$5,196

This is to replace the Wolf Double Oven.

Cameron Park CSD id #: 4117



282 - Microwave Oven Useful Life 10 Remaining Life

Offices- Kitchen/Workroom Quantity 1 Unit of Measure Items

Cost /Itm \$410

% Included 100.00% Total Cost/Study \$410

Summary Replacement Year 2017/2018 Future Cost \$453

This is to replace the microwave oven.



27000 - Appliances

290 - Microwave Oven Useful Life 10 Remaining Life 5

Kitchen- Panasonic Quantity 1 Unit of Measure Items

Cost /Itm \$871

% Included 100.00% Total Cost/Study \$871

Summary Replacement Year 2018/2019 Future Cost \$986

This is to replace the microwave oven.

Panasonic NE-1257R



298 - Stove: Exhaust Hood w/ Fan Useful Life 20 Remaining Life 15

Kitchen- Greencheck Hood Quantity 1 Unit of Measure Items

Cost /Itm \$3,075

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2028/2029 Future Cost \$4,454

This is to replace the exhaust hood and fire suppression system.



27000 - Appliances

320 - Dishwasher, Commercial Useful Life 10 Remaining Life 5

Kitchen- Hobart Quantity 1 Unit of Measure Items

Cost /Itm \$4,305

% Included 100.00% Total Cost/Study \$4,305

Summary Replacement Year 2018/2019 Future Cost \$4,871

This is to replace the commercial grade dishwasher. Hobart door type dish machine.

m/n: AM15



940 - Drinking Fountain Useful Life 20 Remaining Life 15

Community Center Entry Quantity 1 Unit of Measure Items

Cost /Itm \$2,562

% Included 100.00% Total Cost/Study \$2,562

Summary Replacement Year 2028/2029 Future Cost \$3,711

This is to replace the Elkay twin chilled drinking fountain.



27000 - Appliances

950 - Point of Sale Computer Useful Life 6 Remaining Life 1

Pool Maintenance Room Quantity 1 Unit of Measure Items

Cost /Itm \$2,050

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2014/2015 Future Cost \$2,101

This is to replace the Point of Sale cash register system.



954 - Point of Sale Computer Useful Life 6 Remaining Life 1

Pool Concession Room Quantity 1 Unit of Measure Items

Cost /Itm \$2,050

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2014/2015 Future Cost \$2,101

This is to replace the Point of Sale cash register system.



27000 - Appliances

992 - Garbage Disposal Useful Life 10 Remaining Life 5

Kitchen- Savajor Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2018/2019 Future Cost \$1,740

This is to replace the Savajor disposal.



# 30000 - Miscellaneous

806 - Maintenance Equipment Useful Life 20 Remaining Life 19

Riding Mower Quantity 1 Unit of Measure Items

Cost /Itm \$11,651

% Included 100.00% Total Cost/Study \$11,651

Summary Replacement Year 2032/2033 Future Cost \$18,626

This is to replace the Lazer X Mark riding mower.

2012/2013- \$11,367

810 - Maintenance Equipment Useful Life 15 Remaining Life 10

Kitchen Changing Room- Grout Cleaner Quantity 1 Unit of Measure Items

Cost /Itm \$1,230

% Included 100.00% Total Cost/Study \$1,230

Summary Replacement Year 2023/2024 Future Cost \$1,575

This is to replace the Betco GS 15 grout machine.



30000 - Miscellaneous

818 - Maintenance Equipment Useful Life 5 Remaining Life 0

Roof Access Room- Floor Scrubber Quantity 1 Unit of Measure Items

Cost /Itm \$5,637

% Included 100.00% Total Cost/Study \$5,637

Summary Replacement Year 2013/2014 Future Cost \$5,638

This is to replace the Betco Stealth ASD20B scrubber.



822 - Maintenance Equipment Useful Life 10 Remaining Life 5

Pool Egpt Rm- Pressure Washer Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2018/2019 Future Cost \$1,160

This is to replace the North Star pressure washer.



30000 - Miscellaneous

830 - Maintenance Equipment Useful Life 5 Remaining Life 0

Roof Access Room- Floor Buffer Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2013/2014 Future Cost \$1,538

This is to replace the Advance floor buffer.



00030 - Cameron Park Lake

01000 - Paving

108 - Asphalt: Sealing Useful Life 5 Remaining Life 2

5,911 Sq. Ft. Drives & Parking Quantity 5,911 Unit of Measure Square Feet

Cost /SqFt \$0.123

% Included 100.00% Total Cost/Study \$727

Summary Replacement Year 2015/2016 Future Cost \$764

This is to prepare the surface and apply a single coat asphalt emulsion product. If a second coat is desired the cost is generally 10% to 20% higher.

southwesterly parking lot- 14,756 sq ft northwesterly parking lot- 13,125 sq ft mid parking lot- 14,000 sq ft

drives- 15,030 sq ft



## 01000 - Paving

208 - Asphalt: Ongoing Repairs Useful Life 5 Remaining Life 2

56,911 Sq. Ft. Drives & Parking (2%) Quantity 56,911 Unit of Measure Square Feet

Cost /SqFt \$3.33 Qty \* \$/SqFt \$189,585 % Included 2.00% Total Cost/Study \$3,792

Summary Replacement Year 2015/2016 Future Cost \$3,984

This is for miscellaneous repairs including crack fill, skin patching and minor dig out & fill.



408 - Asphalt: Major Repairs Useful Life 20 Remaining Life 9

56,911 Sq. Ft. Drives & Parking (50%)

Quantity 56,911

Unit of Measure Square Feet

Cost /SqFt \$5.12 Qty \* \$/SqFt \$291,669 % Included 50.00% Total Cost/Study \$145,834

Summary Replacement Year 2022/2023 Future Cost \$182,127

This is for major excavation, re-compaction and installation of new hot asphalt to selected areas.



01000 - Paving

800 - Striping Useful Life 5 Remaining Life 2

98 Parking Stalls Quantity 98 Unit of Measure Items

Cost /Itm \$15.37

% Included 100.00% Total Cost/Study \$1,507

Summary Replacement Year 2015/2016 Future Cost \$1,583

This is to re-stripe asphalt to match existing plan.



## 02000 - Concrete

208 - Walkways Useful Life 5 Remaining Life 2

12,350 Sq. Ft. Walkways, Pads, & Slabs
Quantity 12,350
Unit of Measure Square Feet
(2%)
Cost /SqFt \$16.40
Qty \* \$/SqFt \$202,540

% Included 2.00% Total Cost/Study \$4,051

Summary Replacement Year 2015/2016 Future Cost \$4,256

This is to repair, replace or grind concrete flatwork to remove abrupt elevation changes and maintain functionality. Since the concrete useful life exceeds the scope of this study, this component provides for repair only and not full replacement.

160 sq ft- 2- 5' x 16' concrete slabs at floating boat docks 1,100 sq ft- 11- 10' x 10' picnic table pads 280 sq ft- concrete bench pads 10,210 sq ft- concrete walkways 600 sq ft- 20' x 30' enclosure slab



03000 - Painting: Exterior

Summary

104 - Surface Restoration Useful Life 5 Remaining Life 1

1,140 Sq. Ft. Guard Shack & [3] Wood Quantity 1,140 Unit of Measure Square Feet

Replacement Year 2014/2015

Sheds Cost /SqFt \$1.02

% Included 100.00% Total Cost/Study \$1,168

This is to prepare, power wash, sand, scrape, caulk and paint with a 100% premium acrylic paint.

guard shack- 180 sq ft shed- 256 sq ft boat rental shed- 240 sq ft wood shed (with metal roof)- 464 sq ft



Future Cost \$1,198

112 - Surface Restoration Useful Life 5 Remaining Life 0

3,680 Sq. Ft. Corporate Yard House Quantity 3,680 Unit of Measure Square Feet

Cost /SqFt \$1.02

% Included 100.00% Total Cost/Study \$3,772

Summary Replacement Year 2013/2014 Future Cost \$3,772

This is to prepare, power wash, sand, scrape, caulk and paint with a 100% premium acrylic paint.



03000 - Painting: Exterior

116 - Surface Restoration Useful Life 5 Remaining Life 3

1,036 Sq. Ft. Concession Building Quantity 1,036 Unit of Measure Square Feet

Cost /SqFt \$1.02

% Included 100.00% Total Cost/Study \$1,062

Summary Replacement Year 2016/2017 Future Cost \$1,144

This is to prepare, power wash, sand, scrape, caulk and paint with a 100% premium acrylic paint.



120 - Surface Restoration Useful Life 5 Remaining Life 3

1,950 Sq. Ft. Gazebo Painting Quantity 1,950 Unit of Measure Square Feet

Cost /SqFt \$1.02

% Included 100.00% Total Cost/Study \$1,999

Summary Replacement Year 2016/2017 Future Cost \$2,152

This is to prepare, power wash, sand, scrape, caulk and paint with a 100% premium acrylic paint.



03000 - Painting: Exterior

408 - Railings Useful Life 4 Remaining Life 2

186 Lin. Ft. Concrete Footbridge Railings Quantity 186 Unit of Measure Linear Feet

Cost /l.f. \$8.20

% Included 100.00% Total Cost/Study \$1,525

Summary Replacement Year 2015/2016 Future Cost \$1,602

This is to prepare, power wash, sand, scrape and paint the railings.



412 - Railings Useful Life 4 Remaining Life 0

80 Lin. Ft. Lake Observation Deck Quantity 80 Unit of Measure Linear Feet

Cost /l.f. \$8.20

% Included 100.00% Total Cost/Study \$656

Summary Replacement Year 2013/2014 Future Cost \$656

This is to prepare, power wash, sand, scrape and paint the railings.

In 2012/2013 rust is exhibited.



03000 - Painting: Exterior

420 - Wrought Iron Gates Useful Life 4 Remaining Life 0

2 Park Entrance Gates Quantity 2 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2013/2014 Future Cost \$1,025

This is to prepare, power wash, sand, scrape, spot prime and paint the wrought iron gates.

In 2012/2013, rust is exhibited.



504 - Light Poles Useful Life 4 Remaining Life 1

32 Park Light Poles Quantity 32 Unit of Measure Items

Cost /Itm \$190

% Included 100.00% Total Cost/Study \$6,068

Summary Replacement Year 2014/2015 Future Cost \$6,220

This is to prepare and paint the light poles.



03500 - Painting: Interior

400 - Restrooms Useful Life 10 Remaining Life 4

1,904 Sq. Ft. Concession Building Quantity 1,904 Unit of Measure Square Feet

Cost /SqFt \$1.02

% Included 100.00% Total Cost/Study \$1,952

Summary Replacement Year 2017/2018 Future Cost \$2,154

This is to prepare and paint the restroom interiors.



# 04000 - Structural Repairs

200 - Wood: Siding & Trim Useful Life 10 Remaining Life 0

3,680 Sq. Ft. Corporate Yard House (10%) Quantity 3,680 Unit of Measure Square Feet

Cost /SqFt \$20.50 Qty \* \$/SqFt \$75,440

% Included 10.00% Total Cost/Study \$7,544

Summary Replacement Year 2013/2014 Future Cost \$7,544

This is to replace siding and wood trim in conjunction with every other paint cycle. The actual scope of the work will depend on what is found after the existing siding is removed. Includes primer and paint on all new wood

surfaces.



# 04000 - Structural Repairs

550 - Bridge Maintenance Useful Life 5 Remaining Life 3

1,313 Sq. Ft. [3] Pedestrian Bridges (10%) Quantity 1,313 Unit of Measure Square Feet

Cost /SqFt \$51.25 Qty \* \$/SqFt \$67,291 % Included 10.00% Total Cost/Study \$6,729

Summary Replacement Year 2016/2017 Future Cost \$7,247

This is to maintain the bridge.

12' x 21'- masonry bridge with incorporated decomposed granite walk

15' x 25'- masonry and concrete footbridge

7' x 98'- concrete footbridge & metal rails (painting is provided for in another component)



658 - Decking Useful Life 20 Remaining Life 9


800 Sq. Ft. Lake Observation Deck Quantity 800 Unit of Measure Square Feet

Cost /SqFt \$25.62

% Included 100.00% Total Cost/Study \$20,500

Replacement Year 2022/2023 Future Cost \$25,602

This is to replace the wood deck at the lake. Metal railings are provided for in another component.



Summary

# 04000 - Structural Repairs

828 - Dock Floatation Useful Life 10 Remaining Life 4

[2] Docks & [10] Barges Quantity 1 Unit of Measure Lump Sum

Cost /LS \$5,125

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2017/2018 Future Cost \$5,657

This is to repair and replace the dock flotation systems. This component also provides for the maintenance and replacement of the floating pontoon barges. Floating docks consist of  $4.5' \times 12'$  wood gangways and  $11' \times 9'$  wood floating docks. Concrete slabs are provided for in another component.



### 05000 - Roofing

448 - Pitched: Dimensional Composition Useful Life 25 Remaining Life 9

36 Squares- Corporate Yard House Quantity 36 Unit of Measure Squares

Cost /Sqrs \$410

% Included 100.00% Total Cost/Study \$14,760

Summary Replacement Year 2022/2023 Future Cost \$18,433

This is to reroof with a dimensional composition roofing product. Composition roofs should be regularly inspected and repaired as indicated to ensure maximum life.



### 05000 - Roofing

452 - Pitched: Dimensional Composition Useful Life 25 Remaining Life 11

44 Squares- Concession, Gazebo, [3] Quantity 44 Unit of Measure Squares

Small Bldgs Cost /Sgrs \$410

% Included 100.00% Total Cost/Study \$18,040

Summary Replacement Year 2024/2025 Future Cost \$23,670

This is to reroof with a dimensional composition roofing product. Composition roofs should be regularly inspected and repaired as indicated to ensure maximum life.

concession stand- 21 squares gazebo- 20 squares guard shack, shed, boat rental shack- 3 squares, approximately 1 square each



704 - Gutters / Downspouts

184 Lin. Ft. Concession Building Gutters

Useful Life 25 Remaining Life 11

Quantity 184 Unit of Measure Linear Feet

Cost /l.f. \$6.15

% Included 100.00% Total Cost/Study \$1,132

Summary Replacement Year 2024/2025 Future Cost \$1,485

This is to replace the gutters and downspouts. Gutter & downspout inspections should be annually, during fall after deciduous trees have dropped their leaves and in preparation for months of heavier precipitation. Cleaning may be required depending on frequency of debris build-up. Painted metal should be touched up as needed. Any missing or disconnected downspouts should be replaced/repaired immediately.



## 05000 - Roofing

708 - Gutters / Downspouts Useful Life 25 Remaining Life 9

400 Lin. Ft. Corporate Yard House Quantity 400 Unit of Measure Linear Feet

Cost /l.f. \$6.15

% Included 100.00% Total Cost/Study \$2,460

Summary Replacement Year 2022/2023 Future Cost \$3,072

This is to replace the gutters and downspouts. Gutter & downspout inspections should be annually, during fall after deciduous trees have dropped their leaves and in preparation for months of heavier precipitation. Cleaning may be required depending on frequency of debris build-up. Painted metal should be touched up as needed. Any missing or disconnected downspouts should be replaced/repaired immediately.



## 08000 - Rehab

234 - Restrooms Useful Life 20 Remaining Life 9

2 Concession Building Quantity 2 Unit of Measure Items

Cost /Itm \$3,075

% Included 100.00% Total Cost/Study \$6,150

Summary Replacement Year 2022/2023 Future Cost \$7,681

This is to rehab and redecorate the restrooms. Includes items such as partitions, fixtures, lighting, tile, etc. This

item can be further defined with district input.



08000 - Rehab

254 - Kitchen Useful Life 20 Remaining Life 9

Concession Building Quantity 1 Unit of Measure Room

Cost /Rm \$3,075

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2022/2023 Future Cost \$3,840

This is to rehab and redecorate the kitchen. Includes items such as cabinets, countertops, fixtures, lighting, etc. This item can be further defined with district input.

2012/2013- inaccessible and not visually inspected.

# 11000 - Gate Equipment

910 - Vehicle Gate Replacement Useful Life 20 Remaining Life 9

2 Park Entrance Gates Quantity 2 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2022/2023 Future Cost \$3,840

This is to replace the existing vehicle gates. District input will further define this component.



17000 - Tennis Court

100 - Reseal Useful Life 7 Remaining Life 3

28,600 Sq. Ft. [4] Tennis Courts Quantity 28,600 Unit of Measure Square Feet

Cost /SqFt \$0.512

% Included 100.00% Total Cost/Study \$14,657

Summary Replacement Year 2016/2017 Future Cost \$15,785

This is to reseal and re-stripe the tennis courts.



500 - Resurface Useful Life 21 Remaining Life 16

28,600 [4] Tennis Courts Quantity 28,600 Unit of Measure Lump Sum

Cost /LS \$1.54

% Included 100.00% Total Cost/Study \$43,972

Summary Replacement Year 2029/2030 Future Cost \$65,277

This is to resurface the tennis courts.



18000 - Landscaping

112 - Irrigation: Controllers Useful Life 10 Remaining Life 4

Quantity 1 Unit of Measure Items Shed

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2017/2018 Future Cost \$1,131

This is to replace the irrigation controller.

Intermatic T101R



344 - Irrigation: Pumps Useful Life 5 Remaining Life

Quantity 1 Unit of Measure Items 25 GPM Well

Cost /Itm \$5,125

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2015/2016 Future Cost \$5,384

This is to replace, repair and maintain the irrigation system pumps. 25 GPM well supplies east side turf irrigation.

478 - Pathways & Trails

Useful Life 10 Remaining Life 4 Quantity 59,910 Unit of Measure Square Feet 59,910 Sq. Ft. Lake Perimeter- DG Path

(10%)

Cost /SqFt \$5.12 Qty \* \$/SqFt \$307,039 % Included 10.00% Total Cost/Study \$30,704

Replacement Year 2017/2018 Future Cost \$33,891 Summary

This is to maintain pathways and trails.



18500 - Lakes / Ponds

300 - Pumps / Mechanical Useful Life 10 Remaining Life 4

10 GPM Well Quantity 1 Unit of Measure Items

Cost /Itm \$10,250

% Included 100.00% Total Cost/Study \$10,250

Summary Replacement Year 2017/2018 Future Cost \$11,314

This is to repair, maintain and replace the pumps and mechanical equipment associated with the 10gpm well that supplies the lagoon water.

320 - Filter Useful Life 10 Remaining Life 4

5 Filters- Lake & Lagoon Quantity 5 Unit of Measure Items

Cost /Itm \$2,562

% Included 100.00% Total Cost/Study \$12,812

Summary Replacement Year 2017/2018 Future Cost \$14,143

This is to replace the large filters.



990 - Miscellaneous Useful Life 5 Remaining Life 3

300 Lin. Ft. Dam/Spillway (5%)

Quantity 300

Unit of Measure Linear Feet

Cost /l.f. \$512 Qty \* \$/l.f. \$153,750 % Included 5.00% Total Cost/Study \$7,687 Replacement Year 2016/2017 Future Cost \$8,279

This is to maintain and repair the spillway and the associated lake gate valve located at the east end of the lake.



Summary

19000 - Fencing

104 - Chain Link: 4' Useful Life 30 Remaining Life 19

1,644 Lin. Ft. Lake Perimeter Fencing Quantity 1,644 Unit of Measure Linear Feet

Cost /l.f. \$11.27

% Included 100.00% Total Cost/Study \$18,536

Summary Replacement Year 2032/2033 Future Cost \$29,633

This is to replace the 4' chain link fencing.

lake perimeter- 835 linear feet lagoon perimeter- 809 linear feet



128 - Chain Link: 6' Useful Life 30 Remaining Life 19

21 Lin. Ft. Boat Rental Shack Quantity 21 Unit of Measure Linear Feet

Cost /l.f. \$12.30

% Included 100.00% Total Cost/Study \$258

Summary Replacement Year 2032/2033 Future Cost \$413

This is to replace the 6' chain link fencing.



19000 - Fencing

132 - Chain Link: 6' Useful Life 6 Remaining Life 2

6,877 Lin. Ft. Park Perimeter Fencing
Quantity 6,877 Unit of Measure Linear Feet
(20%)
Cost /l.f. \$12.30 Qty \* \$/l.f. \$84,587

% Included 20.00% Total Cost/Study \$16,917
Summary Replacement Year 2015/2016 Future Cost \$17,774

This is for ongoing percentage based replacement of the 6' chain link fencing. This current schedule provides for an overall 30 year useful life.



352 - Wood: 6' Useful Life 18 Remaining Life 14

80 Lin. Ft. Enclosure Quantity 80 Unit of Measure Linear Feet

Cost /l.f. \$25.62

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2027/2028 Future Cost \$2,897

This is to replace the 6' wood fencing including discarded fence material removal and disposal.



19000 - Fencing

356 - Wood: 6' Useful Life 18 Remaining Life 8

555 Lin. Ft. Corporate Yard Perimeter Quantity 555 Unit of Measure Linear Feet

Cost /l.f. \$25.62

% Included 100.00% Total Cost/Study \$14,222

Summary Replacement Year 2021/2022 Future Cost \$17,328

This is to replace the 6' wood fencing including discarded fence material removal and disposal.



522 - Post & Cable Useful Life 25 Remaining Life 14

902 Lin. Ft. Park Post & Chain Fencing Quantity 902 Unit of Measure Linear Feet

Cost /l.f. \$20.50

% Included 100.00% Total Cost/Study \$18,491

Summary Replacement Year 2027/2028 Future Cost \$26,127

This is to repair and replace the post and cable fence.



19500 - Retaining Wall

120 - Wood: 1' Useful Life 20 Remaining Life 9

125 Lin. Ft. Park Entrance Quantity 125 Unit of Measure Linear Feet

Cost /l.f. \$35.87

% Included 100.00% Total Cost/Study \$4,484

Summary Replacement Year 2022/2023 Future Cost \$5,600

This is to repair and replace the 1' retaining wall.

50 linear feet- east side driveway 75 linear feet- west side driveway



124 - Wood: 2' Useful Life 18 Remaining Life 14

80 Lin. Ft. Enclosure Quantity 80 Unit of Measure Linear Feet

Cost /l.f. \$61.50

% Included 100.00% Total Cost/Study \$4,920

Summary Replacement Year 2027/2028 Future Cost \$6,952

This is to repair and replace the 2' retaining wall.



20000 - Lighting

216 - Pole Lights Useful Life 5 Remaining Life 2

32 Park & Lagoon (9%) Quantity 32 Unit of Measure Items

Cost /Itm \$1,230 Qty \* \$/Itm \$39,360 % Included 9.38% Total Cost/Study \$3,690

Summary Replacement Year 2015/2016 Future Cost \$3,877

This is to replace the pole lights.



# 21000 - Signage

778 - Wood Monument Useful Life 5 Remaining Life 3

Park Entrance Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2016/2017 Future Cost \$1,656

This is to maintain, repair and replace the custom identity wood monument sign.



23000 - Mechanical Equipment

232 - HVAC Useful Life 15 Remaining Life 7

Concession Roof Quantity 1 Unit of Measure Items

Cost /Itm \$5,125

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2020/2021 Future Cost \$6,092

This is to replace the Alpine HVAC evaporative air cooler system. It is possible that sub-components of this system can be replaced or re-built to extend its life.

model D45A s/n: D03003793



## 26000 - Outdoor Equipment

104 - Tot Lot: Play Equipment Useful Life 20 Remaining Life 9

Play Area- 4-Swing Set Quantity 1 Unit of Measure Items

Cost /Itm \$7,687

% Included 100.00% Total Cost/Study \$7,687

Summary Replacement Year 2022/2023 Future Cost \$9,601

This is to replace the tot lot play equipment.

26000 - Outdoor Equipment

108 - Tot Lot: Play Equipment Useful Life 20 Remaining Life 9

Play Area- Large Structure Quantity 1 Unit of Measure Items

Cost /Itm \$35,875

% Included 100.00% Total Cost/Study \$35,875

Summary Replacement Year 2022/2023 Future Cost \$44,803

This is to replace the play area 4-swing set.



124 - Tot Lot: Play Equipment Useful Life 20 Remaining Life 9

Play Area- 2-Swing Set Quantity 1 Unit of Measure Items

Cost /Itm \$5,125

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2022/2023 Future Cost \$6,400

This is to replace the play area 2-swing set.

144 - Tot Lot: Safety Surface Useful Life 3 Remaining Life 1

10,000 Sq. Ft. Play Area Quantity 10,000 Unit of Measure Square Feet

Cost /SqFt \$0.256

% Included 100.00% Total Cost/Study \$2,562

Summary Replacement Year 2014/2015 Future Cost \$2,627

This is to replenish the play area engineered impact absorbing wood fiber safety surface.



26000 - Outdoor Equipment

200 - Pedestal Grill BBQ Useful Life 20 Remaining Life 9

11 Park Barbecues Quantity 11 Unit of Measure Items

Cost /Itm \$307

% Included 100.00% Total Cost/Study \$3,382

Summary Replacement Year 2022/2023 Future Cost \$4,224

This is to replace the pedestal grill BBQ's. Includes shipping and installation.



280 - Picnic Tables Useful Life 20 Remaining Life 9

50 Park Picnic Tables Quantity 50 Unit of Measure Items

Cost /Itm \$615

% Included 100.00% Total Cost/Study \$30,750

Summary Replacement Year 2022/2023 Future Cost \$38,403

This is to replace the picnic tables.

metal- 3

wood- 41

double length wood- 2

concrete- 4



26000 - Outdoor Equipment

328 - Benches

25 Park Benches

Summary

Useful Life 20 Remaining Life 9

Quantity 25 Unit of Measure Items

Cost /Itm \$615

% Included 100.00% Total Cost/Study \$15,375

Replacement Year 2022/2023 Future Cost \$19,201

This is to replace the benches.

wood- 7 plastic- 2 concrete with plastic slats- 4 memorial- 4 small concrete & wood- 6 metal (@ tennis courts)- 2



392 - Garbage Receptacles Useful Life 20 Remaining Life 9

40 Park Trash Cans Quantity 40 Unit of Measure Items

Cost /Itm \$205

% Included 100.00% Total Cost/Study \$8,200

Summary Replacement Year 2022/2023 Future Cost \$10,241

This is to replace the garbage containers.

concrete- 1 metal- 30 slat sided- 9



26000 - Outdoor Equipment

492 - Drinking Fountain Useful Life 20 Remaining Life 9

Park Tennis Courts Quantity 1 Unit of Measure Items

Cost /Itm \$2,460

% Included 100.00% Total Cost/Study \$2,460

Summary Replacement Year 2022/2023 Future Cost \$3,072

This is to replace the drinking fountain. The fountain(s) should be inspected, cleaned and sanitized frequently. Handle assemblies should be lubricated every six months.



### 30000 - Miscellaneous

700 - Tools Useful Life 10 Remaining Life 6

Compressor Quantity 1 Unit of Measure Items

Cost /Itm \$2,562

% Included 100.00% Total Cost/Study \$2,562

Summary Replacement Year 2019/2020 Future Cost \$2,972

This is to replace the Pro4000 compressor.

m/n: RASE60VAD

Cameron Park id#: 4020



30000 - Miscellaneous

704 - Tools Useful Life 10 Remaining Life 4

Grinder/Sander Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2017/2018 Future Cost \$1,697

This is to replace the Grizzly grinder/sander.

m/n: G3105 s/n: 1030135

Cameron Park id#: 4022



708 - Tools Useful Life 10 Remaining Life 4

Bench Grinder Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2017/2018 Future Cost \$1,131

This is to replace the 8" Delta Bench grinder.

m/n: 0841

Cameron Park id#: 4021



30000 - Miscellaneous

712 - Tools Useful Life 10 Remaining Life 4

Bench Grinder Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2017/2018 Future Cost \$1,131

This is to replace the 8" Delta Bench grinder.

m/n: 0841

Cameron Park id#: 4023



716 - Tools Useful Life 10 Remaining Life 4

Drill Press Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2017/2018 Future Cost \$1,697

This is to replace the drill press.

model: DPFS-5650 s/n: D95000303

Cameron Park id#: 4024



30000 - Miscellaneous

814 - Maintenance Equipment Useful Life 20 Remaining Life 4

Woods RM500 Quantity 1 Unit of Measure Items

Cost /Itm \$3,587

% Included 100.00% Total Cost/Study \$3,587

Summary Replacement Year 2017/2018 Future Cost \$3,960

This is to replace the Woods mower.



826 - Maintenance Equipment Useful Life 20 Remaining Life 14

Vermeer 1230 Chipper Quantity 1 Unit of Measure Items

Cost /Itm \$51,250

% Included 100.00% Total Cost/Study \$51,250

Summary Replacement Year 2027/2028 Future Cost \$72,415

This is to replace the Vermeer 1230 Chipper.

model: BC1230

s/n: 1VRK1515XW1001527



30000 - Miscellaneous

834 - Tractor

Massey Ferguson 1525

Quantity 1 Cost /Itm \$20,500

Unit of Measure Items

Total Cost/Study \$20,500 % Included 100.00% Replacement Year 2027/2028 Future Cost \$28,966

Useful Life 20 Remaining Life 14

Summary This is to replace the tractor.

m/n: MF1533 s/n: JPA90457

Cameron Park id#: 4055

Blade/Bucket: - model: MP472 - serial: 0143



838 - Vehicle

Dodge 2500 V8- Lic 1101411

Useful Life 10 Remaining Life 0

Quantity 1 Unit of Measure Items

Cost /Itm \$21,525

% Included 100.00% Total Cost/Study \$21,525 Replacement Year 2013/2014 Future Cost \$21,525

This is to replace the pick up truck.

license- 1101411

Summary

vin: 3B7KC26Z01M535149



30000 - Miscellaneous

846 - Vehicle Useful Life 10 Remaining Life 4

Ford Expedition- Lic 1011647 Quantity 1 Unit of Measure Items

Cost /Itm \$51,250

% Included 100.00% Total Cost/Study \$51,250

Summary Replacement Year 2017/2018 Future Cost \$56,570

This is to replace the Ford Expedition.

license: 1011647

vin: 1FMPU18L1XLB88524



850 - Vehicle Useful Life 10 Remaining Life 5

2008 Ford F150 XL- Lic 1273235 Quantity 1 Unit of Measure Items

Cost /Itm \$25,625

% Included 100.00% Total Cost/Study \$25,625

Summary Replacement Year 2018/2019 Future Cost \$28,992

This is to replace the Ford F150 XL.

license: 1273235

vin: 1FTRF122X8KDO2342



30000 - Miscellaneous

854 - Vehicle Useful Life 10 Remaining Life 4

Dodge Pick Up P-01- Lic 1088018 Quantity 1 Unit of Measure Items

Cost /Itm \$15,375

% Included 100.00% Total Cost/Study \$15,375

Summary Replacement Year 2017/2018 Future Cost \$16,971

This is to replace the Dodge pick up truck.

license: 1088018

vin: 1B7FL26P9YS796328



866 - Vehicle Useful Life 10 Remaining Life 1

Ford Bronco- Lic E041782 Quantity 1 Unit of Measure Items

Cost /Itm \$21,525

% Included 100.00% Total Cost/Study \$21,525

Summary Replacement Year 2014/2015 Future Cost \$22,063

This is to replace the Ford Bronco.

license: E041782

vin: 1FMEV15H7TLB62625



30000 - Miscellaneous

894 - Trailer Useful Life 15 Remaining Life 9

PacWest 20'- Lic. E946571 Quantity 1 Unit of Measure Items

Cost /Itm \$5,125

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2022/2023 Future Cost \$6,400

This is to replace the 20' 4-wheel PacWest trailer.

license #: E946571 Cameron Park id#: 4075 vin: 1P9VF1626RN144219

s/n: 44219-1994



898 - Trailer Useful Life 15 Remaining Life 8

Carson 20'- Lic. 1108445 Quantity 1 Unit of Measure Items

Cost /Itm \$4,100

% Included 100.00% Total Cost/Study \$4,100

Summary Replacement Year 2021/2022 Future Cost \$4,995

This is to replace the 20' 2-wheel Carson trailer.

license #: 1108445 Cameron Park id#: 4074

vin: illegible s/n: illegible



30000 - Miscellaneous

902 - Trailer Useful Life 15 Remaining Life 7

11' Trailer- Lic. E323108 Quantity 1 Unit of Measure Items

Cost /Itm \$2,562

% Included 100.00% Total Cost/Study \$2,562

Summary Replacement Year 2020/2021 Future Cost \$3,046

This is to replace the 11' 2-wheel trailer.

license #: E323108 Cameron Park id#: 4076

vin: illegible s/n: illegible



906 - Trailer Useful Life 15 Remaining Life 6

15' Trailer Quantity 1 Unit of Measure Items

Cost /Itm \$3,075

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2019/2020 Future Cost \$3,566

This is to replace the 15' trailer.

vin: illegible s/n: illegible



30000 - Miscellaneous

910 - Trailer Useful Life 15 Remaining Life 9

12' Trailer- Lic. 4LF5474 Quantity 1 Unit of Measure Items

Cost /Itm \$7,175

% Included 100.00% Total Cost/Study \$7,175

Summary Replacement Year 2022/2023 Future Cost \$8,961

This is to replace the 12' 2-wheel enclosed trailer.

model: VICT612SAFS vin: 4RACS1215AK035025

license: 4LF5474



914 - Trailer

2003 Vintage Trailer- Lic 1152569

Useful Life 15 Remaining Life 5

Quantity 1 Unit of Measure Items

Cost /Itm \$7,687

% Included 100.00% Total Cost/Study \$7,687
Replacement Year 2018/2019 Future Cost \$8,698

This is to replace the Vintage trailer.

m/n: J761204

Summary

s/n: 4P2FB12184V044720

license: 1152569



30000 - Miscellaneous

918 - Trailer Useful Life 15 Remaining Life 7

BBQ Trailer Quantity 1 Unit of Measure Items

Cost /Itm \$4,100

% Included 100.00% Total Cost/Study \$4,100

Summary Replacement Year 2020/2021 Future Cost \$4,874

This is to replace the diamond plate BBQ trailer.



00040 - Rasmussen Park

01000 - Paving

112 - Asphalt: Sealing Useful Life 5 Remaining Life 2

27,200 Sq. Ft. Parking Lot Quantity 27,200 Unit of Measure Square Feet

Cost /SqFt \$0.123

% Included 100.00% Total Cost/Study \$3,346

Summary Replacement Year 2015/2016 Future Cost \$3,515

This is to prepare the surface and apply a single coat asphalt emulsion product. If a second coat is desired the cost is generally 10% to 20% higher.



Summary

01000 - Paving

212 - Asphalt: Ongoing Repairs Useful Life 5 Remaining Life 2

27,200 Sq. Ft. Parking Lot (2%) Quantity 27,200 Unit of Measure Square Feet

Replacement Year 2015/2016

% Included 2.00% Total Cost/Study \$1,812

This is for miscellaneous repairs including crack fill, skin patching and minor dig out & fill.



Future Cost \$1,904

412 - Asphalt: Major Repairs Useful Life 25 Remaining Life 14

27,200 Sq. Ft. Parking Lot Quantity 27,200 Unit of Measure Square Feet

Cost /SqFt \$5.12

% Included 100.00% Total Cost/Study \$139,400

Summary Replacement Year 2027/2028 Future Cost \$196,969

This is for major excavation, re-compaction and installation of new hot asphalt to selected areas.



01000 - Paving

804 - Striping Useful Life 5 Remaining Life 2

Parking Lot Quantity 1 Unit of Measure Lump Sum

Cost /LS \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2015/2016 Future Cost \$1,615

This is to re-stripe asphalt to match existing plan.



## 02000 - Concrete

212 - Walkways Useful Life 5 Remaining Life 2

5,610 Sq. Ft. Park Walkways (2%) Quantity 5,610 Unit of Measure Square Feet

Cost /SqFt \$16.40 Qty \* \$/SqFt \$92,004

% Included 2.00% Total Cost/Study \$1,840

Summary Replacement Year 2015/2016 Future Cost \$1,933

This is to repair, replace or grind concrete flatwork to remove abrupt elevation changes and maintain functionality. Since the concrete useful life exceeds the scope of this study, this component provides for repair only and not full

replacement. Includes the two 9' x 10' concrete ramps at the south play area.



03000 - Painting: Exterior

350 - Touch-Up Useful Life 5 Remaining Life 1

3 Park Buildings Quantity 3 Unit of Measure Building

Cost /Bldg \$512

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2014/2015 Future Cost \$1,576

This is to prepare and either paint or touch-up the building surfaces as needed. This component provides for the concession building, the maintenance building and the wood shed.



### 03500 - Painting: Interior

408 - Restrooms Useful Life 10 Remaining Life 4

1,104 Sq. Ft. Concession Building Quantity 1,104 Unit of Measure Square Feet

Restrooms Cost /SqFt \$1.02

% Included 100.00% Total Cost/Study \$1,132

Summary Replacement Year 2017/2018 Future Cost \$1,249

This is to prepare and paint the restroom interiors.



04000 - Structural Repairs

554 - Bridge Maintenance Useful Life 20 Remaining Life 9

Park Pedestrian Bridge Quantity 1 Unit of Measure Items

Cost /Itm \$2,562

% Included 100.00% Total Cost/Study \$2,562

Summary Replacement Year 2022/2023 Future Cost \$3,200

This is to maintain the bridge.



05000 - Roofing

460 - Pitched: Dimensional Composition Useful Life 25 Remaining Life 14

3 Squares- Maint. Bldg & Wood Shed Quantity 3 Unit of Measure Squares

Cost /Sqrs \$410

% Included 100.00% Total Cost/Study \$1,230

Summary Replacement Year 2027/2028 Future Cost \$1,738

This is to reroof with a dimensional composition roofing product. Composition roofs should be regularly inspected and repaired as indicated to ensure maximum life.



05000 - Roofing

684 - Pitched: Metal Useful Life 30 Remaining Life 19

6 Squares- Concession Building Quantity 6 Unit of Measure Squares

Cost /Sqrs \$512

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2032/2033 Future Cost \$4,916

This is to replace the metal roofing system. With proper maintenance, this component's life may be extended.



864 - Skylights Useful Life 20 Remaining Life 9

2 Concession Building Restrooms Quantity 2 Unit of Measure Items

Cost /Itm \$410

% Included 100.00% Total Cost/Study \$820

Summary Replacement Year 2022/2023 Future Cost \$1,024

This is to replace the skylights.



08000 - Rehab

246 - Restrooms Useful Life 20 Remaining Life 9

2 Concession Stand Restrooms Quantity 2 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2022/2023 Future Cost \$3,840

This is to rehab and redecorate the restrooms. Includes items such as partitions, fixtures, lighting, tile, etc. This item can be further defined with association input.



250 - Kitchen Useful Life 20 Remaining Life 9

Concession Stand Interior Quantity 1 Unit of Measure Room

Cost /Rm \$3,075

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2022/2023 Future Cost \$3,840

This is to rehab and redecorate the snack bar area of the concession stand.

In 2012/2013, the concession stand interior was inaccessible and not visually inspected.

# 18000 - Landscaping

104 - Irrigation: Misc. Useful Life 3 Remaining Life 1

Park Irrigation Quantity 1 Unit of Measure Lump Sum

Cost /LS \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2014/2015 Future Cost \$1,051

This is for major irrigation system repair in excess of the operating budget.

18000 - Landscaping

340 - Irrigation: Pumps Useful Life 5 Remaining Life 2

Park- Irrigation Pump Quantity 1 Unit of Measure Items

Cost /Itm \$1,230

% Included 100.00% Total Cost/Study \$1,230

Summary Replacement Year 2015/2016 Future Cost \$1,292

This is to replace the irrigation system pump.



420 - General Repairs/Upgrades Useful Life 3 Remaining Life 1

Park Quantity 1 Unit of Measure Lump Sum

Cost /LS \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2014/2015 Future Cost \$1,051

This is to have funds in excess of the operating budget for miscellaneous plantings, removals and other work as directed by the association.



## 18000 - Landscaping

474 - Pathways & Trails Useful Life 5 Remaining Life 2

15,570 Sq. Ft. Park- Walking Path (10%) Quantity 15,570 Unit of Measure Square Feet

Cost /SqFt \$5.12 Qty \* \$/SqFt \$79,796

% Included 10.00% Total Cost/Study \$7,980

Summary Replacement Year 2015/2016 Future Cost \$8,384

This is to maintain pathways and trails.



498 - Bedding Header Useful Life 20 Remaining Life 9

252 Lin. Ft. South Play Area Quantity 252 Unit of Measure Linear Feet

Cost /l.f. \$3.07

% Included 100.00% Total Cost/Study \$775

Summary Replacement Year 2022/2023 Future Cost \$968

This is to repair and replace the wood header board at the south tot lot perimeter.



19000 - Fencing

100 - Chain Link Useful Life 30 Remaining Life 28

36 Lin. Ft. Tee Ball Field 5' Chain Link Quantity 36 Unit of Measure Linear Feet

Cost /l.f. \$11.27

% Included 100.00% Total Cost/Study \$406

Summary Replacement Year 2041/2042 Future Cost \$810

This is to replace the 5' chain link fencing.



116 - Chain Link Useful Life 30 Remaining Life 14

1,850 Lin. Ft. Ball Fields- 5' Chain Link Quantity 1,850 Unit of Measure Linear Feet

Cost /l.f. \$11.27

% Included 100.00% Total Cost/Study \$20,859

Summary Replacement Year 2027/2028 Future Cost \$29,473

This is to replace the 5' chain link fencing.

925 linear feet- east ball field 925 linear feet- west ball field



124 - Chain Link: 6' Useful Life 30 Remaining Life 28

170 Lin. Ft. Tee Ball Field Quantity 170 Unit of Measure Linear Feet

Cost /l.f. \$12.30

% Included 100.00% Total Cost/Study \$2,091

Summary Replacement Year 2041/2042 Future Cost \$4,175

This is to replace the 6' chain link fencing.

19000 - Fencing

140 - Chain Link: 6' Useful Life 30 Remaining Life 14

332 Lin. Ft. North Play Area Perimeter Quantity 332 Unit of Measure Linear Feet

Cost /l.f. \$12.30

% Included 100.00% Total Cost/Study \$4,084

Summary Replacement Year 2027/2028 Future Cost \$5,770

This is to replace the 6' chain link fencing.



144 - Chain Link: 8' Useful Life 30 Remaining Life 28

65 Lin. Ft. Tee Ball Field Quantity 65 Unit of Measure Linear Feet

Cost /l.f. \$14.35

% Included 100.00% Total Cost/Study \$933

Summary Replacement Year 2041/2042 Future Cost \$1,862

This is to replace the 8' chain link fencing.



19000 - Fencing

148 - Chain Link: 8' Useful Life 30 Remaining Life 14

400 Lin. Ft. Ball Fields Quantity 400 Unit of Measure Linear Feet

Cost /l.f. \$14.35

% Included 100.00% Total Cost/Study \$5,740

Summary Replacement Year 2027/2028 Future Cost \$8,110

This is to replace the 8' chain link fencing.



152 - Chain Link Useful Life 30 Remaining Life 14

150 Lin. Ft. Ball Field Back Stops Quantity 150 Unit of Measure Linear Feet

Cost /l.f. \$25.62

% Included 100.00% Total Cost/Study \$3,844

Summary Replacement Year 2027/2028 Future Cost \$5,431

This is to replace the 15' chain link back stop fencing.



19000 - Fencing

344 - Wood: 6' Useful Life 18 Remaining Life 8

Quantity 885 Unit of Measure Linear Feet 885 Lin. Ft. East & West Perimeter

Cost /l.f. \$25.62

% Included 100.00% Total Cost/Study \$22,678

Summary Replacement Year 2021/2022 Future Cost \$27,631

This is to replace the 6' wood fencing including discarded fence material removal and disposal.

465 linear feet- east 420 linear feet- west



514 - Post & Cable Useful Life 25 Remaining Life 14

Quantity 730 Unit of Measure Linear Feet 730 Lin. Ft. Parking Perimeter

Cost /l.f. \$20.50

% Included 100.00% Total Cost/Study \$14,965

Replacement Year 2027/2028 Future Cost \$21,145 Summary

This is to repair and replace the post and cable fence.

380 linear feet- west parking

350 linear feet- east parking



## 19000 - Fencing

540 - Metal Useful Life 25 Remaining Life 14

980 Lin. Ft. South Perimeter- Post & Wire Quantity 980 Unit of Measure Linear Feet

Cost /l.f. \$10.25

Total Cost/Study \$10,045 % Included 100.00%

Summary Replacement Year 2027/2028 Future Cost \$14,193

This is to replace the metal t-bar post and barbed wire fencing.



# 19500 - Retaining Wall

Useful Life 30 Remaining Life 19 364 - Masonry Wall

Quantity 332 Unit of Measure Linear Feet 332 Lin. Ft. North Play Area

Cost /l.f. \$41.00

% Included 100.00% Total Cost/Study \$13,612

Summary Replacement Year 2032/2033 Future Cost \$21,761

This is to replace the 1 foot nominal height masonry retaining wall located at the tot lot perimeter, beneath the 6'

chain link fencing.



## 21000 - Signage

794 - Wood Monument Useful Life 10 Remaining Life 4

Park Sign Quantity 1 Unit of Measure Items

Cost /Itm \$2,562

% Included 100.00% Total Cost/Study \$2,562

Summary Replacement Year 2017/2018 Future Cost \$2,829

This is to replace the custom identity wood monument sign.



# 25000 - Flooring

404 - Tile Useful Life 20 Remaining Life 9

224 Sq. Ft. Concession Building Restrooms Quantity 224 Unit of Measure Square Feet

Cost /SqFt \$6.15

% Included 100.00% Total Cost/Study \$1,378

Summary Replacement Year 2022/2023 Future Cost \$1,720

This is to replace the tile flooring.



26000 - Outdoor Equipment

100 - Tot Lot: Play Equipment Useful Life 20 Remaining Life 14

North Play Area Quantity 1 Unit of Measure Items

Cost /Itm \$25,625

% Included 100.00% Total Cost/Study \$25,625

Summary Replacement Year 2027/2028 Future Cost \$36,207

This is to replace the tot lot play equipment.



120 - Tot Lot: Play Equipment Useful Life 20 Remaining Life 14

South Play Area Quantity 1 Unit of Measure Items

Cost /Itm \$10,250

% Included 100.00% Total Cost/Study \$10,250

Summary Replacement Year 2027/2028 Future Cost \$14,483

This is to replace the tot lot play equipment.

1- 4-swing set

3- small play pieces



26000 - Outdoor Equipment

140 - Tot Lot: Safety Surface Useful Life 3 Remaining Life 1

10,410 Sq. Ft. North & South Play Areas Quantity 10,410 Unit of Measure Square Feet

Cost /SqFt \$0.256

% Included 100.00% Total Cost/Study \$2,668

Summary Replacement Year 2014/2015 Future Cost \$2,734

This is to replenish the play area engineered wood fiber impact absorbing safety material.

6,360 sq ft- north play area 4,050 sq ft- south play area



294 - Picnic Table: Cement Useful Life 20 Remaining Life 9

2 Park Picnic Tables Quantity 2 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2022/2023 Future Cost \$1,280

This is to replace the cement picnic tables.



26000 - Outdoor Equipment

304 - Picnic Table: Wood Useful Life 15 Remaining Life 7

2 Park Picnic Tables Quantity 2 Unit of Measure Items

Cost /Itm \$410

% Included 100.00% Total Cost/Study \$820

Summary Replacement Year 2020/2021 Future Cost \$975

This is to replace the wood picnic table.



312 - Benches Useful Life 20 Remaining Life 9

6 Park- Metal Benches Quantity 6 Unit of Measure Items

Cost /Itm \$615

% Included 100.00% Total Cost/Study \$3,690

Summary Replacement Year 2022/2023 Future Cost \$4,608

This is to replace the metal benches.

2- play area benches

4- dug out benches

26000 - Outdoor Equipment

320 - Benches

6 Park- Wood Benches

Useful Life 12 Remaining Life 5

Quantity 6 Unit of Measure Items

Cost /Itm \$615

% Included 100.00% Total Cost/Study \$3,690

Replacement Year 2018/2019 Future Cost \$4,175

This is to replace the benches.

4- park area

4 Park

Summary

2- t-ball field dug out benches



380 - Pet Stations Useful Life 15 Remaining Life

Quantity 4 Unit of Measure Items

Cost /Itm \$266

% Included 100.00% Total Cost/Study \$1,066

Summary Replacement Year 2020/2021 Future Cost \$1,267

This is to replace the pet stations.



26000 - Outdoor Equipment

384 - Garbage Receptacles Useful Life 20 Remaining Life 9

6 Park- Trash Cans Quantity 6 Unit of Measure Items

Cost /Itm \$205

% Included 100.00% Total Cost/Study \$1,230

Summary Replacement Year 2022/2023 Future Cost \$1,536

This is to replace the garbage containers.



440 - Bleachers: Aluminum Useful Life 20 Remaining Life 9

4 Ball Field Bleachers Quantity 4 Unit of Measure Items

Cost /Itm \$3,075

% Included 100.00% Total Cost/Study \$12,300

Summary Replacement Year 2022/2023 Future Cost \$15,361

This is to replace the aluminum bleachers.



26000 - Outdoor Equipment

484 - Drinking Fountain Useful Life 20 Remaining Life 9

Park- Drinking Fountain Quantity 1 Unit of Measure Items

Cost /Itm \$2,460

% Included 100.00% Total Cost/Study \$2,460

Summary Replacement Year 2022/2023 Future Cost \$3,072

This is to replace the drinking fountain. The fountain should be inspected, cleaned and sanitized frequently. Handle assemblies should be lubricated every six months.



840 - Shade Structure Useful Life 20 Remaining Life 11

1,240 Sq. Ft. North Play Area Quantity 1,240 Unit of Measure Square Feet

Cost /SqFt \$5.12

% Included 100.00% Total Cost/Study \$6,355

Summary Replacement Year 2024/2025 Future Cost \$8,338

This is to replace the sail fabric shade structure and perform repairs as needed to the 4 metal support posts.

In 2012/2013, the sail fabric is torn.

01000 - Paving

116 - Asphalt: Sealing Useful Life 5 Remaining Life 1

18,563 Sq. Ft. Parking Lot Quantity 18,563 Unit of Measure Square Feet

Cost /SqFt \$0.123

% Included 100.00% Total Cost/Study \$2,283

Summary Replacement Year 2014/2015 Future Cost \$2,340

This is to prepare the surface and apply a single coat asphalt emulsion product. If a second coat is desired the cost is generally 10% to 20% higher.



216 - Asphalt: Ongoing Repairs

18,563 Sq. Ft. Parking Lot (2%)

Useful Life 5 Remaining Life 1

Quantity 18,563 Unit of Measure Square Feet Cost /SqFt \$3.33 Qty \* \$/SqFt \$61,838

% Included 2.00% Total Cost/Study \$1,237

Summary Replacement Year 2014/2015 Future Cost \$1,268

This is for miscellaneous repairs including crack fill, skin patching and minor dig out & fill.



01000 - Paving

416 - Asphalt: Major Repairs Useful Life 25 Remaining Life 14

18,563 Sq. Ft. Parking Lot Quantity 18,563 Unit of Measure Square Feet

Cost /SqFt \$5.12

% Included 100.00% Total Cost/Study \$95,135

Summary Replacement Year 2027/2028 Future Cost \$134,424

This is for major excavation, re-compaction and installation of new hot asphalt to selected areas.



## 02000 - Concrete

216 - Walkways Useful Life 5 Remaining Life 2

2,720 Sq. Ft. Park Walkways (3%) Quantity 2,720 Unit of Measure Square Feet

Cost /SqFt \$16.40 Qty \* \$/SqFt \$44,608 % Included 3.00% Total Cost/Study \$1,338

Summary Replacement Year 2015/2016 Future Cost \$1,406

This is to repair, replace or grind concrete flatwork to remove abrupt elevation changes and maintain functionality. Since the concrete useful life exceeds the scope of this study, this component provides for repair only and not full

replacement.



### 02000 - Concrete

900 - Miscellaneous Useful Life 10 Remaining Life 4

16,000 Sq. Ft. Skate Park Concrete (10%) Quantity 16,000 Unit of Measure Square Feet

Cost /SqFt \$20.50 Qty \* \$/SqFt \$328,000

% Included 10.00% Total Cost/Study \$32,800

Summary Replacement Year 2017/2018 Future Cost \$36,205

This is for miscellaneous concrete repair.



# 03000 - Painting: Exterior

404 - Wrought Iron Useful Life 4 Remaining Life 1

490 Lin. Ft. Play Area Perimeter Quantity 490 Unit of Measure Linear Feet

Cost /l.f. \$9.22

% Included 100.00% Total Cost/Study \$4,520

Summary Replacement Year 2014/2015 Future Cost \$4,633

This is to prepare, power wash, sand, scrape, spot prime and paint the wrought iron.



03500 - Painting: Interior

404 - Restrooms Useful Life 10 Remaining Life 4

1,216 Sq. Ft. Restroom Building Quantity 1,216 Unit of Measure Square Feet

Cost /SqFt \$1.02

% Included 100.00% Total Cost/Study \$1,246

Summary Replacement Year 2017/2018 Future Cost \$1,376

This is to prepare and paint the restroom interiors.



# 04000 - Structural Repairs

994 - Miscellaneous Useful Life 20 Remaining Life 14

300 Sq. Ft. Decorative Wall Resurfacing Quantity 300 Unit of Measure Square Feet

Cost /SqFt \$20.50

% Included 100.00% Total Cost/Study \$6,150

Summary Replacement Year 2027/2028 Future Cost \$8,690

This is to resurface the decorative tile covered masonry wall.



05000 - Roofing

440 - Pitched: Dimensional Composition Useful Life 25 Remaining Life 14

5 Squares- Restroom Building Quantity 5 Unit of Measure Squares

Cost /Sqrs \$410

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2027/2028 Future Cost \$2,897

This is to reroof with a dimensional composition roofing product. Composition roofs should be regularly inspected and repaired as indicated to ensure maximum life.



456 - Pitched: Dimensional Composition

Skate Park Building

Useful Life 25 Remaining Life 4

Quantity 1 Unit of Measure Squares

Cost /Sqrs \$410

% Included 100.00% Total Cost/Study \$410

Summary Replacement Year 2017/2018 Future Cost \$453

This is to reroof with a dimensional composition roofing product. Composition roofs should be regularly inspected and repaired as indicated to ensure maximum life.



08000 - Rehab

112 - General Useful Life 10 Remaining Life 1

Skate Park Building Quantity 1 Unit of Measure Building

Cost /Bldg \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2014/2015 Future Cost \$1,576

This is for a general rehab of the skate park building. Includes lighting, trim, structural repairs and doors.



230 - Restrooms Useful Life 10 Remaining Life 1

Restroom Building Quantity 1 Unit of Measure Lump Sum

Cost /LS \$2,050

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2014/2015 Future Cost \$2,101

This is to rehab and redecorate the restrooms. Includes items such as partitions, fixtures, lighting, tile, etc. This item can be further defined with district input. Painting is provided for in another component.



19000 - Fencing

108 - Chain Link: 4' Useful Life 30 Remaining Life 19

855 Lin. Ft. North Perimeter Quantity 855 Unit of Measure Linear Feet

Cost /l.f. \$11.27

% Included 100.00% Total Cost/Study \$9,640

Summary Replacement Year 2032/2033 Future Cost \$15,411

This is to replace the 4' chain link fencing.



120 - Chain Link: 6' Useful Life 30 Remaining Life 19

1,190 Lin. Ft. South & East Perimeter Quantity 1,190 Unit of Measure Linear Feet

Cost /l.f. \$12.30

% Included 100.00% Total Cost/Study \$14,637

Summary Replacement Year 2032/2033 Future Cost \$23,399

This is to replace the 6' chain link fencing.

860 linear feet- south perimeter 330 linear feet- east perimeter

136 - Chain Link: 6' Useful Life 30 Remaining Life 19

260 Lin. Ft. Skate Park Perimeter Quantity 260 Unit of Measure Linear Feet

Cost /l.f. \$12.30

% Included 100.00% Total Cost/Study \$3,198

Summary Replacement Year 2032/2033 Future Cost \$5,112

This is to replace the 6' chain link fencing.



19000 - Fencing

220 - Wrought Iron: 4' Useful Life 30 Remaining Life 19

490 Lin. Ft. Play Area Perimeter Quantity 490 Unit of Measure Linear Feet

Cost /l.f. \$30.75

% Included 100.00% Total Cost/Study \$15,067

Summary Replacement Year 2032/2033 Future Cost \$24,088

This is to replace the 4' wrought iron fencing. With aggressive paint maintenance, this component's life may be extended. Painting is provided for within another component.



360 - Wood: 6'

395 Lin. Ft. West Perimeter Fence

Useful Life 18 Remaining Life 8

Quantity 395 Unit of Measure Linear Feet

Cost /l.f. \$25.62

% Included 100.00% Total Cost/Study \$10,122

Summary Replacement Year 2021/2022 Future Cost \$12,333

This is to replace the 6' wood fencing including discarded fence material removal and disposal.



### 19000 - Fencing

518 - Post & Cable Useful Life 25 Remaining Life 9

525 Lin. Ft. Parking Lot Perimeter (No Quantity 525 Unit of Measure Linear Feet

Cable) Cost /l.f. \$20.50

% Included 100.00% Total Cost/Study \$10,762

Summary Replacement Year 2022/2023 Future Cost \$13,441

This is to repair and replace the post and cable fence.



# 19500 - Retaining Wall

360 - Masonry Wall Useful Life 30 Remaining Life 19

490 Lin. Ft. Play Area Perimeter Quantity 490 Unit of Measure Linear Feet

Cost /l.f. \$41.00

% Included 100.00% Total Cost/Study \$20,090

Summary Replacement Year 2032/2033 Future Cost \$32,117

This is to replace the 2' nominal height masonry retaining wall.



21000 - Signage

790 - Wood Monument Useful Life 10 Remaining Life 4

Park Monument Sign Quantity 1 Unit of Measure Items

Cost /Itm \$2,562

% Included 100.00% Total Cost/Study \$2,562

Summary Replacement Year 2017/2018 Future Cost \$2,829

This is to replace the custom identity wood monument sign.



# 26000 - Outdoor Equipment

112 - Tot Lot: Play Equipment Useful Life 20 Remaining Life 13

Park Large Play Structure Quantity 1 Unit of Measure Lump Sum

Cost /LS \$30,750

% Included 100.00% Total Cost/Study \$30,750

Summary Replacement Year 2026/2027 Future Cost \$42,389

This is to replace the tot lot play equipment.



26000 - Outdoor Equipment

116 - Tot Lot: Play Equipment Useful Life 20 Remaining Life 13

2 Park- Smaller Structures Quantity 2 Unit of Measure Items

Cost /Itm \$7,687

% Included 100.00% Total Cost/Study \$15,375

Summary Replacement Year 2026/2027 Future Cost \$21,195

This is to replace the tot lot play equipment.

1- 4-swing set (missing swings)

1- tire swing



284 - Picnic Tables Useful Life 20 Remaining Life 9

5 Park Picnic Tables Quantity 5 Unit of Measure Items

Cost /Itm \$615

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2022/2023 Future Cost \$3,840

This is to replace the picnic tables.

4- wood

1- metal



26000 - Outdoor Equipment

324 - Benches Useful Life 20 Remaining Life 14

10 Park Metal Benches Quantity 10 Unit of Measure Items

Cost /Itm \$717

% Included 100.00% Total Cost/Study \$7,175

Summary Replacement Year 2027/2028 Future Cost \$10,138

This is to replace the plastic coated, expanded metal benches.

8- play area

2- skate park (poor condition)



396 - Garbage Receptacles Useful Life 20 Remaining Life 9

10 Park Trash Cans Quantity 10 Unit of Measure Items

Cost /Itm \$205

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2022/2023 Future Cost \$2,560

This is to replace the garbage containers.



26000 - Outdoor Equipment

488 - Drinking Fountain Useful Life 20 Remaining Life 9

3 Park Drinking Fountains Quantity 3 Unit of Measure Items

Cost /Itm \$2,460

% Included 100.00% Total Cost/Study \$7,380

Summary Replacement Year 2022/2023 Future Cost \$9,217

This is to replace the drinking fountain. The fountains should be inspected, cleaned and sanitized frequently. Handle assemblies should be lubricated every six months.

1- restroom building

- 1- skate park
- 1- picnic area



00060 - Chardi Corner 18000 - Landscaping

116 - Irrigation: Controllers Useful Life 10 Remaining Life 4

Chardi Corner- Irrigation Controller Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2017/2018 Future Cost \$1,131

This is to replace the irrigation controller.



18000 - Landscaping

300 - Irrigation: Backflow Preventors Useful Life 20 Remaining Life 9

Chardi Corner- Backflow Prevention Device Quantity 1 Unit of Measure Items

Cost /Itm \$615

% Included 100.00% Total Cost/Study \$615

Summary Replacement Year 2022/2023 Future Cost \$768

This is to replace the backflow prevention valves.



424 - General Repairs/Upgrades Useful Life 3 Remaining Life 1

Chardi Corner Quantity 1 Unit of Measure Lump Sum

Cost /LS \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2014/2015 Future Cost \$1,051

This is to have funds in excess of the operating budget for miscellaneous plantings, removals and other work as

directed by the association.



### 19000 - Fencing

348 - Wood: 6' Useful Life 18 Remaining Life 8

300 Lin. Ft. Chardi Corner- Perimeter Quantity 300 Unit of Measure Linear Feet

Fencing Cost /l.f. \$25.62

% Included 100.00% Total Cost/Study \$7,687

Summary Replacement Year 2021/2022 Future Cost \$9,366

This is to replace the 6' wood fencing including discarded fence material removal and disposal.



# 19500 - Retaining Wall

368 - Masonry Wall Useful Life 30 Remaining Life 19

380 Lin. Ft. Chardi Corner- Perimeter Wall Quantity 380 Unit of Measure Linear Feet

Cost /l.f. \$41.00

% Included 100.00% Total Cost/Study \$15,580

Summary Replacement Year 2032/2033 Future Cost \$24,907

This is to repair, maintain, and replace the retaining wall.



### 20000 - Lighting

220 - Landscape Useful Life 12 Remaining Life 5

Quantity 3 Unit of Measure Items 3 Chardi Corner- Sign Lights

Cost /Itm \$410

% Included 100.00% Total Cost/Study \$1,230

Summary Replacement Year 2018/2019 Future Cost \$1,392

This is to replace the landscape lighting. This component assumes that existing wiring and conduits will be reused.



# 21000 - Signage

Useful Life 5 Remaining Life 3 782 - Monument

Unit of Measure Linear Feet 35 Lin. Ft. Chardi Corner- Monument Sign Quantity 35 (25%)Qty \* \$/l.f. \$8,969 Cost /l.f. \$256

> % Included 25.00% Total Cost/Study \$2,242

Summary Replacement Year 2016/2017 Future Cost \$2,415

This is to maintain, repair, and replace the custom identity monument sign. Includes replacement of the metal lettering, as needed.



26000 - Outdoor Equipment

064 - Flag Pole Useful Life 20 Remaining Life 9

Chardi Corner- Flag Pole Quantity 1 Unit of Measure Items

Cost /Itm \$4,100

% Included 100.00% Total Cost/Study \$4,100

Summary Replacement Year 2022/2023 Future Cost \$5,120

This is to replace the flagpole.



00070 - Hacienda Park

01000 - Paving

120 - Asphalt: Sealing Useful Life 5 Remaining Life 2

4,500 Sq. Ft. Hacienda- Parking Lot Quantity 4,500 Unit of Measure Square Feet

Cost /SqFt \$0.123

% Included 100.00% Total Cost/Study \$553

Summary Replacement Year 2015/2016 Future Cost \$582

This is to prepare the surface and apply a single coat asphalt emulsion product. If a second coat is desired the cost is generally 10% to 20% higher.



## 01000 - Paving

220 - Asphalt: Ongoing Repairs Useful Life 5 Remaining Life 2

4,500 Sq. Ft. Hacienda Parking Lot (3%) Quantity 4,500 Unit of Measure Square Feet

% Included 3.00% Total Cost/Study \$450

Summary Replacement Year 2015/2016 Future Cost \$472

This is for miscellaneous repairs including crack fill, skin patching and minor dig out & fill.



420 - Asphalt: Major Repairs Useful Life 25 Remaining Life 14

4,500 Sq. Ft. Hacienda- Parking Lot Quantity 4,500 Unit of Measure Square Feet

Cost /SqFt \$5.12

% Included 100.00% Total Cost/Study \$23,062

Summary Replacement Year 2027/2028 Future Cost \$32,587

This is for major excavation, re-compaction and installation of new hot asphalt to selected areas.



### 02000 - Concrete

380 - Pad Useful Life 10 Remaining Life 2

462 Sq. Ft. [5] Concrete Slabs (10%) Quantity 462 Unit of Measure Square Feet

Cost /SqFt \$20.50 Qty \* \$/SqFt \$9,471 % Included 10.00% Total Cost/Study \$947

Summary Replacement Year 2015/2016 Future Cost \$995

This is to replace the concrete pads.

3- picnic table pads- 12' x 10'

1- bench pad- 9' x 6'

1- drinking fountain pad- 6' x 8'

In 2012/2013, one of the picnic table pads had a cracked corner.



### 04000 - Structural Repairs

998 - Miscellaneous Useful Life 5 Remaining Life 3

Park- Shed- Upkeep Quantity 1 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$512

Summary Replacement Year 2016/2017 Future Cost \$552

This is to paint and maintain the wood storage shed.

approximately 130 sq ft of paintable wood surface approximately 50 sq ft of dimensional composition roofing



18000 - Landscaping

100 - Irrigation: Misc. Useful Life 3 Remaining Life 0

Park Quantity 1 Unit of Measure Lump Sum

Cost /LS \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2013/2014 Future Cost \$1,025

This is for major irrigation system repair in excess of the operating budget.



450 - Drainage System Maint. Useful Life 3 Remaining Life 1

Deer Creek Tributary Quantity 1 Unit of Measure Lump Sum

Cost /LS \$2,050

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2014/2015 Future Cost \$2,101

This is to repair the common area drainage system as needed. District input will further define this component.



18000 - Landscaping

470 - Pathways & Trails Useful Life 10 Remaining Life 4

29,465 Sq. Ft. Park- DG Paths (20%) Quantity 29,465 Unit of Measure Square Feet Cost /SqFt \$5.12 Qty \* \$/SqFt \$151,008

% Included 20.00% Total Cost/Study \$30,202

Summary Replacement Year 2017/2018 Future Cost \$33,337

This is to replenish decomposed granite and maintain the walking paths. Includes approximately 300 linear feet of cobble path lining.



494 - Bedding Header Useful Life 20 Remaining Life 14

420 Lin. Ft. Turf Perimeter Quantity 420 Unit of Measure Linear Feet

Cost /l.f. \$3.07

% Included 100.00% Total Cost/Study \$1,291

Summary Replacement Year 2027/2028 Future Cost \$1,825

This is to replace the trex-type header board.



### 18000 - Landscaping

500 - Tree Maintenance Useful Life 5 Remaining Life 2

Park- Scrub & Heritage Oaks Quantity 1 Unit of Measure Lump Sum

Cost /LS \$5,125

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2015/2016 Future Cost \$5,384

This is to prune, remove and replace trees as needed to enhance the association's landscaping and to avoid branch and root damage to nearby objects. This is in excess of the operating budget.



### 19000 - Fencing

112 - Chain Link: 4' Useful Life 20 Remaining Life 9

100 Lin. Ft. Creek Perimeter Quantity 100 Unit of Measure Linear Feet

Cost /l.f. \$11.27

% Included 100.00% Total Cost/Study \$1,127

Summary Replacement Year 2022/2023 Future Cost \$1,408

This is to replace the 4' chain link fencing.



19000 - Fencing

364 - Wood: Split Rail Useful Life 20 Remaining Life 14

765 Lin. Ft. Park Perimeter Quantity 765 Unit of Measure Linear Feet

Cost /l.f. \$15.37

% Included 100.00% Total Cost/Study \$11,762

Summary Replacement Year 2027/2028 Future Cost \$16,619

This is to replace the split rail fencing.



510 - Post & Cable Useful Life 10 Remaining Life 4

26 Parking Lot Posts (50%) Quantity 26 Unit of Measure Items

Cost /Itm \$102 Qty \* \$/Itm \$2,665 % Included 50.00% Total Cost/Study \$1,332

Summary Replacement Year 2017/2018 Future Cost \$1,471

This is to repair and replace the 3' tall 12" diameter wood posts at the parking lot perimeter.



## 21000 - Signage

798 - Wood Monument Useful Life 10 Remaining Life 6

Park Sign Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2019/2020 Future Cost \$1,189

This is to replace the custom identity wood monument sign.



# 26000 - Outdoor Equipment

290 - Picnic Table: Cement Useful Life 20 Remaining Life 14

3 Park- Picnic Tables Quantity 3 Unit of Measure Items

Cost /Itm \$769

% Included 100.00% Total Cost/Study \$2,306

Summary Replacement Year 2027/2028 Future Cost \$3,259

This is to replace the cement picnic tables.



26000 - Outdoor Equipment

316 - Benches Useful Life 20 Remaining Life 14

Park Bench Quantity 1 Unit of Measure Items

Cost /Itm \$615

% Included 100.00% Total Cost/Study \$615

Summary Replacement Year 2027/2028 Future Cost \$869

This is to replace the concrete bench.



376 - Pet Stations Useful Life 15 Remaining Life 9

Park- Pet Station Quantity 1 Unit of Measure Items

Cost /Itm \$266

% Included 100.00% Total Cost/Study \$266

Summary Replacement Year 2022/2023 Future Cost \$333

This is to replace the pet stations.



26000 - Outdoor Equipment

388 - Garbage Receptacles Useful Life 20 Remaining Life 14

2 Park- Trash Cans Quantity 2 Unit of Measure Items

Cost /Itm \$205

% Included 100.00% Total Cost/Study \$410

Summary Replacement Year 2027/2028 Future Cost \$579

This is to replace the garbage containers.



480 - Drinking Fountain Useful Life 20 Remaining Life 14

Park- Drinking Fountain Quantity 1 Unit of Measure Items

Cost /Itm \$2,460

% Included 100.00% Total Cost/Study \$2,460

Summary Replacement Year 2027/2028 Future Cost \$3,476

This is to replace the drinking fountain. The fountain should be inspected, cleaned and sanitized frequently. Handle

assemblies should be lubricated every six months.



01000 - Paving

100 - Asphalt: Sealing Useful Life 5 Remaining Life 4

3,950 Sq. Ft. Parking Lot- Seal & Stripe Quantity 3,950 Unit of Measure Square Feet

Cost /SqFt \$0.246

% Included 100.00% Total Cost/Study \$972

Summary Replacement Year 2017/2018 Future Cost \$1,073

This is to prepare the surface, apply a single coat asphalt emulsion product and stripe the parking lot per existing plan.

2013- per client, sealed for \$0.24/sq ft



200 - Asphalt: Ongoing Repairs Useful Life 10 Remaining Life 4

3,950 Sq. Ft. Parking Lot (5%) Quantity 3,950 Unit of Measure Square Feet

Summary Replacement Year 2017/2018 Future Cost \$726

This is for miscellaneous repairs including crack fill, skin patching and minor dig out & fill.



## 01000 - Paving

400 - Asphalt: Major Repairs Useful Life 25 Remaining Life 17

3,950 Sq. Ft. Parking Lot (50%) Quantity 3,950 Unit of Measure Square Feet

Cost /SqFt \$4.10 Qty \* \$/SqFt \$16,195

% Included 50.00% Total Cost/Study \$8,097

Summary Replacement Year 2030/2031 Future Cost \$12,321

This is for major excavation, re-compaction and installation of new hot asphalt to selected areas.



### 02000 - Concrete

200 - Sidewalks, Curbs & Gutters Useful Life 5 Remaining Life 2

2,400 Sq. Ft. Exterior Concrete (3%) Quantity 2,400 Unit of Measure Square Feet

Cost /SqFt \$16.40 Qty \* \$/SqFt \$39,360

% Included 3.00% Total Cost/Study \$1,181

Summary Replacement Year 2015/2016 Future Cost \$1,241

This is to repair, replace or grind concrete sidewalks, curbs and gutters to remove abrupt elevation changes and maintain functionality. The concrete useful life exceeds the scope of this study, so this component provides for

repair only.



### 02000 - Concrete

710 - Sealing Useful Life 5 Remaining Life 2

1,225 Sq. Ft. Vehicle Bays- Concrete Floors Quantity 1,225 Unit of Measure Square Feet

Cost /SqFt \$2.20

% Included 100.00% Total Cost/Study \$2,700

Summary Replacement Year 2015/2016 Future Cost \$2,836

This is to seal the concrete to discourage moisture.



# 03000 - Painting: Exterior

100 - Surface Restoration Useful Life 5 Remaining Life 2

360 Sq. Ft. Patio Shed- Paint & Repair Quantity 360 Unit of Measure Square Feet

Cost /SqFt \$3.07

% Included 100.00% Total Cost/Study \$1,107

Summary Replacement Year 2015/2016 Future Cost \$1,163

This is to prepare, power wash, sand, scrape, caulk and paint with a 100% premium acrylic paint. Also provides for minor repairs that may be needed in conjunction with paining.



03000 - Painting: Exterior

310 - Trim Useful Life 5 Remaining Life 2

825 Sq. Ft. Station 88- Wood Trim Quantity 825 Unit of Measure Square Feet

Cost /SqFt \$1.02

% Included 100.00% Total Cost/Study \$846

Summary Replacement Year 2015/2016 Future Cost \$888

This is to prepare and paint the wood trim, fascia, and soffits.



# 03500 - Painting: Interior

110 - Building Useful Life 10 Remaining Life 4

7,122 Sq. Ft. Station 88- Interior Spaces Quantity 7,122 Unit of Measure Square Feet

Cost /SqFt \$1.02

% Included 100.00% Total Cost/Study \$7,300

Summary Replacement Year 2017/2018 Future Cost \$8,058

This is to prepare and paint all building interior spaces.

kitchen- 500 sq ft lounge- 606 sq ft multi-quarters- 900 sq ft bathroom- 191 sq ft single-quarters- 488 sq ft restroom- 146 sq ft lobby- 666 sq ft hall- 300 sq ft vehicle bays- 3,325 sq ft



04000 - Structural Repairs

364 - Garbage Enclosure Useful Life 10 Remaining Life 4

Parking Area Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2017/2018 Future Cost \$1,697

This is for garbage enclosure repairs including walls, gates, hardware, concrete pad, paint, etc.



910 - Doors Useful Life 20 Remaining Life 9

11 Station 88- Interior & Exterior Doors Quantity 11 Unit of Measure Items

Cost /Itm \$615

% Included 100.00% Total Cost/Study \$6,765

Summary Replacement Year 2022/2023 Future Cost \$8,449

This is to repair, replace and maintain the doors. This component provides for pedestrian type doors only. Large vehicle bay doors are provided for in another component.

interior doors- 7 exterior doors- 4

05000 - Roofing

444 - Pitched: Dimensional Composition Useful Life 25 Remaining Life 15

36 Squares- Station 88 Quantity 36 Unit of Measure Squares

Cost /Sqrs \$410

% Included 100.00% Total Cost/Study \$14,760

Summary Replacement Year 2028/2029 Future Cost \$21,377

This is to reroof with a dimensional composition roofing product. Composition roofs should be regularly inspected and repaired as indicated to ensure maximum life.

2004- roofing replaced



712 - Gutters / Downspouts

110 Lin. Ft. Station 88

Useful Life 25 Remaining Life 15

Quantity 110 Unit of Measure Linear Feet

Cost /l.f. \$6.15

% Included 100.00% Total Cost/Study \$676

Summary Replacement Year 2028/2029 Future Cost \$980

This is to replace the gutters and downspouts. Gutter & downspout inspections should be annually, during fall after deciduous trees have dropped their leaves and in preparation for months of heavier precipitation. Cleaning may be required depending on frequency of debris build-up. Painted metal should be touched up as needed. Any missing or disconnected downspouts should be replaced/repaired immediately.

2004- gutters replaced



05000 - Roofing

860 - Skylights Useful Life 25 Remaining Life 15

2 Lobby & Lounge Quantity 2 Unit of Measure Items

Cost /Itm \$410

% Included 100.00% Total Cost/Study \$820

Summary Replacement Year 2028/2029 Future Cost \$1,188

This is to replace the skylights in conjunction with the roofing cycle.

2004- Roofing and gutters replaced.



08000 - Rehab

120 - General Useful Life 10 Remaining Life 4

2 Quarters Quantity 2 Unit of Measure Room

Cost /Rm \$1,025

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2017/2018 Future Cost \$2,263


This is for a general rehab of the sleeping quarters. Items to include lighting, beds, lockers and shelves. District input may further define this component. Electronics, desks, office chairs, computers, painting, flooring, doors and window coverings are provided for in other components.

## multi-quarters:

- 2 beds, 1 chair, 2 book shelves, 3 fluorescent lights, 1 10'x8' lockers, 2 end tables

### single-quarters:

- 1 bed, 2 end tables, 1 phone, 1 fluorescent light



08000 - Rehab

210 - Bathrooms Useful Life 10 Remaining Life 1

2 Bathroom & Restroom Quantity 2 Unit of Measure Room

Cost /Rm \$1,537

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2014/2015 Future Cost \$3,152

This is to rehab and redecorate the bathroom and the restroom. Includes items such lighting, fixtures, ventilation, drainage, and decor. This item can be further defined with district input. Painting, and tile are provided for in other components.



214 - Kitchen Useful Life 20 Remaining Life 1

Kitchen Quantity 1 Unit of Measure Room

Cost /Rm \$2,050

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2014/2015 Future Cost \$2,101

This is to rehab and redecorate the kitchen. Includes items such as cabinets, countertops, fixtures, lighting, etc. This item can be further defined with district input. Major appliances, painting, flooring and doors are provided for within other components.

20 linear feet of upper cabinet

20 linear feet of lower cabinet and countertop

2- fluorescent lights



14000 - Recreation

200 - Exercise: Treadmill Useful Life 10 Remaining Life 4

Vehicle Bays Quantity 1 Unit of Measure Items

Cost /Itm \$2,050

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2017/2018 Future Cost \$2,263

This is to replace the Cybex treadmill.



204 - Exercise: Miscellaneous Equip. Useful Life 15 Remaining Life 7

Vehicle Bays: Weights & Rack Quantity 1 Unit of Measure Items

Cost /Itm \$3,075

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2020/2021 Future Cost \$3,655

This is to replace the dumbbells and weight rack.



20000 - Lighting

104 - Exterior: Misc. Fixtures Useful Life 15 Remaining Life 9

8 Building & Landscape Lights Quantity 8 Unit of Measure Items

Cost /Itm \$256

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2022/2023 Future Cost \$2,560

This is to replace miscellaneous common area lighting fixtures.

building lights- 6 landscape lights at monument sign- 2



540 - Parking Lot Useful Life 25 Remaining Life 14

Parking Lot Light Quantity 1 Unit of Measure Items

Cost /Itm \$2,255

% Included 100.00% Total Cost/Study \$2,255

Summary Replacement Year 2027/2028 Future Cost \$3,186

This is to replace the parking lot light.



21000 - Signage

786 - Wood Monument Useful Life 10 Remaining Life 0

Station 88 Entrance Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2013/2014 Future Cost \$1,025

This is to replace, repair, and maintain the custom identity wood monument sign.

2013/2014- client report the sign is to be replaced.



# 22000 - Office Equipment

200 - Computers, Misc. Useful Life 6 Remaining Life 3

Lobby Quantity 1 Unit of Measure Items

Cost /Itm \$2,050

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2016/2017 Future Cost \$2,208

This is to replace the Dell Optiplex 380 computer workstation and 2 monitors.

Cameron Park District # 3162



22000 - Office Equipment

204 - Computers, Misc. Useful Life 6 Remaining Life 2

Mulit-Quarters Laptop Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2015/2016 Future Cost \$1,615

This is to replace the Toshiba laptop computer.



208 - Computers, Misc. Useful Life 6 Remaining Life 2

Mulit-Quarters PC Workstation Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2015/2016 Future Cost \$1,615

This is to replace the Dell computer workstation.



22000 - Office Equipment

300 - Copier Useful Life 6 Remaining Life 2

Lobby Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2015/2016 Future Cost \$1,615

This is to replace the Kyocera multi copier.



# 23000 - Mechanical Equipment

200 - HVAC Useful Life 15 Remaining Life 4

Patio Area HVAC Quantity 1 Unit of Measure Items

Cost /Itm \$5,125

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2017/2018 Future Cost \$5,657

This is to replace the AirEase HVAC system. It is possible that sub-components of this system can be replaced or re-built to extend its life.

model #: SCV10B60A-2 serial #: 8401G14589



23000 - Mechanical Equipment

600 - Water Heater Useful Life 12 Remaining Life 5

Water Heater Closet Quantity 1 Unit of Measure Items

Cost /Itm \$820

% Included 100.00% Total Cost/Study \$820

Summary Replacement Year 2018/2019 Future Cost \$928

This is to replace the American Proline Flameguard 50 gallon gas water heater.

model #: FG6250T403P serial #: 0508137469 product #: 0731379



### 24000 - Furnishings

100 - Miscellaneous Useful Life 20 Remaining Life 9

Lobby Additional Furnishings Quantity 1 Unit of Measure Room

Cost /Rm \$5,125

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2022/2023 Future Cost \$6,400

This is a provision for the lobby furniture, equipment, and décor not provided for in other components.

- 3- fluorescent lights
- 2- metal 4-drawer file cabinets
- 1- buffet height wood cabinet
- 1- phone
- 1- wood and fabric chair miscellaneous decorations



24000 - Furnishings

200 - Bar Stools Useful Life 15 Remaining Life 9

2 Lounge Barstools Quantity 2 Unit of Measure Items

Cost /Itm \$256

% Included 100.00% Total Cost/Study \$512

Summary Replacement Year 2022/2023 Future Cost \$640

This is to replace the "high" bar stools.



212 - Chairs Useful Life 10 Remaining Life 5

4 Station 88 Task Chairs Quantity 4 Unit of Measure Items

Cost /Itm \$256

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2018/2019 Future Cost \$1,160

This is to replace the task chairs.

multi-quarters- 2 single quarters- 1

lobby- 1

228 - Chairs Useful Life 20 Remaining Life 6

3 Lounge Recliners Quantity 3 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2019/2020 Future Cost \$1,783

This is to replace the recliners in the lounge.



24000 - Furnishings

640 - Modular Office Desk Useful Life 20 Remaining Life 9

3 Station 88 Office Desks Quantity 3 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2022/2023 Future Cost \$3,840

This is to replace the various office desks.

multi-quarters- 1 single quarters- 1

lobby- 1

910 - Window Coverings Useful Life 15 Remaining Life 9

8 Station 88- Window Blinds Quantity 8 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$4,100

Summary Replacement Year 2022/2023 Future Cost \$5,120

This is to replace the window coverings.

kitchen- 1 lounge- 1

multi-quarters- 1

single- quarters- 2

lobby- 1

vehicle bays- 2

24600 - Safety / Access

340 - Defibrillators Useful Life 5 Remaining Life 2

Lobby Quantity 1 Unit of Measure Items

Cost /Itm \$2,562

% Included 100.00% Total Cost/Study \$2,562

Summary Replacement Year 2015/2016 Future Cost \$2,692

This is to replace the (AED) automated external defibrillator unit.



25000 - Flooring

210 - Carpeting

Summary

hall- 6 sq yd

87 Sq. Yds. Station 88- Carpeting

Useful Life 10 Remaining Life 3

Quantity 87 Unit of Measure Square Yard

Cost /SqYd \$32.80

% Included 100.00% Total Cost/Study \$2,854
Replacement Year 2016/2017 Future Cost \$3,073

This is to replace the carpeting.

lounge- 18 sq yd multi-quarters- 32 sq yd single-quarters- 13 sq yd lobby- 18 sq yd



410 - Tile Useful Life 20 Remaining Life 1

362 Sq. Ft. Bathroom, Restroom, & Lobby Quantity 362 Unit of Measure Square Feet

Cost /SqFt \$6.15

% Included 100.00% Total Cost/Study \$2,226

Summary Replacement Year 2014/2015 Future Cost \$2,282

This is to replace the wall and floor tile.

bathroom- 191 sq ft restroom- 146 sq ft lobby- 25 sq ft



**25000 - Flooring** 

610 - Vinyl Useful Life 20 Remaining Life 1

15 Sq. Yds. Kitchen- Linoleum Quantity 15 Unit of Measure Square Yard

Cost /SqYd \$26.65

% Included 100.00% Total Cost/Study \$400

Summary Replacement Year 2014/2015 Future Cost \$410

This is to replace the vinyl flooring.



# 26000 - Outdoor Equipment

060 - Flag Pole Useful Life 20 Remaining Life 14

Station 88 Entrance Quantity 1 Unit of Measure Items

Cost /Itm \$4,100

% Included 100.00% Total Cost/Study \$4,100

Summary Replacement Year 2027/2028 Future Cost \$5,793

This is to replace the flag pole in the common area.



26000 - Outdoor Equipment

210 - Barbecue Useful Life 8 Remaining Life 4

Patio Barbecue Quantity 1 Unit of Measure Items

Cost /Itm \$615

% Included 100.00% Total Cost/Study \$615

Summary Replacement Year 2017/2018 Future Cost \$679

This is to replace the barbecue.



350 - Furniture Useful Life 10 Remaining Life 4

8 Patio Furniture Items Quantity 8 Unit of Measure Items

Cost /Itm \$256

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2017/2018 Future Cost \$2,263

This is to replace the outdoor furniture.

1- rectangular table

6- chairs

1- umbrella w/stand



27000 - Appliances

208 - Refrigerator Useful Life 7 Remaining Life 3

Kitchen Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2016/2017 Future Cost \$1,104

This is to replace the Maytag refrigerator.

model #: MBF2556HEW serial #: 13826396JA



248 - Ice Machine Useful Life 10 Remaining Life 5

Vehicle Bays- Hoshizaki Quantity 1 Unit of Measure Items

Cost /Itm \$2,050

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2018/2019 Future Cost \$2,319

This is to replace the Hoshizaki ice machine.

model #: AM-100BAE serial #: R03805E



27000 - Appliances

266 - 4-Burner Stove & Oven Useful Life 7 Remaining Life 1

Kitchen Quantity 1 Unit of Measure Items

Cost /Itm \$1,845

% Included 100.00% Total Cost/Study \$1,845

Summary Replacement Year 2014/2015 Future Cost \$1,891

This is to replace the GE Hotpoint 4-burner stove and oven.



302 - Stove: Exhaust Hood w/ Fan Useful Life 20 Remaining Life 9

Kitchen Quantity 1 Unit of Measure Items

Cost /Itm \$2,665

% Included 100.00% Total Cost/Study \$2,665

Summary Replacement Year 2022/2023 Future Cost \$3,328

This is to replace the Roper ventilation hood.



27000 - Appliances

306 - Dishwasher Useful Life 10 Remaining Life 4

Kitchen Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2017/2018 Future Cost \$1,131

This is to replace the Kitchenaid automatic dishwasher.



410 - Washer Useful Life 10 Remaining Life 5

Vehicle Bay Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2018/2019 Future Cost \$1,740

This is to replace the LG washing machine.



27000 - Appliances

414 - Dryer Useful Life 10 Remaining Life 5

Vehicle Bay Quantity 1 Unit of Measure Items

Cost /Itm \$1,845

% Included 100.00% Total Cost/Study \$1,845

Summary Replacement Year 2018/2019 Future Cost \$2,087

This is to replace the LG laundry dryer.



30000 - Miscellaneous

270 - Garage Door: Metal Useful Life 20 Remaining Life 9

2 Vehicle Bay Doors Quantity 2 Unit of Measure Items

Cost /Itm \$5,125

% Included 100.00% Total Cost/Study \$10,250

Summary Replacement Year 2022/2023 Future Cost \$12,801

This is to replace, repair and maintain the metal, roll-up, garage, vehicle bay doors.



30000 - Miscellaneous

842 - Vehicle Useful Life 15 Remaining Life 5

E 88 Lic 1206288 Quantity 1 Unit of Measure Items

Cost /Itm \$597,017

% Included 100.00% Total Cost/Study \$597,017

Summary Replacement Year 2018/2019 Future Cost \$675,470

This is to replace the 2006 fire apparatus and equipment.

Make: 2006 Spartan Model: Smeal

Vin#: 457CT2D9X6C054260

License: 1206688

2006- purchase price, apparatus: \$320,000, equipment: \$170,000



858 - Vehicle Useful Life 15 Remaining Life 12

E 288 Lic 1375275 Quantity 1 Unit of Measure Items

Cost /Itm \$479,216

% Included 100.00% Total Cost/Study \$479,216

Summary Replacement Year 2025/2026 Future Cost \$644,492

This is to replace the 2011 International fire apparatus and equipment, manufactured by HME Aherns Fox.

Make: 2011 HME Model: n/a

Vin#: 1HTWEAZR4CJ565999

License: 1375275

2011- purchase price, apparatus: \$320,000, equipment: \$125,000



30000 - Miscellaneous

898 - Vehicle Useful Life 15 Remaining Life 11

U 88 Lic 127543 Quantity 1 Unit of Measure Items

Cost /Itm \$35,321

% Included 100.00% Total Cost/Study \$35,321

Summary Replacement Year 2024/2025 Future Cost \$46,345

This is to replace the Ford F-150.

Make: 2010 Ford Model: F-150

Vin#: 1FTFX1EV8AFC17326

License: 127543

2010- purchase price: \$32,000

00189 - Station 89

01000 - Paving

104 - Asphalt: Sealing Useful Life 5 Remaining Life 4

20,899 Sq. Ft. Parking Lot- Seal & Stripe Quantity 20,899 Unit of Measure Square Feet

Cost /SqFt \$0.157


% Included 100.00% Total Cost/Study \$3,280

Summary Replacement Year 2017/2018 Future Cost \$3,621

This is to prepare the surface, apply a single coat asphalt emulsion product and stripe the parking lot per existing plan.

current striping plan includes 39 parking stalls (west) & 11 stalls (east) & +/- 350 linear feet of red curb.

2013- \$3,200 expended for re-sealing 20,899 sq ft, information per client



### 01000 - Paving

204 - Asphalt: Ongoing Repairs Useful Life 10 Remaining Life 4

20,899 Sq. Ft. Parking Lot (10%) Quantity 20,899 Unit of Measure Square Feet

Cost /SqFt \$3.33 Qty \* \$/SqFt \$69,620

% Included 10.00% Total Cost/Study \$6,962 Summary Replacement Year 2017/2018 Future Cost \$7,685

This is for miscellaneous repairs including crack fill, skin patching and minor dig out & fill.



404 - Asphalt: Major Repairs Useful Life 25 Remaining Life 15

20,899 Sq. Ft. Parking Lot (50%) Quantity 20,899 Unit of Measure Square Feet

Cost /SqFt \$5.12 Qty \* \$/SqFt \$107,107 % Included 50.00% Total Cost/Study \$53,554

Summary Replacement Year 2028/2029 Future Cost \$77,562

This is for major excavation, re-compaction and installation of new hot asphalt to selected areas.



#### 02000 - Concrete

204 - Sidewalks, Curbs & Gutters Useful Life 5 Remaining Life 2

8,840 Sq. Ft. Exterior Concrete (3%) Quantity 8,840 Unit of Measure Square Feet

Cost /SqFt \$16.40 Qty \* \$/SqFt \$144,976 % Included 3.00% Total Cost/Study \$4,349

Summary Replacement Year 2015/2016 Future Cost \$4,569

This is to repair, replace or grind concrete sidewalks, curbs and gutters to remove abrupt elevation changes and maintain functionality. The concrete useful life exceeds the scope of this study, so this component provides for

repair only.



714 - Sealing Useful Life 5 Remaining Life 0

5,016 Sq. Ft. Vehicle Bays- Concrete Floors Quantity 5,016 Unit of Measure Square Feet

Cost /SqFt \$2.20

% Included 100.00% Total Cost/Study \$11,054

Summary Replacement Year 2013/2014 Future Cost \$11,054

This is to prepare and seal the decking to discourage moisture.

## 03000 - Painting: Exterior

124 - Surface Restoration Useful Life 10 Remaining Life 4

8,500 Lin. Ft. Station 89 Quantity 8,500 Unit of Measure Linear Feet

Cost /l.f. \$1.02

% Included 100.00% Total Cost/Study \$8,712

Summary Replacement Year 2017/2018 Future Cost \$9,617

This is to prepare, power wash, sand, scrape, caulk and paint with a 100% premium acrylic paint.



03000 - Painting: Exterior

416 - Railings Useful Life 4 Remaining Life 1

90 Lin. Ft. Balcony & Stairs Quantity 90 Unit of Measure Linear Feet

Cost /l.f. \$8.20

% Included 100.00% Total Cost/Study \$738

Summary Replacement Year 2014/2015 Future Cost \$756

This is to prepare, power wash, sand, scrape and paint the railings.



920 - Miscellaneous Useful Life 5 Remaining Life 0

Sheds, Wrought Iron, & Touch-Up Quantity 1 Unit of Measure Lump Sum

Cost /LS \$3,587

% Included 100.00% Total Cost/Study \$3,587

Summary Replacement Year 2013/2014 Future Cost \$3,588

This is for miscellaneous exterior painting.

3- wood storage sheds

1- hazardous material shed

20- linear feet of 3' wrought iron fencing touch up painting to trim and railings



## 03500 - Painting: Interior

120 - Building Useful Life 10 Remaining Life 4

24,962 Sq. Ft. Station 89 Interior Painting Quantity 24,962 Unit of Measure Square Feet

Cost /SqFt \$1.02

% Included 100.00% Total Cost/Study \$25,586

Summary Replacement Year 2017/2018 Future Cost \$28,242

This is to prepare and paint all building interior spaces.

#### first floor:

- lobby- 272 sq ft
- reception- 432 sq ft
- hall- 616 sq ft
- captain's office- 384 sq ft
- work room- 406 sq ft
- coffee room- 238 sq ft
- side hall- 756 sq ft
- men's restroom- 49 sq ft
- women's restroom- 49 sq ft
- cleaning closet- 184 sq ft
- weight room- 512 sq ft
- fire marshal- 384 sq ft
- battalion chief's office- 368 sq ft
- conference room- 752 sq ft
- storage (conference)- 238 sq ft
- second floor:
- hall- 1,690 sq ft
- men's bathroom- 669 sq ft
- closet- 255 sq ft
- lounge & kitchen- 2,424 sq ft
- laundry- 342 sq ft
- captains dorm- 592 sq ft
- dorm 1- 530 sq ft
- dorm 2- 530 sq ft
- dorm 3- 895 sq ft
- multiuse bathroom- 411 sq ft
- garage bays
- main- 6,800 sq ft
- mechanic's- 3,600



04000 - Structural Repairs

360 - Garbage Enclosure Useful Life 10 Remaining Life 4

Station 89- Enclosure Quantity 1 Unit of Measure Items

Cost /Itm \$2,562

% Included 100.00% Total Cost/Study \$2,562

Summary Replacement Year 2017/2018 Future Cost \$2,829

This is for garbage enclosure repairs including walls, gates, hardware, concrete pad, paint, etc.



920 - Doors Useful Life 15 Remaining Life 5

31 Station 89 Interior & Exterior Doors Quantity 31 Unit of Measure Items

Cost /Itm \$615

% Included 100.00% Total Cost/Study \$19,065

Summary Replacement Year 2018/2019 Future Cost \$21,570

This is to repair, replace and maintain the doors. Vehicle roll-up bay doors are provided for in another component.

interior doors- 22 exterior doors- 9



04000 - Structural Repairs

990 - Miscellaneous Useful Life 10 Remaining Life 5

Quantity 4 Unit of Measure Items 4 Wood Sheds

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2018/2019 Future Cost \$2,319

This is for miscellaneous repairs to the wood storage sheds. Painting is provided for in another component.



## 04500 - Decking/Balconies

110 - Concrete Useful Life 10 Remaining Life 4

Unit of Measure Square Feet 375 Sq. Ft. South Side Building (25%) Quantity 375

> Cost /SqFt \$15.37 Qty \* \$/SqFt \$5,766 % Included 25.00% Total Cost/Study \$1,441

Summary Replacement Year 2017/2018 Future Cost \$1,591

This is to repair and maintain the concrete balcony. Railings are provided for in other components.



04500 - Decking/Balconies

500 - Railing: Wrought Iron Useful Life 20 Remaining Life 10

90 Lin. Ft. Balcony & Stair Railings Quantity 90 Unit of Measure Linear Feet

Cost /l.f. \$34.85

% Included 100.00% Total Cost/Study \$3,136

Summary Replacement Year 2023/2024 Future Cost \$4,015

This is to replace the balcony and stair railings. Painting is provided for in another component.

balcony railing- 50 linear feet of 4' railing stairs- 40 linear feet of 3' railing



05000 - Roofing

334 - Low Slope: Vinyl Useful Life 20 Remaining Life 10

48 Squares- Station 89 Flat Roofing Quantity 48 Unit of Measure Squares

Cost /Sqrs \$512

% Included 100.00% Total Cost/Study \$24,600

Summary Replacement Year 2023/2024 Future Cost \$31,490

This is to replace the low slope vinyl roofing with a similar type product.



### 05000 - Roofing

680 - Pitched: Metal Useful Life 30 Remaining Life 20

31 Squares- Station 89 Metal Roof Quantity 31 Unit of Measure Squares

Cost /Sqrs \$512

% Included 100.00% Total Cost/Study \$15,887

Summary Replacement Year 2033/2034 Future Cost \$26,034

This is to replace the metal roofing system. With proper maintenance, this component's life may be extended.



720 - Gutters / Downspouts Useful Life 30 Remaining Life 20

210 Lin. Ft. Station 89 Quantity 210 Unit of Measure Linear Feet

Cost /l.f. \$6.15

% Included 100.00% Total Cost/Study \$1,291

Summary Replacement Year 2033/2034 Future Cost \$2,116

This is to replace the gutters and downspouts in conjunction with the metal roof replacement.



08000 - Rehab

128 - General Useful Life 20 Remaining Life 10

4 Dormitory Rooms Quantity 4 Unit of Measure Room

Cost /Rm \$2,050

% Included 100.00% Total Cost/Study \$8,200

Summary Replacement Year 2023/2024 Future Cost \$10,497

This is for a general rehab of the dormitory rooms.

## Captain's Dorm:

- 2 beds
- 4 linear feet of lower cabinet and counter top
- 6 linear feet of full height wood wall locker
- 1 small wood book shelf

## Dorm 1 & Dorm 2:

- 2 end tables
- 4 beds
- 2 small lamps

## Dorm 3:

- 4 beds
- 3 end tables
- 3 small lamps



Prepared for the 2014/2015 Fiscal Year

00189 - Station 89

08000 - Rehab

132 - General Useful Life 20 Remaining Life 10

Work Room Quantity 1 Unit of Measure Room

Cost /Rm \$2,562

% Included 100.00% Total Cost/Study \$2,562

Summary Replacement Year 2023/2024 Future Cost \$3,280

This is for a general rehab of the work room.

1-8' x 4' drafting table

14 linear feet of upper and lower cabinetry

3- 4-drawer metal file cabinets

1- phone

9 linear feet of wood book shelves



08000 - Rehab

136 - General Useful Life 20 Remaining Life 10

3 Offices Quantity 3 Unit of Measure Room

Cost /Rm \$2,050

% Included 100.00% Total Cost/Study \$6,150

Summary Replacement Year 2023/2024 Future Cost \$7,873

This is for a general rehab of the interiors. Includes bookshelves, file cabinets, tables, phones, and ceilings.

## Station Captain's Office:

- 2- small bookshelves
- 1- small wood file cabinet
- 1- end table
- 1- phone
- 140 sq ft false ceiling

### Fire Marshal Office:

- 1- small book shelf
- 1- tall wood book shelf
- 2- small wood file cabinets
- 1- phone
- 140 sq ft false ceiling

### Battalion Chief's Office:

- 2- small wood file cabinets
- 1- wood end table
- 1- phone
- 130 sq ft false ceiling



08000 - Rehab

140 - General Useful Life 20 Remaining Life 10

Reception Quantity 1 Unit of Measure Room

Cost /Rm \$2,562

% Included 100.00% Total Cost/Study \$2,562

Summary Replacement Year 2023/2024 Future Cost \$3,280

This is for a general rehab of the interiors. Includes cabinets, counters, book shelves, file cabinets, ceiling and phones.

1- wood book shelf

4- phones

20 linear feet- lower cabinet and countertop

12 linear feet- upper cabinet

180 sq ft of false ceiling

72 sq ft of false ceiling in the lobby area



218 - Bathrooms Useful Life 20 Remaining Life 2

2 Upstairs Bathrooms Quantity 2 Unit of Measure Room

Cost /Rm \$3,075

% Included 100.00% Total Cost/Study \$6,150

Summary Replacement Year 2015/2016 Future Cost \$6,461

This is to rehab and redecorate the bathrooms. Includes items such as partitions, fixtures, decor, ventilation and drainage. This item can be further defined with district input.



08000 - Rehab

226 - Bathrooms Useful Life 20 Remaining Life 10

2 Downstairs Restrooms Quantity 2 Unit of Measure Room

Cost /Rm \$2,050

% Included 100.00% Total Cost/Study \$4,100

Summary Replacement Year 2023/2024 Future Cost \$5,248

This is to rehab and redecorate the restrooms. Includes items such as fixtures, decor, ventilation and drainage. This item can be further defined with district input.



262 - Kitchen Useful Life 20 Remaining Life 10

Coffee Room Quantity 1 Unit of Measure Room

Cost /Rm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2023/2024 Future Cost \$1,968

This is to rehab and redecorate the kitchenette coffee room.

- 12 linear feet of lower cabinet and counter top
- 8 linear feet of upper cabinet
- 1 double sink
- 1- 3.5' x 4' metal roll up service door



08000 - Rehab

270 - Kitchen Useful Life 20 Remaining Life 19

Kitchen Quantity 1 Unit of Measure Room

Cost /Rm \$3,075

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2032/2033 Future Cost \$4,916

This is to rehab and redecorate the kitchen. Includes items such as cabinets, countertops, fixtures, ventilation, drainage and decor. This item can be further defined with district input. Appliances are provided for within other components.

2012/2013- new counter tops installed



274 - Laundry Room Useful Life 20 Remaining Life 19

Upstairs Laundry Quantity 1 Unit of Measure Room

Cost /Rm \$1,537

% Included 100.00% Total Cost/Study \$1,537
Replacement Year 2032/2033 Future Cost \$2,458

This is for a general rehab of the laundry room. Painting, flooring, door and appliances are provided for in other components.

1- sink

Summary

10 linear feet upper cabinet

5 linear feet lower cabinet and counter top

1- ventilation fan



14000 - Recreation

220 - Exercise: Treadmill Useful Life 10 Remaining Life 4

Weight Room Quantity 1 Unit of Measure Items

Cost /Itm \$2,050

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2017/2018 Future Cost \$2,263

This is to replace the Life Fitness 95 TL treadmill.



224 - Exercise: Cardio Equipment Useful Life 10 Remaining Life 4

Weight Room Elliptical Quantity 1 Unit of Measure Items

Cost /Itm \$1,845

% Included 100.00% Total Cost/Study \$1,845

Summary Replacement Year 2017/2018 Future Cost \$2,037

This is to replace the Precor EFX elliptical.



14000 - Recreation

228 - Exercise: Weight Machine Useful Life 20 Remaining Life 10

Weight Room Quantity 1 Unit of Measure Items

Cost /Itm \$3,587

% Included 100.00% Total Cost/Study \$3,587

Summary Replacement Year 2023/2024 Future Cost \$4,592

This is to replace the Tuff Stuff multi-bench weight machine.



232 - Exercise: Miscellaneous Equip. Useful Life 20 Remaining Life 10

Weight Room Tuff Stuff Rack Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2023/2024 Future Cost \$1,968

This is to replace the Tuff Stuff exercise rack.



### 14000 - Recreation

236 - Exercise: Miscellaneous Equip. Useful Life 15 Remaining Life 9

Weight Room Dumbbells & Rack Quantity 1 Unit of Measure Items

Cost /Itm \$3,075

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2022/2023 Future Cost \$3,840

This is to replace the free weight dumbbells and associated storage rack.



## 18000 - Landscaping

108 - Irrigation: Misc. Useful Life 5 Remaining Life 1

Backflows, Controllers, Valves Quantity 1 Unit of Measure Lump Sum

Cost /LS \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2014/2015 Future Cost \$1,051

This is for major irrigation system repair in excess of the operating budget.



18000 - Landscaping

482 - Pathways & Trails Useful Life 5 Remaining Life 1

520 Sq. Ft. DG Walking Path Quantity 520 Unit of Measure Square Feet

Cost /SqFt \$5.12

% Included 100.00% Total Cost/Study \$2,665

Summary Replacement Year 2014/2015 Future Cost \$2,732

This is to maintain pathways and trails.



19000 - Fencing

310 - Wood: 3' Useful Life 18 Remaining Life 1

50 Lin. Ft. Northeast Perimeter Quantity 50 Unit of Measure Linear Feet

Cost /l.f. \$15.37

% Included 100.00% Total Cost/Study \$769

Summary Replacement Year 2014/2015 Future Cost \$788

This is to replace the 3' wood fencing including discarded fence material removal and disposal.



19000 - Fencing

340 - Wood: 6' Useful Life 18 Remaining Life 3

895 Lin. Ft. Perimeter Fencing Quantity 895 Unit of Measure Linear Feet

Cost /l.f. \$25.62

% Included 100.00% Total Cost/Study \$22,934

Summary Replacement Year 2016/2017 Future Cost \$24,698

This is to replace the 6' wood fencing including discarded fence material removal and disposal.



## 19500 - Retaining Wall

372 - Masonry Wall Maintenance Useful Life 10 Remaining Life 4

225 Lin. Ft. Keystone Retaining Wall (25%) Quantity 225 Unit of Measure Linear Feet

Cost /l.f. \$25.62 Qty \* \$/l.f. \$5,766

% Included 25.00% Total Cost/Study \$1,441

Summary Replacement Year 2017/2018 Future Cost \$1,591

This is for on-going retaining wall maintenance.



20000 - Lighting

100 - Exterior: Misc. Fixtures Useful Life 20 Remaining Life 10

21 Station 89- Exterior Building Lights Quantity 21 Unit of Measure Items

Cost /Itm \$256

% Included 100.00% Total Cost/Study \$5,381

Summary Replacement Year 2023/2024 Future Cost \$6,888

This is to replace the various exterior building lighting fixtures.



420 - Interior Useful Life 20 Remaining Life 10

72 Station 89 Interior Lighting (50%) Quantity 72 Unit of Measure Items

Cost /Itm \$205 Qty \* \$/Itm \$14,760

% Included 50.00% Total Cost/Study \$7,380

Summary Replacement Year 2023/2024 Future Cost \$9,447

This is to replace, repair and maintain the fluorescent interior lighting.



**20000 - Lighting** 

424 - Interior Useful Life 15 Remaining Life 8

6 Station 89 Ceiling Fans Quantity 6 Unit of Measure Items

Cost /Itm \$205

% Included 100.00% Total Cost/Study \$1,230

Summary Replacement Year 2021/2022 Future Cost \$1,499

This is to replace the interior ceiling fans.

### upstairs:

- lounge & kitchen- 2
- captain's dorm- 1
- dorm 1- 1
- dorm 2- 1
- dorm 3- 2



## 21000 - Signage

774 - Wood Monument Useful Life 15 Remaining Life 0

2 Station 89 Signs Quantity 2 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2013/2014 Future Cost \$3,075

This is to replace the custom identity wood monument signs.

2013/2014- work completed



22000 - Office Equipment

212 - Computers, Misc. Useful Life 6 Remaining Life 1

Reception Dell PC Workstation #3101 Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2014/2015 Future Cost \$1,051

This is to replace the Dell Optiplex computer workstation. Includes monitors, connectivity and peripherals as necessary.



216 - Computers, Misc.

, Misc. Useful Life 6 Remaining Life 1

Reception Dell PC Workstation #3102 Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2014/2015 Future Cost \$1,051

This is to replace the Dell Optiplex computer workstation. Includes monitors, connectivity and peripherals as

necessary.



## 22000 - Office Equipment

220 - Computers, Misc. Useful Life 6 Remaining Life 0

Reception Gateway PC Workstation #3092 Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2013/2014 Future Cost \$1,025

This is to replace the Gateway computer workstation. Includes monitors, connectivity and peripherals as necessary.



224 - Computers, Misc. Useful Life 6 Remaining Life 0

Reception Brother Printer Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2013/2014 Future Cost \$1,025

This is to replace the Brother printer.

228 - Computers, Misc. Useful Life 6 Remaining Life 4

Station Captains Office Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2017/2018 Future Cost \$1,131

This is to replace the Dell Optiplex computer workstation. Includes monitors, connectivity and peripherals as

necessary.



22000 - Office Equipment

232 - Computers, Misc. Useful Life 10 Remaining Life 4

Station Captain's Office- Shredder Quantity 1 Unit of Measure Items

Cost /Itm \$1,230

% Included 100.00% Total Cost/Study \$1,230

Summary Replacement Year 2017/2018 Future Cost \$1,358

This is to replace the Shredmaster 960x document/paper shredder.



236 - Computers, Misc. Useful Life 6 Remaining Life 2

Station Captain's Office- Printer Quantity 1 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$512

Summary Replacement Year 2015/2016 Future Cost \$538

This is to replace the HP DeskJet 6540.



22000 - Office Equipment

240 - Computers, Misc. Useful Life 10 Remaining Life 4

Work Room- Fax Quantity 1 Unit of Measure Items

Cost /Itm \$1,332

% Included 100.00% Total Cost/Study \$1,332

Summary Replacement Year 2017/2018 Future Cost \$1,471

This is to replace the Brother Intellifax 4100E fax machine.



244 - Computers, Misc. Useful Life 10 Remaining Life 4

Work Room- Shredder Quantity 1 Unit of Measure Items

Cost /Itm \$1,127

% Included 100.00% Total Cost/Study \$1,127

Summary Replacement Year 2017/2018 Future Cost \$1,245

This is to replace the Fellowes 99ci shredder.



248 - Computers, Misc. Useful Life 6 Remaining Life 2

Equipment Room- UPS 1500 Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2015/2016 Future Cost \$1,615

This is to replace the APC Smart UPS 1500.

22000 - Office Equipment

252 - Computers, Misc. Useful Life 6 Remaining Life 2

Equipment Room- Power Connect 2724 Quantity 1 Unit of Measure Items

Cost /Itm \$5,125

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2015/2016 Future Cost \$5,384

This is to replace the Dell Power Connect 2724.

Cameron Park ID #3124



256 - Computers, Misc. Useful Life 6 Remaining Life 2

Equipment Room- Surge Protector Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2015/2016 Future Cost \$1,077

This is to replace the APC surge protector.

260 - Computers, Misc. Useful Life 6 Remaining Life 2

Equipment Room- Poweredge 2900 Quantity 1 Unit of Measure Items

Cost /Itm \$5,125

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2015/2016 Future Cost \$5,384

This is to replace the Dell Poweredge 2900.

Cameron Park ID #3120



22000 - Office Equipment

264 - Computers, Misc. Useful Life 6 Remaining Life 0

Fire Prevention Office Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2013/2014 Future Cost \$1,025

This is to replace the Gateway computer workstation. Includes monitors, connectivity and peripherals as necessary.

2013/2014- work completed



268 - Computers, Misc. Useful Life 6 Remaining Life 2

Fire Prevention Office- Shredder Quantity 1 Unit of Measure Items

Cost /Itm \$1,230

% Included 100.00% Total Cost/Study \$1,230

Summary Replacement Year 2015/2016 Future Cost \$1,292

This is to replace the Royal 160MX document/paper shredder.

272 - Computers, Misc. Useful Life 6 Remaining Life 4

Battalion Chief's Office Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2017/2018 Future Cost \$1,131

This is to replace the Dell Optiplex 380 computer workstation. Includes monitors, connectivity and peripherals as necessary.

22000 - Office Equipment

304 - Copier Useful Life 10 Remaining Life 4

Work Room- Copier Quantity 1 Unit of Measure Items

Cost /Itm \$3,587

% Included 100.00% Total Cost/Study \$3,587

Summary Replacement Year 2017/2018 Future Cost \$3,960

This is to replace the Copy Star CS-C2525E copy machine.



360 - Telephone Equipment Useful Life 6 Remaining Life 2

Equipment Room- Phone System Quantity 1 Unit of Measure Items

Cost /Itm \$4,612

% Included 100.00% Total Cost/Study \$4,612

Summary Replacement Year 2015/2016 Future Cost \$4,846

This is to replace the IVX S class all in one phone system.

Cameron Park ID #3117



22000 - Office Equipment

364 - Telephone Equipment Useful Life 6 Remaining Life 2

Equipment Room- Integration Hub Quantity 1 Unit of Measure Items

Cost /Itm \$4,612

% Included 100.00% Total Cost/Study \$4,612

Summary Replacement Year 2015/2016 Future Cost \$4,846

This is to replace the Comtech fire station integration hub.

Cameron Park ID #3121



368 - Telephone Equipment Useful Life 6 Remaining Life 2

Equipment Room- Phone System Quantity 1 Unit of Measure Items

Cost /Itm \$4,612

% Included 100.00% Total Cost/Study \$4,612

Summary Replacement Year 2015/2016 Future Cost \$4,846

This is to replace the Comtech fire station integration hub.

Cameron Park ID #3122

23000 - Mechanical Equipment

204 - HVAC Useful Life 15 Remaining Life 7

Quantity 1 Unit of Measure Items Roof- AC-1

Cost /Itm \$10,250

% Included 100.00% Total Cost/Study \$10,250

Summary Replacement Year 2020/2021 Future Cost \$12,184

This is to replace the Carrier HVAC system. It is possible that sub-components of this system can be replaced or re-built to extend its life.

m/n: 48HJD012---571-s/n: 1304G20609



Useful Life 15 Remaining Life 7 208 - HVAC

Unit of Measure Items Quantity 1 Roof- AC-2

Cost /Itm \$10,250

% Included 100.00% Total Cost/Study \$10,250

Future Cost \$12,184 Summary Replacement Year 2020/2021

This is to replace the Carrier HVAC system. It is possible that sub-components of this system can be replaced or re-built to extend its life.

m/n: 48HJD008---541-s/n: 1204G20526



23000 - Mechanical Equipment

212 - Fan Useful Life 20 Remaining Life 10

Roof- Ventilation Fan Quantity 1 Unit of Measure Items

Cost /Itm \$4,612

% Included 100.00% Total Cost/Study \$4,612

Summary Replacement Year 2023/2024 Future Cost \$5,904

This is to replace the ventilation fan hardware including pump and motor.

Cincinnati Fan & Vent Co. m/n: HDBI-150 s/n: 216076-03 NIF 403-3

5 hp pump motor



216 - Fan Useful Life 20 Remaining Life 10

Roof- Captive Aire Systems, Supply Quantity 1 Unit of Measure Items

Cost /Itm \$4,100

% Included 100.00% Total Cost/Study \$4,100

Summary Replacement Year 2023/2024 Future Cost \$5,248

This is to repair, replace and maintain the supply fan.

Captive Aire Systems m/n: NSAU1-G10 job#: 240155 fan #2



23000 - Mechanical Equipment

220 - Fan Useful Life 20 Remaining Life 10

Roof- Captive Aire Systems, Exhaust Quantity 1 Unit of Measure Items

Cost /Itm \$4,100

% Included 100.00% Total Cost/Study \$4,100

Summary Replacement Year 2023/2024 Future Cost \$5,248

This is to repair, replace and maintain the exhaust fan.

Captive Aire Systems m/n: NCA14HPFA job#: 240155 fan #1 KH-1



224 - Swamp Cooler Useful Life 20 Remaining Life 10

Roof- Evaporative Air Cooler Quantity 1 Unit of Measure Items

Cost /Itm \$5,125

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2023/2024 Future Cost \$6,560

This is to replace the evaporative air cooler.



23000 - Mechanical Equipment

228 - Swamp Cooler Useful Life 20 Remaining Life 10

Roof- Evaporative Air Cooler Quantity 1 Unit of Measure Items

Cost /Itm \$5,125

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2023/2024 Future Cost \$6,560

This is to replace the evaporative air cooler.



330 - Fuel Tank Useful Life 30 Remaining Life 20

2 Parking Area Fueling Tanks Quantity 2 Unit of Measure Items

Cost /Itm \$7,687

% Included 100.00% Total Cost/Study \$15,375

Summary Replacement Year 2033/2034 Future Cost \$25,194

This is to maintain the fuel tanks and pumps.



23000 - Mechanical Equipment

580 - Cooling Tower Useful Life 20 Remaining Life 10

Roof- REF-1 Quantity 1 Unit of Measure Items

Cost /Itm \$3,587

% Included 100.00% Total Cost/Study \$3,587

Summary Replacement Year 2023/2024 Future Cost \$4,592

This is to repair maintain and replace the refrigeration cooler.

REF-1

model: DX12B tag: REF-1



604 - Water Heater Useful Life 12 Remaining Life 7

Upstairs Closet Quantity 1 Unit of Measure Items

Cost /Itm \$820

% Included 100.00% Total Cost/Study \$820

Summary Replacement Year 2020/2021 Future Cost \$975

This is to replace the Polaris 34 gallon gas water heater.



23000 - Mechanical Equipment

608 - Water Heater Useful Life 12 Remaining Life 0

Mechanic's Bay Quantity 1 Unit of Measure Items

Cost /Itm \$820

% Included 100.00% Total Cost/Study \$820

Summary Replacement Year 2013/2014 Future Cost \$820

This is to replace the American 50 gallon gas water heater.



24000 - Furnishings

208 - Chairs Useful Life 10 Remaining Life 2

9 Station 89 Task Chairs Quantity 9 Unit of Measure Items

Cost /Itm \$256

% Included 100.00% Total Cost/Study \$2,306

Summary Replacement Year 2015/2016 Future Cost \$2,423

This is to replace the task chairs.



24000 - Furnishings

216 - Chairs

Quantity 10 10 Station 89 Wood/Cloth Chairs

Unit of Measure Items

Cost /Itm \$76.87

% Included 100.00% Total Cost/Study \$769

Useful Life 15 Remaining Life 8

Summary Replacement Year 2021/2022

Future Cost \$937

This is to replace the chairs.

downstairs:

- lobby- 4

- captain's office- 2

- fire marshal office- 2

- battalion chief office- 2



220 - Chairs

Summary

15 Station 89 Stackable Chairs

Useful Life 20 Remaining Life 3

Quantity 15

Unit of Measure Items

Cost /Itm \$76.87

% Included 100.00%

Total Cost/Study \$1,153

Replacement Year 2016/2017

Future Cost \$1,242

This is to replace the chairs.

24000 - Furnishings

224 - Chairs Useful Life 20 Remaining Life 10

46 Station 89 Folding Chairs Quantity 46 Unit of Measure Items

Cost /Itm \$76.87

% Included 100.00% Total Cost/Study \$3,536

Summary Replacement Year 2023/2024 Future Cost \$4,527

This is to replace the folding chairs.

downstairs:

- conference room- 10

- storage room (conference)- 36



232 - Chairs Useful Life 10 Remaining Life 4

6 Lounge- Recliners Quantity 6 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$3,075

Summary Replacement Year 2017/2018 Future Cost \$3,394

This is to replace the lounge recliner easy chairs.



00189 - Station 89

24000 - Furnishings

310 - Tables: Dining: Large Useful Life 20 Remaining Life 10

Lounge & Kitchen Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2023/2024 Future Cost \$1,312

This is to replace the large dining table.



330 - Tables Useful Life 20 Remaining Life 10

17 Station 89 Folding Tables Quantity 17 Unit of Measure Items

Cost /Itm \$102

% Included 100.00% Total Cost/Study \$1,742

Summary Replacement Year 2023/2024 Future Cost \$2,231

This is to replace folding tables.

24000 - Furnishings

650 - Modular Office Desk Useful Life 20 Remaining Life 10

5 Station 89 Office Desks Quantity 5 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2023/2024 Future Cost \$6,560

This is to replace the desks.

downstairs:

- reception- 2

- captain's office- 1

- fire marshal office- 1

- battalion chief office- 1



880 - Security Deposit Boxes

Station Captain's Office Lockbox

Useful Life 12 Remaining Life 5

Quantity 1 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$512

Summary Replacement Year 2018/2019 Future Cost \$580

This is to replace the Sentry small safe/lockbox.



24000 - Furnishings

884 - Security Deposit Boxes Useful Life 20 Remaining Life 10

Station Captain's Office Safe Quantity 1 Unit of Measure Items

Cost /Itm \$2,562

% Included 100.00% Total Cost/Study \$2,562

Summary Replacement Year 2023/2024 Future Cost \$3,280

This is to replace the Sentry safe.



920 - Window Coverings Useful Life 15 Remaining Life 5

19 Station 89 Window Blinds Quantity 19 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$9,737

Summary Replacement Year 2018/2019 Future Cost \$11,017

This is to replace the window coverings.



24500 - Audio / Visual

100 - Television Useful Life 10 Remaining Life 4

Weight Room Quantity 1 Unit of Measure Items

Cost /Itm \$1,537

% Included 100.00% Total Cost/Study \$1,537

Summary Replacement Year 2017/2018 Future Cost \$1,697

This is to replace the Akai 20" flat screen television.



200 - DVD Player Useful Life 6 Remaining Life 2

Storage (Conference)- Sony DVD Quantity 1 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$512

Summary Replacement Year 2015/2016 Future Cost \$538

This is to replace the Sony DVD player.

204 - DVD Player Useful Life 6 Remaining Life 2

Storage (Conference)- Toshiba DVD Quantity 1 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$512

Summary Replacement Year 2015/2016 Future Cost \$538

This is to replace the Toshiba DVD player.

308 - PA System Useful Life 10 Remaining Life 4

Equipment Room- Amplifier Quantity 1 Unit of Measure Items

Cost /Itm \$769

% Included 100.00% Total Cost/Study \$769

Summary Replacement Year 2017/2018 Future Cost \$849

This is to replace the CSI Professional series PA amplifier.

24500 - Audio / Visual

312 - PA System Useful Life 10 Remaining Life 4

Conference Room- Podium Quantity 1 Unit of Measure Lump Sum

Cost /LS \$2,562

% Included 100.00% Total Cost/Study \$2,562

Summary Replacement Year 2017/2018 Future Cost \$2,829

This is to replace the public address podium.



316 - PA System Useful Life 6 Remaining Life 2

Conference Room- Projector Quantity 1 Unit of Measure Items

Cost /Itm \$3,587

% Included 100.00% Total Cost/Study \$3,587

Summary Replacement Year 2015/2016 Future Cost \$3,769

This is to replace the Dell screen and projector.



24600 - Safety / Access

120 - Fire Control Misc Useful Life 10 Remaining Life 4

Building Alarm & Extinguishers Quantity 1 Unit of Measure Lump Sum

Cost /LS \$5,125

% Included 100.00% Total Cost/Study \$5,125

Summary Replacement Year 2017/2018 Future Cost \$5,657

This is to replace miscellaneous fire control items such as fire risers, sprinkler heads, pumps, and extinguishers.



350 - Defibrillators Useful Life 5 Remaining Life 2

Lobby Quantity 1 Unit of Measure Items

Cost /Itm \$2,562

% Included 100.00% Total Cost/Study \$2,562

Summary Replacement Year 2015/2016 Future Cost \$2,692

This is to replace the (AED) automated external defibrillator unit.



25000 - Flooring

Useful Life 10 Remaining Life 4 220 - Carpeting

Quantity 262 Unit of Measure Square Yard 262 Sq. Yds. Station 89 Interior Carpeting

Cost /SqYd \$32.80

% Included 100.00% Total Cost/Study \$8,594

Summary Replacement Year 2017/2018 Future Cost \$9,486

This is to replace the carpeting.

down stairs:

- captain's office- 16 sq yd

- work room- 20 sq yd

- fire marshal office- 16 sq yd

- battalion chief office- 15 sq yd

- conference room- 60 sq yd

- storage (conference)- 7 sq yd upstairs:

- lounge & kitchen- 58 sq yd

- captain's dorm- 15 sq yd

- dorm 1- 13 sq yd - dorm 2- 13 sq yd

- dorm 3- 29 sq yd



## 25000 - Flooring

420 - Tile 2,543 Sq. Ft. Station 89 Floor & Wall Tile Useful Life 20 Remaining Life 10

Quantity 2,543 Unit of Measure Square Feet

Cost /SqFt \$6.15

% Included 100.00% Total Cost/Study \$15,639

Summary Replacement Year 2023/2024 Future Cost \$20,020

This is to replace the floor and wall tile.

## downstairs:

- men's restroom- 245 sq ft
- women's restroom- 245 sq ft
- cleaning closet- 42 sq ft

#### upstairs:

- men's bathroom- 889 sq ft
- closet- 55 sq ft lounge & kitchen- 416 sq ft
- laundry- 70 sq ft
- multiuse bathroom- 581 sq ft



25000 - Flooring

620 - Vinyl Useful Life 20 Remaining Life 10

Quantity 50 Unit of Measure Square Yard 50 Sq. Yds. Bathroom Vinyl Tile

Cost /SqYd \$26.65

% Included 100.00% Total Cost/Study \$1,332 Replacement Year 2023/2024

Future Cost \$1,706

This is to replace the vinyl tile flooring.

upstairs:

Summary

- men's bathroom- 32 sq yd

- multiuse bathroom- 18 sq yd



624 - Vinyl Useful Life 20 Remaining Life

Quantity 166 Unit of Measure Square Yard 166 Sq. Yds. Station 89 Wood Laminate

Flooring Cost /SqYd \$30.75

> % Included 100.00% Total Cost/Study \$5,104

Summary Replacement Year 2023/2024 Future Cost \$6,534

This is to replace the wood laminate flooring.

down stairs:

lobby- 8 sq ydreception- 20 sq yd

- hall- 18 sq yd

- coffee room- 8 sq yd

upstairs:

- hall- 73 sq yd



00189 - Station 89

25000 - Flooring

990 - Miscellaneous Useful Life 15 Remaining Life 9

27 Sq. Yds. Weight Room Rubber Flooring Quantity 27 Unit of Measure Square Yard

Cost /SqYd \$30.75

% Included 100.00% Total Cost/Study \$830

Summary Replacement Year 2022/2023 Future Cost \$1,037

This is to replace the rubber weight room flooring.



# 26000 - Outdoor Equipment

068 - Flag Pole Useful Life 30 Remaining Life 20

Station 89- Flag Pole Quantity 1 Unit of Measure Items

Cost /Itm \$5,637

% Included 100.00% Total Cost/Study \$5,637

Summary Replacement Year 2033/2034 Future Cost \$9,238

This is to replace the flag pole in the common area.



26000 - Outdoor Equipment

220 - Barbecue Useful Life 8 Remaining Life 3

Balcony Quantity 1 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$512

Summary Replacement Year 2016/2017 Future Cost \$552

This is to replace the barbecue.



308 - Picnic Table: Wood Useful Life 15 Remaining Life 8

Patio Quantity 1 Unit of Measure Items

Cost /Itm \$410

% Included 100.00% Total Cost/Study \$410

Summary Replacement Year 2021/2022 Future Cost \$500

This is to replace the wood picnic table.



27000 - Appliances

220 - Refrigerator: Commercial: Large Useful Life 10 Remaining Life 6

Kitchen Quantity 1 Unit of Measure Items

Cost /Itm \$2,050

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2019/2020 Future Cost \$2,377

This is to replace the Arctic Air large refrigerator.



244 - Freezer: Large Useful Life 10 Remaining Life 6

Kitchen Quantity 1 Unit of Measure Items

Cost /Itm \$820

% Included 100.00% Total Cost/Study \$820

Summary Replacement Year 2019/2020 Future Cost \$951

This is to replace the Arctic Air large freezer.



27000 - Appliances

252 - Ice Machine Useful Life 10 Remaining Life 4

Upstairs Closet- Ice-O-Matic Quantity 1 Unit of Measure Items

Cost /Itm \$2,050

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2017/2018 Future Cost \$2,263

This is to replace the Ice-O-Matic ice machine.



256 - Ice Machine Useful Life 10 Remaining Life 4

Mechanic's Bay- Manitowac Quantity 1 Unit of Measure Items

Cost /Itm \$2,050

% Included 100.00% Total Cost/Study \$2,050

Summary Replacement Year 2017/2018 Future Cost \$2,263

This is to replace the Manitowac ice machine.



27000 - Appliances

260 - Stove Useful Life 12 Remaining Life 8

Kitchen Quantity 1 Unit of Measure Items

Cost /Itm \$3,587

% Included 100.00% Total Cost/Study \$3,587

Summary Replacement Year 2021/2022 Future Cost \$4,371

This is to replace the Kitchenaide 3-burner gas stove.



274 - Oven: Wall Useful Life 10 Remaining Life 4

Kitchen Quantity 1 Unit of Measure Items

Cost /Itm \$2,562

% Included 100.00% Total Cost/Study \$2,562

Summary Replacement Year 2017/2018 Future Cost \$2,829

This is to replace the Maytag double wall oven/broiler.



27000 - Appliances

286 - Microwave Oven Useful Life 10 Remaining Life 4

Kitchen Quantity 1 Unit of Measure Items

Cost /Itm \$615

% Included 100.00% Total Cost/Study \$615

Summary Replacement Year 2017/2018 Future Cost \$679

This is to replace the microwave oven.



294 - Stove: Fire Suppression Useful Life 10 Remaining Life 4

Kitchen Quantity 1 Unit of Measure Items

Cost /Itm \$5,637

% Included 100.00% Total Cost/Study \$5,637

Summary Replacement Year 2017/2018 Future Cost \$6,223

This is to replace the Captive Aire hood and fire suppression system.



27000 - Appliances

310 - Dishwasher, Residential Type Useful Life 5 Remaining Life 0

Kitchen Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2013/2014 Future Cost \$1,025

This is to replace the Kitchenaide under the counter dishwasher.

2013/2014- per client, dishwasher is heavily used and therefore has a shorter than normal useful life.



418 - Washer: Large Useful Life 10 Remaining Life 4

Mechanic's Bay- Washer/Extractor Quantity 1 Unit of Measure Items

Cost /Itm \$12,300

% Included 100.00% Total Cost/Study \$12,300

Summary Replacement Year 2017/2018 Future Cost \$13,577

This is to replace with a large commercial washing machine.



27000 - Appliances

422 - Dryer Useful Life 10 Remaining Life 4

Mechanic's Bay- Kenmore Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2017/2018 Future Cost \$1,131

This is to replace the Kenmore clothes dryer.



426 - Washer Useful Life 10 Remaining Life 6

Upstairs Laundry Quantity 1 Unit of Measure Items

Cost /Itm \$717

% Included 100.00% Total Cost/Study \$717

Summary Replacement Year 2019/2020 Future Cost \$832

This is to replace Maytag Neptune washing machine.



27000 - Appliances

430 - Dryer Useful Life 10 Remaining Life 6

Upstairs Laundry Quantity 1 Unit of Measure Items

Cost /Itm \$1,025

% Included 100.00% Total Cost/Study \$1,025

Summary Replacement Year 2019/2020 Future Cost \$1,189

This is to replace the Maytag Neptune clothes dryer.



684 - Miscellaneous Useful Life 10 Remaining Life 4

Coffee Room- Coffee Maker Quantity 1 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$512

Summary Replacement Year 2017/2018 Future Cost \$566

This is to replace the Bunn coffee brewer.



27000 - Appliances

984 - Miscellaneous Useful Life 10 Remaining Life 4

Kitchen- Coffee Maker Quantity 1 Unit of Measure Items

Cost /Itm \$512

% Included 100.00% Total Cost/Study \$512

Summary Replacement Year 2017/2018 Future Cost \$566

This is to replace the Bunn coffee brewer.



988 - Miscellaneous Useful Life 10 Remaining Life 4

Kitchen- Coffee Grinder Quantity 1 Unit of Measure Items

Cost /Itm \$256

% Included 100.00% Total Cost/Study \$256

Summary Replacement Year 2017/2018 Future Cost \$283

This is to replace the Bunn coffee grinder.

30000 - Miscellaneous

266 - Garage Door: Metal Useful Life 20 Remaining Life 19

3 Station 89 Garage Bay Doors Quantity 3 Unit of Measure Items

Cost /Itm \$5,125

% Included 100.00% Total Cost/Study \$15,375

Summary Replacement Year 2032/2033 Future Cost \$24,579

This is to replace, repair and maintain the metal, roll-up, garage, vehicle bay doors at the front, street side, of the building. This component also provides for the smaller delivery type bay door on the east side of the mechanic's

bay.



30000 - Miscellaneous

274 - Garage Door: Metal Useful Life 20 Remaining Life 3

4 Station 89 Garage Bay Doors- Rear Quantity 4 Unit of Measure Items

Cost /Itm \$5,125

% Included 100.00% Total Cost/Study \$20,500

Summary Replacement Year 2016/2017 Future Cost \$22,076

This is to replace, repair and maintain the metal, roll-up, garage, vehicle bay doors at the rear, parking lot, side of the building. This component also provides for the smaller delivery type bay door on the east side of the

mechanic's bay.

870 - Vehicle Useful Life 10 Remaining Life 6

B2715- Lic 1275433 Quantity 1 Unit of Measure Items

Cost /Itm \$39,737

% Included 100.00% Total Cost/Study \$39,737

Summary Replacement Year 2019/2020 Future Cost \$46,083

This is to replace the 2010 Ford F-150 XLT four door pick-up command vehicle.

Make: 2010 Ford Model: F-150

Vin#: 1FTW1EV2AFC17325

License: 1275433

2010- purchase price: \$36,000



874 - Vehicle Useful Life 10 Remaining Life 6

B2716 Lic 1275432 Quantity 1 Unit of Measure Items

Cost /Itm \$39,737

% Included 100.00% Total Cost/Study \$39,737

Summary Replacement Year 2019/2020 Future Cost \$46,083

This is to replace the Ford F-150 command vehicle.

Make: 2010 Ford Model: F-150

Vin#: 1FTW1EV0AFC17324

License: 1275432

2010- purchase price: \$36,000

00189 - Station 89

30000 - Miscellaneous

878 - Vehicle Useful Life 15 Remaining Life 1

E-89- Lic 1206287 Quantity 1 Unit of Measure Items

Cost /Itm \$597,017

% Included 100.00% Total Cost/Study \$597,017

Summary Replacement Year 2014/2015 Future Cost \$611,943

This is to replace the fire apparatus and equipment.

Make: 2006 Spartan

Model: Smeal

Vin#: 4S7CT2D936C054259

License: 1206287

2013/2014- per client, estimated replacement in 2014/2015. 2006- purchase price, apparatus: \$320,000, equipment: \$170,000



00189 - Station 89

30000 - Miscellaneous

882 - Vehicle Useful Life 15 Remaining Life 2

E-289- Lic E1109085 Quantity 1 Unit of Measure Items

Cost /Itm \$490,842

% Included 100.00% Total Cost/Study \$490,842

Summary Replacement Year 2015/2016 Future Cost \$515,691

This is to replace the fire apparatus and equipment.

Make: 2001 International Model: Masterbody

Vin#: 1HTSEADN32H502143

License: E1109085

4800 530 Power

Cameron Park Fire tag: 5C5 Cameron Park CSD #3085

2001- purchase price, apparatus: \$231,000, equipment: \$125,000



00189 - Station 89

30000 - Miscellaneous

886 - Vehicle Useful Life 10 Remaining Life 7

E-389 Lic E000391 Quantity 1 Unit of Measure Items

Cost /Itm \$555,238

% Included 100.00% Total Cost/Study \$555,238

Summary Replacement Year 2020/2021 Future Cost \$660,004

This is to replace the fire apparatus and equipment. This apparatus and equipment is designated as reserve.

Hi Tech Fire Ap. Make: 1996 Spartan

Model: n/a

Vin#: 4S7AT9K08PC0098008

License: E000391

Cameron Park CSD #3091

1996- purchase price, apparatus: \$280,000, equipment: \$170,000



30000 - Miscellaneous

890 - Vehicle Useful Life 15 Remaining Life 3

U-89 Lic 1088016 Quantity 1 Unit of Measure Items

Cost /Itm \$45,491

% Included 100.00% Total Cost/Study \$45,491

Summary Replacement Year 2016/2017 Future Cost \$48,988

This is to replace the Ford F-250 XLT Super Duty pick up truck.

Make: 2001 Ford Model: F-250

Vin#: 1FTNW21L91EB43557

License: 1088016

2001- purchase price: \$33,000



894 - Vehicle Useful Life 15 Remaining Life 2

U-289 Lic 041782 Quantity 1 Unit of Measure Items

Cost /Itm \$39,563

% Included 100.00% Total Cost/Study \$39,563
Summary Replacement Year 2015/2016 Future Cost \$41,566

This is to replace the Ford Expedition.

Make: 1999 Ford Model: Expedition

Vin#: 1FMPU16L72LA88018

License: 041782

2000- purchase price: \$28,000

00189 - Station 89

30000 - Miscellaneous

922 - Generator Useful Life 30 Remaining Life 20

Building East Side- Generac Series Quantity 1 Unit of Measure Items

Cost /Itm \$30,750

% Included 100.00% Total Cost/Study \$30,750

Summary Replacement Year 2033/2034 Future Cost \$50,387

This is to replace the Generac Series generator including existing equipment removal.

manufacture order: M331460 item number: 0045240 serial number: 3521458





#### **Section VII**

Cameron Park Community Services District
Component Tabular Listing

Final

Prepared for the 2014/2015 Fiscal Year

Included Components

Component	Current Replacement Cost	Useful Life	Remaining Life	Quantity	Cost/ U of M Treat	nt Location	
00010 - Community Center							
01000 - Paving							
124 - Asphalt: Sealing	\$7,269	5	2	59,100	\$.12/SqFt	Parking Lot	
224 - Asphalt: Ongoing Repairs	\$4,922	5	2	59,100	\$3.33/SqFt (3%	Parking Lot	
424 - Asphalt: Major Repairs	\$302,887	25	20	59,100	\$5.12/SqFt	Parking Lot	
808 - Striping	\$3,587	5	2	1	\$3,587/Lt	Parking Lot	
02000 - Concrete							
904 - Miscellaneous	\$12,628	5	2	38,500	\$16.40/SqFt (2%	Community Center Concr	ete
03000 - Painting: Exterior							
108 - Surface Restoration	\$28,187	10	5	27,500	\$1.02/SqFt	Community Center Building	ngs
400 - Wrought Iron	\$5,535	4	4	600	\$9.22/l.f.	Pool Fence	
500 - Light Poles	\$2,655	4	1	14	\$190/Itm	Common Area Light Poles	5
03500 - Painting: Interior							
100 - Building	\$47,608	10	5	46,447	\$1.02/SqFt	Community Center Interio	ors
04000 - Structural Repairs							
356 - Garbage Enclosure	\$1,537	5	2	1	\$1,537/Itm	Community Center Enclos	sure
540 - Bridge Maintenance	\$5,125	10	5	1	\$5,125/Itm	Community Center Bridge	
914 - Doors	\$3,075	2	0	45	\$615/Itm (119	Community Center Interior	
05000 - Roofing							
330 - Low Slope: Vinyl	\$91,225	30	25	178	\$512/Sqrs	Community Center Buildi	ngs
688 - Pitched: Metal	\$48,687	30	25	95	\$512/Sqrs	Community Center Buildi	
700 - Gutters / Downspouts	\$2,060	30	25	335	\$6.15/l.f.	Community Center Buildi	
08000 - Rehab							
100 - General	\$3,075	15	10	2	\$1,537/Rm	C02 & Chlorine	
104 - General	\$28,700	20	15	8	\$3,587/Rm	Offices	
108 - General	\$3,075	20	15	2	\$1,537/Rm	First Aid & Lifeguard	
116 - General	\$7,687	10	5	1	\$7,687/Rm	Stage Room	
124 - General	\$5,125	10	5	2	\$2,562/Rm	Classroom & Preschool	

Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

2279 05/09/2014 06fsv4.5.74-543:jf.jf

						Trefuded Companyants
_	Current		Remaining		Cost/	Included Components
Component	Replacement Cost	Life	Life	Quantity	U of M Treatm	ent Location
00010 - Community Center						
08000 - Rehab						
222 - Bathrooms	\$10,250	20	15	2	\$5,125/Itm	Pool Area- Shower/Locker/Restrooms
238 - Restrooms	\$6,150	10	5	2	\$3,075/Itm	Community Center Restrooms
242 - Restrooms	\$3,075	10	5	2	\$1,537/Itm	Community Center Single Restrooms
258 - Kitchen	\$3,075	20	15	1	\$3,075/Rm	Pool Concession Room
266 - Kitchen	\$10,250	20	15	1	\$10,250/Rm	Kitchen
380 - Tile	\$1,025	10	5	2	\$512/Itm	Outdoor Showers
590 - Operable Wall/Partition	\$36,900	20	15	720	\$51.25/SqFt	Stage Room
12000 - Pool						
110 - Resurface	\$30,750	12	7	375	\$82.00/l.f.	Pool
200 - Edge: Tile, Coping, Mastic	\$17,297	24	19	375	\$46.12/l.f.	Pool
210 - Tile: Lanes	\$22,570	12	7	734	\$30.75/l.f.	Pool
320 - Hand Rail / Ladder	\$7,380	24	19	6	\$1,230/Itm	Pool
400 - ADA Chair Lift	\$4,510	10	5	1	\$4,510/Itm	Pool Equipment Room
700 - Equipment: Replacement	\$1,537	10	5	1	\$1,537/Itm	Pool Eqpt Rm- Ultra Max
704 - Equipment: Replacement	\$1,025	10	5	1	\$1,025/Itm	Pool Eqpt Rm- Aquavac
708 - Equipment: Replacement	\$5,125	10	5	2	\$2,562/Itm	Pool Equipment Room- Filters
720 - Heater	\$15,375	10	5	1	\$15,375/Itm	Pool Equipment Room
740 - Pumps	\$2,050	8	3	1	\$2,050/Itm	Pool Equipment Room- Pool Pump
744 - Pumps	\$2,050	8	3	1	\$2,050/Itm	Pool Equipment Room- Slide Pump
748 - Pumps	\$2,050	8	3	1	\$2,050/Itm	Pool Equipment Room- Feature Pump
752 - Cover	\$7,611	5	1	7,425	\$1.02/SqFt	Pool
780 - Water Feature	\$30,750	15	10	1	\$30,750/Itm	Pool Area Slide Structure
800 - Solar System	\$15,375	12	7	30	\$512/Itm	Roof- Pool Solar System Panels
950 - Furniture: Lifeguard Chair	\$8,200	10	5	4	\$2,050/Itm	Pool Area
960 - Furniture: Misc	\$10,250	10	5	1	\$10,250/LS	Pool Furniture (Stored)
990 - Miscellaneous	\$2,562	10	5	1	\$2,562/Itm	Floating Racing Lanes
17500 - Basketball / Sport Court						
300 - Basketball Standard	\$13,837	15	10	6	\$2,306/Itm	Basketball Hoops
680 - Scoreboard	\$4,407	20	15	1	\$4,407/Itm	Gym
19000 - Fencing						
230 - Wrought Iron: 6'	\$22,140	30	25	600	\$36.90/l.f.	Pool Fence
20000 - Lighting						
300 - Common Area	\$26,137	20	15	17	\$1,537/Itm	Common Area Light Standards
	•					

2279 05/09/2014 06fsv4.5.74-543:jf.jf Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

			Remaining		Cost/		Included Components
Component	Replacement Cost	Life	Life	Quantity	U of M	Treatment	Location
00010 - Community Center							
20000 - Lighting	+42 200	2.0	4-	2.4	+540 (7)		0
400 - Interior	\$12,300	20	15	24	\$512/Itm		Gym- Lighting
900 - Miscellaneous	\$25,625	20	15	1	\$25,625/Itm	l	RF Access Rm- Lighting Controller
22000 - Office Equipment							
100 - Computers, Misc.	\$1,537	10	5	1	\$1,537/Itm		Offices- Main Room- PC
104 - Computers, Misc.	\$1,025	10	5	1	\$1,025/LS		Roof Access Room- PC
108 - Computers, Misc.	\$1,537	10	5	1	\$1,537/Itm		Offices- Receptionist- PC
112 - Computers, Misc.	\$5,125	10	5	1	\$5,125/Itm		Gym Building Electrical Room- Server
116 - Computers, Misc.	\$1,537	10	5	1	\$1,537/Itm		Offices- Main Room- PC
120 - Computers, Misc.	\$1,537	10	5	1	\$1,537/Itm		Offices- Receptionist- PC
124 - Computers, Misc.	\$5,125	10	5	1	\$5,125/Itm	1	Gym Building Electrical Room- Server
128 - Computers, Misc.	\$1,537	10	5	1	\$1,537/Itm	1	Gym Building Electrical Room- PC
132 - Computers, Misc.	\$1,537	10	5	1	\$1,537/Itm	1	Offices- Mary- PC
136 - Computers, Misc.	\$769	10	5	1	\$769/Itm		Offices- Kitchen/Workroom- Printer
140 - Computers, Misc.	\$1,537	10	5	1	\$1,537/Itm		Offices- Main Room- Shredder
144 - Computers, Misc.	\$769	10	5	1	\$769/Itm		Offices- Mary- Printer
148 - Computers, Misc.	\$1,537	10	5	1	\$1,537/Itm		Offices- Robert- PC
152 - Computers, Misc.	\$769	10	5	1	\$769/Itm		Offices- Robert- Printer
156 - Computers, Misc.	\$1,537	10	5	1	\$1,537/Itm		Offices- Office 1- PC
160 - Computers, Misc.	\$769	10	5	1	\$769/Itm	ı	Offices- Office 1- Printer
164 - Computers, Misc.	\$30,750	10	5	1	\$30,750/LS	;	Electrical Room- Server
308 - Copier	\$3,587	10	5	1	\$3,587/Itm	ı	Offices- Kitchen/Workroom- Copier
312 - Copier	\$3,587	10	5	1	\$3,587/Itm		Offices- Main Room
23000 - Mechanical Equipment							
240 - HVAC	\$10,250	15	10	1	\$10,250/Itm		Roof- Trane: AC 1
244 - HVAC	\$20,500	15	10	1	\$20,500/Itm		Roof- Trane: AC 2, 3
248 - HVAC	\$20,500	15	10	1	\$20,500/Itm		Roof- Trane: AC 4, 5
252 - HVAC	\$10,250	15	10	1	\$10,250/Itm	ı	Roof- Trane AC 6
256 - HVAC	\$10,250	15	10	1	\$10,250/Itm	l	Roof- Trane AC 7
260 - HVAC	\$10,250	15	10	1	\$10,250/Itm	l	Roof- Trane AC 8
264 - HVAC	\$10,250	15	10	1	\$10,250/Itm	l	Roof- Trane: AC 9
268 - HVAC	\$10,250	15	10	1	\$10,250/Itm		Roof- Trane: AC 10
272 - HVAC	\$30,750	15	10	1	\$30,750/Itm		Roof- AC-11
276 - HVAC	\$30,750	15	10	1	\$30,750/Itm		Roof- AC-12
280 - HVAC	\$10,250	15	10	1	\$10,250/LS		Roof- Reznor Preeva Air Handler

2279 05/09/2014 06fsv4.5.74-543:jf.jf

325 © Browning Reserve Group 2014 Version 4/8/2014 11:17:33 AM

	Current	Useful	Remaining		Cost/		Included Components
Component	Replacement Cost	Life	Life	Quantity	U of M	Treatment	Location
00010 - Community Center							
23000 - Mechanical Equipment							
284 - HVAC	\$10,250	15	10	1	\$10,250/Itm	1	Roof- Reznor Preeva Air Handler
288 - HVAC	\$10,250	15	10	1	\$10,250/Itm	1	Roof- Reznor Preeva Air Handler
292 - HVAC	\$7,687	15	10	1	\$7,687/Itm	1	Roof Carrier: HP-1
296 - HVAC	\$7,687	15	10	1	\$7,687/Itm	1	Roof Carrier: HP-2
300 - HVAC	\$5,125	15	10	1	\$5,125/Itm	1	Roof- Fujitsu
612 - Water Heater	\$5,637	12	7	1	\$5,637/Itm	1	Pool Storage/Water Heater Rm
616 - Water Heater	\$5,637	12	7	1	\$5,637/Itm	1	Kitchen Storage- Rheem
620 - Water Heater	\$820	12	7	1	\$820/LS	3	Janitorial Room- Rheem
24000 - Furnishings							
104 - Miscellaneous	\$5,125	10	5	1	\$5,125/Rm	1	Social Room Furnishings
192 - Chairs	\$4,766	15	10	93	\$51.25/Itm	1	Community Center Folding Chairs
196 - Chairs	\$17,989	20	15	270	\$66.62/Itm	1	Community Center Stackable Chairs
204 - Chairs	\$4,612	10	5	9	\$512/Itm	1	Office Task Chairs
334 - Tables	\$9,635	20	15	47	\$205/Itm	1	Community Center Folding Tables
644 - Modular Office Desk	\$19,680	20	15	8	\$2,460/Itm	1	Office Desks
24500 - Audio / Visual							
112 - Television, Large Screen	\$3,075	10	5	1	\$3,075/Itm	1	Social Room
300 - PA System	\$2,562	10	5	1	\$2,562/Itm	1	Roof Access Room- QSC Mixer
304 - PA System	\$2,306	10	5	3	\$769/Itm	1	Roof Access Room- Speakers & Stands
24600 - Safety / Access							
900 - Miscellaneous	\$10,250	15	10	1	\$10,250/LS	3	Stage Room- Handicap Lift
25000 - Flooring							
200 - Carpeting	\$6,199	10	5	189	\$32.80/SqYd	İ	Community Center Offices
400 - Tile	\$57,398	20	15	9,333	\$6.15/SqFt		Restrooms, Concession, Kitchen
600 - Vinyl	\$29,475	20	15	1,106	\$26.65/SqYd		Community Center Vinyl Tile
700 - Hardwood Floors	\$44,631	15	10	7,257	\$6.15/SqFt		Yoga Room & Gym
920 - Coatings	\$6,537	12	7	1,063	\$6.15/SqFt		Community Center Concrete Floors
25500 - Wallcoverings							
300 - FRP	\$11,999	20	15	1,951	\$6.15/SqFt	t	Community Center
26000 - Outdoor Equipment							
050 - Flag Pole	\$4,100	20	15	1	\$4,100/Itm	1	Community Center
300 - Picnic Table: Wood	\$820	15	10	2	\$410/Itm	1	Pool Area
332 - Benches	\$1,230	20	15	2	\$615/Itm	1	Common Area

2279 05/09/2014 06fsv4.5.74-543:jf.jf

Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

						Included Components
Component	Current Replacement Cost	Useful Life	Remaining Life	Quantity	Cost/ U of M Treatr	•
00010 - Community Center						
26000 - Outdoor Equipment						
336 - Picnic Table: Metal	\$6,970	20	15	8	\$871/Itm	Pool Area
380 - Garbage Receptacles	\$2,870	20	15	14	\$205/Itm	Common Area & Pool
430 - Bleachers	\$10,762	20	15	3	\$3,587/Itm	Gym- Wood & Metal Bleachers
844 - Shade Structure	\$6,765	10	5	12	\$564/Itm	Portable Shade Structures
27000 - Appliances						
200 - Refrigerator	\$512	7	2	1	\$512/Itm	Pool Maintenance Room
204 - Refrigerator	\$1,025	10	5	1	\$1,025/Itm	Offices- Kitchen/Workroom
224 - Refrigerator: Commercial: Large	\$4,100	20	15	1	\$4,100/Itm	Kitchen- Fridge
240 - Freezer: Large	\$4,100	20	15	1	\$4,100/Itm	Kitchen- Fridge/Freezer Combo
270 - Stove / Oven: Commercial grade 6-burner	\$4,612	20	15	1	\$4,612/Itm	Kitchen
278 - Oven: Wall	\$3,587	20	15	1	\$3,587/Itm	Kitchen- Double Oven
282 - Microwave Oven	\$410	10	4	1	\$410/Itm	Offices- Kitchen/Workroom
290 - Microwave Oven	\$871	10	5	1	\$871/Itm	Kitchen- Panasonic
298 - Stove: Exhaust Hood w/ Fan	\$3,075	20	15	1	\$3,075/Itm	Kitchen- Greencheck Hood
320 - Dishwasher, Commercial	\$4,305	10	5	1	\$4,305/Itm	Kitchen- Hobart
940 - Drinking Fountain	\$2,562	20	15	1	\$2,562/Itm	Community Center Entry
950 - Point of Sale Computer	\$2,050	6	1	1	\$2,050/Itm	Pool Maintenance Room
954 - Point of Sale Computer	\$2,050	6	1	1	\$2,050/Itm	Pool Concession Room
992 - Garbage Disposal	\$1,537	10	5	1	\$1,537/Itm	Kitchen- Savajor
30000 - Miscellaneous						
806 - Maintenance Equipment	\$11,651	20	19	1	\$11,651/Itm	Riding Mower
810 - Maintenance Equipment	\$1,230	15	10	1	\$1,230/Itm	Kitchen Changing Room- Grout Cleaner
818 - Maintenance Equipment	\$5,637	5	0	1	\$5,637/Itm	Roof Access Room- Floor Scrubber
822 - Maintenance Equipment	\$1,025	10	5	1	\$1,025/Itm	Pool Eqpt Rm- Pressure Washer
830 - Maintenance Equipment	\$1,537	5	0	1	\$1,537/Itm	Roof Access Room- Floor Buffer
00030 - Cameron Park Lake 01000 - Paving						
108 - Asphalt: Sealing	\$727	5	2	5,911	\$.12/SqFt	Drives & Parking
208 - Asphalt: Ongoing Repairs	\$3,792	5	2	56,911	\$3.33/SqFt (2%)	Drives & Parking
408 - Asphalt: Major Repairs	\$145,834	20	9	56,911	\$5.12/SqFt (50%	) Drives & Parking
800 - Striping	\$1,507	5	2	98	\$15.37/Itm	Parking Stalls

2279 05/09/2014 06fsv4.5.74-543:jf.jf Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

Prepared for the 2014/2015 Fiscal Year

Included Components

Component	Current Replacement Cost	Useful Life	Remaining Life	Quantity	Cost/ U of M	Treatment	Included Components  Location
00030 - Cameron Park Lake							
02000 - Concrete							
208 - Walkways	\$4,051	5	2	12,350	\$16.40/SqFt	t (2%)	Walkways, Pads, & Slabs
03000 - Painting: Exterior							
104 - Surface Restoration	\$1,168	5	1	1,140	\$1.02/SqFt	t	Guard Shack & [3] Wood Sheds
112 - Surface Restoration	\$3,772	5	0	3,680	\$1.02/SqFt	t	Corporate Yard House
116 - Surface Restoration	\$1,062	5	3	1,036	\$1.02/SqFt	t	Concession Building
120 - Surface Restoration	\$1,999	5	3	1,950	\$1.02/SqFt	t	Gazebo Painting
408 - Railings	\$1,525	4	2	186	\$8.20/l.f		Concrete Footbridge Railings
412 - Railings	\$656	4	0	80	\$8.20/l.f		Lake Observation Deck
420 - Wrought Iron Gates	\$1,025	4	0	2	\$512/Itm	า	Park Entrance Gates
504 - Light Poles	\$6,068	4	1	32	\$190/Itm	า	Park Light Poles
03500 - Painting: Interior							
400 - Restrooms	\$1,952	10	4	1,904	\$1.02/SqFt	t	Concession Building
04000 - Structural Repairs							
200 - Wood: Siding & Trim	\$7,544	10	0	3,680	\$20.50/SqFf	t (10%)	Corporate Yard House
550 - Bridge Maintenance	\$6,729	5	3	1,313	\$51.25/SqFf	t (10%)	[3] Pedestrian Bridges
658 - Decking	\$20,500	20	9	800	\$25.62/SqFt	t	Lake Observation Deck
828 - Dock Floatation	\$5,125	10	4	1	\$5,125/LS	5	[2] Docks & [10] Barges
05000 - Roofing							
448 - Pitched: Dimensional Composition	\$14,760	25	9	36	\$410/Sqrs	5	Corporate Yard House
452 - Pitched: Dimensional Composition	\$18,040	25	11	44	\$410/Sqrs	5	Concession, Gazebo, [3] Small Bldgs
704 - Gutters / Downspouts	\$1,132	25	11	184	\$6.15/l.f		Concession Building Gutters
708 - Gutters / Downspouts	\$2,460	25	9	400	\$6.15/l.f		Corporate Yard House
08000 - Rehab							
234 - Restrooms	\$6,150	20	9	2	\$3,075/Itm	า	Concession Building
254 - Kitchen	\$3,075	20	9	1	\$3,075/Rm	ı	Concession Building
11000 - Gate Equipment							
910 - Vehicle Gate Replacement	\$3,075	20	9	2	\$1,537/Itm	า	Park Entrance Gates
17000 - Tennis Court							
100 - Reseal	\$14,657	7	3	28,600	\$.51/SqFf	t	[4] Tennis Courts
500 - Resurface	\$43,972	21	16	28,600	\$1.54/LS		[4] Tennis Courts
500 - Resurface	\$43,972	21	16	20,000	\$1.54/L3	•	[4] Tellilis Courts

2279 05/09/2014 06fsv4.5.74-543:jf.jf Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

	Current	Useful	Remaining		Cost/			<b>Included Components</b>
Component	Replacement Cost	Life	Life	Quantity	U of M	Treatment	Location	
00030 - Cameron Park Lake								
18000 - Landscaping								
112 - Irrigation: Controllers	\$1,025	10	4	1	\$1,025/Itm	ı	Shed	
344 - Irrigation: Pumps	\$5,125	5	2	1	\$5,125/Itm	ı	25 GPM Well	
478 - Pathways & Trails	\$30,704	10	4	59,910	\$5.12/SqFt	(10%)	Lake Perimeter- DG Path	
18500 - Lakes / Ponds								
300 - Pumps / Mechanical	\$10,250	10	4	1	\$10,250/Itm		10 GPM Well	
320 - Filter	\$12,812	10	4	5	\$2,562/Itm		Filters- Lake & Lagoon	
990 - Miscellaneous	\$7,687	5	3	300	\$512/I.f.	(5%)	Dam/Spillway	
19000 - Fencing								
104 - Chain Link: 4'	\$18,536	30	19	1,644	\$11.27/l.f.		Lake Perimeter Fencing	
128 - Chain Link: 6'	\$258	30	19	21	\$12.30/l.f.		Boat Rental Shack	
132 - Chain Link: 6'	\$16,917	6	2	6,877	\$12.30/l.f.	(20%)	Park Perimeter Fencing	
352 - Wood: 6'	\$2,050	18	14	80	\$25.62/l.f.		Enclosure	
356 - Wood: 6'	\$14,222	18	8	555	\$25.62/l.f.		Corporate Yard Perimeter	
522 - Post & Cable	\$18,491	25	14	902	\$20.50/l.f.		Park Post & Chain Fencing	
19500 - Retaining Wall								
120 - Wood: 1'	\$4,484	20	9	125	\$35.87/l.f.		Park Entrance	
124 - Wood: 2'	\$4,920	18	14	80	\$61.50/l.f.		Enclosure	
20000 - Lighting								
216 - Pole Lights	\$3,690	5	2	32	\$1,230/Itm	(9%)	Park & Lagoon	
21000 - Signage								
778 - Wood Monument	\$1,537	5	3	1	\$1,537/Itm		Park Entrance	
23000 - Mechanical Equipment								
232 - HVAC	\$5,125	15	7	1	\$5,125/Itm		Concession Roof	
26000 - Outdoor Equipment	1-7				1-, -, -			
104 - Tot Lot: Play Equipment	\$7,687	20	9	1	\$7,687/Itm		Play Area- 4-Swing Set	
108 - Tot Lot: Play Equipment	\$35,875	20	9	1	\$35,875/Itm		Play Area- Large Structure	
124 - Tot Lot: Play Equipment	\$5,125	20	9	1	\$5,125/Itm		Play Area- 2-Swing Set	
144 - Tot Lot: Safety Surface	\$2,562	3	1	10,000	\$.26/SqFt		Play Area	
200 - Pedestal Grill BBQ	\$3,382	20	9	11	\$307/Itm		Park Barbecues	
280 - Picnic Tables	\$30,750	20	9	50	\$615/Itm		Park Picnic Tables	
328 - Benches	\$15,375	20	9	25	\$615/Itm		Park Benches	
392 - Garbage Receptacles	\$8,200	20	9	40	\$205/Itm		Park Trash Cans	
492 - Drinking Fountain	\$2,460	20	9	1	\$2,460/Itm		Park Tennis Courts	

2279 05/09/2014 06fsv4.5.74-543:jf.jf

329 © Browning Reserve Group 2014 Version 4/8/2014 11:17:33 AM

Included Components

Component		Useful Life	Remaining	Quantity	Cost/	Location	Included Components
Component	Replacement Cost	Life	Life	Quantity	U of M Treatment	Location	
00030 - Cameron Park Lake							
26000 - Outdoor Equipment							
30000 - Miscellaneous						_	
700 - Tools	\$2,562	10	6	1	\$2,562/Itm	Compressor	
704 - Tools	\$1,537	10	4	1	\$1,537/Itm	Grinder/Sander	
708 - Tools	\$1,025	10	4	1	\$1,025/Itm	Bench Grinder	
712 - Tools	\$1,025	10	4	1	\$1,025/Itm	Bench Grinder	
716 - Tools	\$1,537	10	4	1	\$1,537/Itm	Drill Press	
814 - Maintenance Equipment	\$3,587	20	4	1	\$3,587/Itm	Woods RM500	
826 - Maintenance Equipment	\$51,250	20	14	1	\$51,250/Itm	Vermeer 1230 Chipper	
834 - Tractor	\$20,500	20	14	1	\$20,500/Itm	Massey Ferguson 1525	
838 - Vehicle	\$21,525	10	0	1	\$21,525/Itm	Dodge 2500 V8- Lic 1101411	
846 - Vehicle	\$51,250	10	4	1	\$51,250/Itm	Ford Expedition- Lic 1011647	
850 - Vehicle	\$25,625	10	5	1	\$25,625/Itm	2008 Ford F150 XL- Lic 1273235	, )
854 - Vehicle	\$15,375	10	4	1	\$15,375/Itm	Dodge Pick Up P-01- Lic 108801	8
866 - Vehicle	\$21,525	10	1	1	\$21,525/Itm	Ford Bronco- Lic E041782	
894 - Trailer	\$5,125	15	9	1	\$5,125/Itm	PacWest 20'- Lic. E946571	
898 - Trailer	\$4,100	15	8	1	\$4,100/Itm	Carson 20'- Lic. 1108445	
902 - Trailer	\$2,562	15	7	1	\$2,562/Itm	11' Trailer- Lic. E323108	
906 - Trailer	\$3,075	15	6	1	\$3,075/Itm	15' Trailer	
910 - Trailer	\$7,175	15	9	1	\$7,175/Itm	12' Trailer- Lic. 4LF5474	
914 - Trailer	\$7,687	15	5	1	\$7,687/Itm	2003 Vintage Trailer- Lic 115256	59
918 - Trailer	\$4,100	15	7	1	\$4,100/Itm	BBQ Trailer	
00040 - Rasmussen Park							
01000 - Paving							
112 - Asphalt: Sealing	\$3,346	5	2	27,200	\$.12/SqFt	Parking Lot	
212 - Asphalt: Ongoing Repairs	\$1,812	5	2	27,200	\$3.33/SqFt (2%)	Parking Lot	
412 - Asphalt: Major Repairs	\$139,400	25	14	27,200	\$5.12/SqFt	Parking Lot	
804 - Striping	\$1,537	5	2	1	\$1,537/LS	Parking Lot	
02000 - Concrete							
212 - Walkways	\$1,840	5	2	5,610	\$16.40/SqFt (2%)	Park Walkways	
03000 - Painting: Exterior							
350 - Touch-Up	\$1,537	5	1	3	\$512/Bldg	Park Buildings	
03500 - Painting: Interior							
408 - Restrooms	\$1,132	10	4	1,104	\$1.02/SqFt	Concession Building Restrooms	

2279 05/09/2014 06fsv4.5.74-543:jf.jf Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

Component	Current Replacement Cost	Useful Life	Remaining Life	Quantity	Cost/ U of M	Treatment	Location	Included Components
00040 - Rasmussen Park								
04000 - Structural Repairs								
554 - Bridge Maintenance	\$2,562	20	9	1	\$2,562/Itm	า	Park Pedestrian Bridge	
05000 - Roofing								
460 - Pitched: Dimensional Composition	\$1,230	25	14	3	\$410/Sqrs	5	Maint. Bldg & Wood Shed	
684 - Pitched: Metal	\$3,075	30	19	6	\$512/Sqr	S	Concession Building	
864 - Skylights	\$820	20	9	2	\$410/Itm	า	Concession Building Restrooms	
08000 - Rehab								
246 - Restrooms	\$3,075	20	9	2	\$1,537/Itm	า	Concession Stand Restrooms	
250 - Kitchen	\$3,075	20	9	1	\$3,075/Rm	า	Concession Stand Interior	
18000 - Landscaping								
104 - Irrigation: Misc.	\$1,025	3	1	1	\$1,025/LS	5	Park Irrigation	
340 - Irrigation: Pumps	\$1,230	5	2	1	\$1,230/Itm	า	Park- Irrigation Pump	
420 - General Repairs/Upgrades	\$1,025	3	1	1	\$1,025/LS	5	Park	
474 - Pathways & Trails	\$7,980	5	2	15,570	\$5.12/SqF	t (10%)	Park- Walking Path	
498 - Bedding Header	\$775	20	9	252	\$3.07/I.f		South Play Area	
19000 - Fencing								
100 - Chain Link	\$406	30	28	36	\$11.27/l.f		Tee Ball Field 5' Chain Link	
116 - Chain Link	\$20,859	30	14	1,850	\$11.27/I.f		Ball Fields- 5' Chain Link	
124 - Chain Link: 6'	\$2,091	30	28	170	\$12.30/l.f		Tee Ball Field	
140 - Chain Link: 6'	\$4,084	30	14	332	\$12.30/l.f		North Play Area Perimeter	
144 - Chain Link: 8'	\$933	30	28	65	\$14.35/l.f		Tee Ball Field	
148 - Chain Link: 8'	\$5,740	30	14	400	\$14.35/l.f		Ball Fields	
152 - Chain Link	\$3,844	30	14	150	\$25.62/l.f		Ball Field Back Stops	
344 - Wood: 6'	\$22,678	18	8	885	\$25.62/I.f		East & West Perimeter	
514 - Post & Cable	\$14,965	25	14	730	\$20.50/l.f		Parking Perimeter	
540 - Metal	\$10,045	25	14	980	\$10.25/l.f	•	South Perimeter- Post & Wire	
19500 - Retaining Wall								
364 - Masonry Wall	\$13,612	30	19	332	\$41.00/l.f		North Play Area	
21000 - Signage								
794 - Wood Monument	\$2,562	10	4	1	\$2,562/Itm	า	Park Sign	
25000 - Flooring	. ,						-	
404 - Tile	\$1,378	20	9	224	\$6.15/SqF	t	Concession Building Restrooms	
							-	

2279 05/09/2014 06fsv4.5.74-543:jf.jf Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

Prepared for the 2014/2015 Fiscal Year **Included Components** 

	Current	Hseful	Remaining		Cost/	Included Compone
Component	Replacement Cost	Life	Life	Quantity	U of M Treatment	Location
00040 - Rasmussen Park						
26000 - Outdoor Equipment						
100 - Tot Lot: Play Equipment	\$25,625	20	14	1	\$25,625/Itm	North Play Area
120 - Tot Lot: Play Equipment	\$10,250	20	14	1	\$10,250/Itm	South Play Area
140 - Tot Lot: Safety Surface	\$2,668	3	1	10,410	\$.26/SqFt	North & South Play Areas
294 - Picnic Table: Cement	\$1,025	20	9	2	\$512/Itm	Park Picnic Tables
304 - Picnic Table: Wood	\$820	15	7	2	\$410/Itm	Park Picnic Tables
312 - Benches	\$3,690	20	9	6	\$615/Itm	Park- Metal Benches
320 - Benches	\$3,690	12	5	6	\$615/Itm	Park- Wood Benches
380 - Pet Stations	\$1,066	15	7	4	\$266/Itm	Park
384 - Garbage Receptacles	\$1,230	20	9	6	\$205/Itm	Park- Trash Cans
440 - Bleachers: Aluminum	\$12,300	20	9	4	\$3,075/Itm	Ball Field Bleachers
484 - Drinking Fountain	\$2,460	20	9	1	\$2,460/Itm	Park- Drinking Fountain
840 - Shade Structure	\$6,355	20	11	1,240	\$5.12/SqFt	North Play Area
00050 - Christa McAuliffe Park						
01000 - Paving						
116 - Asphalt: Sealing	\$2,283	5	1	18,563	\$.12/SqFt	Parking Lot
216 - Asphalt: Ongoing Repairs	\$1,237	5	1	18,563	\$3.33/SqFt (2%)	Parking Lot
416 - Asphalt: Major Repairs	\$95,135	25	14	18,563	\$5.12/SqFt	Parking Lot
02000 - Concrete						
216 - Walkways	\$1,338	5	2	2,720	\$16.40/SqFt (3%)	Park Walkways
900 - Miscellaneous	\$32,800	10	4	16,000	\$20.50/SqFt (10%)	Skate Park Concrete
03000 - Painting: Exterior						
404 - Wrought Iron	\$4,520	4	1	490	\$9.22/l.f.	Play Area Perimeter
03500 - Painting: Interior						
404 - Restrooms	\$1,246	10	4	1,216	\$1.02/SqFt	Restroom Building
04000 - Structural Repairs	4-/		•	-,	4 / 4· ·	
994 - Miscellaneous	\$6,150	20	14	300	\$20.50/SqFt	Decorative Wall Resurfacing
	\$0,130	20	17	300	\$20.30/3qi t	Decorative wan Resurracing
05000 - Roofing	+2.050	2.5		F	+440/6	D 1 D 111
440 - Pitched: Dimensional Composition	\$2,050	25	14	5	\$410/Sqrs	Restroom Building
456 - Pitched: Dimensional Composition	\$410	25	4	1	\$410/Sqrs	Skate Park Building
08000 - Rehab						
112 - General	\$1,537	10	1	1	\$1,537/Bldg	Skate Park Building

2279 05/09/2014 06fsv4.5.74-543:jf.jf

Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

	Current	Heaful	Remaining		Cost/	Included Components
Component	Replacement Cost	Life	Life	Quantity	U of M Treatme	ent Location
00050 - Christa McAuliffe Park						
08000 - Rehab						
230 - Restrooms	\$2,050	10	1	1	\$2,050/LS	Restroom Building
19000 - Fencing						
108 - Chain Link: 4'	\$9,640	30	19	855	\$11.27/l.f.	North Perimeter
120 - Chain Link: 6'	\$14,637	30	19	1,190	\$12.30/l.f.	South & East Perimeter
136 - Chain Link: 6'	\$3,198	30	19	260	\$12.30/l.f.	Skate Park Perimeter
220 - Wrought Iron: 4'	\$15,067	30	19	490	\$30.75/l.f.	Play Area Perimeter
360 - Wood: 6'	\$10,122	18	8	395	\$25.62/l.f.	West Perimeter Fence
518 - Post & Cable	\$10,762	25	9	525	\$20.50/l.f.	Parking Lot Perimeter (No Cable)
19500 - Retaining Wall						
360 - Masonry Wall	\$20,090	30	19	490	\$41.00/l.f.	Play Area Perimeter
21000 - Signage						
790 - Wood Monument	\$2,562	10	4	1	\$2,562/Itm	Park Monument Sign
26000 - Outdoor Equipment						
112 - Tot Lot: Play Equipment	\$30,750	20	13	1	\$30,750/LS	Park Large Play Structure
116 - Tot Lot: Play Equipment	\$15,375	20	13	2	\$7,687/Itm	Park- Smaller Structures
284 - Picnic Tables	\$3,075	20	9	5	\$615/Itm	Park Picnic Tables
324 - Benches	\$7,175	20	14	10	\$717/Itm	Park Metal Benches
396 - Garbage Receptacles	\$2,050	20	9	10	\$205/Itm	Park Trash Cans
488 - Drinking Fountain	\$7,380	20	9	3	\$2,460/Itm	Park Drinking Fountains
00060 - Chardi Corner						
18000 - Landscaping						
116 - Irrigation: Controllers	\$1,025	10	4	1	\$1,025/Itm	Chardi Corner- Irrigation Controller
300 - Irrigation: Backflow Preventors	\$615	20	9	1	\$615/Itm	Chardi Corner- Backflow Prevention Device
424 - General Repairs/Upgrades	\$1,025	3	1	1	\$1,025/LS	Chardi Corner
19000 - Fencing						
348 - Wood: 6'	\$7,687	18	8	300	\$25.62/l.f.	Chardi Corner- Perimeter Fencing
19500 - Retaining Wall						
368 - Masonry Wall	\$15,580	30	19	380	\$41.00/l.f.	Chardi Corner- Perimeter Wall
20000 - Lighting						
220 - Landscape	\$1,230	12	5	3	\$410/Itm	Chardi Corner- Sign Lights
21000 - Signage						
782 - Monument	\$2,242	5	3	35	\$256/I.f. (25%)	Chardi Corner- Monument Sign
	, ,				, , , , ,	<b>3</b>

2279 05/09/2014 06fsv4.5.74-543:jf.jf Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

	Current	Heaful	Remaining		Cost/		Included Components
Component	Replacement Cost	Life	Life	Quantity	U of M Treatment	Location	
00060 - Chardi Corner							
26000 - Outdoor Equipment							
064 - Flag Pole	\$4,100	20	9	1	\$4,100/Itm	Chardi Corner- Flag Pole	
00070 - Hacienda Park							
01000 - Paving							
120 - Asphalt: Sealing	\$553	5	2	4,500	\$.12/SqFt	Hacienda- Parking Lot	
220 - Asphalt: Ongoing Repairs	\$450	5	2	4,500	\$3.33/SqFt (3%)	Hacienda Parking Lot	
420 - Asphalt: Major Repairs	\$23,062	25	14	4,500	\$5.12/SqFt	Hacienda- Parking Lot	
02000 - Concrete							
380 - Pad	\$947	10	2	462	\$20.50/SqFt (10%)	[5] Concrete Slabs	
04000 - Structural Repairs							
998 - Miscellaneous	\$512	5	3	1	\$512/Itm	Park- Shed- Upkeep	
18000 - Landscaping							
100 - Irrigation: Misc.	\$1,025	3	0	1	\$1,025/LS	Park	
450 - Drainage System Maint.	\$2,050	3	1	1	\$2,050/LS	Deer Creek Tributary	
470 - Pathways & Trails	\$30,202	10	4	29,465	\$5.12/SqFt (20%)	Park- DG Paths	
494 - Bedding Header	\$1,291	20	14	420	\$3.07/l.f.	Turf Perimeter	
500 - Tree Maintenance	\$5,125	5	2	1	\$5,125/LS	Park- Scrub & Heritage Oaks	
19000 - Fencing							
112 - Chain Link: 4'	\$1,127	20	9	100	\$11.27/l.f.	Creek Perimeter	
364 - Wood: Split Rail	\$11,762	20	14	765	\$15.37/l.f.	Park Perimeter	
510 - Post & Cable	\$1,332	10	4	26	\$102/Itm (50%)	Parking Lot Posts	
21000 - Signage							
798 - Wood Monument	\$1,025	10	6	1	\$1,025/Itm	Park Sign	
26000 - Outdoor Equipment							
290 - Picnic Table: Cement	\$2,306	20	14	3	\$769/Itm	Park- Picnic Tables	
316 - Benches	\$615	20	14	1	\$615/Itm	Park Bench	
376 - Pet Stations	\$266	15	9	1	\$266/Itm	Park- Pet Station	
388 - Garbage Receptacles	\$410	20	14	2	\$205/Itm	Park- Trash Cans	
480 - Drinking Fountain	\$2,460	20	14	1	\$2,460/Itm	Park- Drinking Fountain	
00188 - Station 88							
01000 - Paving							
100 - Asphalt: Sealing	\$972	5	4	3,950	\$.25/SqFt	Parking Lot- Seal & Stripe	
200 - Asphalt: Ongoing Repairs	\$658	10	4	3,950	\$3.33/SqFt (5%)	Parking Lot	
400 - Asphalt: Major Repairs	\$8,097	25	17	3,950	\$4.10/SqFt (50%)	Parking Lot	

2279 05/09/2014 06fsv4.5.74-543:jf.jf

334 © Browning Reserve Group 2014 Version 4/8/2014 11:17:33 AM

				Included Components
Current Us	seful Remaining	Cost/		•
5 / / /	1.0	0 111 111 111	<del>-</del>	

Component	Current Replacement Cost	Useful Life	Remaining Life	Quantity	Cost/ U of M	Treatment	Location
00188 - Station 88							
01000 - Paving							
02000 - Concrete							
200 - Sidewalks, Curbs & Gutters	\$1,181	5	2	2,400	\$16.40/SqFt	(3%)	Exterior Concrete
710 - Sealing	\$2,700	5	2	1,225	\$2.20/SqFt		Vehicle Bays- Concrete Floors
03000 - Painting: Exterior							
100 - Surface Restoration	\$1,107	5	2	360	\$3.07/SqFt		Patio Shed- Paint & Repair
310 - Trim	\$846	5	2	825	\$1.02/SqFt		Station 88- Wood Trim
03500 - Painting: Interior							
110 - Building	\$7,300	10	4	7,122	\$1.02/SqFt		Station 88- Interior Spaces
04000 - Structural Repairs							
364 - Garbage Enclosure	\$1,537	10	4	1	\$1,537/Itm		Parking Area
910 - Doors	\$6,765	20	9	11	\$615/Itm		Station 88- Interior & Exterior Doors
05000 - Roofing							
444 - Pitched: Dimensional Composition	\$14,760	25	15	36	\$410/Sqrs		Station 88
712 - Gutters / Downspouts	\$676	25	15	110	\$6.15/l.f.		Station 88
860 - Skylights	\$820	25	15	2	\$410/Itm		Lobby & Lounge
08000 - Rehab							
120 - General	\$2,050	10	4	2	\$1,025/Rm		Quarters
210 - Bathrooms	\$3,075	10	1	2	\$1,537/Rm		Bathroom & Restroom
214 - Kitchen	\$2,050	20	1	1	\$2,050/Rm		Kitchen
14000 - Recreation							
200 - Exercise: Treadmill	\$2,050	10	4	1	\$2,050/Itm		Vehicle Bays
204 - Exercise: Miscellaneous Equip.	\$3,075	15	7	1	\$3,075/Itm		Vehicle Bays: Weights & Rack
20000 - Lighting							
104 - Exterior: Misc. Fixtures	\$2,050	15	9	8	\$256/Itm		Building & Landscape Lights
540 - Parking Lot	\$2,255	25	14	1	\$2,255/Itm		Parking Lot Light
21000 - Signage							
786 - Wood Monument	\$1,025	10	0	1	\$1,025/Itm		Station 88 Entrance
22000 - Office Equipment							
200 - Computers, Misc.	\$2,050	6	3	1	\$2,050/Itm		Lobby
204 - Computers, Misc.	\$1,537	6	2	1	\$1,537/Itm		Mulit-Quarters Laptop
208 - Computers, Misc.	\$1,537	6	2	1	\$1,537/Itm		Mulit-Quarters PC Workstation

2279 05/09/2014 06fsv4.5.74-543:jf.jf

335 © Browning Reserve Group 2014 Version 4/8/2014 11:17:33 AM

Prepared for the 2014/2015 Fiscal Year Included Components

Component	Current Replacement Cost	Useful Life	Remaining Life	Quantity	Cost/ U of M	Treatment	Location	Included Components
00188 - Station 88								
22000 - Office Equipment								
300 - Copier	\$1,537	6	2	1	\$1,537/Itm	1	Lobby	
23000 - Mechanical Equipment								
200 - HVAC	\$5,125	15	4	1	\$5,125/Itm	1	Patio Area HVAC	
600 - Water Heater	\$820	12	5	1	\$820/Itm	1	Water Heater Closet	
24000 - Furnishings								
100 - Miscellaneous	\$5,125	20	9	1	\$5,125/Rm	1	Lobby Additional Furnishings	
200 - Bar Stools	\$512	15	9	2	\$256/Itm	١	Lounge Barstools	
212 - Chairs	\$1,025	10	5	4	\$256/Itm	١	Station 88 Task Chairs	
228 - Chairs	\$1,537	20	6	3	\$512/Itm	1	Lounge Recliners	
640 - Modular Office Desk	\$3,075	20	9	3	\$1,025/Itm	1	Station 88 Office Desks	
910 - Window Coverings	\$4,100	15	9	8	\$512/Itm	1	Station 88- Window Blinds	
24600 - Safety / Access								
340 - Defibrillators	\$2,562	5	2	1	\$2,562/Itm	١	Lobby	
25000 - Flooring								
210 - Carpeting	\$2,854	10	3	87	\$32.80/SqYd	I	Station 88- Carpeting	
410 - Tile	\$2,226	20	1	362	\$6.15/SqFt	:	Bathroom, Restroom, & Lobby	
610 - Vinyl	\$400	20	1	15	\$26.65/SqYd	I	Kitchen- Linoleum	
26000 - Outdoor Equipment								
060 - Flag Pole	\$4,100	20	14	1	\$4,100/Itm	1	Station 88 Entrance	
210 - Barbecue	\$615	8	4	1	\$615/Itm	1	Patio Barbecue	
350 - Furniture	\$2,050	10	4	8	\$256/Itm	1	Patio Furniture Items	
27000 - Appliances								
208 - Refrigerator	\$1,025	7	3	1	\$1,025/Itm	1	Kitchen	
248 - Ice Machine	\$2,050	10	5	1	\$2,050/Itm		Vehicle Bays- Hoshizaki	
266 - 4-Burner Stove & Oven	\$1,845	7	1	1	\$1,845/Itm	1	Kitchen	
302 - Stove: Exhaust Hood w/ Fan	\$2,665	20	9	1	\$2,665/Itm	١	Kitchen	
306 - Dishwasher	\$1,025	10	4	1	\$1,025/Itm	1	Kitchen	
410 - Washer	\$1,537	10	5	1	\$1,537/Itm	1	Vehicle Bay	
414 - Dryer	\$1,845	10	5	1	\$1,845/Itm	1	Vehicle Bay	
30000 - Miscellaneous								
270 - Garage Door: Metal	\$10,250	20	9	2	\$5,125/Itm	1	Vehicle Bay Doors	
842 - Vehicle	\$597,017	15	5	1	\$597,017/Itm		E 88 Lic 1206288	
858 - Vehicle	\$479,216	15	12	1	\$479,216/Itm	1	E 288 Lic 1375275	

2279 05/09/2014 06fsv4.5.74-543:jf.jf

336 Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

	Current	Useful	Remaining		Cost/		Included Component
Component	Replacement Cost	Life	Life	Quantity	U of M	Treatment	Location
00188 - Station 88							
30000 - Miscellaneous							
898 - Vehicle	\$35,321	15	11	1	\$35,321/Itm	1	U 88 Lic 127543
00189 - Station 89							
01000 - Paving							
104 - Asphalt: Sealing	\$3,280	5	4	20,899	\$.16/SqFt	t	Parking Lot- Seal & Stripe
204 - Asphalt: Ongoing Repairs	\$6,962	10	4	20,899	\$3.33/SqFt	(10%)	Parking Lot
404 - Asphalt: Major Repairs	\$53,554	25	15	20,899	\$5.12/SqFt	t (50%)	Parking Lot
02000 - Concrete							
204 - Sidewalks, Curbs & Gutters	\$4,349	5	2	8,840	\$16.40/SqFf	(3%)	Exterior Concrete
714 - Sealing	\$11,054	5	0	5,016	\$2.20/SqFf	t	Vehicle Bays- Concrete Floors
03000 - Painting: Exterior							
124 - Surface Restoration	\$8,712	10	4	8,500	\$1.02/l.f		Station 89
416 - Railings	\$738	4	1	90	\$8.20/l.f		Balcony & Stairs
920 - Miscellaneous	\$3,587	5	0	1	\$3,587/LS	5	Sheds, Wrought Iron, & Touch-Up
03500 - Painting: Interior							
120 - Building	\$25,586	10	4	24,962	\$1.02/SqFt	t	Station 89 Interior Painting
04000 - Structural Repairs							
360 - Garbage Enclosure	\$2,562	10	4	1	\$2,562/Itm	1	Station 89- Enclosure
920 - Doors	\$19,065	15	5	31	\$615/Itm	1	Station 89 Interior & Exterior Doors
990 - Miscellaneous	\$2,050	10	5	4	\$512/Itm	1	Wood Sheds
04500 - Decking/Balconies							
110 - Concrete	\$1,441	10	4	375	\$15.37/SqFt	(25%)	South Side Building
500 - Railing: Wrought Iron	\$3,136	20	10	90	\$34.85/l.f	<u>.</u>	Balcony & Stair Railings
05000 - Roofing							
334 - Low Slope: Vinyl	\$24,600	20	10	48	\$512/Sqrs	5	Station 89 Flat Roofing
680 - Pitched: Metal	\$15,887	30	20	31	\$512/Sqrs	5	Station 89 Metal Roof
720 - Gutters / Downspouts	\$1,291	30	20	210	\$6.15/l.f	<u>.</u>	Station 89
08000 - Rehab							
128 - General	\$8,200	20	10	4	\$2,050/Rm	1	Dormitory Rooms
132 - General	\$2,562	20	10	1	\$2,562/Rm		Work Room
136 - General	\$6,150	20	10	3	\$2,050/Rm	1	Offices
140 - General	\$2,562	20	10	1	\$2,562/Rm	1	Reception
218 - Bathrooms	\$6,150	20	2	2	\$3,075/Rm	1	Upstairs Bathrooms
226 - Bathrooms	\$4,100	20	10	2	\$2,050/Rm	1	Downstairs Restrooms

2279 05/09/2014 06fsv4.5.74-543:jf.jf

337 © Browning Reserve Group 2014 Version 4/8/2014 11:17:33 AM

	Current	Useful	Remaining		Cost/		Included Components
Component	Replacement Cost	Life	Life	Quantity	U of M	Treatment	Location
00189 - Station 89							
08000 - Rehab							
262 - Kitchen	\$1,537	20	10	1	\$1,537/Rm	l	Coffee Room
270 - Kitchen	\$3,075	20	19	1	\$3,075/Rm	l	Kitchen
274 - Laundry Room	\$1,537	20	19	1	\$1,537/Rm	l	Upstairs Laundry
14000 - Recreation							
220 - Exercise: Treadmill	\$2,050	10	4	1	\$2,050/Itm	1	Weight Room
224 - Exercise: Cardio Equipment	\$1,845	10	4	1	\$1,845/Itm	]	Weight Room Elliptical
228 - Exercise: Weight Machine	\$3,587	20	10	1	\$3,587/Itm	1	Weight Room
232 - Exercise: Miscellaneous Equip.	\$1,537	20	10	1	\$1,537/Itm	1	Weight Room Tuff Stuff Rack
236 - Exercise: Miscellaneous Equip.	\$3,075	15	9	1	\$3,075/Itm	ı	Weight Room Dumbbells & Rack
18000 - Landscaping							
108 - Irrigation: Misc.	\$1,025	5	1	1	\$1,025/LS	;	Backflows, Controllers, Valves
482 - Pathways & Trails	\$2,665	5	1	520	\$5.12/SqFt	-	DG Walking Path
19000 - Fencing							
310 - Wood: 3'	\$769	18	1	50	\$15.37/l.f.		Northeast Perimeter
340 - Wood: 6'	\$22,934	18	3	895	\$25.62/l.f.		Perimeter Fencing
19500 - Retaining Wall							
372 - Masonry Wall Maintenance	\$1,441	10	4	225	\$25.62/l.f.	(25%)	Keystone Retaining Wall
20000 - Lighting	, ,						,
100 - Exterior: Misc. Fixtures	\$5,381	20	10	21	\$256/Itm	1	Station 89- Exterior Building Lights
420 - Interior	\$7,380	20	10	72	\$205/Itm		Station 89 Interior Lighting
424 - Interior	\$1,230	15	8	6	\$205/Itm		Station 89 Ceiling Fans
21000 - Signage	, ,				,,		<b>3</b>
774 - Wood Monument	\$3,075	15	0	2	\$1,537/Itm	1	Station 89 Signs
22000 - Office Equipment	Ψ3/3/3	13	Ü	-	Ψ1/33//10.	•	Station 05 Signs
212 - Computers, Misc.	\$1,025	6	1	1	\$1,025/Itm		Reception Dell PC Workstation #3101
216 - Computers, Misc.	\$1,025 \$1,025	6	1	1	\$1,025/Itm \$1,025/Itm		Reception Dell PC Workstation #3102
220 - Computers, Misc.	\$1,025 \$1,025	6	0	1	\$1,025/Itm		Reception Gateway PC Workstation #3092
224 - Computers, Misc.	\$1,025 \$1,025	6	0	1	\$1,025/Itm		Reception Brother Printer
228 - Computers, Misc.	\$1,025 \$1,025	6	4	1	\$1,025/Itm \$1,025/Itm		Station Captains Office
232 - Computers, Misc.	\$1,025	10	4	1	\$1,023/Itm		Station Captain's Office- Shredder
236 - Computers, Misc.	\$1,230 \$512	6	2	1	\$1,230/1tm \$512/Itm		Station Captain's Office- Printer
240 - Computers, Misc.	\$1,332	10	4	1	\$1,332/Itm		Work Room- Fax
244 - Computers, Misc.	\$1,127	10	4	1	\$1,332/Itm		Work Room- Shredder
Z i i Computers, inser	Ψ1,127	10	<del>-</del>		Ψ1,12//1011	·	WORK ROOM SHICAACI

2279 05/09/2014 06fsv4.5.74-543:jf.jf

338 Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

Component	Current Replacement Cost	Useful Life	Remaining Life	Quantity	Cost/ U of M	Treatment	Included Components  Location
00189 - Station 89	•						
22000 - Office Equipment							
248 - Computers, Misc.	\$1,537	6	2	1	\$1,537/Itm	1	Equipment Room- UPS 1500
252 - Computers, Misc.	\$5,125	6	2	1	\$5,125/Itm		Equipment Room- Power Connect 2724
256 - Computers, Misc.	\$1,025	6	2	1	\$1,025/Itm		Equipment Room- Surge Protector
260 - Computers, Misc.	\$5,125	6	2	1	\$5,125/Itm		Equipment Room- Poweredge 2900
264 - Computers, Misc.	\$1,025	6	0	1	\$1,025/Itm		Fire Prevention Office
268 - Computers, Misc.	\$1,230	6	2	1	\$1,230/Itm		Fire Prevention Office- Shredder
272 - Computers, Misc.	\$1,025	6	4	1	\$1,025/Itm	1	Battalion Chief's Office
304 - Copier	\$3,587	10	4	1	\$3,587/Itm	า	Work Room- Copier
360 - Telephone Equipment	\$4,612	6	2	1	\$4,612/Itm		Equipment Room- Phone System
364 - Telephone Equipment	\$4,612	6	2	1	\$4,612/Itm		Equipment Room- Integration Hub
368 - Telephone Equipment	\$4,612	6	2	1	\$4,612/Itm	า	Equipment Room- Phone System
23000 - Mechanical Equipment							
204 - HVAC	\$10,250	15	7	1	\$10,250/Itm	1	Roof- AC-1
208 - HVAC	\$10,250	15	7	1	\$10,250/Itm		Roof- AC-2
212 - Fan	\$4,612	20	10	1	\$4,612/Itm		Roof- Ventilation Fan
216 - Fan	\$4,100	20	10	1	\$4,100/Itm		Roof- Captive Aire Systems, Supply
220 - Fan	\$4,100	20	10	1	\$4,100/Itm		Roof- Captive Aire Systems, Exhaust
224 - Swamp Cooler	\$5,125	20	10	1	\$5,125/Itm		Roof- Evaporative Air Cooler
228 - Swamp Cooler	\$5,125	20	10	1	\$5,125/Itm		Roof- Evaporative Air Cooler
330 - Fuel Tank	\$15,375	30	20	2	\$7,687/Itm	า	Parking Area Fueling Tanks
580 - Cooling Tower	\$3,587	20	10	1	\$3,587/Itm	า	Roof- REF-1
604 - Water Heater	\$820	12	7	1	\$820/Itm	า	Upstairs Closet
608 - Water Heater	\$820	12	0	1	\$820/Itm	า	Mechanic's Bay
24000 - Furnishings							
208 - Chairs	\$2,306	10	2	9	\$256/Itm	า	Station 89 Task Chairs
216 - Chairs	\$769	15	8	10	\$76.87/Itm	า	Station 89 Wood/Cloth Chairs
220 - Chairs	\$1,153	20	3	15	\$76.87/Itm	ı	Station 89 Stackable Chairs
224 - Chairs	\$3,536	20	10	46	\$76.87/Itm	า	Station 89 Folding Chairs
232 - Chairs	\$3,075	10	4	6	\$512/Itm	า	Lounge- Recliners
310 - Tables: Dining: Large	\$1,025	20	10	1	\$1,025/Itm	า	Lounge & Kitchen
330 - Tables	\$1,742	20	10	17	\$102/Itm	า	Station 89 Folding Tables
650 - Modular Office Desk	\$5,125	20	10	5	\$1,025/Itm	า	Station 89 Office Desks
880 - Security Deposit Boxes	\$512	12	5	1	\$512/Itm	า	Station Captain's Office Lockbox
884 - Security Deposit Boxes	\$2,562	20	10	1	\$2,562/Itm	า	Station Captain's Office Safe

2279 05/09/2014 06fsv4.5.74-543:jf.jf

339 © Browning Reserve Group 2014 Version 4/8/2014 11:17:33 AM

Component	Current Replacement Cost	Useful Life	Remaining Life	Quantity	Cost/ U of M	Treatment	Included Components  Location
00189 - Station 89							
24000 - Furnishings							
920 - Window Coverings	\$9,737	15	5	19	\$512/Itm	า	Station 89 Window Blinds
24500 - Audio / Visual							
100 - Television	\$1,537	10	4	1	\$1,537/Itm	ı	Weight Room
200 - DVD Player	\$512	6	2	1	\$512/Itm	า	Storage (Conference)- Sony DVD
204 - DVD Player	\$512	6	2	1	\$512/Itm	า	Storage (Conference)- Toshiba DVD
308 - PA System	\$769	10	4	1	\$769/Itm	า	Equipment Room- Amplifier
312 - PA System	\$2,562	10	4	1	\$2,562/LS	5	Conference Room- Podium
316 - PA System	\$3,587	6	2	1	\$3,587/Itm	า	Conference Room- Projector
24600 - Safety / Access							
120 - Fire Control Misc	\$5,125	10	4	1	\$5,125/LS	6	Building Alarm & Extinguishers
350 - Defibrillators	\$2,562	5	2	1	\$2,562/Itm	า	Lobby
25000 - Flooring							
220 - Carpeting	\$8,594	10	4	262	\$32.80/SqYd	d	Station 89 Interior Carpeting
420 - Tile	\$15,639	20	10	2,543	\$6.15/SqFt	t	Station 89 Floor & Wall Tile
620 - Vinyl	\$1,332	20	10	50	\$26.65/SqYc	d	Bathroom Vinyl Tile
624 - Vinyl	\$5,104	20	10	166	\$30.75/SqYd	d	Station 89 Wood Laminate Flooring
990 - Miscellaneous	\$830	15	9	27	\$30.75/SqYd	d	Weight Room Rubber Flooring
26000 - Outdoor Equipment							
068 - Flag Pole	\$5,637	30	20	1	\$5,637/Itm	า	Station 89- Flag Pole
220 - Barbecue	\$512	8	3	1	\$512/Itm	า	Balcony
308 - Picnic Table: Wood	\$410	15	8	1	\$410/Itm	า	Patio
27000 - Appliances							
220 - Refrigerator: Commercial: Large	\$2,050	10	6	1	\$2,050/Itm	ı	Kitchen
244 - Freezer: Large	\$820	10	6	1	\$820/Itm	า	Kitchen
252 - Ice Machine	\$2,050	10	4	1	\$2,050/Itm	า	Upstairs Closet- Ice-O-Matic
256 - Ice Machine	\$2,050	10	4	1	\$2,050/Itm	า	Mechanic's Bay- Manitowac
260 - Stove	\$3,587	12	8	1	\$3,587/Itm	า	Kitchen
274 - Oven: Wall	\$2,562	10	4	1	\$2,562/Itm	า	Kitchen
286 - Microwave Oven	\$615	10	4	1	\$615/Itm	า	Kitchen
294 - Stove: Fire Suppression	\$5,637	10	4	1	\$5,637/Itm		Kitchen
310 - Dishwasher, Residential Type	\$1,025	5	0	1	\$1,025/Itm	า	Kitchen
418 - Washer: Large	\$12,300	10	4	1	\$12,300/Itm	า	Mechanic's Bay- Washer/Extractor

2279 05/09/2014 06fsv4.5.74-543:jf.jf

Version 4/8/2014 11:17:33 AM © Browning Reserve Group 2014

**Included Components** 

341

Prepared for the 2014/2015 Fiscal Year

Component	Current Replacement Cost	Useful Life	Remaining Life	Quantity	Cost/ U of M	Treatment	Location	Included Components
00189 - Station 89								
27000 - Appliances								
422 - Dryer	\$1,025	10	4	1	\$1,025/Itm	1	Mechanic's Bay- Kenmore	
426 - Washer	\$717	10	6	1	\$717/Itm	1	Upstairs Laundry	
430 - Dryer	\$1,025	10	6	1	\$1,025/Itm	1	Upstairs Laundry	
684 - Miscellaneous	\$512	10	4	1	\$512/Itm	1	Coffee Room- Coffee Maker	
984 - Miscellaneous	\$512	10	4	1	\$512/Itm	1	Kitchen- Coffee Maker	
988 - Miscellaneous	\$256	10	4	1	\$256/Itm	1	Kitchen- Coffee Grinder	
30000 - Miscellaneous								
266 - Garage Door: Metal	\$15,375	20	19	3	\$5,125/Itm	1	Station 89 Garage Bay Doors	
274 - Garage Door: Metal	\$20,500	20	3	4	\$5,125/Itm	1	Station 89 Garage Bay Doors- R	.ear
870 - Vehicle	\$39,737	10	6	1	\$39,737/Itm	1	B2715- Lic 1275433	
874 - Vehicle	\$39,737	10	6	1	\$39,737/Itm	1	B2716 Lic 1275432	
878 - Vehicle	\$597,017	15	1	1	\$597,017/Itm	1	E-89- Lic 1206287	
882 - Vehicle	\$490,842	15	2	1	\$490,842/Itm	1	E-289- Lic E1109085	
886 - Vehicle	\$555,238	10	7	1	\$555,238/Itm	1	E-389 Lic E000391	
890 - Vehicle	\$45,491	15	3	1	\$45,491/Itm	1	U-89 Lic 1088016	

\$39,563/Itm

\$30,750/Itm

U-289 Lic 041782

Building East Side- Generac Series

1

1

2279 05/09/2014 06fsv4.5.74-543:jf.jf © Browning Reserve Group 2014 Version 4/8/2014 11:17:33 AM

2

20

15

30

\$39,563

\$30,750

894 - Vehicle

922 - Generator





# Cameron Park Community Services District

### Expenditures by Year - Next 3 Years

Reserve Component	Life Useful	Current Replacement Cost	Forecast Inflated Cost @ 2.50%
2013/14			
00010 - Community Center			
04000 - Structural Repairs 914 - Doors	2	2.075	
45 Community Center Interior Doors (11%)	2	3,075	
30000 - Miscellaneous			
818 - Maintenance Equipment Roof Access Room- Floor Scrubber	5	5,637	5,638
830 - Maintenance Equipment Roof Access Room- Floor Buffer	5	1,537	1,538
	Total 30000 - Miscellaneous:	7,174	7,176
	Total Community Center:	10,249	10,251
00030 - Cameron Park Lake	rotal community contern	10,243	10,231
03000 - Painting: Exterior			
112 - Surface Restoration 3,680 Sq. Ft. Corporate Yard House	5	3,772	
412 - Railings 80 Lin. Ft. Lake Observation Deck	4	656	
420 - Wrought Iron Gates 2 Park Entrance Gates	4	1,025	
	Total 03000 - Painting: Exterior:	5,453	5,453
04000 - Structural Repairs		-,	2, 22
200 - Wood: Siding & Trim 3,680 Sq. Ft. Corporate Yard House (10%)	10	7,544	
30000 - Miscellaneous			
838 - Vehicle Dodge 2500 V8- Lic 1101411	10	21,525	
	Total Cameron Park Lake:	34,522	34,522
00070 - Hacienda Park 18000 - Landscaping			
100 - Irrigation: Misc. Park	3	1,025	
	Total Hacienda Park:	1,025	1,025
00188 - Station 88		_,===	_,0_0
21000 - Signage			
786 - Wood Monument Station 88 Entrance	10	1,025	
	Total Station 88:	1,025	1,025
00189 - Station 89	Total Station 66.	1,023	1,023
02000 - Concrete			
714 - Sealing 5,016 Sq. Ft. Vehicle Bays- Concrete Floors	5	11,054	
03000 - Painting: Exterior	_	2.507	2.500
920 - Miscellaneous Sheds, Wrought Iron, & Touch-Up	5	3,587	3,588

December Commonwell	Life	Current	Forecast Inflated Cost @ 2.50%
Reserve Component	Useful	Replacement Cost	Timated Cost @ 2.50 %
2013/14			
00189 - Station 89 21000 - Signage			
774 - Wood Monument	15	3,075	
2 Station 89 Signs	13	3,073	
22000 - Office Equipment			
220 - Computers, Misc. Reception Gateway PC Workstation #3092	6	1,025	
224 - Computers, Misc. Reception Brother Printer	6	1,025	
264 - Computers, Misc. Fire Prevention Office	6	1,025	
	Total 22000 - Office Equipment:	3,075	3,075
23000 - Mechanical Equipment			
608 - Water Heater Mechanic's Bay	12	820	
27000 - Appliances			
310 - Dishwasher, Residential Type Kitchen	5	1,025	
	Total Station 89:	22,636	22,637
	Total 2013/14:	69,457	69,460
2014/15			
00010 - Community Center			
03000 - Painting: Exterior			
500 - Light Poles 14 Common Area Light Poles	4	2,655	2,721
12000 - Pool			
752 - Cover 7,425 Sq. Ft. Pool	5	7,611	7,801
27000 - Appliances			
950 - Point of Sale Computer Pool Maintenance Room	6	2,050	2,101
954 - Point of Sale Computer Pool Concession Room	6	2,050	2,101
	Total 27000 - Appliances:	4,100	4,202
	Total Community Center:	14,366	14,724
00030 - Cameron Park Lake		•	,
03000 - Painting: Exterior			
104 - Surface Restoration 1,140 Sq. Ft. Guard Shack & [3] Wood Sheds	5	1,168	1,198
504 - Light Poles 32 Park Light Poles	4	6,068	6,220
	Total 03000 - Painting: Exterior:	7,236	7,418
26000 - Outdoor Equipment			
144 - Tot Lot: Safety Surface 10,000 Sq. Ft. Play Area	3	2,562	2,627
30000 - Miscellaneous			
866 - Vehicle Ford Bronco- Lic E041782	10	21,525	22,063
	Total Cameron Park Lake:	31,323	32,108

Prepared for the 2014/2015 Fiscal Year

	1:6-	Current	Forecast	
Reserve Component	Life Useful		Inflated Cost @ 2.50%	
2014/15				
00040 - Rasmussen Park				
03000 - Painting: Exterior				
350 - Touch-Up 3 Park Buildings	5	1,537	1,576	
18000 - Landscaping				
104 - Irrigation: Misc. Park Irrigation	3	1,025	1,051	
420 - General Repairs/Upgrades Park	3	1,025	1,051	
	Total 18000 - Landscaping:	2,050	2,102	
26000 - Outdoor Equipment				
140 - Tot Lot: Safety Surface 10,410 Sq. Ft. North & South Play Areas	3	2,668	2,734	
	Total Rasmussen Park:	6,255	6,412	
00050 - Christa McAuliffe Park 01000 - Paving				
116 - Asphalt: Sealing 18,563 Sq. Ft. Parking Lot	5	2,283	2,340	
216 - Asphalt: Ongoing Repairs 18,563 Sq. Ft. Parking Lot (2%)	5	1,237	1,268	
	Total 01000 - Paving:	3,520	3,608	
03000 - Painting: Exterior				
404 - Wrought Iron 490 Lin. Ft. Play Area Perimeter	4	4,520	4,633	
08000 - Rehab				
112 - General Skate Park Building	10	1,537	1,576	
230 - Restrooms Restroom Building	10	2,050	2,101	
	Total 08000 - Rehab:	3,587	3,677	
	Total Christa McAuliffe Park:	11,627	11,918	
00060 - Chardi Corner				
18000 - Landscaping				
424 - General Repairs/Upgrades Chardi Corner	3	1,025	1,051	
	Total Chardi Corner:	1,025	1,051	
00070 - Hacienda Park				
18000 - Landscaping		2.050	2.404	
450 - Drainage System Maint. Deer Creek Tributary	3	2,050	2,101	
	Total Hacienda Park:	2,050	2,101	
00188 - Station 88				
08000 - Rehab 210 - Bathrooms	10	2 075	3,152	
2 Bathroom & Restroom		3,075		
214 - Kitchen Kitchen	20	2,050	2,101	
	Total 08000 - Rehab:	5,125	5,253	

Reserve Component				for the 2014/2015 Fiscal Yea
	Reserve Component	Life Useful	Current Replacement Cost	Forecast Inflated Cost @ 2.50%
	2014/15			
10 - Tile	•			
Sac Sq. Rt. Bathroom, Restroom, & Lobby   20	25000 - Flooring			
15 Sq. Yds. Kitchen- Linoleum   Total 25000 - Flooring:   2,626   2,692		20	2,226	2,282
27000 - Appliances         266 - 4-Burner Stove & Oven Kitchen         7 total Station 88         1,891           266 - 4-Burner Stove & Oven Kitchen         Total Station 88         9,596         9,836           00189 - Station 89         30000 - Painting: Exterior           416 - Raillings	•	20	400	410
266 - 4 Burner Stove & Oven Kitchen     7 total Station 88: 1,891       Notal Station 88: 9,596     9,836       O0189 - Station 89       3000 - Painting: Exterior       416 - Rallings 9 90 Lin. Ft. Balcony & Statirs 9 90 Lin. Ft. Balcony & Statirs 9 90 Lin. Pt. Balcony & Statirs 9 1,005 1 1		Total 25000 - Flooring:	2,626	2,692
Name	27000 - Appliances			
		7	1,845	1,891
03000 - Painting: Exterior         416 - Raillings 90 Lin. Ft. Balcony & Stairs       4 738       756         18000 - Landscaping       5 1,025       1,051         108 - Irrigation: Misc. Backflows, Controllers, Valves       5 2,665       2,732         482 - Pathways & Trails 520 Sq. Ft. DG Walking Path       Total 18000 - Landscaping: 3,690       3,783         19000 - Fencing       8 769       3,880         310 - Wood: 3' So Lin. Ft. Northeast Perimeter       8 769       788         22000 - Office Equipment       1 ,025       1,051         212 - Computers, Misc. Reception Dell PC Workstation #3101       6 1,025       1,051         216 - Computers, Misc. Reception Dell PC Workstation #3102       7 total 22000 - Office Equipment: 2,050       2,102         30000 - Miscellaneous       15 597,017       611,943         288 - Vehicle E-89- Lic 1206287       15 597,017       611,943         289 - Lic 1206287       Total 211/15: 680,506       697,522         2015/16       00010 - Community Center         01000 - Paving       5 7,269       7,637         124 - Asphalt: Sealing 59,100 Sq. Ft. Parking Lot       5 7,269       7,637         224 - Asphalt: Ongoing Repairs 59,100 Sq. Ft. Parking Lot       5 3,587       3,769         224 - Asphalt: Ongoing Repairs 59,100 Sq. Ft.		Total Station 88:	9,596	9,836
416 - Railings   4   738   756   90 Lin. Pt. Balcony & Stairs   18000 - Landscaping   108 - Irrigation: Misc.   5   1,025   1,051   1,				
188 One - Landscaping       108 - Irrigation: Misc. Backflows, Controllers, Valves     5     1,025     1,051       482 - Pathways & Trails 520 Sq. Ft. DG Walking Path     5     2,665     2,732       19000 - Fencing     3,690     3,783       310 - Wood: 3' 50 Lin. Ft. Northeast Perimeter     8     769     788       2000 - Office Equipment     8     769     788       212 - Computers, Misc. Reception Dell PC Workstation #3101     6     1,025     1,051       216 - Computers, Misc. Reception Dell PC Workstation #3102     6     1,025     1,051       Reception Dell PC Workstation #3102     5     597,017     611,943       878 - Vehicle E-89- Lic 1206287     15     597,017     611,943       878 - Vehicle E-89- Lic 1206287     Total Station 89:     604,264     619,372       7000 - Paving     7000 Sq. 50,000     697,522       2015/16     20015 Sq. 50,000 Sq. 75, Parking Lot     7,269     7,637       224 - Asphalt: Scaling Sq. 100 Sq. Ft. Parking Lot     5     7,269     7,637       224 - Asphalt: Ongoing Repairs Sq. 100 Sq. Ft. Parking Lot     5     3,587     3,769       808 - Striping Parking Lot     Total 01000 - Paving:     15,778     16,577       800 - Concrete     70000 - Concrete     70000 - Concrete     700000 - Concrete     70		4	738	756
108 - Irrigation: Misc. Backflows, Controllers, Valves 482 - Pathways & Trails 520 Sq. Ft. DG Walking Path  Total 18000 - Landscaping: 3,690 3,783  19000 - Fencing 310 - Wood: 3' 50 Uin. Ft. Northeast Perimeter 22000 - Office Equipment 212 - Computers, Misc. Reception Dell PC Workstation #3101 216 - Computers, Misc. 6 1,025 1,051 Reception Dell PC Workstation #3101 216 - Computers, Misc. 6 1,025 1,051 Reception Dell PC Workstation #3102  Total 22000 - Office Equipment: 2,050 2,102  30000 - Miscellaneous 878 - Vehicle Fence	90 Lin. Ft. Balcony & Stairs			
482 - Pathways & Trails     5     2,665     2,732       19000 - Fencing       310 - Wood: 3' 50 Lin. Ft. Northeast Perimeter       22000 - Office Equipment       212 - Computers, Misc. Reception Dell PC Workstation #3101     6     1,025     1,051       Total 22000 - Office Equipment:       216 - Computers, Misc. Reception Dell PC Workstation #3102     6     1,025     1,051       Total 22000 - Office Equipment:     2,050     2,102       30000 - Miscellaneous       878 - Vehicle E-89- Lic 1206287     15     597,017     611,943       Total Station 89: 604,264     619,372       Total 2014/15: 680,506     697,522       2015/16       00010 - Community Center       124 - Asphalt: Sealing Spinos Spin	108 - Irrigation: Misc.	5	1,025	1,051
Total   18000 - Landscaping:   3,690   3,783	482 - Pathways & Trails	5	2,665	2,732
19000 - Fencing   18   769   788   750   15. Northeast Perimeter   2000 - Office Equipment   212 - Computers, Misc. Reception Dell PC Workstation #3101   216 - Computers, Misc. Reception Dell PC Workstation #3102   70tal 22000 - Office Equipment:   2,050   2,102   2000 - Miscellaneous   2000 - Miscellaneous   2000 - Miscellaneous   2,050   2,102   2000 - Miscellaneous   2,050   2,102	3 11	Total 18000 - Landscaping:	3.690	3.783
So Lin. Ft. Northeast Perimeter	19000 - Fencing		2,223	27. 23
212 - Computers, Misc. Reception Dell PC Workstation #3101       6       1,025       1,051         216 - Computers, Misc. Reception Dell PC Workstation #3102       Total 22000 - Office Equipment:       2,050       2,102         30000 - Miscellaneous       597,017       611,943         878 - Vehicle E-89- Lic 1206287       15       597,017       611,943         Total Station 89: Total 2014/15:       604,264       619,372         2015/16       680,506       697,522         2015/16       50,100 - Community Center         01000 - Paving       5       7,269       7,637         124 - Asphalt: Sealing 59,100 Sq. Ft. Parking Lot       5       7,269       7,637         224 - Asphalt: Ongoing Repairs 59,100 Sq. Ft. Parking Lot (3%)       5       3,587       3,769         808 - Striping Parking Lot       5       3,587       3,769         702000 - Concrete       702000 - Paving:       15,778       16,577         02000 - Concrete       904 - Miscellaneous       5       12,628       13,267		18	769	788
Reception Dell PC Workstation #3101 216 - Computers, Misc. Reception Dell PC Workstation #3102  Total 22000 - Office Equipment: 2,050 2,102  30000 - Miscellaneous 878 - Vehicle E-89- Lic 1206287  Total Station 89: 604,264 619,372 Total 2014/15: 680,506 697,522  2015/16  00010 - Community Center 01000 - Paving 124 - Asphalt: Sealing 5 7,269 7,637 59,100 Sq. Ft. Parking Lot 224 - Asphalt: Ongoing Repairs 59,100 Sq. Ft. Parking Lot (3%) 808 - Striping Parking Lot Total 01000 - Paving: 15,778 16,577  02000 - Concrete 904 - Miscellaneous 5 12,628 13,267	22000 - Office Equipment			
Reception Dell PC Workstation #3102   Total   22000 - Office Equipment:   2,050   2,102		6	1,025	1,051
30000 - Miscellaneous  878 - Vehicle E-89- Lic 1206287  Total Station 89:  Total Station 89:  604,264 619,372  Total 2014/15: 680,506 697,522  2015/16  00010 - Community Center 01000 - Paving 124 - Asphalt: Sealing 59,100 Sq. Ft. Parking Lot 224 - Asphalt: Ongoing Repairs 59,100 Sq. Ft. Parking Lot 224 - Asphalt: Ongoing Repairs 59,100 Sq. Ft. Parking Lot 2015/16  Total 01000 - Paving: 15,778 16,577  15,778 16,577  15,778 16,577  15,778 16,577		6	1,025	1,051
878 - Vehicle E-89- Lic 1206287  Total Station 89: 597,017 611,943  Total Station 89: 604,264 619,372  Total 2014/15: 680,506 697,522  2015/16  00010 - Community Center 01000 - Paving  124 - Asphalt: Sealing 59,100 Sq. Ft. Parking Lot (3%)  808 - Striping Parking Lot  Total 01000 - Paving: 15,778 16,577  02000 - Concrete  904 - Miscellaneous 5 12,628 13,267		Total 22000 - Office Equipment:	2,050	2,102
Total Station 89: 604,264 619,372  Total 2014/15: 680,506 697,522  2015/16  00010 - Community Center 01000 - Paving  124 - Asphalt: Sealing 5 7,269 7,637 59,100 Sq. Ft. Parking Lot 224 - Asphalt: Ongoing Repairs 59,100 Sq. Ft. Parking Lot (3%)  808 - Striping Parking Lot  Total 01000 - Paving: 15,778 16,577  02000 - Concrete  904 - Miscellaneous 5 12,628 13,267	30000 - Miscellaneous			
Total 2014/15: 680,506 697,522  2015/16  00010 - Community Center 01000 - Paving  124 - Asphalt: Sealing 5 7,269 7,637 59,100 Sq. Ft. Parking Lot  224 - Asphalt: Ongoing Repairs 5 4,922 5,171 59,100 Sq. Ft. Parking Lot (3%)  808 - Striping Parking Lot  Total 01000 - Paving: 15,778 16,577  02000 - Concrete  904 - Miscellaneous 5 12,628 13,267		15	597,017	611,943
2015/16  00010 - Community Center  01000 - Paving  124 - Asphalt: Sealing		Total Station 89:	604,264	619,372
00010 - Community Center         01000 - Paving       5       7,269       7,637         124 - Asphalt: Sealing 59,100 Sq. Ft. Parking Lot       5       4,922       5,171         224 - Asphalt: Ongoing Repairs 59,100 Sq. Ft. Parking Lot (3%)       5       3,587       3,769         808 - Striping Parking Lot       5       3,587       3,769         Total 01000 - Paving: 15,778       16,577         02000 - Concrete         904 - Miscellaneous       5       12,628       13,267		Total 2014/15:	680,506	697,522
00010 - Community Center         01000 - Paving       5       7,269       7,637         124 - Asphalt: Sealing 59,100 Sq. Ft. Parking Lot       5       4,922       5,171         224 - Asphalt: Ongoing Repairs 59,100 Sq. Ft. Parking Lot (3%)       5       3,587       3,769         808 - Striping Parking Lot       5       3,587       3,769         Total 01000 - Paving: 15,778       16,577         02000 - Concrete         904 - Miscellaneous       5       12,628       13,267	2015/16			
124 - Asphalt: Sealing 5 7,269 7,637 59,100 Sq. Ft. Parking Lot  224 - Asphalt: Ongoing Repairs 5 4,922 5,171 59,100 Sq. Ft. Parking Lot (3%)  808 - Striping Parking Lot  Total 01000 - Paving: 15,778 16,577  02000 - Concrete  904 - Miscellaneous 5 12,628 13,267	00010 - Community Center			
224 - Asphalt: Ongoing Repairs 5 4,922 5,171 59,100 Sq. Ft. Parking Lot (3%)  808 - Striping 5 3,587 3,769 Parking Lot  Total 01000 - Paving: 15,778 16,577  02000 - Concrete  904 - Miscellaneous 5 12,628 13,267	124 - Asphalt: Sealing	5	7,269	7,637
808 - Striping 5 3,587 3,769 Parking Lot  Total 01000 - Paving: 15,778 16,577  02000 - Concrete  904 - Miscellaneous 5 12,628 13,267	224 - Asphalt: Ongoing Repairs	5	4,922	5,171
Total 01000 - Paving: 15,778 16,577  02000 - Concrete  904 - Miscellaneous 5 12,628 13,267	808 - Striping	5	3,587	3,769
<b>02000 - Concrete</b> 904 - Miscellaneous 5 12,628 13,267	9	Total 01000 - Paving	15 778	16 577
904 - Miscellaneous 5 12,628 13,267	02000 - Concrete	22000 . a.m.g.	13,770	10,577
	904 - Miscellaneous		12,628	13,267

Einal

	Life	Current	for the 2014/2015 Fiscal Yea <i>Forecast</i>
Reserve Component	Useful	Replacement Cost	Inflated Cost @ 2.50%
2015/16			
00010 - Community Center			
04000 - Structural Repairs			
356 - Garbage Enclosure Community Center Enclosure	5	1,537	1,615
914 - Doors 45 Community Center Interior Doors (11%)	2	3,075	3,231
2700	Total 04000 - Structural Repairs:	4,612	4,846
27000 - Appliances 200 - Refrigerator	7	512	538
Pool Maintenance Room	,		
	Total Community Center:	33,530	35,228
00030 - Cameron Park Lake			
01000 - Paving	E	727	764
108 - Asphalt: Sealing 5,911 Sq. Ft. Drives & Parking	5	727	764
208 - Asphalt: Ongoing Repairs 56,911 Sq. Ft. Drives & Parking (2%)	5	3,792	3,984
800 - Striping 98 Parking Stalls	5	1,507	1,583
	Total 01000 - Paving:	6,026	6,331
02000 - Concrete			
208 - Walkways 12,350 Sq. Ft. Walkways, Pads, & Slabs (2%)	5	4,051	4,256
03000 - Painting: Exterior			
408 - Railings 186 Lin. Ft. Concrete Footbridge Railings	4	1,525	1,602
18000 - Landscaping			
344 - Irrigation: Pumps 25 GPM Well	5	5,125	5,384
19000 - Fencing			
132 - Chain Link: 6' 6,877 Lin. Ft. Park Perimeter Fencing (20%)	6	16,917	17,774
20000 - Lighting	E	2 600	2 077
216 - Pole Lights 32 Park & Lagoon (9%)	5	3,690	3,877
	Total Cameron Park Lake:	37,334	39,224
00040 - Rasmussen Park			
01000 - Paving 112 - Asphalt: Sealing 27,200 Sq. Ft. Parking Lot	5	3,346	3,515
212 - Asphalt: Ongoing Repairs 27,200 Sq. Ft. Parking Lot (2%)	5	1,812	1,904
804 - Striping	5	1,537	1,615
Parking Lot	Total 01000 - Paving:	6,695	7,034
02000 - Concrete			
212 - Walkways 5,610 Sq. Ft. Park Walkways (2%)	5	1,840	1,933
18000 - Landscaping			
340 - Irrigation: Pumps Park- Irrigation Pump	5	1,230	1,292

Prepared for the 2014/2015 Fiscal Year

			Forecast
Reserve Component	Life Useful	Current Replacement Cost	Forecast Inflated Cost @ 2.50%
2015/16			
00040 - Rasmussen Park			
18000 - Landscaping			
474 - Pathways & Trails 15,570 Sq. Ft. Park- Walking Path (10%)	5	7,980	8,384
	Total 18000 - Landscaping:	9,210	9,676
	Total Rasmussen Park:	17,745	18,643
00050 - Christa McAuliffe Park			
02000 - Concrete	_	4 222	4.406
216 - Walkways 2,720 Sq. Ft. Park Walkways (3%)	5	1,338	1,406
	Total Christa McAuliffe Park:	1,338	1,406
00070 - Hacienda Park			
01000 - Paving	F	FF2	F02
120 - Asphalt: Sealing 4,500 Sq. Ft. Hacienda- Parking Lot	5	553	582
220 - Asphalt: Ongoing Repairs 4,500 Sq. Ft. Hacienda Parking Lot (3%)	5	450	472
	Total 01000 - Paving:	1,003	1,054
02000 - Concrete			
380 - Pad 462 Sq. Ft. [5] Concrete Slabs (10%)	10	947	995
18000 - Landscaping	F	E 12E	F 204
500 - Tree Maintenance Park- Scrub & Heritage Oaks	5	5,125	5,384
	Total Hacienda Park:	7,075	7,433
00188 - Station 88 02000 - Concrete			
200 - Sidewalks, Curbs & Gutters 2,400 Sq. Ft. Exterior Concrete (3%)	5	1,181	1,241
710 - Sealing 1,225 Sq. Ft. Vehicle Bays- Concrete Floors	5	2,700	2,836
	Total 02000 - Concrete:	3,881	4,077
03000 - Painting: Exterior			
100 - Surface Restoration 360 Sq. Ft. Patio Shed- Paint & Repair	5	1,107	1,163
310 - Trim 825 Sq. Ft. Station 88- Wood Trim	5	846	888
	Total 03000 - Painting: Exterior:	1,953	2,051
22000 - Office Equipment			
204 - Computers, Misc. Mulit-Quarters Laptop	6	1,537	1,615
208 - Computers, Misc. Mulit-Quarters PC Workstation	6	1,537	1,615
300 - Copier Lobby	6	1,537	1,615
	Total 22000 - Office Equipment:	4,611	4,845
24600 - Safety / Access			
340 - Defibrillators Lobby	5	2,562	2,692

	r	Ir	ıa	ı

Current Forecast Life Inflated Cost @ 2.50% Reserve Component Useful Replacement Cost

Reserve Component	Useful	Replacement Cost	Illiated Cost @ 2.50%
2015/16			
00188 - Station 88			
	Total Station 88:	13,007	13,665
00189 - Station 89 02000 - Concrete		-5,555	
204 - Sidewalks, Curbs & Gutters 8,840 Sq. Ft. Exterior Concrete (3%)	5	4,349	4,569
08000 - Rehab			
218 - Bathrooms 2 Upstairs Bathrooms	20	6,150	6,461
22000 - Office Equipment			
236 - Computers, Misc. Station Captain's Office- Printer	6	512	538
248 - Computers, Misc. Equipment Room- UPS 1500	6	1,537	1,615
252 - Computers, Misc. Equipment Room- Power Connect 2724	6	5,125	5,384
256 - Computers, Misc. Equipment Room- Surge Protector	6	1,025	1,077
260 - Computers, Misc. Equipment Room- Poweredge 2900	6	5,125	5,384
268 - Computers, Misc. Fire Prevention Office- Shredder	6	1,230	1,292
360 - Telephone Equipment Equipment Room- Phone System	6	4,612	4,846
364 - Telephone Equipment Equipment Room- Integration Hub	6	4,612	4,846
368 - Telephone Equipment Equipment Room- Phone System	6	4,612	4,846
,	Total 22000 - Office Equipment:	28,390	29,828
24000 - Furnishings		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	- /-
208 - Chairs 9 Station 89 Task Chairs	10	2,306	2,423
24500 - Audio / Visual			
200 - DVD Player Storage (Conference)- Sony DVD	6	512	538
204 - DVD Player Storage (Conference)- Toshiba DVD	6	512	538
316 - PA System Conference Room- Projector	6	3,587	3,769
	Total 24500 - Audio / Visual:	4,611	4,845
24600 - Safety / Access			
350 - Defibrillators Lobby	5	2,562	2,692
30000 - Miscellaneous			
882 - Vehicle E-289- Lic E1109085	15	490,842	515,691
894 - Vehicle U-289 Lic 041782	15	39,563	41,566
	Total 30000 - Miscellaneous:	530,405	557,257
	Total Station 89:	578,773	608,075

Cameron Park Community Services District Expenditures by Year- Next 3 Years

Fina

Prepared for the 2014/2015 Fiscal Year

Life Current Forecast
Useful Replacement Cost Inflated Cost @ 2.50%

Reserve Component

2015/16

Total 2015/16:

688,802

723,674

#### **Section X**



Cameron Park Community Services District

Notes to the Auditor

Final Prepared for the 2014/2015 Fiscal Year

This report is intended to assist the auditor while preparing the audit, review or compilation of Cameron Park Community Services District's (the "District") financial documents.

Browning Reserve Group ("BRG") prepared a reserve study for the District during the 2013/2014 fiscal year. This was done to help determine the District's reserve contribution for the next fiscal year (2014/2015) and future fiscal years. In addition, BRG prepared reserve fund disclosures for distribution to the District members.

This Reserve Study is a Full Study. A **Full Study** includes an on-site review upon where the following tasks are performed:

- development of a reserve component inventory;
- condition assessment based upon on-site visual observation;
- life and valuation estimates;
- fund status;
- and a funding plan. Please note, in order to complete these study tasks, one or more visits were conducted by BRG to Cameron Park Community Services District.

For BRG reserve studies, the year in which the study is being conducted, is the first year of the study. For example, this study is being prepared during 2013/2014 and is the District's first year in the study. This enables BRG to use a starting point which ties to the last audited financial statement, June 30, 2013. You will notice in <u>Section III</u>, <u>Reserve Fund Balance Forecast</u>, a Beginning Reserve Balance of \$3,154,345 is being used which ties to the last completed audit or review of the District's financial statements. BRG then re-builds the first year of the study, in this case 2013/2014, and estimates an ending reserve fund balance. Again, see <u>Section III</u> and the 2013/2014 ending reserve balance estimate of \$3,162,877.

"Re-building" the first year of the study as mentioned above simply means using the 2013/2014 adopted budget for the 2013/2014 reserve contribution. Finally, the 2013/2014 reserve expenses both actual and projected are estimated.


We find by using the above method a more accurate reserve study is possible because the beginning reserve fund balance ties directly to the District's audited financial statement or, in the absence of an audit or review, the year end balance sheet. There is no need to rely on others for determining mid year reserve balances or estimating current year ending reserve balances. This approach forces all involved, to look at the current year's reserve fund activities so a more accurate ending reserve fund balance can be estimated.

With respect to the reserve component Percent Funded values on the next page(s), here are the calculations:

FFB = Year Cost X Year Effective Age / Useful Life % Funded = Year Estimated Ending Reserve Balance / Year FFB

Please see <u>Section V - Reserve Fund Balance Forecast</u>.

Browning Reserve Group





## Schedule of Supplementary Information for Auditor Component Method

Final

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
00010 - Community Center						
01000 - Paving						
124 - Asphalt: Sealing 59,100 Sq. Ft. Parking Lot	7,269	5	2	4,362	5,961	1,174
224 - Asphalt: Ongoing Repairs 59,100 Sq. Ft. Parking Lot (3%)	4,922	5	2	2,953	4,036	795
424 - Asphalt: Major Repairs 59,100 Sq. Ft. Parking Lot	302,887	25	20	60,578	74,510	15,255
808 - Striping Parking Lot	3,587	5	2	2,153	2,942	579
02000 - Concrete						
904 - Miscellaneous 38,500 Sq. Ft. Community Center Concrete (2%)	12,628	5	2	7,577	10,355	2,039
03000 - Painting: Exterior			_			
108 - Surface Restoration 27,500 Sq. Ft. Community Center Buildings	28,187	10	5	14,094	17,335	2,451
400 - Wrought Iron 600 Lin. Ft. Pool Fence	5,535	4	4	1,107	1,418	939
500 - Light Poles 14 Common Area Light Poles	2,655	4	1	1,991	2,721	523
03500 - Painting: Interior						
100 - Building 46,447 Sq. Ft. Community Center Interiors	47,608	10	5	23,804	29,279	4,139
04000 - Structural Repairs						
356 - Garbage Enclosure Community Center Enclosure	1,538	5	2	923	1,261	248
540 - Bridge Maintenance Community Center Bridge	5,125	10	5	2,563	3,152	446
914 - Doors 45 Community Center Interior Doors (11%)	3,075	2	0	3,075	1,576	1,181
05000 - Roofing	01 225	20	25	15 204	10.701	4 222
330 - Low Slope: Vinyl 178 Squares- Community Center Buildings 688 - Pitched: Metal	91,225	30	25 25	15,204	18,701	4,332
95 Squares- Community Center Buildings 700 - Gutters / Downspouts	48,687	30 30	25	8,115 343	9,981 422	2,312 98
335 Lin. Ft. Community Center Buildings	2,060	30	25	343	422	96
100 - General	3,075	15	10	1,025	1,261	202
2 CO2 & Chlorine 104 - General	28,700	20	15	7,175	8,825	1,597
8 Offices						
108 - General 2 First Aid & Lifeguard	3,075	20	15	769	946	171
116 - General Stage Room	7,687	10	5	3,844	4,728	668
124 - General 2 Classroom & Preschool	5,125	10	5	2,563	3,152	446
222 - Bathrooms 2 Pool Area- Shower/Locker/Restrooms	10,250	20	15	2,563	3,152	570
238 - Restrooms 2 Community Center Restrooms	6,150	10	5	3,075	3,782	535
242 - Restrooms 2 Community Center Single Restrooms	3,075	10	5	1,538	1,891	267

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
00010 - Community Center						
08000 - Rehab 258 - Kitchen Pool Concession Room	3,075	20	15	769	946	171
266 - Kitchen Kitchen	10,250	20	15	2,563	3,152	570
380 - Tile 2 Outdoor Showers	1,025	10	5	513	630	89
590 - Operable Wall/Partition 720 Sq. Ft. Stage Room	36,900	20	15	9,225	11,347	2,053
12000 - Pool						
110 - Resurface 375 Lin. Ft. Pool	30,750	12	7	12,813	15,759	2,341
200 - Edge: Tile, Coping, Mastic 375 Lin. Ft. Pool	17,297	24	19	3,604	4,432	885
210 - Tile: Lanes 734 Lin. Ft. Pool	22,570	12	7	9,404	11,567	1,718
320 - Hand Rail / Ladder 6 Pool	7,380	24	19	1,538	1,891	378
400 - ADA Chair Lift Pool Equipment Room	4,510	10	5	2,255	2,774	392
700 - Equipment: Replacement Pool Eqpt Rm- Ultra Max	1,538	10	5	769	946	134
704 - Equipment: Replacement Pool Egpt Rm- Aquavac	1,025	10	5	513	630	89
708 - Equipment: Replacement 2 Pool Equipment Room- Filters	5,125	10	5	2,563	3,152	446
720 - Heater Pool Equipment Room	15,375	10	5	7,688	9,456	1,337
740 - Pumps Pool Equipment Room- Pool Pump	2,050	8	3	1,281	1,576	212
744 - Pumps Pool Equipment Room- Slide Pump	2,050	8	3	1,281	1,576	212
748 - Pumps Pool Equipment Room- Feature Pump	2,050	8	3	1,281	1,576	212
752 - Cover 7,425 Sq. Ft. Pool	7,611	5	1	6,089	7,801	1,199
780 - Water Feature Pool Area Slide Structure	30,750	15	10	10,250	12,608	2,016
800 - Solar System 30 Roof- Pool Solar System Panels	15,375	12	7	6,406	7,880	1,170
950 - Furniture: Lifeguard Chair 4 Pool Area	8,200	10	5	4,100	5,043	713
960 - Furniture: Misc Pool Furniture (Stored)	10,250	10	5	5,125	6,304	891
990 - Miscellaneous Floating Racing Lanes	2,562	10	5	1,281	1,576	223
17500 - Basketball / Sport Court 300 - Basketball Standard	12 027	15	10	4 612	5,673	907
6 Basketball Hoops 680 - Scoreboard	13,837 4,407	20	15	4,613		245
Gym 19000 - Fencing	4,407	20	13	1,102	1,355	243
230 - Wrought Iron: 6' 600 Lin. Ft. Pool Fence 20000 - Lighting	22,140	30	25	3,690	4,539	1,051
300 - Common Area 17 Common Area Light Standards	26,137	20	15	6,534	8,037	1,454
400 - Interior 24 Gym- Lighting	12,300	20	15	3,075	3,782	684
900 - Miscellaneous RF Access Rm- Lighting Controller	25,625	20	15	6,406	7,880	1,426

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
00010 - Community Center						
22000 - Office Equipment  100 - Computers, Misc. Offices- Main Room- PC	1,538	10	5	769	946	134
104 - Computers, Misc. Roof Access Room- PC	1,025	10	5	513	630	89
108 - Computers, Misc. Offices- Receptionist- PC	1,538	10	5	769	946	134
112 - Computers, Misc. Gym Building Electrical Room- Server	5,125	10	5	2,563	3,152	446
116 - Computers, Misc. Offices- Main Room- PC	1,538	10	5	769	946	134
120 - Computers, Misc. Offices- Receptionist- PC	1,538	10	5	769	946	134
124 - Computers, Misc. Gym Building Electrical Room- Server	5,125	10	5	2,563	3,152	446
128 - Computers, Misc. Gym Building Electrical Room- PC	1,538	10	5	769	946	134
132 - Computers, Misc. Offices- Mary- PC	1,538	10	5	769	946	134
136 - Computers, Misc.	769	10	5	384	473	67
Offices- Kitchen/Workroom- Printer 140 - Computers, Misc. Offices- Main Room- Shredder	1,538	10	5	769	946	134
144 - Computers, Misc. Offices- Mary- Printer	769	10	5	384	473	67
148 - Computers, Misc. Offices- Robert- PC	1,538	10	5	769	946	134
152 - Computers, Misc. Offices- Robert- Printer	769	10	5	384	473	67
156 - Computers, Misc. Offices- Office 1- PC	1,538	10	5	769	946	134
160 - Computers, Misc. Offices- Office 1- Printer	769	10	5	384	473	67
164 - Computers, Misc. Electrical Room- Server	30,750	10	5	15,375	18,911	2,673
308 - Copier Offices- Kitchen/Workroom- Copier	3,587	10	5	1,794	2,206	312
312 - Copier Offices- Main Room	3,587	10	5	1,794	2,206	312
23000 - Mechanical Equipment						
240 - HVAC Roof- Trane: AC 1	10,250	15	10	3,417	4,203	672
244 - HVAC Roof- Trane: AC 2, 3	20,500	15	10	6,833	8,405	1,344
248 - HVAC Roof- Trane: AC 4, 5	20,500	15	10	6,833	8,405	1,344
252 - HVAC Roof- Trane AC 6	10,250	15	10	3,417	4,203	672
256 - HVAC Roof- Trane AC 7	10,250	15	10	3,417	4,203	672
260 - HVAC Roof- Trane AC 8	10,250	15	10	3,417	4,203	672
264 - HVAC Roof- Trane: AC 9	10,250	15	10	3,417	4,203	672
268 - HVAC Roof- Trane: AC 10	10,250	15	10	3,417	4,203	672
272 - HVAC Roof- AC-11	30,750	15	10	10,250	12,608	2,016
276 - HVAC Roof- AC-12	30,750	15	10	10,250	12,608	2,016
280 - HVAC Roof- Reznor Preeva Air Handler	10,250	15	10	3,417	4,203	672

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
00010 - Community Center						
23000 - Mechanical Equipment 284 - HVAC	10,250	15	10	3,417	4,203	672
Roof- Reznor Preeva Air Handler		15	10	3,417	4,203	672
288 - HVAC Roof- Reznor Preeva Air Handler	10,250	15	10	3,417	4,203	672
292 - HVAC Roof Carrier: HP-1	7,687	15	10	2,563	3,152	504
296 - HVAC Roof Carrier: HP-2	7,687	15	10	2,563	3,152	504
300 - HVAC Roof- Fujitsu	5,125	15	10	1,708	2,101	336
612 - Water Heater Pool Storage/Water Heater Rm	5,637	12	7	2,349	2,889	429
616 - Water Heater Kitchen Storage- Rheem	5,637	12	7	2,349	2,889	429
620 - Water Heater Janitorial Room- Rheem	820	12	7	342	420	62
24000 - Furnishings						
104 - Miscellaneous Social Room Furnishings	5,125	10	5	2,563	3,152	446
192 - Chairs 93 Community Center Folding Chairs	4,766	15	10	1,589	1,954	313
196 - Chairs 270 Community Center Stackable Chairs	17,989	20	15	4,497	5,532	1,001
204 - Chairs 9 Office Task Chairs	4,612	10	5	2,306	2,837	401
334 - Tables 47 Community Center Folding Tables	9,635	20	15	2,409	2,963	536
644 - Modular Office Desk 8 Office Desks	19,680	20	15	4,920	6,052	1,095
24500 - Audio / Visual						
112 - Television, Large Screen Social Room	3,075	10	5	1,538	1,891	267
300 - PA System Roof Access Room- QSC Mixer	2,562	10	5	1,281	1,576	223
304 - PA System 3 Roof Access Room- Speakers & Stands	2,306	10	5	1,153	1,418	200
24600 - Safety / Access 900 - Miscellaneous	10,250	15	10	3,417	4,203	672
Stage Room- Handicap Lift	10,230	13	10	3,417	4,203	072
25000 - Flooring 200 - Carpeting	6,199	10	5	3,100	3,813	539
189 Sq. Yds. Community Center Offices						
400 - Tile 9,333 Sq. Ft. Restrooms, Concession, Kitchen	57,398	20	15	14,349	17,650	3,194
600 - Vinyl 1,106 Sq. Yds. Community Center Vinyl Tile	29,475	20	15	7,369	9,064	1,640
700 - Hardwood Floors 7,257 Sq. Ft. Yoga Room & Gym	44,631	15	10	14,877	18,299	2,927
920 - Coatings 1,063 Sq. Ft. Community Center Concrete Floors	6,537	12	7	2,724	3,350	498
25500 - Wallcoverings						
300 - FRP 1,951 Sq. Ft. Community Center	11,999	20	15	3,000	3,690	668
26000 - Outdoor Equipment 050 - Flag Pole	4,100	20	15	1 025	1,261	228
Community Center	,			1,025	,	
300 - Picnic Table: Wood 2 Pool Area	820	15	10	273	336	54
332 - Benches 2 Common Area	1,230	20	15	308	378	68
336 - Picnic Table: Metal	6,970	20	15	1,743	2,143	388

Section   Community Center   Section   Secti	Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
Brook Area   388	00010 - Community Center						
Sab - Carbage Receptacles   14 Common Area & Pool   14 Common Area & Pool   14 Common Area & Pool   10,762   20   15   2,691   3,309   599   1844 - Shade Structure   12 Portable Shade Structure   12 Portable Shade Structure   27000 - Appliances   27000 - 2700							
1930 Bleachers   10,762   20   15   2,691   3,309   599   184   3 Gym-Wood & Metal Bleachers   6,765   10   5   3,383   4,160   588   1844   5146	380 - Garbage Receptacles	2,870	20	15	718	883	160
1200	430 - Bleachers	10,762	20	15	2,691	3,309	599
200 - Refrigerator		6,765	10	5	3,383	4,160	588
Pool Maintenance Room   204 - Refrigerator   1,025   10   5   513   630   89							
204 - Refrigerator		513	7	2	366	450	59
Kitchen-Fridge   Care	204 - Refrigerator	1,025	10	5	513	630	89
Kitchen Fridge/Freezer Combo 707 - Stove / Oven: Commercial grade 6-burner Kitchen 727 - Stove / Oven: Commercial grade 6-burner Kitchen 728 - Oven: Wall Kitchen- Double Oven 83,587 20 15 897 1,103 200 828 - Microwave Oven Offices- Kitchen/Workroom Offices- Kitchen/Workroom Offices- Kitchen/Workroom Offices- Kitchen/Workroom Ritchen- Fanasonic 83 - 10 5 436 536 76 83 76 84 76 85 5tove: Exhaust Hood w/ Fan 85 5tove: Exhaust		4,100	20	15	1,025	1,261	228
Kitchen Double Oven (Kitchen Double Oven Kitchen- Double Oven (Kitchen- Double Oven (Kitchen- Double Oven (Kitchen- Double Oven (Kitchen- Morkroom)	Kitchen- Fridge/Freezer Combo	•	20		•	,	
Stricken		4,612	20	15	1,153	1,418	257
Section		3,587	20	15	897	1,103	200
Kitchen- Panasonic 298 - Stove: Exhaust Hood W/ Fan Kitchen- Greencheck Hood W Fan Kitchen- Hobart W Fan		410	10	4	246	294	35
Kitchen- Greencheck Hood 320 - Dishwasher, Commercial Kitchen- Hobart 940 - Drinking Fountain 2,562 20 15 641 788 143 Community Center Entry 950 - Point of Sale Computer Pool Maintenance Room 954 - Point of Sale Computer 2,050 6 1 1,708 2,101 269 Pool Concession Room 992 - Garbage Disposal 1,538 10 5 769 946 134 Kitchen- Savajor 30000 - Miscellaneous 806 - Maintenance Equipment 11,651 20 19 583 1,194 716 Riding Mower 810 - Maintenance Equipment 1,230 15 10 410 504 81 Kitchen- Changing Room - Grout Cleaner 818 - Maintenance Equipment 5,637 5 0 5,638 1,156 866 Roof Access Room - Floor Scrubber 822 - Maintenance Equipment 1,025 10 5 513 630 89 Pool Egit Rm- Pressure Washer 830 - Maintenance Equipment 1,538 5 0 1,538 315 236 Roof Access Room- Floor Buffer 5 50+0-tolal Community Center 1,595,388 5 0 1,538 315 236 Roof Access Room- Floor Buffer 5,911 Sq. Ft. Drives & Parking (2%) 808 - Asphalt: Sealing 727 5 2 436 596 117 S,911 Sq. Ft. Drives & Parking (2%) 809 - Striping 98 Parking (5%) 809 - Striping 98 Parking (5%) 809 - Striping 98 Parking (5%) 800 - Concrete		871	10	5	436	536	76
Kitchen- Hobart 940 - Drinking Fountain Community Center Entry 950 - Point of Sale Computer Pool Maintenance Room 954 - Point of Sale Computer Pool Maintenance Room 954 - Point of Sale Computer Pool Concession Room 992 - Garbage Disposal Kitchen Savajor  3000 - Miscellaneous 806 - Maintenance Equipment Riding Mower 810 - Maintenance Equipment Riding Mower 810 - Maintenance Equipment Riding Mower 811 - Maintenance Equipment Riding Mower 812 - Maintenance Equipment Riding Mower 813 - Maintenance Equipment Riding Mower 814 - Maintenance Equipment Riding Mower 815 - Maintenance Equipment Riding Mower 816 - Maintenance Equipment Riding Mower 817 - Maintenance Equipment Riding Mower 818 - Maintenance Equipment Riding Room - Grout Cleaner 819 - Maintenance Equipment Riding Mower 810 - Maintenance Equipment Riding Mower 811 - Maintenance Equipment Riding Room - Grout Cleaner 812 - Maintenance Equipment Riding Room - Grout Cleaner 813 - Maintenance Equipment Roof Access Room - Floor Scrubber 820 - Maintenance Equipment Roof Access Room - Floor Buffer Sub-total Community Center Roof Access Room - Floor Buffer Sub-total Community Center Roof Access Room - Floor Buffer Sub-total Community Center Roof Access Room - Floor Buffer Sub-total Community Center Roof Access Room - Floor Buffer Sub-total Community Center Roof Access Room - Floor Buffer Sub-total Community Center Roof Access Room - Floor Buffer Sub-total Community Center Roof Access Room - Floor Buffer Sub-total Community Center Roof Access Room - Floor Buffer Roof	•	3,075	20	15	769	946	171
Community Center Entry 950 - Point of Sale Computer Pool Maintenance Room 954 - Point of Sale Computer Pool Concession Room 992 - Garbage Disposal Kitchen- Savajor 30000 - Miscellaneous 806 - Maintenance Equipment Riding Mower 810 - Maintenance Equipment Riding Momer 811,651 20 19 583 1,194 716 Riding Momer 810 - Maintenance Equipment Richen Changing Room- Grout Cleaner 818 - Maintenance Equipment Roof Access Room- Floor Scrubber 822 - Maintenance Equipment Pool Egypt Rm- Pressure Washer 830 - Maintenance Equipment Roof Access Room- Floor Scrubber 830 - Maintenance Equipment Roof Access Room- Floor Scrubber 830 - Maintenance Equipment Roof Access Room- Floor Scrubber 830 - Maintenance Equipment Roof Access Room- Floor Scrubber 830 - Maintenance Equipment Roof Access Room- Floor Scrubber 830 - Maintenance Equipment Roof Access Room- Floor Scrubber 830 - Maintenance Equipment Roof Access Room- Floor Scrubber 830 - Maintenance Equipment Roof Access Room- Floor Buffer Sub-total Community Center 1,595,388 5 0 1,538 315 236 Roof Access Room- Floor Buffer Sub-total Community Center 1,595,388 5 0 1,538 315 236 Roof Access Room- Floor Buffer Sub-total Community Center 1,595,388 501,280 610,579 106,190  00030 - Cameron Park Lake 01000 - Paving 108 - Asphalt: Sealing 5,911 Sq. Ft. Drives & Parking 5,911 Sq. Ft. Drives & Parking 5,911 Sq. Ft. Drives & Parking (2%) 408 - Asphalt: Major Repairs 56,911 Sq. Ft. Drives & Parking (50%) 800 - Striping 98 Parking Stalls  02000 - Concrete 208 - Walkways 4,051 5 2 2,430 3,322 654		4,305	10	5	2,153	2,648	374
950 - Point of Sale Computer   2,050   6   1   1,708   2,101   269     954 - Point of Sale Computer   2,050   6   1   1,708   2,101   269     954 - Point of Sale Computer   2,050   6   1   1,708   2,101   269     992 - Garbage Disposal   1,538   10   5   769   946   134     Kitchen- Savajor   30000 - Miscellaneous		2,562	20	15	641	788	143
Pool Concession Room 992 - Garbage Disposal Kitchen - Savajor  30000 - Miscellaneous  806 - Maintenance Equipment Riding Mower 810 - Maintenance Equipment Riding Mower 810 - Maintenance Equipment Roof - Maintenance Equipment Roof Access Room- Floor Scrubber 818 - Maintenance Equipment Roof Access Room- Floor Scrubber 822 - Maintenance Equipment Pool Equipment Roof Access Room- Floor Scrubber 830 - Maintenance Equipment Roof Access Room- Floor Scrubber 830 - Maintenance Equipment Roof Access Room- Floor Buffer Sub-total Community Center 1,595,388  1,504  805  806  807  808  809  809  800000000000000000	950 - Point of Sale Computer	2,050	6	1	1,708	2,101	269
Ritchen   Savajor   Sava		2,050	6	1	1,708	2,101	269
11,651   20   19   583   1,194   716   Riding Mower   1,230   15   10   410   504   81   81   810 - Maintenance Equipment   1,230   15   10   410   504   81   81   81   81   81   81   81   8		1,538	10	5	769	946	134
Riding Mower  810 - Maintenance Equipment Kitchen Changing Room- Grout Cleaner  818 - Maintenance Equipment Roof Access Room- Floor Scrubber  822 - Maintenance Equipment Pool Eqpt Rm- Pressure Washer  830 - Maintenance Equipment Roof Access Room- Floor Scrubber  810 - Maintenance Equipment Pool Eqpt Rm- Pressure Washer  811 - Maintenance Equipment Roof Access Room- Floor Buffer Sub-total Community Center  812 - Maintenance Equipment Roof Access Room- Floor Buffer Sub-total Community Center  813 - Maintenance Equipment Roof Access Room- Floor Buffer Sub-total Community Center  814 - Maintenance Equipment Roof Access Room- Floor Buffer Sub-total Community Center  815 - Maintenance Equipment Roof Access Room- Floor Buffer Sub-total Community Center  816 - Maintenance Equipment Roof Access Room- Floor Buffer Sub-total Community Center  817 - Maintenance Equipment Roof Access Room- Floor Buffer Sub-total Community Center  817 - Maintenance Equipment Roof Access Room- Floor Buffer Sub-total Community Center  818 - Maintenance Equipment Roof Access Room- Floor Suffer Roof Access Room- Floor Suffer Roof Access Room- Floor Suffer Roof Access Room- Floor Buffer Sub-total Community Center Roof Access Room- Floor Buffer Sub-total Community Center Roof Access Room- Floor Buffer Roof Access Room	30000 - Miscellaneous						
Kitchen Changing Room- Grout Cleaner  818 - Maintenance Equipment 5,637 5 0 5,638 1,156 866 Roof Access Room- Floor Scrubber  822 - Maintenance Equipment 1,025 10 5 513 630 89 Pool Eqpt Rm- Pressure Washer  830 - Maintenance Equipment 1,538 5 0 1,538 315 236 Roof Access Room- Floor Buffer Sub-total Community Center 1,595,388 5 0 1,538 315 236  Room- Floor Buffer 500,0000 610,579 106,190  00030 - Cameron Park Lake  01000 - Paving  108 - Asphalt: Sealing 727 5 2 436 596 117 5,911 Sq. Ft. Drives & Parking 208 - Asphalt: Ongoing Repairs 3,792 5 2 2,275 3,109 612 56,911 Sq. Ft. Drives & Parking (2%)  408 - Asphalt: Major Repairs 145,834 20 9 80,209 89,688 6,997 56,911 Sq. Ft. Drives & Parking (50%)  800 - Striping 1,507 5 2 904 1,236 243 98 Parking Stalls  02000 - Concrete 208 - Walkways 4,051 5 2 2,430 3,322 654	Riding Mower	•				,	
Roof Access Room- Floor Scrubber 822 - Maintenance Equipment	Kitchen Changing Room- Grout Cleaner						
Pool Eqpt Rm- Pressure Washer  830 - Maintenance Equipment Roof Access Room- Floor Buffer  Sub-total Community Center 1,595,388 501,280 610,579 106,190  00030 - Cameron Park Lake  01000 - Paving  108 - Asphalt: Sealing 727 5 2 436 596 117 5,911 Sq. Ft. Drives & Parking  208 - Asphalt: Ongoing Repairs 3,792 5 2 2,275 3,109 612 56,911 Sq. Ft. Drives & Parking (2%)  408 - Asphalt: Major Repairs 145,834 20 9 80,209 89,688 6,997 56,911 Sq. Ft. Drives & Parking (50%)  800 - Striping 98 Parking Stalls  02000 - Concrete  208 - Walkways 4,051 5 2 2,430 3,322 654	Roof Access Room- Floor Scrubber	•			•		
Roof Access Room- Floor Buffer Sub-total Community Center 1,595,388 501,280 610,579 106,190  00030 - Cameron Park Lake  01000 - Paving  108 - Asphalt: Sealing 727 5 2 436 596 117 5,911 Sq. Ft. Drives & Parking 208 - Asphalt: Ongoing Repairs 56,911 Sq. Ft. Drives & Parking (2%)  408 - Asphalt: Major Repairs 145,834 20 9 80,209 89,688 6,997 56,911 Sq. Ft. Drives & Parking (50%)  800 - Striping 98 Parking Stalls  02000 - Concrete 208 - Walkways 4,051 5 2 2,430 3,322 654	Pool Eqpt Rm- Pressure Washer						
00030 - Cameron Park Lake         01000 - Paving         108 - Asphalt: Sealing 5,911 Sq. Ft. Drives & Parking       727 5 2 436 596 117         208 - Asphalt: Ongoing Repairs 56,911 Sq. Ft. Drives & Parking (2%)       3,792 5 2 2,275 3,109 612         408 - Asphalt: Major Repairs 56,911 Sq. Ft. Drives & Parking (50%)       145,834 20 9 80,209 89,688 6,997         800 - Striping 98 Parking Stalls       1,507 5 2 904 1,236 243         02000 - Concrete         208 - Walkways       4,051 5 2 2,430 3,322 654		1,538	5	0	1,538	315	236
01000 - Paving         108 - Asphalt: Sealing 5,911 Sq. Ft. Drives & Parking       727 5 2 436 596 117         208 - Asphalt: Ongoing Repairs 56,911 Sq. Ft. Drives & Parking (2%)       3,792 5 2 2,275 3,109 612         408 - Asphalt: Major Repairs 56,911 Sq. Ft. Drives & Parking (50%)       145,834 20 9 80,209 89,688 6,997         800 - Striping 98 Parking Stalls       1,507 5 2 904 1,236 243         02000 - Concrete         208 - Walkways       4,051 5 2 2,430 3,322 654	Sub-total Community Center	1,595,388			501,280	610,579	106,190
108 - Asphalt: Sealing       727       5       2       436       596       117         5,911 Sq. Ft. Drives & Parking       3,792       5       2       2,275       3,109       612         208 - Asphalt: Ongoing Repairs       3,792       5       2       2,275       3,109       612         56,911 Sq. Ft. Drives & Parking (2%)       145,834       20       9       80,209       89,688       6,997         800 - Striping       1,507       5       2       904       1,236       243         98 Parking Stalls         02000 - Concrete         208 - Walkways       4,051       5       2       2,430       3,322       654	00030 - Cameron Park Lake						
5,911 Sq. Ft. Drives & Parking  208 - Asphalt: Ongoing Repairs	_		_	2	43.6	F0.5	447
56,911 Sq. Ft. Drives & Parking (2%) 408 - Asphalt: Major Repairs 145,834 20 9 80,209 89,688 6,997 56,911 Sq. Ft. Drives & Parking (50%) 800 - Striping 1,507 5 2 904 1,236 243 98 Parking Stalls  02000 - Concrete 208 - Walkways 4,051 5 2 2,430 3,322 654	5,911 Sq. Ft. Drives & Parking						
56,911 Sq. Ft. Drives & Parking (50%)  800 - Striping	56,911 Sq. Ft. Drives & Parking (2%)						
98 Parking Stalls  02000 - Concrete  208 - Walkways	56,911 Sq. Ft. Drives & Parking (50%)	•			•		·
208 - Walkways 4,051 5 2 2,430 3,322 654	98 Parking Stalls	1,507	5	2	904	1,236	243
12,350 Sg. Ft. Walkways, Pads, & Slabs (2%)		4,051	5	2	2,430	3,322	654

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
00030 - Cameron Park Lake						
03000 - Painting: Exterior						
104 - Surface Restoration 1,140 Sq. Ft. Guard Shack & [3] Wood Sheds	1,169	5	1	935	1,198	184
112 - Surface Restoration 3,680 Sq. Ft. Corporate Yard House	3,772	5	0	3,772	773	580
116 - Surface Restoration 1,036 Sq. Ft. Concession Building	1,062	5	3	425	653	176
120 - Surface Restoration 1,950 Sq. Ft. Gazebo Painting	1,999	5	3	800	1,229	331
408 - Railings 186 Lin. Ft. Concrete Footbridge Railings	1,525	4	2	763	1,172	308
412 - Railings 80 Lin. Ft. Lake Observation Deck	656	4	0	656	168	126
420 - Wrought Iron Gates 2 Park Entrance Gates	1,025	4	0	1,025	263	197
504 - Light Poles 32 Park Light Poles	6,068	4	1	4,551	6,220	1,195
03500 - Painting: Interior						
400 - Restrooms 1,904 Sq. Ft. Concession Building	1,952	10	4	1,171	1,400	166
04000 - Structural Repairs 200 - Wood: Siding & Trim 3,680 Sq. Ft. Corporate Yard House (10%)	7,544	10	0	7,544	773	580
550 - Bridge Maintenance 1,313 Sq. Ft. [3] Pedestrian Bridges (10%)	6,729	5	3	2,692	4,138	1,114
658 - Decking 800 Sq. Ft. Lake Observation Deck	20,500	20	9	11,275	12,608	984
828 - Dock Floatation [2] Docks & [10] Barges  05000 - Roofing	5,125	10	4	3,075	3,677	435
448 - Pitched: Dimensional Composition 36 Squares- Corporate Yard House	14,760	25	9	9,446	10,288	567
452 - Pitched: Dimensional Composition 44 Squares- Concession, Gazebo, [3] Small Bldgs	18,040	25	11	10,102	11,095	728
704 - Gutters / Downspouts 184 Lin. Ft. Concession Building Gutters	1,132	25	11	634	696	46
708 - Gutters / Downspouts 400 Lin. Ft. Corporate Yard House	2,460	25	9	1,574	1,715	94
08000 - Rehab 234 - Restrooms	C 150	20	0	2 202	2 702	205
2 Concession Building 254 - Kitchen	6,150 3,075	20 20	9	3,383 1,691	3,782 1,891	295 148
Concession Building	3,073	20	9	1,091	1,091	140
11000 - Gate Equipment						
910 - Vehicle Gate Replacement 2 Park Entrance Gates	3,075	20	9	1,691	1,891	148
17000 - Tennis Court  100 - Reseal	14,657	7	3	8,376	10,731	1,733
28,600 Sq. Ft. [4] Tennis Courts 500 - Resurface 28,600 [4] Tennis Courts	43,972	21	16	10,470	12,878	2,389
18000 - Landscaping						
112 - Irrigation: Controllers Shed	1,025	10	4	615	735	87
344 - Irrigation: Pumps 25 GPM Well	5,125	5	2	3,075	4,203	827
478 - Pathways & Trails 59,910 Sq. Ft. Lake Perimeter- DG Path (10%)	30,704	10	4	18,422	22,030	2,604
18500 - Lakes / Ponds 300 - Pumps / Mechanical 10 GPM Well	10,250	10	4	6,150	7,354	869
320 - Filter	12,812	10	4	7,688	9,193	1,087

00030 - Cameron Park Lake         18500 - Lakes / Ponds         5 Filters- Lake & Lagoon         990 - Miscellaneous       7,687       5       3       3,075       4,728       1,272         300 Lin. Ft. Dam/Spillway (5%)       19000 - Fencing       104 - Chain Link: 4'       18,536       30       19       6,797       7,600       759         1,644 Lin. Ft. Lake Perimeter Fencing       258       30       19       95       106       11         128 - Chain Link: 6'       258       30       19       95       106       11         21 Lin. Ft. Boat Rental Shack       16,917       6       2       11,278       14,450       2,276         6,877 Lin. Ft. Park Perimeter Fencing (20%)       2,050       18       14       456       584       124         352 - Wood: 6'       2,050       18       14       456       584       124         356 - Wood: 6'       14,222       18       8       7,901       8,908       740         555 Lin. Ft. Corporate Yard Perimeter       18,491       25       14       8,136       9,098       803         902 Lin. Ft. Park Post & Chain Fencing       18,491       25       14       8,136       9,098	Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
5 Filters- Lake & Lagoon 990 - Miscellaneous 300 Lin. Ft. Dam/Spillway (5%)  19000 - Fencing 104 - Chain Link: 4' 18,536 30 19 6,797 7,600 759 1,644 Lin. Ft. Lake Perimeter Fencing 128 - Chain Link: 6' 258 30 19 95 106 11 21 Lin. Ft. Boat Rental Shack 132 - Chain Link: 6' 16,917 6 2 11,278 14,450 2,276 6,877 Lin. Ft. Park Perimeter Fencing (20%) 352 - Wood: 6' 2,050 18 14 456 584 124 80 Lin. Ft. Enclosure 356 - Wood: 6' 14,222 18 8 7,901 8,908 740 555 Lin. Ft. Corporate Yard Perimeter 522 - Post & Cable 18,491 25 14 8,136 9,098 803	00030 - Cameron Park Lake						
990 - Miscellaneous 300 Lin. Ft. Dam/Spillway (5%)  19000 - Fencing  104 - Chain Link: 4' 18,536 30 19 6,797 7,600 759 1,644 Lin. Ft. Lake Perimeter Fencing  128 - Chain Link: 6' 258 30 19 95 106 11 21 Lin. Ft. Boat Rental Shack  132 - Chain Link: 6' 16,917 6 2 11,278 14,450 2,276 6,877 Lin. Ft. Park Perimeter Fencing (20%)  352 - Wood: 6' 2,050 18 14 456 584 124 80 Lin. Ft. Enclosure  356 - Wood: 6' 14,222 18 8 7,901 8,908 740 555 Lin. Ft. Corporate Yard Perimeter  522 - Post & Cable 18,491 25 14 8,136 9,098 803							
300 Lin. Ft. Dam/Spillway (5%)  19000 - Fencing  104 - Chain Link: 4' 1,644 Lin. Ft. Lake Perimeter Fencing  128 - Chain Link: 6' 21 Lin. Ft. Boat Rental Shack  132 - Chain Link: 6' 6,877 Lin. Ft. Park Perimeter Fencing (20%)  352 - Wood: 6' 80 Lin. Ft. Enclosure  356 - Wood: 6' 555 Lin. Ft. Corporate Yard Perimeter  18,491 25 14 8,136 9,098 803	-	7 687	5	3	3 075	<i>1</i> 728	1 272
104 - Chain Link: 4' 1,644 Lin. Ft. Lake Perimeter Fencing  128 - Chain Link: 6' 21 Lin. Ft. Boat Rental Shack  132 - Chain Link: 6' 6,877 Lin. Ft. Park Perimeter Fencing (20%)  352 - Wood: 6' 80 Lin. Ft. Enclosure  356 - Wood: 6' 555 Lin. Ft. Corporate Yard Perimeter  18,536 30 19 6,797 7,600 759 106 11 21 Lin. Ft. Boat Rental Shack  16,917 6 2 11,278 14,450 2,276 2,276 6,877 Lin. Ft. Park Perimeter Fencing (20%)  352 - Wood: 6' 555 Lin. Ft. Corporate Yard Perimeter  14,222 18 8 7,901 8,908 740 555 Lin. Ft. Corporate Yard Perimeter  522 - Post & Cable 18,491 25 14 8,136 9,098 803	300 Lin. Ft. Dam/Spillway (5%)	7,007	3	3	3,073	7,720	1,2,2
1,644 Lin. Ft. Lake Perimeter Fencing  128 - Chain Link: 6'	_	18 536	30	19	6 797	7 600	759
21 Lin. Ft. Boat Rental Shack  132 - Chain Link: 6' 16,917 6 2 11,278 14,450 2,276 6,877 Lin. Ft. Park Perimeter Fencing (20%)  352 - Wood: 6' 2,050 18 14 456 584 124 80 Lin. Ft. Enclosure  356 - Wood: 6' 14,222 18 8 7,901 8,908 740 555 Lin. Ft. Corporate Yard Perimeter  522 - Post & Cable 18,491 25 14 8,136 9,098 803	1,644 Lin. Ft. Lake Perimeter Fencing	•			•	•	
6,877 Lin. Ft. Park Perimeter Fencing (20%)  352 - Wood: 6' 2,050 18 14 456 584 124 80 Lin. Ft. Enclosure  356 - Wood: 6' 14,222 18 8 7,901 8,908 740 555 Lin. Ft. Corporate Yard Perimeter  522 - Post & Cable 18,491 25 14 8,136 9,098 803		258	30	19	95	106	11
80 Lin. Ft. Enclosure  356 - Wood: 6' 14,222 18 8 7,901 8,908 740 555 Lin. Ft. Corporate Yard Perimeter  522 - Post & Cable 18,491 25 14 8,136 9,098 803		16,917	6	2	11,278	14,450	2,276
356 - Wood: 6' 14,222 18 8 7,901 8,908 740 555 Lin. Ft. Corporate Yard Perimeter 18,491 25 14 8,136 9,098 803		2,050	18	14	456	584	124
522 - Post & Cable 18,491 25 14 8,136 9,098 803	356 - Wood: 6'	14,222	18	8	7,901	8,908	740
	·	18,491	25	14	8,136	9,098	803
19500 - Retaining Wall							
120 - Wood: 1' 4,484 20 9 2,466 2,758 215 125 Lin. Ft. Park Entrance		4,484	20	9	2,466	2,758	215
124 - Wood: 2' 4,920 18 14 1,093 1,401 297 80 Lin. Ft. Enclosure		4,920	18	14	1,093	1,401	297
20000 - Lighting		2.600	_	2	2 214	2.026	F0.6
216 - Pole Lights 3,690 5 2 2,214 3,026 596 32 Park & Lagoon (9%)		3,690	Э	2	2,214	3,026	390
<b>21000 - Signage</b> 778 - Wood Monument  1.538 5 3 615 946 254		1 520	_	2	C1F	0.46	254
778 - Wood Monument 1,538 5 3 615 946 254 Park Entrance		1,538	Э	3	012	946	254
<b>23000 - Mechanical Equipment</b> 232 - HVAC 5,125 15 7 2,733 3,152 312		E 12E	1 E	7	2 722	2 152	212
Concession Roof	Concession Roof	5,125	15	/	2,/33	3,132	312
<b>26000 - Outdoor Equipment</b> 104 - Tot Lot: Play Equipment 7,687 20 9 4,228 4,728 369		7 607	20	0	A 220	4 720	260
Play Area- 4-Swing Set	Play Area- 4-Swing Set	7,007	20	9	•	4,720	309
108 - Tot Lot: Play Equipment 35,875 20 9 19,731 22,063 1,721 Play Area- Large Structure		•	20	9		22,063	1,721
124 - Tot Lot: Play Equipment 5,125 20 9 2,819 3,152 246 Play Area- 2-Swing Set		5,125	20	9	2,819	3,152	246
144 - Tot Lot: Safety Surface 2,562 3 1 1,708 2,627 673 10,000 Sq. Ft. Play Area	•	2,562	3	1	1,708	2,627	673
200 - Pedestal Grill BBQ 3,382 20 9 1,860 2,080 162 11 Park Barbecues		3,382	20	9	1,860	2,080	162
280 - Picnic Tables 30,750 20 9 16,913 18,911 1,475 50 Park Picnic Tables		30,750	20	9	16,913	18,911	1,475
328 - Benches 15,375 20 9 8,456 9,456 738 25 Park Benches	328 - Benches	15,375	20	9	8,456	9,456	738
392 - Garbage Receptacles 8,200 20 9 4,510 5,043 393 40 Park Trash Cans	392 - Garbage Receptacles	8,200	20	9	4,510	5,043	393
492 - Drinking Fountain 2,460 20 9 1,353 1,513 118 Park Tennis Courts		2,460	20	9	1,353	1,513	118
30000 - Miscellaneous							
700 - Tools 2,562 10 6 1,025 1,313 228 Compressor		2,562	10	6	1,025	1,313	228
704 - Tools 1,538 10 4 923 1,103 130 Grinder/Sander		1,538	10	4	923	1,103	130
708 - Tools 1,025 10 4 615 735 87 Bench Grinder		1,025	10	4	615	735	87
712 - Tools 1,025 10 4 615 735 87 Bench Grinder		1,025	10	4	615	735	87
716 - Tools 1,538 10 4 923 1,103 130 Drill Press		1,538	10	4	923	1,103	130
814 - Maintenance Equipment 3,587 20 4 2,870 3,126 152		3,587	20	4	2,870	3,126	152

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
00030 - Cameron Park Lake						
30000 - Miscellaneous						
Woods RM500 826 - Maintenance Equipment	51,250	20	14	15,375	18,386	2,782
Vermeer 1230 Chipper	·				•	•
834 - Tractor Massey Ferguson 1525	20,500	20	14	6,150	7,354	1,113
838 - Vehicle Dodge 2500 V8- Lic 1101411	21,525	10	0	21,525	2,206	1,654
846 - Vehicle Ford Expedition- Lic 1011647	51,250	10	4	30,750	36,772	4,347
850 - Vehicle 2008 Ford F150 XL- Lic 1273235	25,625	10	5	12,813	15,759	2,228
854 - Vehicle	15,375	10	4	9,225	11,032	1,304
Dodge Pick Up P-01- Lic 1088018 866 - Vehicle	21,525	10	1	19,373	22,063	1,695
Ford Bronco- Lic E041782	F 12F	1 -	0		2.451	220
894 - Trailer PacWest 20'- Lic. E946571	5,125	15	9	2,050	2,451	328
898 - Trailer Carson 20'- Lic. 1108445	4,100	15	8	1,913	2,241	256
902 - Trailer 11' Trailer- Lic. E323108	2,562	15	7	1,367	1,576	156
906 - Trailer 15' Trailer	3,075	15	6	1,845	2,101	183
910 - Trailer 12' Trailer 12' Trailer- Lic. 4LF5474	7,175	15	9	2,870	3,432	459
914 - Trailer 2003 Vintage Trailer- Lic 1152569	7,687	15	5	5,125	5,778	446
918 - Trailer BBQ Trailer	4,100	15	7	2,187	2,522	250
Sub-total Cameron Park Lake	843,760			456,229	498,824	58,186
00040 - Rasmussen Park						
01000 - Paving	2 246	_	2	2.007	2 742	F40
112 - Asphalt: Sealing 27,200 Sq. Ft. Parking Lot	3,346	5	2	2,007	2,743	540
212 - Asphalt: Ongoing Repairs 27,200 Sq. Ft. Parking Lot (2%)	1,812	5	2	1,087	1,486	293
412 - Asphalt: Major Repairs 27,200 Sq. Ft. Parking Lot	139,400	25	14	61,336	68,585	6,054
804 - Striping Parking Lot	1,538	5	2	923	1,261	248
02000 - Concrete						
212 - Walkways 5,610 Sq. Ft. Park Walkways (2%)	1,840	5	2	1,104	1,509	297
03000 - Painting: Exterior						
350 - Touch-Up 3 Park Buildings	1,538	5	1	1,230	1,576	242
03500 - Painting: Interior						
408 - Restrooms 1,104 Sq. Ft. Concession Building Restrooms	1,132	10	4	679	812	96
04000 - Structural Repairs						
554 - Bridge Maintenance Park Pedestrian Bridge	2,562	20	9	1,409	1,576	123
<b>05000 - Roofing</b> 460 - Pitched: Dimensional Composition	1,230	25	14	541	605	53
3 Squares- Maint. Bldg & Wood Shed 684 - Pitched: Metal	3,075	30	19	1,128	1,261	126
6 Squares- Concession Building	•					
864 - Skylights 2 Concession Building Restrooms	820	20	9	451	504	39

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
00040 - Rasmussen Park						
08000 - Rehab 246 - Restrooms 2 Concession Stand Restrooms	3,075	20	9	1,691	1,891	148
250 - Kitchen Concession Stand Interior	3,075	20	9	1,691	1,891	148
18000 - Landscaping						
104 - Irrigation: Misc. Park Irrigation	1,025	3	1	683	1,051	269
340 - Irrigation: Pumps Park- Irrigation Pump	1,230	5	2	738	1,009	199
420 - General Repairs/Upgrades Park	1,025	3	1	683	1,051	269
474 - Pathways & Trails 15,570 Sq. Ft. Park- Walking Path (10%)	7,980	5	2	4,788	6,543	1,288
498 - Bedding Header 252 Lin. Ft. South Play Area	775	20	9	426	477	37
19000 - Fencing 100 - Chain Link	406	20	20	27	42	21
36 Lin. Ft. Tee Ball Field 5' Chain Link	406	30	28	27	42	21
116 - Chain Link 1,850 Lin. Ft. Ball Fields- 5' Chain Link	20,859	30	14	11,125	12,115	755
124 - Chain Link: 6' 170 Lin. Ft. Tee Ball Field	2,091	30	28	139	214	107
140 - Chain Link: 6' 332 Lin. Ft. North Play Area Perimeter	4,084	30	14	2,178	2,372	148
144 - Chain Link: 8' 65 Lin. Ft. Tee Ball Field	933	30	28	62	96	48
148 - Chain Link: 8' 400 Lin. Ft. Ball Fields	5,740	30	14	3,061	3,334	208
152 - Chain Link 150 Lin. Ft. Ball Field Back Stops	3,844	30	14	2,050	2,233	139
344 - Wood: 6' 885 Lin. Ft. East & West Perimeter	22,678	18	8	12,599	14,205	1,180
514 - Post & Cable 730 Lin. Ft. Parking Perimeter	14,965	25	14	6,585	7,363	650
540 - Metal 980 Lin. Ft. South Perimeter- Post & Wire	10,045	25	14	4,420	4,942	436
19500 - Retaining Wall						
364 - Masonry Wall 332 Lin. Ft. North Play Area	13,612	30	19	4,991	5,581	557
21000 - Signage						
794 - Wood Monument Park Sign	2,562	10	4	1,538	1,839	217
25000 - Flooring	4 070	2.0		750	0.47	
404 - Tile 224 Sq. Ft. Concession Building Restrooms	1,378	20	9	758	847	66
26000 - Outdoor Equipment	25.625	20		7.600	0.103	1 201
100 - Tot Lot: Play Equipment North Play Area	25,625	20	14	7,688	9,193	1,391
120 - Tot Lot: Play Equipment South Play Area	10,250	20	14	3,075	3,677	556
140 - Tot Lot: Safety Surface 10,410 Sq. Ft. North & South Play Areas	2,668	3	1	1,778	2,734	700
294 - Picnic Table: Cement 2 Park Picnic Tables	1,025	20	9	564	630	49
304 - Picnic Table: Wood 2 Park Picnic Tables	820	15	7	437	504	50
312 - Benches 6 Park- Metal Benches	3,690	20	9	2,030	2,269	177
320 - Benches 6 Park- Wood Benches	3,690	12	5	2,153	2,522	267
380 - Pet Stations	1,066	15	7	569	656	65

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
00040 - Rasmussen Park						
26000 - Outdoor Equipment						
4 Park 384 - Garbage Receptacles	1,230	20	9	677	756	59
6 Park- Trash Cans	1,230	20	9	077	730	39
440 - Bleachers: Aluminum 4 Ball Field Bleachers	12,300	20	9	6,765	7,565	590
484 - Drinking Fountain Park- Drinking Fountain	2,460	20	9	1,353	1,513	118
840 - Shade Structure 1,240 Sq. Ft. North Play Area	6,355	20	11	2,860	3,257	320
Sub-total Rasmussen Park	350,851			162,075	186,289	19,345
00050 - Christa McAuliffe Park						
01000 - Paving		_				
116 - Asphalt: Sealing 18,563 Sq. Ft. Parking Lot	2,283	5	1	1,827	2,340	360
216 - Asphalt: Ongoing Repairs 18,563 Sq. Ft. Parking Lot (2%)	1,237	5	1	989	1,268	195
416 - Asphalt: Major Repairs 18,563 Sq. Ft. Parking Lot	95,135	25	14	41,860	46,807	4,132
02000 - Concrete 216 - Walkways 2,720 Sq. Ft. Park Walkways (3%)	1,338	5	2	803	1,097	216
900 - Miscellaneous 16,000 Sq. Ft. Skate Park Concrete (10%)	32,800	10	4	19,680	23,534	2,782
03000 - Painting: Exterior						
404 - Wrought Iron 490 Lin. Ft. Play Area Perimeter	4,520	4	1	3,390	4,633	890
03500 - Painting: Interior						
404 - Restrooms 1,216 Sq. Ft. Restroom Building	1,246	10	4	748	894	106
04000 - Structural Repairs 994 - Miscellaneous	6 150	20	14	1,845	2,206	334
300 Sq. Ft. Decorative Wall Resurfacing	6,150	20	14	1,043	2,200	334
<b>05000 - Roofing</b> 440 - Pitched: Dimensional Composition	2,050	25	14	902	1,009	89
5 Squares- Restroom Building	2,030		14	902	1,009	09
456 - Pitched: Dimensional Composition Skate Park Building	410	25	4	344	370	14
<b>08000 - Rehab</b> 112 - General	1,538	10	1	1,384	1,576	121
Skate Park Building 230 - Restrooms	2,050	10	1	1,845	2,101	161
Restroom Building	2,030	10	-	1,043	2,101	101
19000 - Fencing						
108 - Chain Link: 4' 855 Lin. Ft. North Perimeter	9,640	30	19	3,535	3,952	395
120 - Chain Link: 6' 1,190 Lin. Ft. South & East Perimeter	14,637	30	19	5,367	6,001	599
136 - Chain Link: 6' 260 Lin. Ft. Skate Park Perimeter	3,198	30	19	1,173	1,311	131
220 - Wrought Iron: 4' 490 Lin. Ft. Play Area Perimeter	15,067	30	19	5,525	6,178	617
360 - Wood: 6' 395 Lin. Ft. West Perimeter Fence	10,122	18	8	5,623	6,340	526
518 - Post & Cable 525 Lin. Ft. Parking Lot Perimeter (No Cable) 19500 - Retaining Wall	10,762	25	9	6,888	7,501	413
360 - Masonry Wall 490 Lin. Ft. Play Area Perimeter	20,090	30	19	7,366	8,237	823

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
00050 - Christa McAuliffe Park						
21000 - Signage 790 - Wood Monument Park Monument Sign	2,562	10	4	1,538	1,839	217
26000 - Outdoor Equipment  112 - Tot Lot: Play Equipment Park Large Play Structure	30,750	20	13	10,763	12,608	1,629
116 - Tot Lot: Play Equipment 2 Park- Smaller Structures	15,375	20	13	5,381	6,304	814
284 - Picnic Tables 5 Park Picnic Tables	3,075	20	9	1,691	1,891	148
324 - Benches 10 Park Metal Benches	7,175	20	14	2,153	2,574	390
396 - Garbage Receptacles	2,050	20	9	1,128	1,261	98
10 Park Trash Cans 488 - Drinking Fountain 3 Park Drinking Fountains	7,380	20	9	4,059	4,539	354
Sub-total Christa McAuliffe Park	302,642			137,805	158,371	16,553
00060 - Chardi Corner						
18000 - Landscaping 116 - Irrigation: Controllers Chardi Corner- Irrigation Controller	1,025	10	4	615	735	87
300 - Irrigation: Backflow Preventors Chardi Corner- Backflow Prevention Device	615	20	9	338	378	30
424 - General Repairs/Upgrades Chardi Corner	1,025	3	1	683	1,051	269
19000 - Fencing						
348 - Wood: 6' 300 Lin. Ft. Chardi Corner- Perimeter Fencing	7,687	18	8	4,271	4,815	400
19500 - Retaining Wall 368 - Masonry Wall 380 Lin. Ft. Chardi Corner- Perimeter Wall	15,580	30	19	5,713	6,388	638
20000 - Lighting 220 - Landscape 3 Chardi Corner- Sign Lights	1,230	12	5	718	841	89
21000 - Signage 782 - Monument 35 Lin. Ft. Chardi Corner- Monument Sign (25%)	2,242	5	3	897	1,379	371
26000 - Outdoor Equipment  064 - Flag Pole  Chardi Corner- Flag Pole	4,100	20	9	2,255	2,522	197
Sub-total Chardi Corner	33,505			15,489	18,108	2,080
00070 - Hacienda Park 01000 - Paving						
120 - Asphalt: Sealing 4,500 Sg. Ft. Hacienda- Parking Lot	554	5	2	332	454	89
220 - Asphalt: Ongoing Repairs 4,500 Sq. Ft. Hacienda Parking Lot (3%)	450	5	2	270	369	73
420 - Asphalt: Major Repairs 4,500 Sq. Ft. Hacienda- Parking Lot	23,062	25	14	10,148	11,347	1,002
02000 - Concrete 380 - Pad 462 Sq. Ft. [5] Concrete Slabs (10%) 04000 - Structural Repairs	947	10	2	758	874	76
998 - Miscellaneous Park- Shed- Upkeep	513	5	3	205	315	85
18000 - Landscaping 100 - Irrigation: Misc.	1,025	3	0	1,025	350	263
Park 450 - Drainage System Maint. Deer Creek Tributary	2,050	3	1	1,367	2,101	538

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
00070 - Hacienda Park						
18000 - Landscaping						
470 - Pathways & Trails 29,465 Sq. Ft. Park- DG Paths (20%)	30,202	10	4	18,121	21,670	2,562
494 - Bedding Header 420 Lin. Ft. Turf Perimeter	1,292	20	14	387	463	70
500 - Tree Maintenance Park- Scrub & Heritage Oaks	5,125	5	2	3,075	4,203	827
19000 - Fencing						
112 - Chain Link: 4' 100 Lin. Ft. Creek Perimeter	1,128	20	9	620	693	54
364 - Wood: Split Rail 765 Lin. Ft. Park Perimeter	11,762	20	14	3,529	4,220	639
510 - Post & Cable 26 Parking Lot Posts (50%)	1,333	10	4	800	956	113
21000 - Signage	1 025	10	C	410	F2F	0.1
798 - Wood Monument Park Sign	1,025	10	6	410	525	91
26000 - Outdoor Equipment						
290 - Picnic Table: Cement 3 Park- Picnic Tables	2,306	20	14	692	827	125
316 - Benches Park Bench	615	20	14	185	221	33
376 - Pet Stations Park- Pet Station	267	15	9	107	127	17
388 - Garbage Receptacles 2 Park- Trash Cans	410	20	14	123	147	22
480 - Drinking Fountain Park- Drinking Fountain	2,460	20	14	738	883	134
Sub-total Hacienda Park	86,523			42,889	50,745	6,813
00188 - Station 88						
01000 - Paving						
100 - Asphalt: Sealing 3,950 Sq. Ft. Parking Lot- Seal & Stripe	972	5	4	194	398	165
200 - Asphalt: Ongoing Repairs 3,950 Sq. Ft. Parking Lot (5%)	658	10	4	395	472	56
400 - Asphalt: Major Repairs 3,950 Sq. Ft. Parking Lot (50%) <b>02000 - Concrete</b>	8,097	25	17	2,591	2,988	379
200 - Sidewalks, Curbs & Gutters 2,400 Sq. Ft. Exterior Concrete (3%)	1,181	5	2	708	968	191
710 - Sealing 1,225 Sq. Ft. Vehicle Bays- Concrete Floors	2,700	5	2	1,620	2,214	436
03000 - Painting: Exterior						
100 - Surface Restoration 360 Sq. Ft. Patio Shed- Paint & Repair	1,107	5	2	664	908	179
310 - Trim 825 Sq. Ft. Station 88- Wood Trim	846	5	2	507	693	137
03500 - Painting: Interior						
110 - Building 7,122 Sq. Ft. Station 88- Interior Spaces	7,300	10	4	4,380	5,238	619
04000 - Structural Repairs						
364 - Garbage Enclosure Parking Area	1,538	10	4	923	1,103	130
910 - Doors 11 Station 88- Interior & Exterior Doors	6,765	20	9	3,721	4,160	325
05000 - Roofing						
444 - Pitched: Dimensional Composition 36 Squares- Station 88	14,760	25	15	5,904	6,657	657
712 - Gutters / Downspouts 110 Lin. Ft. Station 88	677	25	15	271	305	30
860 - Skylights	820	25	15	328	370	37

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
00188 - Station 88						
05000 - Roofing						
2 Lobby & Lounge 08000 - Rehab						
120 - General	2,050	10	4	1,230	1,471	174
2 Quarters		10	•	1,230	1,1,1	
210 - Bathrooms 2 Bathroom & Restroom	3,075	10	1	2,768	3,152	242
214 - Kitchen Kitchen	2,050	20	1	1,948	2,101	81
14000 - Recreation						
200 - Exercise: Treadmill Vehicle Bays	2,050	10	4	1,230	1,471	174
204 - Exercise: Miscellaneous Equip. Vehicle Bays: Weights & Rack	3,075	15	7	1,640	1,891	187
20000 - Lighting						
104 - Exterior: Misc. Fixtures 8 Building & Landscape Lights	2,050	15	9	820	981	131
540 - Parking Lot Parking Lot Light	2,255	25	14	992	1,109	98
21000 - Signage 786 - Wood Monument	1,025	10	0	1,025	105	79
Station 88 Entrance	1,023	10	O	1,023	105	, ,
22000 - Office Equipment 200 - Computers, Misc. Lobby	2,050	6	3	1,025	1,401	283
204 - Computers, Misc. Mulit-Quarters Laptop	1,538	6	2	1,025	1,313	207
208 - Computers, Misc. Mulit-Quarters PC Workstation	1,538	6	2	1,025	1,313	207
300 - Copier Lobby	1,538	6	2	1,025	1,313	207
23000 - Mechanical Equipment						
200 - HVAC	5,125	15	4	3,758	4,203	290
Patio Area HVAC 600 - Water Heater	820	12	5	478	560	59
Water Heater Closet						
24000 - Furnishings 100 - Miscellaneous	5,125	20	9	2,819	3,152	246
Lobby Additional Furnishings	•			,		
200 - Bar Stools 2 Lounge Barstools	513	15	9	205	245	33
212 - Chairs 4 Station 88 Task Chairs	1,025	10	5	513	630	89
228 - Chairs 3 Lounge Recliners	1,538	20	6	1,076	1,182	69
640 - Modular Office Desk 3 Station 88 Office Desks	3,075	20	9	1,691	1,891	148
910 - Window Coverings 8 Station 88- Window Blinds	4,100	15	9	1,640	1,961	262
24600 - Safety / Access 340 - Defibrillators Lobby	2,562	5	2	1,538	2,101	414
25000 - Flooring						
210 - Carpeting 87 Sq. Yds. Station 88- Carpeting	2,854	10	3	1,998	2,340	236
410 - Tile 362 Sq. Ft. Bathroom, Restroom, & Lobby	2,226	20	1	2,115	2,282	88
610 - Vinyl 15 Sq. Yds. Kitchen- Linoleum	400	20	1	380	410	16
26000 - Outdoor Equipment 060 - Flag Pole Station 88 Entrance	4,100	20	14	1,230	1,471	223
Station 88 Entrance						

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
00188 - Station 88						
26000 - Outdoor Equipment	64.5	•		200	204	65
210 - Barbecue Patio Barbecue	615	8	4	308	394	65
350 - Furniture 8 Patio Furniture Items	2,050	10	4	1,230	1,471	174
27000 - Appliances						
208 - Refrigerator Kitchen	1,025	7	3	586	750	121
248 - Ice Machine	2,050	10	5	1,025	1,261	178
Vehicle Bays- Hoshizaki 266 - 4-Burner Stove & Oven	1,845	7	1	1,581	1,891	208
Kitchen					,	
302 - Stove: Exhaust Hood w/ Fan Kitchen	2,665	20	9	1,466	1,639	128
306 - Dishwasher Kitchen	1,025	10	4	615	735	87
410 - Washer Vehicle Bay	1,538	10	5	769	946	134
414 - Dryer Vehicle Bay	1,845	10	5	923	1,135	160
30000 - Miscellaneous						
270 - Garage Door: Metal 2 Vehicle Bay Doors	10,250	20	9	5,638	6,304	492
842 - Vehicle E 88 Lic 1206288	597,017	15	5	398,012	448,758	34,602
858 - Vehicle E 288 Lic 1375275	479,216	15	12	95,843	130,986	33,015
898 - Vehicle U 88 Lic 127543	35,321	15	11	9,419	12,068	2,374
Sub-total Station 88	1,241,636			574,811	674,862	79,317
00189 - Station 89						
01000 - Paving 104 - Asphalt: Sealing	3,280	5	4	656	1,345	556
20,899 Sq. Ft. Parking Lot- Seal & Stripe					,	
204 - Asphalt: Ongoing Repairs 20,899 Sq. Ft. Parking Lot (10%)	6,962	10	4	4,177	4,995	590
404 - Asphalt: Major Repairs 20,899 Sq. Ft. Parking Lot (50%)	53,554	25	15	21,421	24,153	2,384
02000 - Concrete	4 340	F	2	2.610	2.566	702
204 - Sidewalks, Curbs & Gutters 8,840 Sq. Ft. Exterior Concrete (3%)	4,349	5	2	2,610	3,566	702
714 - Sealing 5,016 Sq. Ft. Vehicle Bays- Concrete Floors	11,054	5	0	11,054	2,266	1,699
03000 - Painting: Exterior 124 - Surface Restoration	8,712	10	4	5,228	6,251	739
8,500 Lin. Ft. Station 89		10	4			
416 - Railings 90 Lin. Ft. Balcony & Stairs	738	4	1	554	756	145
920 - Miscellaneous Sheds, Wrought Iron, & Touch-Up	3,587	5	0	3,588	735	551
03500 - Painting: Interior	25 506	10	4	15.252	10.250	2.170
120 - Building 24,962 Sq. Ft. Station 89 Interior Painting	25,586	10	4	15,352	18,358	2,170
<b>04000 - Structural Repairs</b> 360 - Garbage Enclosure	2 562	10	4	1 520	1 020	217
Station 89- Enclosure	2,562	10	4	1,538	1,839	217
920 - Doors 31 Station 89 Interior & Exterior Doors	19,065	15	5	12,710	14,331	1,105
990 - Miscellaneous 4 Wood Sheds	2,050	10	5	1,025	1,261	178

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
00189 - Station 89						
04500 - Decking/Balconies		4.0		0.55	4 004	400
110 - Concrete 375 Sq. Ft. South Side Building (25%)	1,441	10	4	865	1,034	122
500 - Railing: Wrought Iron 90 Lin. Ft. Balcony & Stair Railings	3,136	20	10	1,568	1,768	154
05000 - Roofing						
334 - Low Slope: Vinyl 48 Squares- Station 89 Flat Roofing	24,600	20	10	12,300	13,868	1,210
680 - Pitched: Metal 31 Squares- Station 89 Metal Roof	15,887	30	20	5,296	5,971	667
720 - Gutters / Downspouts 210 Lin. Ft. Station 89	1,292	30	20	431	485	54
08000 - Rehab						
128 - General 4 Dormitory Rooms	8,200	20	10	4,100	4,623	403
132 - General	2,562	20	10	1,281	1,445	126
Work Room 136 - General	6,150	20	10	3,075	3,467	302
3 Offices 140 - General	2,562	20	10	1,281	1,445	126
Reception	•			·	,	
218 - Bathrooms 2 Upstairs Bathrooms	6,150	20	2	5,535	5,989	248
226 - Bathrooms 2 Downstairs Restrooms	4,100	20	10	2,050	2,311	202
262 - Kitchen Coffee Room	1,538	20	10	769	867	76
270 - Kitchen Kitchen	3,075	20	19	154	315	189
274 - Laundry Room Upstairs Laundry	1,538	20	19	77	158	94
14000 - Recreation						
220 - Exercise: Treadmill Weight Room	2,050	10	4	1,230	1,471	174
224 - Exercise: Cardio Equipment Weight Room Elliptical	1,845	10	4	1,107	1,324	156
228 - Exercise: Weight Machine Weight Room	3,587	20	10	1,794	2,022	176
232 - Exercise: Miscellaneous Equip. Weight Room Tuff Stuff Rack	1,538	20	10	769	867	76
236 - Exercise: Miscellaneous Equip. Weight Room Dumbbells & Rack	3,075	15	9	1,230	1,471	197
18000 - Landscaping		_				
108 - Irrigation: Misc. Backflows, Controllers, Valves	1,025	5	1	820	1,051	161
482 - Pathways & Trails 520 Sq. Ft. DG Walking Path	2,665	5	1	2,132	2,732	420
19000 - Fencing						
310 - Wood: 3' 50 Lin. Ft. Northeast Perimeter	769	18	1	726	788	34
340 - Wood: 6' 895 Lin. Ft. Perimeter Fencing	22,934	18	3	19,112	20,896	1,054
19500 - Retaining Wall 372 - Masonry Wall Maintenance 225 Lin. Ft. Keystone Retaining Wall (25%) 20000 - Lighting	1,441	10	4	865	1,034	122
100 - Exterior: Misc. Fixtures 21 Station 89- Exterior Building Lights	5,381	20	10	2,691	3,034	265
420 - Interior	7,380	20	10	3,690	4,160	363
72 Station 89 Interior Lighting (50%) 424 - Interior 6 Station 89 Ceiling Fans	1,230	15	8	574	672	77
5 Station 65 Celling Lans						

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
00189 - Station 89						
21000 - Signage 774 - Wood Monument 2 Station 89 Signs	3,075	15	0	3,075	210	158
22000 - Office Equipment 212 - Computers, Misc.	1,025	6	1	854	1,051	135
Reception Dell PC Workstation #3101	,				•	
216 - Computers, Misc. Reception Dell PC Workstation #3102	1,025	6	1	854	1,051	135
220 - Computers, Misc. Reception Gateway PC Workstation #3092	1,025	6	0	1,025	175	131
224 - Computers, Misc. Reception Brother Printer	1,025	6	0	1,025	175	131
228 - Computers, Misc. Station Captains Office	1,025	6	4	342	525	145
232 - Computers, Misc. Station Captain's Office- Shredder	1,230	10	4	738	883	104
236 - Computers, Misc.	513	6	2	342	438	69
Station Captain's Office- Printer 240 - Computers, Misc.	1,333	10	4	800	956	113
Work Room- Fax 244 - Computers, Misc.	1,128	10	4	677	809	96
Work Room- Shredder 248 - Computers, Misc.	1,538	6	2	1,025	1,313	207
Equipment Room- UPS 1500 252 - Computers, Misc.	5,125	6	2	3,417	4,378	690
Equipment Room- Power Connect 2724 256 - Computers, Misc.	1,025	6	2	683	876	138
Equipment Room- Surge Protector	,					
260 - Computers, Misc. Equipment Room- Poweredge 2900	5,125	6	2	3,417	4,378	690
264 - Computers, Misc. Fire Prevention Office	1,025	6	0	1,025	175	131
268 - Computers, Misc. Fire Prevention Office- Shredder	1,230	6	2	820	1,051	165
272 - Computers, Misc. Battalion Chief's Office	1,025	6	4	342	525	145
304 - Copier Work Room- Copier	3,587	10	4	2,153	2,574	304
360 - Telephone Equipment	4,612	6	2	3,075	3,940	621
Equipment Room- Phone System 364 - Telephone Equipment	4,612	6	2	3,075	3,940	621
Equipment Room- Integration Hub 368 - Telephone Equipment	4,612	6	2	3,075	3,940	621
Equipment Room- Phone System  23000 - Mechanical Equipment	·			·	•	
204 - HVAC Roof- AC-1	10,250	15	7	5,467	6,304	624
208 - HVAC	10,250	15	7	5,467	6,304	624
Roof- AC-2 212 - Fan	4,612	20	10	2,306	2,600	227
Roof- Ventilation Fan 216 - Fan	4,100	20	10	2,050	2,311	202
Roof- Captive Aire Systems, Supply 220 - Fan	4,100	20	10	2,050	2,311	202
Roof- Captive Aire Systems, Exhaust 224 - Swamp Cooler	5,125	20	10	2,563	2,889	252
Roof- Evaporative Air Cooler						
228 - Swamp Cooler Roof- Evaporative Air Cooler	5,125	20	10	2,563	2,889	252
330 - Fuel Tank 2 Parking Area Fueling Tanks	15,375	30	20	5,125	5,778	645
580 - Cooling Tower Roof- REF-1	3,587	20	10	1,794	2,022	176

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
00189 - Station 89						
23000 - Mechanical Equipment	020	10	7	242	420	63
604 - Water Heater Upstairs Closet	820	12	7	342	420	62
608 - Water Heater Mechanic's Bay	820	12	0	820	70	53
24000 - Furnishings						
208 - Chairs 9 Station 89 Task Chairs	2,306	10	2	1,845	2,128	186
216 - Chairs 10 Station 89 Wood/Cloth Chairs	769	15	8	359	420	48
220 - Chairs 15 Station 89 Stackable Chairs	1,153	20	3	980	1,064	48
224 - Chairs 46 Station 89 Folding Chairs	3,536	20	10	1,768	1,994	174
232 - Chairs	3,075	10	4	1,845	2,206	261
6 Lounge- Recliners 310 - Tables: Dining: Large	1,025	20	10	513	578	50
Lounge & Kitchen 330 - Tables	1,743	20	10	871	982	86
17 Station 89 Folding Tables 650 - Modular Office Desk	5,125	20	10	2,563	2,889	252
5 Station 89 Office Desks 880 - Security Deposit Boxes	513	12	5	299	350	37
Station Captain's Office Lockbox 884 - Security Deposit Boxes	2,562	20	10	1,281	1,445	126
Station Captain's Office Safe 920 - Window Coverings	9,737	15	5	6,492	7,319	564
19 Station 89 Window Blinds 24500 - Audio / Visual						
100 - Television Weight Room	1,538	10	4	923	1,103	130
200 - DVD Player Storage (Conference)- Sony DVD	513	6	2	342	438	69
204 - DVD Player Storage (Conference)- Toshiba DVD	513	6	2	342	438	69
308 - PA System Equipment Room- Amplifier	769	10	4	461	552	65
312 - PA System	2,562	10	4	1,538	1,839	217
Conference Room- Podium 316 - PA System Conference Room- Projector	3,587	6	2	2,392	3,064	483
24600 - Safety / Access						
120 - Fire Control Misc Building Alarm & Extinguishers	5,125	10	4	3,075	3,677	435
350 - Defibrillators Lobby	2,562	5	2	1,538	2,101	414
25000 - Flooring						
220 - Carpeting 262 Sq. Yds. Station 89 Interior Carpeting	8,594	10	4	5,156	6,166	729
420 - Tile 2,543 Sq. Ft. Station 89 Floor & Wall Tile	15,639	20	10	7,820	8,817	769
620 - Vinyl 50 Sq. Yds. Bathroom Vinyl Tile	1,333	20	10	666	751	66
624 - Vinyl 166 Sq. Yds. Station 89 Wood Laminate Flooring	5,104	20	10	2,552	2,878	251
990 - Miscellaneous 27 Sq. Yds. Weight Room Rubber Flooring	830	15	9	332	397	53
26000 - Outdoor Equipment						
068 - Flag Pole Station 89- Flag Pole	5,637	30	20	1,879	2,119	237
220 - Barbecue Balcony	513	8	3	320	394	53

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
00189 - Station 89						
26000 - Outdoor Equipment 308 - Picnic Table: Wood Patio	410	15	8	191	224	26
27000 - Appliances						
220 - Refrigerator: Commercial: Large Kitchen	2,050	10	6	820	1,051	183
244 - Freezer: Large Kitchen	820	10	6	328	420	73
252 - Ice Machine Upstairs Closet- Ice-O-Matic	2,050	10	4	1,230	1,471	174
256 - Ice Machine Mechanic's Bay- Manitowac	2,050	10	4	1,230	1,471	174
260 - Stove Kitchen	3,587	12	8	1,196	1,532	280
274 - Oven: Wall Kitchen	2,562	10	4	1,538	1,839	217
286 - Microwave Oven Kitchen	615	10	4	369	441	52
294 - Stove: Fire Suppression Kitchen	5,637	10	4	3,383	4,045	478
310 - Dishwasher, Residential Type Kitchen	1,025	5	0	1,025	210	158
418 - Washer: Large Mechanic's Bay- Washer/Extractor	12,300	10	4	7,380	8,825	1,043
422 - Dryer Mechanic's Bay- Kenmore	1,025	10	4	615	735	87
426 - Washer Upstairs Laundry	718	10	6	287	368	64
430 - Dryer Upstairs Laundry	1,025	10	6	410	525	91
684 - Miscellaneous Coffee Room- Coffee Maker	513	10	4	308	368	43
984 - Miscellaneous Kitchen- Coffee Maker	513	10	4	308	368	43
988 - Miscellaneous Kitchen- Coffee Grinder	256	10	4	154	184	22
30000 - Miscellaneous 266 - Garage Door: Metal	15.225	20	10	760	1 576	0.4.4
3 Station 89 Garage Bay Doors 274 - Garage Door: Metal	15,375	20	19	769	1,576	944
4 Station 89 Garage Bay Doors- Rear	20,500	20	3	17,425	18,911	848
870 - Vehicle B2715- Lic 1275433	39,737	10	6	15,895	20,365	3,541
874 - Vehicle B2716 Lic 1275432	39,737	10	6	15,895	20,365	3,541
878 - Vehicle E-89- Lic 1206287	597,017	15	1	557,216	611,943	31,348
882 - Vehicle E-289- Lic E1109085	490,842	15	2	425,396	469,572	26,417
886 - Vehicle E-389 Lic E000391	555,238	10	7	166,572	227,648	50,714
890 - Vehicle U-89 Lic 1088016	45,491	15	3	36,392	40,411	2,509
894 - Vehicle U-289 Lic 041782	39,563	15	2	34,288	37,849	2,129
922 - Generator Building East Side- Generac Series	30,750	30	20	10,250	11,557	1,291
Sub-total Station 89	2,386,508		1	,566,830	1,772,765	159,516

Reserve Component	Current Repl. Cost	Useful Life	Remaining Life	2013/2014 Fully Funded Balance	2014/2015 Fully Funded Balance	2014/2015 Line Item Contribution based on Cash Flow Method
Totals	6,840,814		3.	[A] <b>457,409</b>	[B] <b>3,970,543</b>	448,000
Totals	0,040,014		3,	[EndBal] [A]	[EndBal]	448,000
Percent Funded				91.48%	75.29%	

## Section XI



Cameron Park Community Services District

Glossary

of Reserve Study Terms

Final

Prepared for the 2014/2015 Fiscal Year

## **Terms & Definitions CAI**

CASH FLOW METHOD: A method of developing a Reserve Funding Plan where contributions to the Reserve fund are designed to offset the variable annual expenditures from the Reserve fund. Different Reserve Funding Plans are tested against the anticipated schedule of Reserve expenses until the desired Funding Goal is achieved.

COMPONENT INVENTORY: The task of selecting and quantifying Reserve Components. This task can be accomplished through on-site visual observations, review of association design and organizational documents, a review of established association precedents, and discussion with appropriate representative(s) of the association or cooperative.

COMPONENT METHOD: A method of developing a Reserve Funding Plan where the total contribution is based on the sum of contributions for individual components. See "Cash Flow Method.

COMPONENT: The individual line items in the Reserve Study, developed or updated in the Physical Analysis. These elements form the building blocks for the Reserve Study. Components typically are: 1) Association responsibility, 2) with limited Useful Life expectancies, 3) predictable Remaining Useful Life expectancies, 4) above a minimum threshold cost, and 5) as required by local codes.

CONDITION ASSESSMENT: The task of evaluating the current condition of the component based on observed or reported characteristics.

CURRENT REPLACEMENT COST: See "Replacement Cost."

DEFICIT: An actual (or projected) Reserve Balance less than the Fully Funded Balance. The opposite would be a Surplus.

EFFECTIVE AGE: The difference between Useful Life and Remaining Useful Life. Not always equivalent to chronological age, since some components age irregularly. Used primarily in computations.

FINANCIAL ANALYSIS: The portion of a Reserve Study where current status of the Reserves (measured as cash or Percent Funded) and a recommended Reserve contribution rate (Reserve Funding Plan) are derived, and the projected Reserve income and expense over time is presented. The Financial Analysis is one of the two parts of a Reserve Study.

FULLY FUNDED BALANCE (FFB): Total Accrued Depreciation. An indicator against which Actual (or projected) Reserve balance can be compared. The Reserve balance that is in direct proportion to the fraction of life "used up" of the current Repair or Replacement cost. This number is calculated for each component, then summed together for an association total. Two formulae can be utilized, depending on the provider's sensitivity to interest and inflation effects. Note: Both yield identical results when interest and inflation are equivalent.

```
FFB = Current Cost X Effective Age / Useful Life
or
FFB = (Current Cost X Effective Age / Useful Life) +
[(Current Cost X Effective Age / Useful Life) / (1 + Interest Rate) ^ Remaining Life] -
[(Current Cost X Effective Age / Useful Life) / (1 + Inflation Rate) ^ Remaining Life]
```

FULLY FUNDED: 100% Funded. When the actual (or projected) Reserve balance is equal to the Fully Funded Balance.

FUND STATUS: The status of the reserve fund as compared to an established benchmark such as percent funding.

FUNDING GOALS: Independent of methodology utilized, the following represent the basic categories of Funding Plan goals:

Baseline Funding: Establishing a Reserve funding goal of keeping the Reserve cash

balance above zero.

**Full Funding:** Setting a Reserve funding goal of attaining and maintaining

Reserves at or near 100% funded.

Statutory Funding: Establishing a Reserve funding goal of setting aside the specific

minimum amount of Reserves required by local statues.

Threshold Funding: Establishing a Reserve funding goal of keeping the Reserve

balance above a specified dollar or Percent Funded amount.

Depending on the threshold, this may be more or less

conservative than "Fully Funding."

FUNDING PLAN: An association's plan to provide income to a Reserve fund to offset anticipated expenditures from that fund.

## FUNDING PRINCIPLES:

- Sufficient Funds When Required
- Stable Contribution Rate over the Years
- Evenly Distributed Contributions over the Years
- Fiscally Responsible

LIFE AND VALUATION ESTIMATES: The task of estimating Useful Life, Remaining Useful Life, and Repair or Replacement Costs for the Reserve components.

PERCENT FUNDED: The ratio, at a particular point of time (typically the beginning of the Fiscal Year), of the actual (or projected) Reserve Balance to the Fully Funded Balance, expressed as a percentage.

PHYSICAL ANALYSIS: The portion of the Reserve Study where the Component Inventory, Condition Assessment, and Life and Valuation Estimate tasks are performed. This represents one of the two parts of the Reserve Study.

REMAINING USEFUL LIFE (RUL): Also referred to as "Remaining Life" (RL). The estimated time, in years, that a reserve component can be expected to continue to serve its intended function. Projects anticipated to occur in the initial year have "zero" Remaining Useful Life.

REPLACEMENT COST: The cost of replacing, repairing, or restoring a Reserve Component to its original functional condition. The Current Replacement Cost would be the cost to replace, repair, or restore the component during that particular year.

RESERVE BALANCE: Actual or projected funds as of a particular point in time that the association has identified for use to defray the future repair or replacement of those major components which the association is obligated to maintain. Also known as Reserves, Reserve Accounts and Cash Reserves. Based upon information provided and not audited.

RESERVE PROVIDER: An individual that prepares Reserve Studies.

RESERVE STUDY: A budget planning tool which identifies the current status of the Reserve fund and a stable and equitable Funding Plan to offset the anticipated future major common area expenditures. The Reserve Study consists of two parts: the Physical Analysis and the Financial Analysis.

RESPONSIBLE CHARGE: A reserve specialist in responsible charge of a reserve study shall render regular and effective supervision to those individuals performing services which directly and materially affect the quality and competence rendered by the reserve specialist. A reserve specialist shall maintain such records as are reasonably necessary to establish that the reserve specialist exercised regular and effective supervision of a reserve study of which he was in responsible charge. A reserve specialist engaged in any of the following acts or practices shall be deemed not to have rendered the regular and effective supervision required herein:

- 1. The regular and continuous absence from principal office premises from which professional services are rendered; except for performance of field work or presence in a field office maintained exclusively for a specific project;
- 2. The failure to personally inspect or review the work of subordinates where necessary and appropriate;
- 3. The rendering of a limited, cursory or perfunctory review of plans or projects in lieu of an appropriate detailed review;
- 4. The failure to personally be available on a reasonable basis or with adequate advance notice for consultation and inspection where circumstances require personal availability.

SPECIAL ASSESSMENT: An assessment levied on the members of an association in addition to regular assessments. Special Assessments are often regulated by governing documents or local statutes.

SURPLUS: An actual (or projected) Reserve Balance greater than the Fully Funded Balance. See "Deficit."

USEFUL LIFE (UL): Total Useful Life or Depreciable Life. The estimated time, in years, that a reserve component can be expected to serve its intended function if properly constructed in its present application or installation.

The above terms and definitions are from the Community Associations Institute (CAI) national standards.

## **Terms & Definitions BRG**

Browning Reserve Group reserve studies use several terms that are unique to our reports. Our specialized systems have been developed to offer flexibility in many areas of our reporting. Please see below for definitions of abbreviations and symbols used in many of our reserve studies.

NR-1 (LIMITED RECURRENCE, 1 TIME): This signifies a major reserve component recurs for only a fixed number of cycles. Most often used to display a cost in a specific year only, NR-1 signifies the component only occurs one time. An NR-2 means the component will display for two cycles and so on. This makes it easy to enter one-time costs that pop up from time to time, or to display a cost that may be unique at one replacement date only.

SE-2 (SPREAD EVENLY OVER 2 YEARS): This signifies the major component, when replaced is spread evenly over 2 or more years. For example if a component will be replaced in year 8 of the study, and there is a SE-2, then the component will be replaced over 2 years, year 8 and year 9. Although the component is split over 2 or more years, each subsequent year will increase by the study's inflation factor. An SE-3 signifies the component is split over three years and so on.

NSE-2 (SPREAD NON-EVENLY OVER 2 YEARS): Similar to above, but the spread is not equal in each year. The spread is entered at a different amount for each year in the spread. The total of the spread will always equal 100% of the total replacement cost, excluding inflation.

% (PERCENT TO INCLUDE): This signifies that the component is being replaced at less than 100 percent of its replacement cost or quantity. Perhaps a component is replaced partially at each replacement year. Another example would be to do a small portion of the work at each replacement year. Oftentimes wood fencing is replaced over several cycles, and the study will display a percentage of the fence at each replacement cycle.

DELAYED START (REMAINING LIFE GREATER THAN USEFUL): In many instances a component's replacement cycle may not begin immediately, so the replacement cycle start is delayed. Delay is accomplished by setting the remaining life greater than the useful life.

ZERO REMAINING LIFE: Zero remaining life signifies that the component is replaced in the year which the study is prepared. All replacements are reflected in their replacement year, and the year in which the study is prepared is no different than any other year.